



Vehicle History Detail

Darling Downs
Haulage

Fleet #	008
Registration	DDH008
Make	Kenworth
Model	T659
VIN / Chassis #	6F5000000LA467777

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
		Fault R-1953			\$0.00
		Fault R-1961			\$0.00
25/07/2026	997,350 kms	C - 100K/Annual S-3227	Internal Workshop		\$0.00
22/07/2026	995,349 kms 179,907 hrs	Fault R-1960			\$0.00
15/07/2026		Brakes R-1954 ZEKE MURUCH DRIVER COMPLAINED OF BRAKES SMELLING. INSPECT ALL - SEEMS FINE, CHECKED TO MAKE SURE ALL SLACK ADJUSER WERE RELEASING.			\$0.00
14/07/2026	989,919 kms 17,900 hrs	Fault R-1952			\$0.00
06/06/2026	974,869 kms	B - 25-30K S-3172	Internal Workshop		\$0.00
15/04/2026	949,000 kms	B - 25-30K S-3108 JACK SHAFT SEAL REPLACED			\$0.00
08/04/2026		sleeper air R-1838			\$0.00
27/03/2026	938,269 kms 16,932 hrs	Mirror R-1825			\$0.00
26/02/2026	932,264 kms	Spot Light R-1797			\$0.00
07/02/2026	924,000 kms	B - 25-30K S-3025			\$0.00
04/02/2026	924,600 kms 166,418 hrs	drive belts R-1774			\$0.00
03/02/2026	923,859 kms 16,630 hrs	Lights R-1766			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
03/02/2026	923,859 kms 16,630 hrs	auto greaser R-1768			\$0.00
03/02/2026	923,859 kms 16,630 hrs	wipers R-1767			\$0.00
23/11/2025	907,750 kms	airconditioner R-1732 R&R THERMISTOR, TX VALVE, SLAVE SOLENOID PFM INV PFM1338			\$0.00
07/10/2025	897,350 kms	NHVR Truck Annual Inspection I-120			\$0.00
04/10/2025	897,350 kms	C - 100K/Annual S-2896			\$0.00
15/09/2025	884,497 kms	springs R-1635 Jack vehicle up and put on safety stands. Undo and remove u bolts and spring pins. Remove springs from vehicle. Fit upgraded 4 leaf springs. Fit old pins and new u bolts. Remove safety stands from vehicle. Tension and grease as required. Take one leaf off old pack and add 1 leaf to each spring pack to make a 4 leaf parabolic spring. Add longer center bolts.	TOOWOOMBA TRUCK ALIGNMENTS	INV-6010	\$0.00
17/08/2025	872,000 kms	diff, Steering R-1609			\$0.00
16/08/2025	872,500 kms	B - 25-30K S-2846 REPLACE STEERING BOX	Internal Workshop		\$0.00
10/07/2025	850,000 kms	diff R-1630 Remove all drive axles, Undo all rear diff mount bolts, Split diff and clean up surfaces, Reseal diff and refit axles. Undo all front diff mount bolts, Split diff and clean up surfaces. Reseal diff and refit axles. Remove power divider, replace thrust washer, Reshimmed and fitted with new 'o' rings. Replaced input seal. Removed thru shaft assembly, Replaced bearings and seal, Refit . Removed tailshaft at gearbox, Replaced loose yoke nut and tightened , Refit all tailshafts.			\$0.00
05/07/2025	850,000 kms	B - 25-30K S-2784	Internal Workshop		\$0.00
17/06/2025		DRIVE TYRES, Steer T-188			\$0.00
17/05/2025	827,000 kms	B - 25-30K S-2725	Internal Workshop		\$0.00
08/05/2025	819,576 kms	TYRE R-1509	Internal Workshop		\$0.00
10/04/2025		GEARBOX R-1628 Drain gearbox oil, Remove tailshaft, tank spreader and exhaust pipe. Remove all wiring, lines and hoses from gearbox. Remove clutch linkages and hydraulic pump. Remove gearbox from truck, Remove clutch and flywheel. Remove and replace rear main seal and rear engine mounts . Replace all clutch rod ends, pivot bearings and clutch lever . Fit machined flywheel and new clutch. Fit rebuilt gearbox and refit all accessories that were removed. Fill with oil and adjust clutch. Rebuild 18 Speed roadranger parts supplied.	ZAC WELSH		\$0.00
03/03/2025		NHVR Truck Annual Inspection I-102	Internal Workshop		\$0.00
01/03/2025		Prime Mover R-1269			\$0.00
01/03/2025		Prime Mover R-1270			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
01/03/2025	799,700 kms	C - 100K/Annual S-2631	Internal Workshop		\$0.00
05/02/2025	180,114 kms 13,600 hrs	LIGHT R-1256 Repair Resolved	Internal Workshop		\$0.00
05/02/2025	785,728 kms	TYRE R-1277 Repair Resolved	Internal Workshop		\$0.00
01/02/2025		LIGHT R-1272 Repair Resolved	Internal Workshop		\$0.00
13/01/2025	777,689 kms 13,551 hrs	Suspension R-1243 Repair resolved	Internal Workshop		\$0.00
11/01/2025	777,689 kms 13,551 hrs	windscreen R-1244 Repair resolved	Internal Workshop		\$0.00
06/01/2025	777,000 kms	B - 25-30K S-2555	Internal Workshop		\$0.00
14/12/2024		Prime Mover R-1232 Repair resolved	Internal Workshop		\$0.00
26/10/2024	745,334 kms	B - 25-30K S-2425 Damp pip rubbers bell crank bearing rose joint - clutch linkage rear diff pinion seal leaking front cab mounts rear cab shockie Cab filter A/C TRPCAF0001 Short flexi exhaust from turbo dump pipe	Dependable Diesel, Internal Workshop		\$0.00
09/10/2024		Cab R-1168 Repair Resolved	Brown & Hurley		\$0.00
23/09/2024		Icepack R-1129 Repair Resolved	BDS Mechanical	CL-RIN03187	\$230.45
10/09/2024	720,334 kms 12,548 hrs	B - 25-30K S-2361 DDH008 - 720334km & 12548hrs B- service	MPP Diesel	INV-0160	\$288.00
07/09/2024		Icepack R-1115 Repair resolved	Internal Workshop		\$0.00
29/08/2024	694,065 kms 12,158 hrs	C - 100K/Annual S-2614 694065KM -12158 HRS	Internal Workshop		\$0.00
28/08/2024		Prime Mover R-1094 Repair resolved	Internal Workshop		\$0.00
26/08/2024	711,704 kms 12,414 hrs	A S-2358 Check over and grease	MPP Diesel	INV-0152	\$0.00
13/08/2024	702,663 kms 12,285 hrs	Prime Mover R-1097 DDH008 - 702663km & 12285hrs Tune up Transfer pipe re seal Heater and draw down hose replace Sleeper air service Drive brakes + Drums	MPP Diesel	0144	\$1,044.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
13/08/2024		Prime Mover R-1098 LHS Front Drive Wheelseal	Internal Workshop		\$0.00
01/08/2024	694,065 kms 12,158 hrs	Bonnet Mounts R-1084 R&R BONNET MOUNTS, SIGHT GLASS COOLANT, AIR LEAKS, POWER STEERING OIL	MPP Diesel	INV-0134	\$0.00
01/08/2024	694,065 kms 12,158 hrs	NHVR Truck Annual Inspection I-93 694065KM -12158 HRS COMPLETED WITH C SERVICE	Internal Workshop		\$0.00
25/07/2024		New T-123 2 x 385/65R22.5 BRIDGESTONE R249 160K HWY (STEER) 2 STRIP AND FIT TRUCK TYRE 2 TYRE DUMPING CHARGE	Wise's mobile tyres	CO91431	\$2,627.60
01/07/2024	670,000 kms	B - 25-30K S-2261	Internal Workshop		\$0.00
19/06/2024		New T-97 8 BOLT ONS 11R22.5 2 245/70R19.5 HAULMAX ATT101 18PR 1 PUNCTURE REPAIR 11R22.5 3 STRIP AND FIT TRUCK TYRE 2 TYRE DUMPING CHARGE	Wise's mobile tyres	CO89344	\$1,103.10
11/06/2024		Prime Mover R-1022 Repair Resolved	Internal Workshop		\$0.00
11/05/2024	647,700 kms	B - 25-30K S-2198	Internal Workshop		\$0.00
27/04/2024		Prime Mover R-1021 Repair resolved	Internal Workshop		\$0.00
02/04/2024	625,543 kms	B - 25-30K S-2105	Internal Workshop		\$0.00
14/03/2024		Prime Mover R-1011 Repaired leak in ice pack, filled auto greaser, repaired air leaks	Internal Workshop		\$0.00
27/02/2024		Prime Mover R-1004 Replaced stopper for sliding turntable	Internal Workshop		\$45.28
21/12/2023		NHVR Truck Annual Inspection I-56	Internal Workshop		\$0.00
21/12/2023	596,000 kms	C - 100K/Annual S-2066 Tightened both yokes on front diff, clutch adjust, replaced govner	Internal Workshop		\$0.00
06/11/2023		Prime Mover R-979 Repaired air leaks, replaced 3 airbags	Internal Workshop		\$0.00
26/10/2023	575,000 kms	B - 25-30K S-1926 Change our Horton main Belt tensioners ac belt - MRowe	Internal Workshop		\$0.00
30/09/2023		Clutch R-617 Clutch adjust	Internal Workshop		\$0.00
30/09/2023		fan R-647 Replaced horton fan solenoid	Internal Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
30/09/2023	529,895 kms 9,500 hrs	Tyres R-857	Wise's mobile tyres		\$0.00
30/09/2023		Tyres R-856	Wise's mobile tyres		\$0.00
30/09/2023	516,964 kms 9,304 hrs	Gauges R-853	Internal Workshop		\$0.00
30/09/2023	516,964 kms 9,304 hrs	Lights R-852	Internal Workshop		\$0.00
30/09/2023		Air Leaks, Heater Tap R-635 Replace heater tap, blew radiator out and fixed air leaks.	Internal Workshop		\$0.00
30/09/2023		Repair R-632 replaced air bag on silver dolley at chinchilla	Internal Workshop		\$0.00
30/09/2023		Clutch R-630	Internal Workshop		\$0.00
30/09/2023	315,177 kms	Brakes R-714	Internal Workshop		\$0.00
30/09/2023	285,578 kms	Tyres R-704	Wise's mobile tyres		\$0.00
30/09/2023		airbag R-614 Replaced air bag on silver dolley at chinchilla	Internal Workshop		\$0.00
22/09/2023	558,404 kms	B - 25-30K S-1907 Fit new diff rods Upgrade sleeperair	Internal Workshop		\$229.68
31/08/2023	533,442 kms	D - 150k/tuneup S-2291			\$0.00
31/08/2023	533,442 kms	Prime Mover R-1043 Guidanz SO Number:665544 Hrs/Klms:9,674hrs/533,442kms Fuel Burn:328,555L - Components replaced as per customer request during low liner warranty repair	Cummins	9895813	\$0.00
22/08/2023		Rotate T-108	Wise's mobile tyres	CO76295	\$292.00
11/08/2023		Prime Mover R-907 Change drive tyres, replace 4 x shocks, fixed wheel seal	Internal Workshop		\$0.00
03/08/2023	523,000 kms	B - 25-30K S-1892			\$0.00
13/07/2023	475,000 kms	B - 25-30K S-1820 B service 48 litres lcepack service	Internal Workshop		\$0.00
13/07/2023	498,130 kms	C - 100K/Annual S-1859 C service 489130kms 48 litre 15w40 40 litres 85/140	Internal Workshop		\$0.00
13/07/2023		NHVR Truck Annual Inspection I-9	Internal Workshop		\$0.00
22/05/2023		breakdown R-591 Replace alternator and belt. Locked fan hub in.	Internal Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
22/05/2023		Repair R-593 New pulleys, belts, fan hub, clutch linkages.	Internal Workshop		\$0.00
22/05/2023		diff R-610 replaced diff oil and filter 40ltrs	Internal Workshop		\$0.00
11/05/2023	475,000 kms	B - 25-30K S-1733 B service, 48 ltrs.	Internal Workshop		\$623.57
05/04/2023	445,741 kms	B - 25-30K S-1719			\$0.00
25/01/2023	421,000 kms	B - 25-30K S-1702	Internal Workshop		\$585.30
17/01/2023		A S-1681			\$0.00
09/01/2023		Icepack R-569 Replace alternator on icepack Replace turntable pad	Internal Workshop		\$0.00
09/01/2023		Electrical R-561 Diadnose wiring issue	Internal Workshop		\$129.80
05/01/2023	389,452 kms	air dryer R-572 Replace air dryer	Internal Workshop		\$715.00
05/01/2023		Electrical R-574 Remote tipper control	Internal Workshop		\$0.00
30/12/2022		Prime Mover R-762	Internal Workshop		\$0.00
27/10/2022	391,096 kms	C - 100K/Annual S-1645	Internal Workshop		\$1,680.23
29/09/2022	383,000 kms	New T-45 New steer	Wise's mobile tyres	CO60492	\$2,501.00
14/09/2022		Clutch, shocks R-488 Clutch adjustment Replaced shocks	Internal Workshop		\$0.00
14/09/2022		Repair R-470 Repaired grease lines	Internal Workshop		\$0.00
14/09/2022		aircon R-483 Regas aircon	Internal Workshop		\$0.00
31/08/2022	359,026 kms	B - 25-30K S-1598 Replace engine mounts Replace turntable bushes, pads, horse shoe Service ice pack Replace dash lights	Internal Workshop		\$1,270.02
15/08/2022		Registration O-179			\$3,324.10
27/06/2022	331,650 kms	B - 25-30K S-1586	Internal Workshop		\$633.92
13/05/2022		aircon R-446 Fit cabin filter Recharge with gas AC	Internal Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
12/05/2022	307,665 kms	C - 100K/Annual S-1573	Internal Workshop		\$1,013.16
12/05/2022		Registration O-178			\$3,249.20
18/03/2022	280,750 kms	B - 25-30K S-1545 Repair grease lines	Internal Workshop		\$331.09
09/02/2022		Registration O-177			\$3,248.95
02/02/2022	255,000 kms	B - 25-30K S-1503	Internal Workshop		\$716.38
25/01/2022	260,741 kms	WHEEL ALIGNMENT R-500 Wheel alignment	Pengelly Trucks & Trailers	241073	\$214.50
18/01/2022		Repair R-422 Filled washer bottle and auto greaser Run wiring for spotties	Internal Workshop		\$0.00
18/01/2022		wipers R-392 New wipers	Internal Workshop		\$0.00
18/01/2022		Repair R-396 Fit gear nob Wire up	Internal Workshop		\$0.00
14/01/2022	258,024 kms	New T-37 11R22.5 HAULMAX	Wise's mobile tyres		\$0.00
30/11/2021	237,297 kms	Electrical R-465 Power supply to doser sump	Brown & Hurley	2347670	\$0.00
25/11/2021	235,000 kms	Electrical R-474 Aftertreatment fault Engine derate	Cummins	9176995	\$1,427.03
18/11/2021	225,240 kms	B - 25-30K S-1481	Internal Workshop		
15/11/2021		Registration O-152			\$3,247.30
11/10/2021	209,913 kms	GUAGE R-448 Inspect and repair after treatment faults Inspect and repair fuel gauge reading erratic	Brown & Hurley	2305381	\$698.43
30/09/2021	200,000 kms	C - 100K/Annual S-1467	Brown & Hurley, Internal Workshop	2298235	\$1,753.83
31/08/2021	172,000 kms	B - 25-30K S-1455 Sleeper air service	Internal Workshop		
10/08/2021		Registration O-134			\$3,244.90
19/07/2021	146,602 kms	B - 25-30K S-1416	Internal Workshop		
16/06/2021		Repair R-355 Install trackers Grease	Internal Workshop		

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
16/06/2021		Repair R-362 Move reflective signs Fit cab air blower to dog box	Internal Workshop		
16/06/2021		Lights R-339 Replace spotlight	Internal Workshop		
16/06/2021		Icepack R-338 Service sleeper air	Internal Workshop		
02/06/2021	124,616 kms	B - 25-30K S-1389	Internal Workshop		
20/05/2021	126,943 kms	New T-30 New steer tyres	Wise's mobile tyres	CO416480	\$2,929.00
14/05/2021		Registration O-119			\$3,176.10
28/04/2021	98,674 kms	C - 100K/Annual S-1375	Internal Workshop		
17/02/2021	69,797 kms	Clutch R-298 Adjust clutch to spec	Brown & Hurley	2119615	\$90.75
12/02/2021		Icepack R-265 Service	Internal Workshop		
11/02/2021	75,515 kms	B - 25-30K S-1348	Internal Workshop		
29/01/2021		A S-1338	Internal Workshop		
15/01/2021		A S-1334	Internal Workshop		
18/12/2020	57,000 kms	A S-1327	Internal Workshop		
03/12/2020	47,759 kms	B - 25-30K S-1241 Service ice pack	Internal Workshop		
23/10/2020		A S-1198	Internal Workshop		
09/10/2020		A S-1196	Internal Workshop		
25/09/2020		A S-1195	Internal Workshop		
09/09/2020	13,897 kms	B - 25-30K S-1137	Brown & Hurley	2000179	
144 Records				Total:	\$42,663.67