



Vehicle History Detail

Darling Downs
Haulage

Fleet #	012
Registration	DDH012
Make	Kenworth
Model	T909
VIN / Chassis #	6F5000000KA466762

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
		Fault R-1955			\$0.00
27/05/2026		COOLANT LEAK R-1904 HEATH - COOLANT LEAKING, HEATER HOSE HAS SPLIT IN IT			\$0.00
01/05/2026		Fault R-1858			\$0.00
01/05/2026	1,024,562 kms	B - 25-30K S-3173 COMPLETED BY HEATH REPLACE FRONT LEFT DRIVE SHOCKY REPLACE LOWER CAB HEATER TAB MADE NEW HYDRAULIC LINE REPLACED TOP AC IDLER PULLEY ADJUSTED CLUTCH CHECK ENGINE LIGHT IS ON, FIND FAULT, TOP UP COOLANT NEW SHOCKY MOUNT LH FD			\$0.00
27/03/2026	4,277 kms 176,984 hrs	airconditioner R-1826			\$0.00
23/03/2026		Icepack R-1930 CARRIED OUT AN INSPECTION ON THE ICEPACK UNIT FOR NO START OPERATION/ELECTRICAL FAULTS, CONFIRMED THE UNIT TO BE NOT STARTING, FOUND THE STRATER MOTOR TO BE BURNT OUT, REPLACED THE RELAYS & STARTER MOTOR ASSEMBLY ON THE ENGINE IN FRAME, ONCE REPLACED, STARTED THE ICEPACK ENGINE & FOUND THE ENGINE TO BE FAILED DUE TO EXCESSIVE MOVEMENT IN THE CRANKSHAFT THAT RESULTED IN THE STARTER FAILURE (ENGINE TO BE REPLACED NEW ICE PACK ENGINE INSTALL ENGINE SERAIL # 6SU0813. DEGASSED THE AIR CON SYSTEM & VAC DOWN, REMOVED ALL THE HOSES & ELECTRICS AS REQUIRED, REMOVED THE FRAME & ENGINE FROM THE CHASSIS & STRIPPED THE FAILED ENGINE FROM THE FRAME, TRANSFER THE REQUIRED COMPONENTS OVER TO THE NEW ENGINE & INSTALL IN THE MOUNTING FRAME, REPLACED THE AIR CLEANER FILTER, REPLACED THE FUEL FILTER, REFIT THE FRAME & ENGINE TO THE CHASSIS, REFIT ALL REMOVED HOSES & ELECTRICS, REGASSED THE SYSTEM & TEST RUN THE UNIT AS REQUIRED, CONFIRMED THE DESIRED TEMP AT THE VENTS, ALL OK.		00060757	\$0.00
07/03/2026	1,000,000 kms	C - 100K/Annual S-3035			\$0.00
04/02/2026	992,978 kms 17,489 hrs	Steering R-1773			\$0.00
22/11/2025	960,000 kms	B - 25-30K S-2957			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
04/11/2025		CLEARANCE LIGHT R-1688 REPAIR WIRING TO CLEARANCE LIGHT	Dependable Diesel		\$0.00
24/10/2025		airconditioner R-1684 REPLACE COMPRESSOR. REC DRIVER.	Internal Workshop		\$0.00
08/10/2025	935,359 kms 16,605 hrs	airconditioner R-1651			\$0.00
29/09/2025	930,000 kms	NHVR Truck Annual Inspection I-113			\$0.00
29/09/2025	930,000 kms	B - 25-30K S-2895			\$0.00
17/09/2025	924,416 kms 16,419 hrs	GREASE LINE R-1596	Internal Workshop		\$0.00
22/08/2025	912,110 kms 16,202 hrs	drive belts R-1577			\$0.00
19/08/2025	909,435 kms 16,161 hrs	LIGHT R-1569 Repaired Light	Internal Workshop		\$0.00
16/08/2025		Guard & Mud Flaps R-1568 GUARD RIPPED OFF AFTER BEING BOGGED TRAVEL TO CHINCHILLA, REPLACE HOCKEY STICK BRACKET. REFIT MUDGUARD, REMOVE FRONT MUDFLAPS. GREASED JAWS ON TURNTABLE			\$0.00
15/08/2025	907,885 kms 16,122 hrs	Guard & Mud Flaps R-1572			\$0.00
11/08/2025		leak R-1501	Internal Workshop		\$0.00
08/08/2025	904,000 kms	B - 25-30K S-2801			\$0.00
10/07/2025		DRIVE TYRES T-185 8 X GOODRIDE EZ73 DRIVE TYRES			\$0.00
09/07/2025	897,170 kms 15,865 hrs	Lights R-1534	Internal Workshop		\$0.00
05/07/2025	895,331 kms 15,823 hrs	Brakes R-1531	Internal Workshop		\$0.00
30/06/2025		windscreen R-1486	Garden City Autoglass	inv-2345	\$0.00
25/06/2025	892,629 kms 15,754 hrs	gauge R-1488	Internal Workshop		\$0.00
24/06/2025	892,280 kms 15,742 hrs	gauge R-1487	Internal Workshop		\$0.00
15/06/2025	889,268 kms	Hydraulics R-1497	PITTSWORTH FLEET MAINTENANCE		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
29/05/2025		speed sensor R-1521	Internal Workshop		\$0.00
27/05/2025		speed sensor R-1519	Internal Workshop		\$0.00
23/05/2025	885,092 kms 155,829 hrs	Heater R-1516	Internal Workshop		\$0.00
22/05/2025	882,810 kms	tune up R-1499	MPP Diesel		\$0.00
14/05/2025	880,665 kms	AD BLUE FAULT R-1512	Internal Workshop		\$0.00
10/05/2025	879,000 kms	C - 100K/Annual S-2723 Done by Zac Welsh - Centre Bearing, front, rear diff reseal, through shaft seal & brgs, pinion seal, Check over, NHVR check list for annual inspection	Internal Workshop		\$0.00
09/05/2025		tensioner R-1471			\$0.00
09/05/2025		windscreen washer R-1441			\$0.00
09/05/2025		Clutch R-1474			\$0.00
09/05/2025		airleak R-1462			\$0.00
09/05/2025		windscreen R-1372			\$0.00
06/05/2025	878,149 kms 154,695 hrs	OIL LEAK R-1505	Internal Workshop		\$0.00
06/05/2025	878,149 kms 154,695 hrs	windscreen washer R-1504	Internal Workshop		\$0.00
03/05/2025		TYRE R-1452			\$0.00
03/05/2025		LIGHT R-1451			\$0.00
02/05/2025		COOLANT R-1442	Internal Workshop		\$0.00
02/05/2025		Adblue R-1443			\$0.00
27/03/2025		Icepack R-1430			\$0.00
27/03/2025	846,822 kms 14,852 hrs	Lights R-1325			\$0.00
27/03/2025		COOLANT R-1365			\$0.00
27/03/2025		auto greaser R-1369			\$0.00
27/03/2025		Icepack R-1386			\$0.00
27/03/2025		COOLANT R-1389			\$0.00
27/03/2025		Prime Mover R-1390			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
27/03/2025		windscreen washer R-1395			\$0.00
27/03/2025		auto greaser R-1414			\$0.00
27/03/2025		Icepack R-1418			\$0.00
27/03/2025		COOLANT R-1419			\$0.00
27/03/2025		windscreen washer R-1422			\$0.00
27/03/2025		COOLANT R-1423			\$0.00
27/03/2025		auto greaser R-1424			\$0.00
27/03/2025		windscreen washer R-1428			\$0.00
27/03/2025		COOLANT R-1429			\$0.00
05/03/2025	840,256 kms 17,419 hrs	Lights R-1282 Repair resolved	Internal Workshop		\$0.00
05/03/2025	839,945 kms 14,715 hrs	Lights R-1280 Repair resolved	Internal Workshop		\$0.00
05/03/2025	843,699 kms 14,788 hrs	COOLANT R-1299 Repair resolved	Internal Workshop		\$0.00
01/03/2025	847,454 kms 14,860 hrs	Prime Mover R-1334			\$0.00
28/02/2025	844,713 kms 14,813 hrs	Lights R-1311 Repair resolved	Internal Workshop		\$0.00
28/02/2025	843,699 kms 14,788 hrs	Lights R-1298 Repair resolved	Internal Workshop		\$0.00
28/02/2025	847,454 kms 14,860 hrs	Prime Mover R-1335 Repair resolved	Internal Workshop		\$0.00
28/02/2025	846,822 kms 14,852 hrs	Prime Mover R-1328 Repair resolved	Internal Workshop		\$0.00
28/02/2025	846,433 kms 14,844 hrs	windscreen washer R-1321 Repair resolved	Internal Workshop		\$0.00
28/02/2025	846,433 kms 14,844 hrs	Lights R-1320 Repair resolved	Internal Workshop		\$0.00
28/02/2025	850,641 kms 14,914 hrs	Prime Mover R-1351 Repair resolved	Internal Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
27/02/2025	843,699 kms 14,788 hrs	Prime Mover R-1349 Repair resolved	Internal Workshop		\$0.00
27/02/2025	854,875 kms 14,992 hrs	windscreen R-1368 Repair resolved	Internal Workshop		\$0.00
26/02/2025	847,454 kms 14,860 hrs	Lights R-1332 Repair resolved	Internal Workshop		\$0.00
22/02/2025	851,000 kms	B - 25-30K S-2616	Internal Workshop		\$0.00
20/02/2025	847,454 kms 14,860 hrs	windscreen washer R-1333 Repair resolved	Internal Workshop		\$0.00
20/02/2025	846,822 kms 14,852 hrs	Prime Mover R-1326 Repair resolved	Internal Workshop		\$0.00
18/02/2025	845,197 kms 14,823 hrs	Lights R-1318 Repaired by James			\$0.00
18/02/2025	846,822 kms 14,852 hrs	Prime Mover R-1327 replaced bolts			\$0.00
18/02/2025	845,197 kms 14,823 hrs	Prime Mover R-1319 filled auto greaser correctly			\$0.00
18/02/2025	844,713 kms 14,813 hrs	Prime Mover R-1312 replaced bolts			\$0.00
18/02/2025	842,984 kms 14,773 hrs	Prime Mover R-1296 replaced air con vent			\$0.00
18/02/2025	842,984 kms 14,773 hrs	LIGHT R-1295			\$0.00
17/02/2025	842,463 kms 14,760 hrs	Prime Mover R-1293			\$0.00
14/02/2025	843,699 kms 14,788 hrs	Prime Mover R-1300 Repair Resolved	Internal Workshop		\$0.00
12/02/2025	840,256 kms 17,419 hrs	Prime Mover R-1283 Repair Resolved	Internal Workshop		\$0.00
11/02/2025	842,463 kms 14,760 hrs	Prime Mover R-1292 Repair Resolved	Internal Workshop		\$0.00
14/01/2025		Prime Mover R-1274 HOSE 1 2 WIRE BRAID AG EZIFLEX STEM 1" BSPP S/FEM STEM 1"BSP S/F FERRULE 1&2 WIRE 40MM PROTECTIVE WRAP (20m per Box) Consumables BSPP FEMALE X MALE X MALE TEE BSPPF X BSPTM ELBOW BSPPF X BSPTM CPLG MALE TEMA EQ' 1 BSPP BSPTM NIPPLE BSPPF X BSPTM 45 ELBOW 1	Downs Onsite Hydraulics	INV-6216	\$820.41

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
15/11/2024	824,974 kms	C - 100K/Annual S-2458 4 X BATTERIES REPLACED AUTO GREASER UNIT REPLACED (WARRANTY) AS WAS NOT PUMPING. DETAILS LODGED WITH ALEMLUBE. V DAQ INSTALLED	Internal Workshop		\$0.00
26/10/2024		New T-145 565225R249 385/65R22.5 160K BS R249 1 1225.00 1225.00 ACWEIGHT BALANCE BAG BB08 2 16.00 32.00 ZFITTBR FIT TBR TYRE 1 25.00 25.00 ZZSCRAPTYRETBRSU SCRAP TYRES TBR SUPER SINGLE 1 65.00 65.00 JOB# 46552 ZPUNCTURETBROFF PUNCTURE REPAIR TBR 1 60.00 60.00 ACSLEEVE #110 SLEEVE 1 4.00 4.00 REGN: YQ20VY A TRAILER P/REPAIR- REAR AXLE INNER, RHS BORDER TYRES AND BATTERIES BSB: 014-583	Bridgestone	103825	\$1,411.00
21/10/2024		Prime Mover R-1182 Hardwire kit	V-Daq	INV-8194	\$55.00
16/10/2024		A S-2421 Coolant leak - coolant filter A service	MPP Diesel	INV-0174	\$0.00
27/09/2024		New T-141 8 11R22.5 JINYU JD720 DRIVE 148/145L 16PR WHEEL BALANCE KIT - AMERICAN STEER (1 PAIR) 8 STRIP AND FIT TRUCK TYRE	Wise's mobile tyres	CO94286	\$5,520.00
27/09/2024	806,450 kms	C - 100K/Annual S-2363	Internal Workshop		\$0.00
27/09/2024	806,450 kms	NHVR Truck Annual Inspection I-64	Internal Workshop		\$0.00
24/09/2024		Alternator R-1165 Alternator replaced	CDM Hydraulics	1681	\$2,981.00
97 Records				Total:	\$10,787.41