

Number	Type	Date Open	Date Closed	Kilometres	Clos Hours	Closed	Fuel Usage	Clos Fault	Repairer / Notes	Cost / Invoice
R-8860	1000 hr filter quote.	09/08/2025	04/20/2026					0	12425 1000 hr filter quote.	\$0.00
S-7357	C - 1000	10/10/2025	12/10/2025		7,000	1,00		0	Tightened loose fittings at swivel ACTUALLLY DONE AT 6999HRS.	\$0.00
R-8707	Tracks	07/09/2025	08/28/2025				6,543	0	10719 Internal Workshop - Field Service Cut old bolts off removed and cleaned plate and chain replaced with new bolts.	\$0.00
S-7192	B - 500	08/08/2025	08/26/2025		6,534	534		0	Internal Workshop - Field Service Actually, done at 6534 hrs.	\$0.00
R-8526	Wipers	05/02/2025	07/23/2025				6,363	0	10246 inspected fine	\$0.00
R-8383	Welding Repair	02/24/2025	07/16/2025				6,325	0	9903 Internal Workshop - Fabrication Sent to workshop and repaired	\$0.00
R-8567	Carrier rollers	05/22/2025	05/22/2025				6,073	0	Internal Workshop - Field Service Hosepowewr Called hose power out to change hose. Borrowed tele handler from ricks and put man basket on to change hose. Washed down machine and adjusted hyd oil level	\$0.00
R-8544	HYD Hose	05/14/2025	05/14/2025				6,031	0	Internal Workshop - Field Service Remove 2 x rollers and had Damien come out to weld nuts on to broken bolts and removed. Fitted 2x new rollers sourced from BRIS VEGAS Went through and checked tenson on all roller and track guide bolts. Loose ones removed and anti seezd then tensioned.	\$0.00
R-8303	Roller	01/30/2025	05/14/2025				6,031	0		\$0.00
S-6937	C - 1000	05/09/2025	05/14/2025		6,000	1,00		0		\$0.00
R-8446	Tracks	03/21/2025	04/28/2025				5,943	0	10024 RETAINER PIN ON TRACK JOINER SNAPPED..	\$0.00
R-8366	UHF Radio	02/25/2025	02/25/2025				5,674	0	Internal Workshop - Field Service Hand piece for uhf has the button not working, had wayne from a grade source one and i fitted to machine.	\$0.00
R-8365	Bracket	02/25/2025	02/25/2025				5,674	0	Internal Workshop - Field Service Bracket that holds still pipe on bucket cylinder broken and rubber bush split out. Sourced new bracket and rubber insert from bris vegas, fitted to machine	\$0.00
R-8362	Batteries	02/24/2025	02/24/2025				5,667	0	Internal Workshop - Field Service Machine has been struggling to start after sitting over the weekends. Load tested volts dropping 18v. Removed and changed batteries Sourced from Battery Power Centre slacks creek	\$0.00
R-7881	Welding Repair	09/05/2024	01/24/2025				5,488	0	8989, 9127 Internal Workshop - Fabrication Boilys repaired at yard	\$0.00
S-6778	B - 500	01/24/2025	01/24/2025		5,500	500		0	1X Roller leaking and has a snapped bolt, another roller has a snapped bolt Hose bits found in return filter , hose failing somewhere from the inside.	\$0.00
R-7954	Cracks	09/17/2024	12/19/2024	0			5,379	0	9126, 9318, 942 brisvegas/RDW Internal Workshop - Fabrication removed dipper and sent to workshop to be welded, fit dipper to machine with new pins from brisvegas and seals/shims from	\$0.00
R-7810	Cracks	08/28/2024	12/19/2024	0			5,379	0	8938 Internal Workshop - Fabrication removed hitch, sent to workshop to be welded back up, then fit hitch with shims from RDW	\$0.00
R-7735	Quick Hitch	07/31/2024	12/19/2024	0			5,379	0	8780 Internal Workshop - Field Service Hitch springs replaced	\$0.00
R-7276	Mirror	03/13/2024	12/19/2024				5,379	0	Internal Workshop - Field Service mirror replaced, from brisvegas	\$0.00
R-8116	Tracks	11/04/2024	11/20/2024				5,305	0	9426 Internal Workshop - Field Service Track joining pin missing keeper. Replaced with bolt.	\$0.00
S-6393	C - 1000	07/12/2024	09/20/2024		5,000	1,00		0	Internal Workshop - Field Service	\$0.00
R-6712	Turbo Timer	10/26/2023	08/15/2024				4,797	0	Internal Workshop - Field Service A grade fitted new turbo timer agrade RERPLACED AC COMPRESSOR AND RE-GASED. FULL DETAILS	\$0.00
R-8411	Air con	03/17/2025	07/10/2024				4,643	0	ATTACHED.	\$0.00

R-7633	Bucket Teeth	07/01/2024	07/01/2024		4,593	0	Internal Workshop - Field Service	Replaced bucket teeth for spare bucket Teeth sourced from WPA	\$0.00
S-6308	B - 500	06/14/2024	06/14/2024	0	4,500	500		Actually serviced at 45412hrs	\$0.00
R-7275	HYD Breather	03/13/2024	05/24/2024		4,375	0	Internal Workshop - Field Service	Fitted 2x complete hydro breathers.	\$0.00
R-7494	Engine	05/13/2024	05/21/2024		4,360	0	Internal Workshop - Field Service	Replaced engine filler cap supplied by bris Vegas.	\$0.00
R-7496	Bucket Teeth	05/15/2024	05/15/2024		4,336	0	Internal Workshop - Field Service	Replaced worn bucket teeth Supplied by WPA	\$0.00
R-7087	Cracks	01/19/2024	03/20/2024		4,053	0	7523 Internal Workshop - Fabrication	Cracks in hitch	\$0.00
R-5878	Hydraulic fitting	02/21/2023	03/20/2024		4,053	0	6067, 6162, 640 Internal Workshop - Field Service		\$0.00
R-7106	Quick Hitch	01/29/2024	03/12/2024		4,006	0	7556 Internal Workshop - Field Service	Removed old saftey springs Replaced all springs for quick hitch, operated and checked. *Toung for hitch and slides worn will need to repair, this may of been reason as to spring coming of originally* Actual service hours 4006hrs Replaced hitch springs and Danny welded cracks(J/C filled out)	\$0.00
S-6118	C - 1000	03/11/2024	03/11/2024	0	4,000	978		Broken hyd tank breathers â€¦ parts on order (J/C done) Loose mounting bolts for main control valve , tightened bolts back up Broken offside mirror for access to top of machine(J/C done)	\$0.00
R-7240	Bucket Teeth	03/04/2024	03/04/2024		3,966	0	Internal Workshop - Field Service	Teeth have been flipped and worn down again. Removed teeth and fitted new teeth supplied by WPA	\$0.00
S-5956	B - 500	12/06/2023	12/06/2023	0	3,500	478		weld repaired bucket steel hyd. hose service actually done at 3520	\$0.00
R-6744	Ripper	11/03/2023	11/03/2023	0	3,332	0	Internal Workshop - Field Service	Worn ripper boot, removed and replaced. Sourced from WPA	\$0.00
R-6669	HYD Hose	10/12/2023	10/12/2023	0	3,189	0	Internal Workshop - Field Service	Removed steel bracket and steel hyd line to bucket cylinder. Cleaned welded back up and fitted to machine . tested	\$0.00
S-5778	C - 1000	09/07/2023	09/14/2023	0	3,022	1,01		Found safety locl spring assembly missing on quick hitch (chasing paarts up) Front of side mirror glass missing from mirror	\$0.00
R-6104	Bucket	04/06/2023	09/08/2023	0		0	6283	Repaired bucket as per Jay Audit 8/9/23	\$0.00
R-6886	UHF Radio	08/23/2023	08/23/2023		2,890	0	A Grade Auto Repair	Remove and replace reducer. A grade invoice attached.	\$0.00
R-6506	Ripper	08/09/2023	08/09/2023	0	2,797	0		replaced ripper boot	\$0.00
R-6458	Seat	07/21/2023	07/20/2023	0	2,684	0	Internal Workshop - Field Service		\$0.00
R-6459	Bucket Teeth, Ripper	07/21/2023	07/19/2023	0	2,684	0	Internal Workshop - Field Service	replaced bucket teeth x5 and ripper boot x1 supplied by WPA	\$0.00
R-6067	Belts, Breathers	03/20/2023	07/03/2023		2,569	0	Internal Workshop - Field Service	Kobelco issued wrong fan belts and did not supply hydraulic breathers for March C service.	\$0.00
S-5574	B - 500	06/13/2023	06/27/2023	0	2,543	533		service completed buy Max and Thom	\$0.00
R-6237	Windows	05/17/2023	06/12/2023	0	2,440	0	6411	replaced window buy MC auto glass	\$0.00
S-5355	C - 1000	03/17/2023	03/20/2023	0	2,010	983		Internal Workshop - Field Service missing fan belts and hydraulic breathers and there should be 2 small breathers. (R-6067).	\$0.00
R-6180	Bucket Teeth	05/05/2023	03/03/2023		1,909	0	Internal Workshop - Field Service	Max - changed out bucket and ripper teeth.	\$0.00
R-5806	Bucket Teeth	01/17/2023	01/17/2023		1,616	0	Internal Workshop - Field Service	Max - Replaced bucket teeth.	\$0.00

S-5202	B - 500	01/10/2023	12/21/2022	0	1,522	495	0	Internal Workshop - Field Service	\$0.00
R-5268	Teeth	10/03/2022	12/15/2022	0		1,485	0	Internal Workshop - Fabrication Other. Ground engaging gear: locks, pins, wear. 5411, 5457, 556 3x teeth missing	\$0.00
R-5190	Belts, Filters	09/19/2022	09/28/2022			1,062	0	Hydraulic filters and belts not changed at September C service due to the kit provided being a 500 hour kit and not 1000.	\$0.00
R-5064	Teeth	08/29/2022	09/28/2022			1,062	0	5251 Other. G.e.t needs replacing.	\$0.00
R-5035	Tracks	08/19/2022	09/28/2022	0		1,062	0	5202 Other. Chain tension. Right track losing tension	\$0.00
								Hydraulic filters and belts not changed due to kit being a 500 not 1000 (R-5190).	
S-4911	C - 1000	09/19/2022	09/19/2022		1,027	1,02	0	belts checked and adjusted	\$0.00
R-5034	Teeth	08/19/2022	08/30/2022	0		920	0	5201 swapping around	\$0.00
R-4833	Seat	07/29/2022	08/08/2022	0		760	0	5102 Not Working. Seat condition & seat belts. Seat base doesn't slide	\$0.00
R-4797	Bucket Teeth	07/30/2022	08/08/2022	0		760	0	5105, 5106 Other. Ground engaging gear: locks, pins, wear. Need teeth	\$0.00
R-4787	Chains	07/22/2022	08/08/2022	0		760	0	5046 Other. Chain tension. RHS track Keeps losing tension	\$0.00
R-4574	Tracks	06/29/2022	07/07/2022	0		577	0	4892 Other. Chain, sprocket and roller condition. Tracks need adjustment Max: tracks adjusted at service	\$0.00
S-4622	B - 500	06/08/2022	07/01/2022	0	550	550	0	Service actually completed at 598 hours.	\$0.00
R-4513	Bolts	06/20/2022	06/30/2022	0		586	0	4803 Other. Check attachments (if item failed - take photo). Keeper bolts for both on ripper and front pin on GP bucket broken Max: replaced bolts	\$0.00
R-4510	Steps	06/20/2022	06/30/2022	0		586	0	4802 Damaged. Check grab handles, steps & walk ways. 3 X Lower steps broken off Jay - repaired bent steps and refitted.	\$0.00
R-4330	Boot	05/20/2022	06/30/2022	0		586	0	4606, 4891 Other. Check attachments (if item failed - take photo). Ripper needs new boot	\$0.00
R-4168	Steps	04/08/2022	06/30/2022	0		586	0	4433, 4758, 477 Damaged. Check grab handles, steps & walk ways. Bent step Max :bottom steps too low and will always get ripped off still has to step and is safe	\$0.00
R-4427	Pin bolts	06/03/2022	06/10/2022	0		477	0	4692, 4759 Replace bucket pin bolts with 12.9 socket head cap screws.	\$0.00
R-3958	First Aid Kit	02/23/2022	05/17/2022	0		348	0	4283	\$0.00
R-4187	Pin	04/20/2022	05/12/2022	0		337	0	4459	\$0.00
R-4182	UHF	04/19/2022	05/12/2022	0		337	0	4456	\$0.00
R-4105	1st Service	03/17/2022	03/17/2022			100	0	Brisvegas Machinery 1st Service - 100hrs Engine Oil and Engine Oil Filter Changed	\$0.00