



Corner Garage Inc.
406C Highway 11
Fort Frances, ON P9A 3M2
(807) 270-7467
sales@cornergarage.ca

Invoice for RO #1861

Service Advisor: Marlene Brubacher
Posted Date: 07/08/25 at 10:38 AM EST

Client: Myron Huber

Vehicle: 2021 Chevrolet Silverado 2500 HD LT

	2021 Chevrolet Silverado 2500 HD LT 6.6L 8Cyl DIESEL L5P Turbocharged VIN: 1GC1YLEY4MF165601 License: BZ 48332 Color: White Odometer In: 128501 / Out: 128909	RO # 1861 Time-In: 03/27/25 at 11:24 AM EST Save Parts: No
--	---	---

Client concerns:

- Transmission Filter and Fluid
- Power Steering Leak
- Pass thro programming

1 - Transmission Filter and Fluid

Tech: J Torkelson

Labo:	Remove & Replace Transmission Fluid & Filter	3.75 hrs	\$110.00	\$412.50
Parts:	Motocraft Mercon ULV	15.5	\$13.98	\$216.69
	OEM Transmission Filter	1	\$105.97	\$105.97
	OEM Transmission Pan comes with mag and plug	1	\$288.97	\$288.97
	OEM Transmission Gasket	1	\$126.97	\$126.97

✓ Approved on 03/27/25 at 02:06 PM EST

Subtotal \$1,151.10 + est. Tax \$149.64

\$1,300.74

2 - Transmission - warranty

Tech: J Torkelson

Note: Programmed it twice at our shop, using SnapOn Passthru Assist. Performed Fast Relearn multiple times. Took to our local Chevy Dealer and had them diagnose. They programmed transmission the third time, and performed Fast Learn. Noted lots of internal transmission growling. Reperformed Fast Learn and test drive. Found 3-4, 5-6, 8-9, and 9-10 shift slip. Suspect damaged internal mechanical part prior to install of transmission assembly. Leaning toward cracked reaction carrier assembly, based off of GM document ID 5163972. Suggest tear-down for internal mechanical failure, or replace transmission assembly.

Labo:	Remove & Replace Transmission Assembly	13.20 hrs	\$110.00	\$1,452.00
	Flush Trans Oil Cooler Line	0.70 hrs	\$110.00	\$77.00
	Programming Transmission	2.00 hrs	\$110.00	\$220.00
Parts:	TRANS FLUSH	2	\$57.64	\$115.28
	OEM Trans Fluid Cooler Pipe Seal	1	\$33.43	\$33.43
	Motocraft Mercon ULV	17	\$13.98	\$237.66
	First Programming Fee	1	\$285.00	\$285.00
	Second Programming	1	\$285.00	\$285.00
	Third Programming	1	\$285.00	\$285.00

✓ Approved on 07/16/25 at 02:27 PM EST

Subtotal \$2,990.37 + est. Tax \$388.75

\$3,379.12

3 - Transmission

Tech: J. Torkelson

Note: Removed complete bumper and grille assembly to change transmission cooler and lines.

Labor:	Remove & Replace Transmission Assembly	13.20 hrs	\$110.00	\$1,452.00
	Remove & Replace Trans Oil Cooler Assembly	3.30 hrs	\$110.00	\$363.00
	Remove & Replace Trans Oil Cooler Lines	3.30 hrs	\$110.00	\$363.00
Parts:	General Motors TRANSMISSION, AUTOMATIC	1	\$5,787.38	\$5,787.38
	OEM Trans Oil Cooler	1	\$331.70	\$331.70
	Shipping - Trans cooler	1	\$34.48	\$34.48
	Trans Cooler Line Set	1	\$369.17	\$369.17
	Shipping - Cooler lines	1	\$61.94	\$61.94
	General Motors SEAL, TRANSMISSION FLUID COOLER PIPE	1	\$33.43	\$33.43
	OEM Trans Cooler Seal	1	\$34.99	\$34.99
	Shipping for Seals	1	\$34.60	\$34.60
	Motocraft Mercon ULV	7	\$13.98	\$97.86
	Programming Fee	1	\$285.00	\$285.00
	Trans Flush	1	\$57.64	\$57.64
	Shipping for Trans	1	\$195.91	\$195.91
	Fuel	1	\$60.00	\$60.00
	Return Shipping for Trans	1	\$114.36	\$114.36

✓ Approved on 06/09/25 at 11:53 AM EST

Subtotal \$9,676.46 + est. Tax \$1,257.94

\$10,934.40Please send e-transfers to sales@comeracerace.ca

Clients assume liability for vehicles and contents while parked on premises.

Wheels removed? Please swing by our shop for a free retorque within 100 kms.

Total Repair Order & Signature:

Total Jobs:	\$13,817.93
Total Fees:	\$0.00
Subtotal:	\$13,817.93
Taxes:	\$1,796.33
Grand Total:	\$15,614.26
BALANCE DUE:	\$0.00

X

✓ PAID

Completed Transactions