


Itec Equipment Inc. 26 Gardner Road Rosslyn, ON P7K 0P1 Ph no: (807) 768-8584

Toll free: (833) 483-2200



Quantity Quantity Back Ordered Shipped Ordered		Part Number and Description		Code	Price	Net Amount	
REQUEST	1: REPAIR	BUCKET			50		
1	1		WOR LABOUR2	INTRA-COMPANY	TH	74.950	74.95
			LABOUR TO LASER CLEAN SHANKS				
4	4	15	FUT FT430	FUTURA TWISTER ADAPTER	TH	193.171	772.68
4	. 4		FUT FT430RC	FUTURA TWISTER ROCK TOOTH	TH	149.631	598.52
4	4		ITR V43PN	SUPER V 43 PIN	TH	21.546	86.18
1	1		MSC STEEL	STEEL	TH	2802.780	2802.78
	12		NEW BUCKET BOTTOM	1/2"			
1	1		MSC STEEL	STEEL	TH	1370.180	1370.18
		189	4"x48"x5/8" HARDOX	500TUF WEARSTRIPS			
1	1		MSC STEEL	STEEL	TH	2882.620	2882.62
			-12"x48"x2" BUCKET-	ЫР - ∼~			
43.00	43.00		SRV SHOP01	SHOP LABOUR	TH	155.000	6665.00
	15		3	SHOP SUPPLIES	TH		666.50
	PARTS: 85	87.91	LABOR: 66	65.00 SUBLETS: 0.	00	SUPPLIES: 666.50	

HARMONIZED SALES TAX (CODE H) \$2,069.52

8 8 9	9	20 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	a a	N S			0
Goods Received By Please Print Name	r. ·		Signature X		4	SUBTOTAL TAX	15919.41 2069.52
ALL REBUILT COMPONENTS QUOTED COMPONENTS TH		TOTAL	17988.93				
Terms: Full payment to be in to avoid storage charges, G picked up within 90 days be	oods that have n	ot been authorized by the	terest charges to be applied on a e customer to be repaired are to	ill overdue accounts. Upon con be picked up within 45 days fro	apletion of work order C om date of quoted repai	Customer is responsible for Ir to avaid s take the light	olckup of goods wilhin 45 days At custom algood striat are not