

WHELANS GROUP INVESTMENTS PTY. LTD.

ABN: 83 143 750 449

ACN: 143 750 449

103 Rupert Street Bairnsdale Vic 3875

PH: 03 5152 2844 FAX: 03 5152 7202

WEB: www.whelansgroup.com.au



Technician Name: B

Date: 15/4/24

Unit No: L3

Make: cat

Model: 982M

Km's/Hours:

Job Description:

- Diagnose flat battery serpentine belt
- Snapped alternator not charging
- batteries - Replace belt ✓
-
-
-
-
-
-
-

Additional work required or any safety concerns noted:

Technician Name: jamie Clements Date: 13/1/25
Unit No: L3
Make: Cat Model: Km's/Hours: 8928

Job Description:

-	Replace Bango grease nips on front pins
-	Ripped off on Pugmill feed bin
-	
-	
-	
-	
-	
-	
-	
-	

Additional work required or any safety concerns noted:

Detailed description of completed works Including any parts used:

Replace 4 lost new bungs grease fitting

Technician Signature:

Date:

Operator Signature:

Date:

Supervisor Signature:

Date:

The electronic copy on the server is the master copy. All other copies are uncontrolled.

File Ref: WHELANS GROUP – MECHANICAL REPAIRS JOB CARD

Revision 2.0 September 2024

2

Technician Name: Jordan N

Date: 7/2/25

Unit No: L3

Make: CAT

Model: 982

Km's/Hours: 9100-8

Job Description:




2742-S Brake Solenoid fault

Additional work required or any safety concerns noted:

N/A

Detailed description of completed works including any parts used:

- Coil for brake accumulator charge solenoid failed.
- Replaced coil.

Technician Signature:		Date:	7/2/25
Operator Signature:		Date:	
Supervisor Signature:		Date:	7/2/25

Technician Name:

B

Date:

7-5-25

Unit No:

L3

Make:

CAT

Model:

982M

Km's/Hours:

9502

Job Description:

Replace Heel Plates and cutting edges

Additional work required or any safety concerns noted:

[illegible]

Date: 7/5/25