



Vehicle History Summary

Fleet #	PM388
Registration	XQ85MI
Make	Kenworth
Model	K200
VIN / Chassis #	6F5000000LA467767
Build Date	2020

Date	Reading / Units	Type / Repairer Notes	Repairer
17/07/2025		WINDSCREEN R-5983	THE FIXER CORPORATION PTY LTD
25/06/2025	13,399 kms	A S-14351	QLD WORKSHOP
25/06/2025	13,399 kms	C S-14352 ADJUSTED THE CLUTCH DOWNLOADED ECM	QLD WORKSHOP
24/06/2025	1,013,399 kms	Heavy Vehicle Inspection Checklist - Truck I-736	QLD WORKSHOP
04/06/2025	1,079,046 kms	NEW STEERS T-3381	QLD WORKSHOP
03/06/2025	1,079 kms	ABS SENSOR R-5884 REPLACED ABS SENSOR ON PASSENGER SIDE	QLD WORKSHOP
27/05/2025	995,566 kms	A S-14139 REPLACE EBS PLUG, A SERVICE	QLD WORKSHOP
07/05/2025	982,200 kms	A S-13975 A SERVICE	QLD WORKSHOP
06/05/2025	982,200 kms	ROTATE DRIVES, ROTATE STEER T-3318 ROTATED DRIVES DIAGONAL FLIPPED POS 2 STEER ON RIM	QLD WORKSHOP
06/05/2025	978,287 kms	DRIVE BRAKES R-5779	QLD WORKSHOP
09/04/2025	967,316 kms	CHECK BATTERIES R-5689 REPLACED BATTERIES	QLD WORKSHOP
09/04/2025	967,316 kms	B S-13784 B SERVICE	QLD WORKSHOP
25/02/2025	950,504 kms	A S-13489 CUSTOM AIR 4625HRS DUE 4860HRS LOWEST BRAKE 7MM REAR DRIVE BOTH CAB SHOCKS LEAKING, FUEL PUMP FLUFFY	QLD WORKSHOP
04/02/2025	937,688 kms	ROTATE DRIVES, ROTATE STEER T-3123 QLD WORKSHOP ROTATED DRIVES SIDE TO SIDE, STEERS SIDE TO SIDE	DARREN BUDD'S TYRES PTY LTD
04/02/2025	937,688 kms	A S-13311 CUSTOM AIR SERVICED, @4558HRS NEXT DUE 4860HRS	QLD WORKSHOP
14/01/2025	924,610 kms	AIR CONDITIONER R-5351 SERVICE A/C SYSTEM. RECOVER 1.13L OF GAS, REMOVE AND REPLACED RECIVER DRYER, REPLACED ALL ORINGS, VACCUM DOWN SYSTEM FOR 20MINS, HOLDING VACCUM PRESSURE. RE-GAS SYSTEM WITH 1.32L OF GAS. BLOW OUT RADIATOR SENT BACK INTO SERVICE	QLD WORKSHOP
07/01/2025	920,990 kms	A S-13085	QLD WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
		A SERVICE	
19/12/2024		MARKER LIGHTS R-5289 INSPECTED TRUCK FOR PARKER LIGHT FUSE KEEPS BLOWING FOUND RUBBED WIRE AT REAR BAG AGAINST CUSTOM AIR REPAIRED WIRE AND SECURED LOOM ALL OK	MELBOURNE DIESEL MECHANICS
17/12/2024	910,039 kms	ENGINE OIL LEAK R-5268 FOUND MISSING BOLT AND LEAKING COVER, REMOVED BELTS, TENSIONERS AND HORTON FAN HUB, REMOVED AND CLEANED FRONT COVER REMOVED DIAMOND SEAL AND CLEANED SEALING SURFACE AND GROOVE INSTALLED SEAL ADDING GREY MAX TO OVERLAPPING AREA FITTED COVER INSTALLING MORE GREYMAX TO OVERLAP, BOLTED COVER DOWN DOUBLE CHECKED ALL BOLTS/ NUTS REINSTALLED PULLEYS AND TENSIONERS, FANHUB AND BELTS. STARTED ENGINE AND TESTED FOR LEAKS NO LEAKS PRESENT WASHED DOWN AND SENT BACK TO SERVICE.	QLD WORKSHOP
10/12/2024	906,305 kms	B S-12914	QLD WORKSHOP
10/12/2024	906,305 kms	BRAKE RELINE, EXHAUST FLEXI R-5237 RELINED BOTH FRONT DRIVE BRAKES AND DRUMS , REPLACED EXHAUST FLEX NEAR TURBO	QLD WORKSHOP
19/11/2024	893,254 kms	A S-12702 A-SERVICE CUSTOM AIR SERVICED AT 4237HRS REPLACED STARTER AND ALTERNATOR TORQUED UBOLTS, TIGHTENED BELLY BAR CAB SHOCKS LEAKING, FIRST UNI HAS MOVEMENT	QLD WORKSHOP
19/11/2024	893,254 kms	ALTERNATOR ON KLMS, NOx SENSOR, STARTER MOTOR R-5171 DISCONNECTED BATTERIES, REPLACED ALTERNATOR WITH NEW ALTERNATOR TOOK OF PULLEY FROM OLD ALTERNATOR AND INSPECTED PULLEY FOR ANY DAMAGE AND CHECKED EVERYTHING FOR ANY DAMAGE DONE BY LUKE.L REMOVED EARTH AND POWER LEADS AND EXCITER PLUG REMOVED MOUNTING BOLTS REMOVED STARTER AND REMOVED PLUG HARNESS INSTALLED ON TO NEW STARTER REFITTED CHECKED TIGHTNESS ALL GOOD TESTED 3 TIMES ALL OPERATIONAL DONE BY MATT.C REMOVE AND REPLACED NOX SENSOR, TESTED ALL WORKING SENT BACK TO SERVICE	QLD WORKSHOP
29/10/2024	880,404 kms	A S-12517 CUSTOM AIR UNIT AT 4192 HOURS DUE AT 4233 HOURS TENSIONED]BOTH CUSTOM AIR BELTS AS WERE LOOSE	QLD WORKSHOP
02/10/2024	863,961 kms	A S-12293 A-SERVICE	QLD WORKSHOP
04/09/2024	845,535 kms	ROTATE DRIVES, ROTATE STEER T-2803 ROTATED DRIVES DIAGONAL ROTATED STEERS AS NEEDED DONE BY QLD WORKSHOP	QLD WORKSHOP
04/09/2024	845,535 kms	B S-12096 ICE PACK 4148hrs Due @ 4230hrs	QLD WORKSHOP
27/08/2024	839,974 kms	UNLOADER VALVE R-4896 FOUND UNLOADER VALVE CONSTANTLY LEAKING ONCE BLOWING OFF, REMOVED AND REPLACED UNLOADER VALVE, NEW SEALS, SECURED INTO PLACE STARTED TRUCK AND BUILT FULL AIR AND DRAINED ALL AIR AND LET IT BUILD BACK UP, SPRAY TESTED UNLOADER VALVE NO LEAKS PRESENT, ALL OKAY	QLD WORKSHOP
13/08/2024	830,749 kms	A S-11851 CUSTOM AIR, 4140HRS DUE 4230HRS MOVEMENT IN 1ST AND 2ND UNI LOWEST BRAKE 7MM, NEEDS DRIVE BRAKES NEXT SERVICE	QLD WORKSHOP
17/07/2024	814,135 kms	A S-11642 A-SERVICE	QLD WORKSHOP
27/06/2024	800,245 kms	A S-11504 ICE PACK AT 4128 HOURS DUE AT 4233 HOURS CLUTCH ADJUSTED AS REQUIRED ADDED 10 LITRES COOLANT ADDED 3 LITRES ENGINE OIL 1ST UNI HAS MOVEMENT 2ND DRIVE INPUT SEAL WEEPING CAB SHOCKS LEAKING	QLD WORKSHOP
12/06/2024	793,583 kms	Heavy Vehicle Inspection Checklist - Truck I-507	QLD WORKSHOP
12/06/2024	799,999 kms	ROTATE DRIVES, ROTATE STEER T-2635	DARREN BUDD'S TYRES PTY LTD

Date	Reading / Units	Type / Repairer Notes	Repairer
		ROTATE 8 DRIVES DIAGONAL	
12/06/2024	793,583 kms	C S-11329	QLD WORKSHOP
		C-SERVICE FOUND PARTS OF THRUST WASHER IN DIFF OIL STRAINER	
29/05/2024	784,593 kms	UNLOADER VALVE , WIPER BLADE R-4564	QLD WORKSHOP
		REMOVED AND REPLACED AIRDRYER UNLOADER AS WAS LEAKING TESTED FOR LEAKS NONE PRESENT SENT BACK TO SERVICE REPLACED WIPER BLADES AS PER REQUESTED	
29/05/2024	784,593 kms	B S-11121	QLD WORKSHOP
		B-SERVICE REPLACED AIRDRYER UNLOADER REPLACED WIPER BLADES 1ST UNI HAS MOVEMENT CAB SHOCKS LEAKING	
30/04/2024	767,751 kms	A S-10916	QLD WORKSHOP
		A-SERVICE REAR DIFF WEARPING FROM INPUT SHAFT (WASHED DOWN) CAB SHOCKS LEAKING	
04/04/2024	751,949 kms	A S-10718	QLD WORKSHOP
		MOVEMENT IN UNI OUT OF GEARBOX BACK OF FUEL PUMP LEAKING IMPUT SEAL ON SECOND DIFF IS LEAKING	
04/04/2024	751,950 kms	NEW DRIVE TYRES, ROTATE STEER T-2477	DARREN BUDD'S TYRES PTY LTD
		8 X M866 DRIVES FITTED ROTATE STEERS SIDE/SIDE	
28/02/2024	737,265 kms	A S-10442	QLD WORKSHOP
		MOVEMENT IN 1ST UNI 2ND DIFF INPUT LEAKING, BACK OF FUEL PUMP LEAKING ICE-PACK HRS CURRENTLY 4024HRS DUE 4233HRS	
06/02/2024	722,362 kms	B S-10233	MELBOURNE VIC WORKSHOP
05/02/2024		BREAK DOWN, LIGHT PLUG R-4040	CANBERRA TRUCK REPAIRS PTY LIMITED
		CALLED OUT CANBERRA TRUCK CENTRE TO REPAIR LIGHTS TO TRAILERS	
18/01/2024	711,104 kms	NEW STEERS, ROTATE DRIVES T-2241	DARREN BUDD'S TYRES PTY LTD
		ROTATED DRIVES SIDE/SIDE X8 STRIP/FIT R154 BRIDGESTONE STEERS X2	
16/01/2024	709,226 kms	A S-9984	MELBOURNE VIC WORKSHOP
		REPLACED HUBCAP DRIVER FRONT	
19/12/2023	698,151 kms	CALLOUT FEE, DUMP TYRE, STRIP/FIT RUNOUT T-2220	DARREN BUDD'S TYRES PTY LTD
		1X CALLOUT SRV TO COCA-COLA 1X RUNOUT FITTED 1X DUMP	
11/12/2023	692,597 kms	A S-9731	MELBOURNE VIC WORKSHOP
30/11/2023	686,931 kms	DASH GLOBES R-3783	MELBOURNE VIC WORKSHOP
		Replaced X2 T10 wedge globes	
19/11/2023	679,460 kms	PUNCTURE REPAIR T-2131	TREADCARE PTY LTD
		CALL OUT TO REPAIR A PUNCHER ON TRUCK IN MELBOURNE YARD	
17/11/2023	679,460 kms	A S-9501	MELBOURNE VIC WORKSHOP
20/10/2023	662,170 kms	B S-9270	MELBOURNE VIC WORKSHOP
16/10/2023	662,170 kms	ROTATE DRIVES, ROTATE STEER T-2037	TREADCARE PTY LTD
		ROTATED DRIVES CROSS TO CROSS ROTATED STEERS SIDE TO SIDE	
29/09/2023	647,821 kms	wheel alignment R-3598	BRETT STEELE LASER ALIGNMENTS PTY LTD
		CALLED IN BRETT STEELS TO CARRY OUT FULL WHEEL ALIGNMENT FRONT AND REAR. ALL DONE OK SENT TRUCK BACK INTO SERVICE	
27/09/2023		PUNCTURE REPAIR T-2004	TREADCARE PTY LTD

Date	Reading / Units	Type / Repairer Notes	Repairer
		REPAIRED LEFT FRONT	
26/09/2023	645,657 kms	A S-9120 Pitman arm loose tightened, Spring crossbar loose tightened, Diff input seal weeping 3rd axle, Oil filler tube leaking tightened clamp, Intake stack loose tightened	MELBOURNE VIC WORKSHOP
22/09/2023	645,657 kms	A S-9073	MELBOURNE VIC WORKSHOP
01/09/2023	630,513 kms	A S-8793	MELBOURNE VIC WORKSHOP
01/09/2023	630,513 kms	WEATHER SHIELD R-3422 REMOVED DAMAGED WEATHER SHIELD AND CLEANED OLD DOUBLE SIDED TAKE OFF DOOR FITTED NEW WEATHER SHIELD	MELBOURNE VIC WORKSHOP
04/08/2023	615,600 kms	A S-8623 FRONT BAR HAS BEEN DAMAGED - INCIDENT REPORT AND PHOTOS SENT TO COMPLIANCE	MELBOURNE VIC WORKSHOP
04/08/2023	615,600 kms	ROTATE DRIVES, ROTATE STEER T-1869 ROTATED DRIVES SIDE TO SIDE ROTATED STEERS SIDE TO SIDE	TREADCARE PTY LTD
14/07/2023	600,148 kms	REKIT HORTON FAN HUB, REPLACE COMP ON KLMS R-3252 fitted kit to horton fan replaced 2 worn studs and fitted 6 new nyloc nuts to studs tested all ok removed and replaced air compressor fitted new gaskets and o rings, fitted new governor valve tested air system all ok	MELBOURNE VIC WORKSHOP
14/07/2023	600,148 kms	B S-8413	MELBOURNE VIC WORKSHOP
15/06/2023	583,075 kms	Heavy Vehicle Inspection Checklist - Truck I-285	
15/06/2023	583,075 kms	C S-8273	MELBOURNE VIC WORKSHOP
05/06/2023	575,673 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-1766 QLD WORKSHOP ROTATED DRIVES DIANONAL FLIPPED POS # 1 ON RIM 2 X STEER BALANCES	DARREN BUDD'S TYRES PTY LTD, QLD WORKSHOP
05/06/2023	575,673 kms	BATTERY, CHECK BATTERIES R-3164 LOAD TESTED BATTERY 2 FAILED. REMOVED AND REPLACED ALL BATTERIES	QLD WORKSHOP
31/05/2023	573,747 kms	A S-8152	MELBOURNE VIC WORKSHOP
19/04/2023	556,397 kms	A S-7763 FOUND COOLANT WAS LOW, FOUND COOLANT FILTER LEAKING REPLACED WITH NEW. RAN A BUBBLE TEST TO SEE IF ENGINE HAD DROPPED A LINER, BUBBLE TEST WAS POSTIVE, TRUCK GOING TO CUMMINS ICE PACK SERVICED AT 4495HRS INSTALLED REVERSE SQUAWKER	QLD WORKSHOP
19/04/2023	556,397 kms	ICE PACK SERVICE, REVERSE BUZZER R-3046 REMOVE REVERSE ALARM AND INSTALL REVERSE SQUAWKER ICE PACK SERVICED AT 4500HRS BUBBLE TEST ENGINE, ENGINE FAILED BUBBLE TEST, TRUCK BEING SENT TO CUMMINS FOR REBUILD	QLD WORKSHOP
18/04/2023	556,523 kms 7,592 hrs	ENGINE REBULD, TURBO ON KLMS R-3018 CUMMINS FOUND LINER DROPPED AT CYLINDER 5, REMOVED HEAD AND SUMP PAN, REPLACED ALL LINERS AND PISTON RINGS. REPLACED ALL GASKETS AND SEAL. REMOVED AND REPLACED TURBO ON KLMS, REPLACED ALL O-RINGS STUDS AND NUTS AS NEEDED DRIVING BACK FROM CUMMINS NOTICE OIL PRESSUR DIAL NOT WORKING CORRECTLEY. TEST SENDER ON MOTOR TO FIND FAULTY. REPLACE SENDER WITH NEW AND START UP AND CHECK IF LEAKING. NO LEAKS. TAKE FOR TEST DRIVE DIAL NOW WORKING PROPERLY.	CUMMINS SOUTH PACIFIC PTY LTD
24/03/2023	541,579 kms	B S-7580	MELBOURNE VIC WORKSHOP
24/02/2023	524,741 kms	WIPER BLADE R-2871 Have removed the old worn blades and fitted brand new wiper blades on	MELBOURNE VIC WORKSHOP
24/02/2023	524,741 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-1580	TREADCARE PTY LTD

Date	Reading / Units	Type / Repairer Notes	Repairer
		ROTATE ALL DRIVES SIDE TO SIDE ROTATE AND BALANCE STEER TYRES	
20/02/2023	524,741 kms	A S-7289	MELBOURNE VIC WORKSHOP
08/02/2023	511,546 kms	A S-7187	MELBOURNE VIC WORKSHOP
25/01/2023	506,160 kms	TRAILER PLUG, WATER IN FUEL R-2782	MELBOURNE VIC WORKSHOP
		Have replaced the trailer plug with brand new trailer plug Have drained fuel pro out	
05/01/2023	495,755 kms	BRAKES, DRUM R-2726	MELBOURNE VIC WORKSHOP
		Have removed both wheels on the rear drive axel and removed the brakes and drums also the bush shimming has been bashed out the have fitted brand new Brakes +drums also new brake bush shimming has been bashed in as well wheels put back on and wheel nuts torqued down at 600nm brakes adjusted as well	
05/01/2023	495,755 kms	A S-6891	MELBOURNE VIC WORKSHOP
		Rear drive brakes and drums have been replaced	
06/12/2022	485,282 kms	ENGINE BRAKE N/W, ICE PACK SERVICE R-2639	MELBOURNE VIC WORKSHOP
		Have serviced the ice pack with brand new oil, oil filter and fuel filter looked over belts, tentionors and bushes Have adjusted the engine brake switch and engine brake now activates	
18/11/2022	483,596 kms	CLUTCH, GEARBOX SHARFT/BEARING R-2577	MELBOURNE VIC WORKSHOP
		removed gearbox and clutch assy, flywheel machined, rebuild front of gearbox, fitted flywheel and clutch assy, refitted gearbox and took for test drive all ok	
15/11/2022	479,596 kms	B S-6487	MELBOURNE VIC WORKSHOP
		Rear axel drives brakes due next service @7mm Clutch have been adjusted	
14/11/2022	479,596 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-1382	TREADCARE PTY LTD
		rotate drives cross to cross rotate steers side to side	
26/10/2022	464,543 kms	A S-6323	QLD WORKSHOP
10/10/2022	451,268 kms	A S-6217	MELBOURNE VIC WORKSHOP
		Ice pack serviced@2929hrs slight movement in uni cap end play, front uni REPLACED MISSING STEER HUB CAP	
16/09/2022	436,401 kms	ROTATE DRIVES T-1311	MELBOURNE VIC WORKSHOP
		rotated drives side to side - workshop	
16/09/2022	436,401 kms	A S-6052	MELBOURNE VIC WORKSHOP
22/08/2022	416,257 kms	NEW STEERS T-1307	DARREN BUDD'S TYRES PTY LTD
		2 X NEW BRIDGESTONE STEER TYRES FITTED UP ALL OK	
22/08/2022	420,000 kms	B S-5886	QLD WORKSHOP
22/08/2022	420,000 kms	GUSSET R-2478	QLD WORKSHOP
		REMOVED AND REPLAVED 2 X GUSSITS BEHIND GEAR BOX ALL OK	
26/07/2022	399,729 kms	A S-5683	MELBOURNE VIC WORKSHOP
		REPLACED MISSING HORN COVERS	
29/06/2022	384,906 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-1177	TREADCARE PTY LTD
		ROTATE ALL DRIVES SIDE TO SIDE ROTATE AND BALANCE STEERS	
28/06/2022	384,906 kms	ADBLUE INJECTOR, DOSER PUMP R-2169	MELBOURNE VIC WORKSHOP
		removed injector and tried to unblock with hot water and wire wouldn't unblock so replaced, tried flushing doser pump but wouldn't prime or shot air through the system replaced doser pump and primed ok all faults went inactive, cleared codes, tested ok	
28/06/2022	384,906 kms	C S-5474	MELBOURNE VIC WORKSHOP
		ice pack serviced @2460hrs	

Date	Reading / Units	Type / Repairer Notes	Repairer
28/06/2022		Heavy Vehicle Inspection Checklist - Truck I-125	
09/06/2022	373,879 kms	A S-5370	QLD WORKSHOP
16/05/2022	359,810 kms	B S-5170	MELBOURNE VIC WORKSHOP
26/04/2022	343,902 kms	A S-5025 Steers and drive tire rotation Ice pack services at 2154hrs	MELBOURNE VIC WORKSHOP
26/04/2022	343,902 kms	NEW DRIVE TYRES, ROTATE/BALANCE STEER T-1069 rotate and balance steers fitted new drive tyres	TREADCARE PTY LTD
24/03/2022	336,951 kms	EXHAUST LEAK R-1797 Replace brand new AFM gasket	MELBOURNE VIC WORKSHOP
09/03/2022	330,267 kms	A S-4736	MELBOURNE VIC WORKSHOP
17/02/2022	313,215 kms	A S-4567	MELBOURNE VIC WORKSHOP
02/02/2022	301,643 kms	ICE PACK NOT RUNNING R-1567 FIND THAT THE POWER LINE WAS BROKEN AT CRIMP REMOVED BROKEN CRIMP AND PUT A NEW ONE ON THE LINE FIND THE ONE OFF THE BELTS WAS LOSS SO TIGHTEN THE BELT CHEAKED THE CHARGE RATE AND ALL OK	QLD WORKSHOP
27/01/2022	297,980 kms	B S-4396	QLD WORKSHOP
26/01/2022	297,980 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-925 ROTATED ALL DRIVES CROSS TO CROSS ROTATED STEER SIDE TO SIDE ONLY	DARREN BUDD'S TYRES PTY LTD
12/01/2022	286,949 kms	BATTERY, CHECK BATTERIES R-1495 tested battery 3 out of 4 batteries not holding charge under load replaced all 4 batteries	MELBOURNE VIC WORKSHOP
06/01/2022	283,330 kms	A S-4272 serviced ice pack 1605hrs	MELBOURNE VIC WORKSHOP
12/12/2021	267,199 kms	A S-4085	MELBOURNE VIC WORKSHOP
18/11/2021	251,903 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-776 rotated and balanced steers rotated driven front to back	TREADCARE PTY LTD
18/11/2021	251,903 kms	A S-3910	MELBOURNE VIC WORKSHOP
03/11/2021	243,364 kms	power socket R-1288 piggy backed wires off inverter ran up along side the bed and fitted a power socket to the end of it	MELBOURNE VIC WORKSHOP
30/09/2021	237,387 kms	B S-3519	MELBOURNE VIC WORKSHOP
09/09/2021	222,062 kms	A S-3385 REPLACED MISSING HUB CAP WITH GOOD SECOND HAND ONE AND NEW NUT COVERS	QLD WORKSHOP
31/08/2021	229,457 kms	axle cover R-1073 fitted axle cover	QLD WORKSHOP
17/08/2021	208,476 kms	A S-2968	MELBOURNE VIC WORKSHOP
17/08/2021	208,476 kms	295/80R22.5 TOYO, NEW STEERS, ROTATE DRIVES T-596 FITTED NEW STEER TYRES ROTATED DRIVES CROSS TO CROSS	TREADCARE PTY LTD
28/07/2021	197,299 kms	C S-3046	QLD WORKSHOP
08/06/2021	177,761 kms	B S-2647	MELBOURNE VIC WORKSHOP

Date	Reading / Units	Type / Repairer Notes	Repairer
CHECK TYRES ROTATE DUE AT 208168KLMS			
20/05/2021	163,168 kms	A S-2494	QLD WORKSHOP
19/05/2021	163,170 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-430 ROTATED ALL DRIVE TYRES FRONT TO BACK ROTATED AND BALANCED BOTH STEER TYRES, FLIPPED POS# 2 TYRE ON RIM	QLD WORKSHOP
25/04/2021	148,032 kms	A S-2186 tyre rotation next service	MELBOURNE VIC WORKSHOP
31/03/2021		WINDSCREEN R-551 THE FIXER WINDSCREENS COME OUT REMOVED AND REPLACED WINDSCREEN ALL OK	THE FIXER CORPORATION PTY LTD
31/03/2021	132,034 kms	HEATER TAP, LIGHT PLUG R-526 Replaced leaking heater tap back of engine Replaced trailer plug	QLD WORKSHOP
25/03/2021		HUB COVER R-502 REPLACED COVER ALL OK	QLD WORKSHOP
18/03/2021	132,034 kms	A S-1948	QLD WORKSHOP
08/03/2021	118,523 kms	B S-1756	
02/03/2021	113,068 kms	HUB CAP COVERS R-398 Replace missing hub cover	QLD WORKSHOP
01/03/2021	121,054 kms	100,000KLM ENGINE TUNE] R-314 Carry out 100,000km top tune Intake 0.14 Exhaust 0.27 Jake break 7mm	QLD WORKSHOP
16/02/2021	105,590 kms	A S-1513	
25/01/2021	90,982 kms	A S-1371	QLD WORKSHOP
02/12/2020	60,217 kms	B S-847	
02/12/2020	60,217 kms	DIFF OILS, ESOC FITTINGS R-135 Fitted ESOC fittings to truck Drained front and rear diffs, found metal chunks in front diff Took oil sample to show Brown&Hurley and awaiting phone call from Brown&Hurley	
12/11/2020	48,556 kms	ROTATE/BALANCE STEER, ROTATE DRIVES T-76 ROTATE ALL DRIVE TYRES ROTATE AND BALANCE STEER TYRES	DARREN BUDD'S TYRES PTY LTD
10/11/2020	45,632 kms	A S-620	
14/10/2020	30,192 kms	A S-411	
01/08/2020		C S-1703	

Signed: _____

Name: _____

Date: _____