

Service
History



TAX INVOICE

Goulburn Valley Resources

Invoice Date
25 Mar 2024

Invoice Number
INV-0840

Reference
D6N

ABN
17 983 452 012

A.P DUNDON & S.E
DUNDON
275 Bromfields Rd
NORTHWOOD VIC 3660
AUSTRALIA
0400324462
asddiesels@gmail.com

Description	Quantity	Unit Price	GST	Amount AUD
Caterpillar D6N Serial - CBX00317 Hrs - 3925				
Travel out to site, remove blown hydraulic hose on blade tilt cylinder.	3.50	110.00	10%	385.00
Take hose to Mac's as sample and have new hose made.				
Travel back to site, install hose on machine and test operation, all working fine, refit all covers and clamps etc.				
Pack up and return to workshop.				
Less payment (Credit), For payment made twice.	1.00	(363.00)	10%	(363.00)
			Subtotal	22.00
			TOTAL GST 10%	2.20
			TOTAL AUD	24.20

Due Date: 8 Apr 2024

Payment Terms: Overdue invoices may incur a late fee of \$15.00

Continuous non payment of invoices will result in a 12% increase of invoice total, every 30 days overdue.

Please make payment to the following:

Account Name: ASD Diesel

BSB: 063545

Account number: 10413890

For Credit Card or EFT Payments:

In person at ASD Diesels workshop

Shed 2 104 Wimble Street Seymour, 3660

or via phone - license number may be required for security purposes.




PAYMENT ADVICE

To: A.P DUNDON & S.E DUNDON
275 Bromfields Rd
NORTHWOOD VIC 3660
AUSTRALIA
0400324462
asddiesels@gmail.com

Customer	Goulburn Valley Resources
Invoice Number	INV-0840
Amount Due	24.20
Due Date	8 Apr 2024
Amount Enclosed	
	Enter the amount you are paying above

ETA Mechanical Solutions Pty Ltd

11 Commercial Drive
WALLAN Vic 3756
Ph: 0408 541 027



A.B.N. 13 139 858 512

Goulburn Valley Resources
Po Box 880
Seymour Vic 3661
Australia

Tax Invoice
Invoice #: 00012417

Customer Order Number				TERMS	DATE
D6				Net 14	30/06/2022
QTY.	DESCRIPTION	PRICE	UNIT	EXTENDED PRICE	TAX
	Cat D6N s/n KCB00317 @ 38978hrs				
	Description of Job #				
	Please refer FSR 10143- Remove track chains, supply and fit new chains and sprockets, bolt supplied grousers on with new bolts. Supplied 4x additional grouser plates.				
	Tracks, sprockets & bolts	\$10,225.36		\$10,225.36	GST
	Parts Freight	\$265.00		\$265.00	GST
27	Labour	\$120.00	Hr	\$3,240.00	GST
	Consumables	\$80.00		\$80.00	GST
4	Grouser plate	\$103.22		\$412.88	GST
Account Details: Account Name: ETA Mechanical Solutions Pty Ltd BSB: 063 698 Account Number: 1029 2201		Payment Due By: 14/07/2022		SALE AMT.	\$14,223.24
				FREIGHT	\$0.00
				GST	\$1,422.32
				TOTAL AMT.	\$15,645.56
				PAID TODAY	\$0.00
Customer ABN:			BALANCE DUE	\$15,645.56	



ETA MECHANICAL SOLUTIONS PTY LTD
ABN 13 139 858 512
Phone David: 0417 404 147 Luke: 0408 541 027

No. 8304

Client: CUB
Make: Caterpillar Model: D6N
Address: Serial No: CBL00317
Other S/N: Hrs / Kms: 3657
Technician: Andrew Job: Repair
Job Location: Seymour Oil Sample Taken ☐ Yes ☐ No

Sub Job No	Description
	Travel to site, drive down to machine -
	blow down frame -
	Remove belly plate under frame + remove floor
	plates, align, remove hose from frame
	fit new hose in place, install clamps, test run +
	check for leaks, oil cooler line, top up frame
	oil, refit floor cover plates, lock belly plate up
	into place + fit all bolts.

Comments

	Job Safety Analysis
W	What is the job?
W	What is different?
W	What can HURT me?
R	Risk Rating:
C	Controls put in place:
N	New Risk Rating:
(the)	(Remember that the consequences cannot change just the likelihood)
C	Can I proceed? (Yes/No)

E	Date	Working Time		Travel Time		Kms
		Start	Finish	Start	Finish	
L	29/7			1.0		80
L						

REQUISITION		QTY
frame oil 430		81
hose		1
Freight		6
labour		1
T		50
K/M		
C/M		

48
324.55
25
630
105
68
12.60
1226.55
1237.45

- (a) Tr (b) EI (c) EI (d) O
- (a) The machine / vehicle will be at my risk as regards to damage by fire or from any other cause whilst in the possession or control of ETA Mechanical Solutions Pty Ltd
- (b) EI (a) The machine / vehicle will not be liable for loss or damage which I may suffer due to delays in completion of this repair.
- (c) EI (a) ETA Mechanical Solutions Pty Ltd will only be liable to replace or repair defective parts or make good defective workmanship.
- (d) O (a) Other than the above, ETA Mechanical Solutions Pty Ltd or its agents will not be held liable for any loss, damage, injury or any kind resulting from this work.

I have read and agree to the above conditions

Customers Signature

Date



ETA MECHANICAL SOLUTIONS PTY LTD
ABN 13 139 858 512
Phone David: 0417 404 147 Luke: 0408 541 027

No. 7836

Client..... Make..... Model.....
Address..... Serial No.....
..... Other S/N..... Hrs / Kms.....
Technician..... Job.....
Job Location..... Oil Sample Taken ☐ Yes ☒ No

Sub Job No	Description
	Travel to site. Carry out 500hr Service as required
	change engine oil & filters. replace fuel filter
	replace air filter & cabin filter
	check other levels. Carry out inspection & grease
	drive line. Carry out source repairs to auto
	greasing system. Requires 3 or 4 new hoses
	re-fit one hose with reusable end as it had broken
	off road grease & carry out manual greasing of
	systems - replace R/H hand work light & replace
	R/L top work light globe. Pack up & have to stop

Comments Requires new front wiper arm assembly - worn
has to replace all bolts & pullies & bushings
starting to get noisy.

Job Safety Analysis

What is the job?
What is different?
What can HURT me?
Risk Rating:
Controls put in place:
New Risk Rating:
Remember that the consequences can change with the situation.
Can I proceed? (Yes/No)

REQUISITION

QTY

H3 24V 70W Glb 1 ✓
Brake clean 1

Date	Working Time		Travel Time		Kms
	Start	Finish	Start	Finish	
1/5	5.5		7.5		80

- (a) The machine / vehicle will be at my risk as regards to damage by fire or from any other cause whilst in the possession or control of ETA Mechanical Solutions Pty Ltd
(b) ETA Mechanical Solutions Pty Ltd will not be liable for loss or damage which I may suffer due to delays in completion of this repair.
(c) ETA Mechanical Solutions Pty Ltd will only be liable to replace or repair defective parts or make good defective workmanship
(d) Other than the above, ETA Mechanical Solutions Pty Ltd or its agents will not be held liable for any loss, damage, injury or any kind resulting from this work

I have read and agree to the above conditions

Customers Signature

Date



ETA MECHANICAL SOLUTIONS PTY LTD
ABN 13 139 858 512
Phone David: 0417 404 147 Luke: 0408 541 027

No. **6171**

Client... GUR Make... CAT Model... D6N
Address... Serial No... 00317
Technician... TAYLOR Other S/N... Hrs / Kms... 3483 Hrs
Job Location... SEYMOUR Job... SCOOP SERVICE
Oil Sample Taken ☐ Yes ☒ No

Sub Job No	Description
	TRAVEL TO SITE.
	LOAD UP FOR JOB. TRAVEL TO MACHINE IN QUARRY.
	DRY OUT SCOOP HA SERVICE.
	ENG OIL & FILTER CHANGE. FILL FILTER CHANGE CHANGE AIR
	WATER. FILL COOLANT. FILL WITH WATER & RUN. DRAIN
	A LONG TIME - VERY SLOTTED. BLOW OUT RADIATOR - TOOK
	TRACKS. INSPECT BELTS, PULLIES, TENSIONER. CHECK (HORN) FUEL
	WASHER (WASHER) TOP UP. FRONT WASHER MOTOR FOUND TO BE FAULTY. RATED
	WASHER LUBS (FAN) INTO CAB. REMOVED REAR TUNING. FOUND BURNING
	IN BURNER HOSE FILTER. JOURNAL TEST. FIT PUMP LING. BURN UP. BLOW OUT
	CAB FILTER. REMOVED & BLOW OUT FILTERS. CHECK

Comments

Job Safety Analysis	
What is the job?	<u>SERVICE</u>
What is different?	<u>MACHINE</u>
What can HURT me?	<u>Slips / Trips</u>
Risk Rating:	<u>18</u>
Controls put in place:	<u>PPE</u>
New Risk Rating:	<u>20</u>
(Remember that the consequences cannot change just the likelihood)	
Can I proceed? (Yes/No)	<u>Y/N</u>

Date	Working Time		Travel Time		Kms
	Start	Finish	Start	Finish	
10/4/15	5.75	hrs.	1.25	hrs.	118
11/4/15	1.0	hrs.			

REQUISITION	QTY
COOLANT RED	40L
COOLANT RED (LEFT FOR TOP UP)	20L
WASHER JOURNAL	1

- (a) The machine / vehicle will be at my risk as regards to damage by fire or from any other cause whilst in the possession or control of ETA Mechanical Solutions Pty Ltd
(b) ETA Mechanical Solutions Pty Ltd will not be liable for loss or damage which I may suffer due to delays in completion of this repair.
(c) ETA Mechanical Solutions Pty Ltd will only be liable to replace or repair defective parts or make good defective workmanship.
(d) Other than the above, ETA Mechanical Solutions Pty Ltd or its agents will not be held liable for any loss, damage, injury or any kind resulting from this work.

I have read and agree to the above conditions

Customers Signature

Date