



451 Leakes Road
TRUGANINA VIC 3029

Phone: 9978-0840

Email: truganina@ultratune.com.au

If any of your contact details are incorrect, please inform us immediately so they may be corrected.

Contact: BILD GROUP

Work:

Home:

Mobile: 0418882313

Email: carlav_21@yahoo.com.au

Bill to: Ms. BILD GROUP
133 Metrolink Circuit
CAMPBELLFIELD VIC 3061

Payment Term: C.O.D.

Registration: **BDK331**

Make: FORD

Model: RANGER

Manufacture Date:

Recorded Rego. Due:

Odometer: 197810

Deliver to: m: 0418882313

Recall Details:

MHS SERV 12M/10K recall at 193254, or by 4/02/2026

MHS SERV 12M/15K recall at 212810, or by 17/06/2026

Code	Stock description or line text	RRP	Quantity	Unit	Line total
Manufacturers Handbook Service					
Servicing should be performed periodically. Periods for servicing is time or distance based and should be performed on which period elapses first, whether time or distance. Prolonging service periods beyond the recommended time may be damaging to the vehicle, reducing the vehicle's performance and reliability.					
Carried out this service as per check list below in accordance with manufacturers specifications. (refer parts listed below).					
	WASTE MANAGEMENT FEE	\$10.000	1.00	\$10.000	\$10.00
	WORKSHOP SUPPLY	\$10.000	1.00	\$10.000	\$10.00
	SUMP PLUG WASHER	\$2.000	1.00	\$2.000	\$2.00
3418104	CASTROL ENGINE SHAMPOO	\$25.000	1.00	\$25.000	\$25.00
R2720P	RYCO OIL FILTER	\$33.690	1.00	\$30.300	\$30.30
337242	MAGNATEC PROF A5 5W30 SYNTHETIC	\$21.500	9.80	\$21.500	\$210.70
LABOUR	LABOUR (P/H)	\$120.000	1.50	\$120.000	\$180.00
AIR FILTER R&R					
Remove necessary components and covers to access air filter.					
Remove filter, supply & fit replacement filter.					
WA5251	WESFIL AIR FILTER	\$63.000	1.00	\$63.000	\$63.00
LABOUR	LABOUR (P/H)	\$120.000	0.10	\$120.000	\$12.00
CABIN/POLLEN FILTER R&R					
Remove necessary components and covers to access cabin/pollen filter, remove filter, supply & fit replacement filter.					
WACF0172	WESFIL CABIN FILTER	\$66.000	1.00	\$66.000	\$66.00
LABOUR	LABOUR (P/H)	\$120.000	0.10	\$120.000	\$12.00
FUEL FILTER EXTERNAL R&R					
Remove necessary components and covers to access fuel filter, disconnect fuel lines clamps and mounts, remove filter, supply & fit replacement filter, bleed fuel system if required, check for leaks, road test vehicle for correct operation.					
R2724P	FUEL FILTER	\$75.000	1.00	\$75.000	\$75.00
LABOUR	LABOUR (P/H)	\$120.000	0.50	\$120.000	\$60.00



451 Leakes Road
TRUGANINA VIC 3029

Phone: 9978-0840
Email: truganina@ultratune.com.au

THANK YOU

from the team at Ultra Tune Truganina.
If you have any questions or feedback about your recent experience
at our centre, please feel free to contact us.

GENERAL DISCOUNT
This Invoice has been discounted,

*Service Notes

MULTIPLE CODES LISTED
CAM SENCOR CORELATION CODES POSSIBLE CHAIN STREACHED ISSUE
CRANK SENCOR CODES FIRST STEP REPLACE CRANK SENCOR REF DEALER
REF TO DEALER
17/06/2025
SMALL CRACK ON TURBO HOSE

 BSB: 083427 BSB Account: 842194710
BSB Account name: TRUGANINA AUTOMOTIVE PTY LTD
Reference: BUILD5-110369

Tax in this document: \$68.71
(Unit amounts marked "X" = tax free)

Total:	\$756.00
Initial Payment:	\$756.00
Outstanding:	\$0.00

BUILD5

COPY - COPY