

DATE	T/S	INIT	KMS/ HRS	FUEL	OIL	NOTES
MT11 - 2015 CAT 299D - S/No GTC01928						
2025						
OCTOBER						
2-Oct	928	MH				TOW INTO WORKSHOP
2-Oct	930	MG				WASH ENGINE, REMOVE TOP PANEL, LIFT UP CAB, REMOVE DIRT/MUD/WASH, GET READY TO REMOVE ENGINE
6-Oct	960	JD				START REMOVING MOTOR
7-Oct	977	JD				REMOVED MOTOR, CLEANED ENGINE BAY
8-Oct	991	JD				REMOVE PARTS OFF MOTOR
10-Oct	20	JD				WASHED MOTOR
14-Oct	Ashdown Ingram					STR 12V 9TH CW MITSUBISHI STYLE
31-Oct	272	JD				WASHED PARTS
NOVEMBER						
17-Nov	417	JD				WASHED PARTS
18-Nov	William Adams Pty Ltd					345-3464 FAN
18-Nov	William Adams Pty Ltd					345-3477 HOSE
2026						
JANUARY						
9-Jan	DieselWorks Australia Pty Ltd					CON-ROD
9-Jan	DieselWorks Australia Pty Ltd					INJECTOR TEST
9-Jan	DieselWorks Australia Pty Ltd					ENGINE KUBOTA V3800 CR-T REBUILD - REBUILT ENGINE WITH 6 MONTHS RBT WARRANTY
19-Jan	15	JD				REMOVED TURBO OFF EXHAUST
22-Jan	R.M. Turbochargers Pty Ltd					OVERHAUL MITSUBISHI TURBOCHARGER TD04 S/NO 141001021
FEBRUARY						
6-Feb	RM Diesel Injectors Pumps Centre					KUBOTA 3.8L INJECTORS REMANUFACTURED x4
12-Feb	295	BP				FIT NEW INJECTOR/ROCKER BOX/COVERS/TENSION INJECTOR HOLD-DOWN/LEAK BACK LINE
13-Feb	308	BP				CONTINUE ASSEMBLING PARTS ON TO ENGINE
13-Feb	William Adams Pty Ltd					388-7456 GASKET
13-Feb	William Adams Pty Ltd					387-9868 GASKET, 387-5398 GASKET, 389-5305 GASKET, 389-5308 REGULATOR AS, 345-3579 GASKET EXHAU
13-Feb	William Adams Pty Ltd					389-5353 GASKET
16-Feb	324	BP				FIT THERMOSTAT/GASKET, START FITTING TURBO/PIPING
16-Feb	William Adams Pty Ltd					389-5358 GASKET
17-Feb	339	BP				TAPE UP ELECTRICAL PLUG/GET READY FOR PAINT, TEST FIT TURBO/OIL FEED AND RETURN
17-Feb	William Adams Pty Ltd					389-5399 HOSE
20-Feb	389	HE				PAINT ENGINE
20-Feb	394	JD				CLEANED UP PARTS
23-Feb	407	AC				REFIT EXTERNAL ENGINE PARTS, FIT ENGINE TO MACHINE, RE-WIRE, RE-PLUMB, RECONFIGURE INCORRECTLY INSTALLED PARTS FROM ENGINE BUILDERS
23-Feb	408	JD				PUT MOTOR TOGETHER AND PUT INTO BOBCAT, START WIRING UP
23-Feb	William Adams Pty Ltd					110-6326 MAIN ELEMENT, 110-6331 ELEMENT, 363-5819 FILTER ELEMENT FUEL
24-Feb	247	AC			18	CONTINUE ASSEMBLY, FILL FLUIDS ETC, TROUBLESHOOT NO START (OIL; 12L RX SUPER, 6L TRANSMAX OFFROAD 10W, 11L CAT COOLANT)

DATE	T/S	INIT	KMS/ HRS	FUEL	OIL	NOTES
MT11 - 2015 CAT 299D - S/No GTC01928						
24-Feb	430	JD				ASSEMBLED AND WIRED UP MOTOR, GOT MOTOR RUNNING, STARTED DIAGNOSING STARTER ISSUE
24-Feb	431	MG				REMOVE OLD COMPANY STICKERS
24-Feb	William Adams Pty Ltd					377-6970 FILTER AS
24-Feb	William Adams Pty Ltd					393-7589 BOLT, 387-9868 GASKET
25-Feb	443	AC				DIAGNOSE AND REPAIR NO START ISSUES, PARTS RUN UP STREET, START/RUN, CHECK PRESSURES, TEMPS ETC, REPAIR COOLANT LEAKS, TEND TO TEETHING ISSUES
25-Feb	445	JD				START, RUN MOTOR, CHECK PRESSURES, LEAKS, CHANGED FAN COIL AND SEALS
25-Feb	Bertoli's Automotive and Agricultural					SUPERCHARGE BATTERY MF95D31L x1
25-Feb	William Adams Pty Ltd					389-5330 HOSE AIR
25-Feb	William Adams Pty Ltd					238-4628 COIL AS 12V
25-Feb	William Adams Pty Ltd					453-5488 KIT SEAL
26-Feb	461	AC				PARTS RUN FOR FITTINGS TO REPAIR COOLANT LEAK, CARRY OUT DIAGNOSTICS FOR DPF FAULTS
26-Feb	463	JD				FIXED COOLANT LEAK, DIAGNOSE DPF ISSUE, WENT AND GOT PARTS
26-Feb	Rapid Hose Systems Benalla					SUPPLY BRASS FITTINGS AND HOSE - #26 3/8 HEX SOCKET 01-2603, #27 3/8 HEX NIPPLE 01-2703, P6 5/8 BARB x 3/8 BSPT MALE ELBOW, HOSE 5/8" LOCK ON FIB/BRA BLACK x0.9, FUEL LINE SAE30R7 6MM P/M x1
26-Feb	Rapid Hose Systems Benalla					SUPPLY HOSE - FUEL LINE SAE30R7 8MM P/M x1.5
26-Feb	Rapid Hose Systems Benalla					P7R 5/8x1/2 BARB REDUCING JOINER, P3 5/8 BARB x 3/8 BSPT MALE STRAIGHT
27-Feb	477	AC				FIT BELLY PLATES, BOLT DOWN CAB, MOVE OUT OF SHED, MOP UP SPILL IN WORKSHOP
28-Feb	William Adams Pty Ltd					377-6963 SENSOR TEMPERATURE
MARCH						
2-Mar	493	AC				DIAGNOSE JOYSTICK SNESEOR ISSUES, ORDER PARTS, FIT NEW DPF TEMP SENSOR
2-Mar	William Adams Pty Ltd					456-0168 BASE AS
10-Mar	573	BP				FIT NEW LH JOYSTICK/TEST/FIT CABIN PANELS/COVERS
APRIL						
10-Apr	William Adams Pty Ltd					2x 258-3289 LATCH AS OUTER TY, 4x 6V-7357 BOLT, 2x 258-4085 BUSHING TYPE, 436-2988 ACTUATOR, 3x 8t-4205 WASHER, 8R-6974 BOLT, 146-6433 BLADE AS WIPER 500, 252-1862 HANDLE AS TYPE 1, 2x 5P-4115 WASHER, 74x 386-6028 CM SEAL BULK
10-Apr	William Adams Pty Ltd					345-6284 GASKET, 258-3697 WASHER NYLON, 258-3280 LATCH AS INNER, 345-6283 GASKET, 345-6233 BRACKET, 5x 215-6406 SCREW TRUSS, 3x 9X-2480 BOLT, 253-1817 SPACER, 256x 386-6028 CM SEAL BULK
12-Apr	William Adams Pty Ltd					330x 386-6028 CM SEAL BULK
13-Apr	204	BP				START ASSEMBLING CABIN DOOR, SEALS/WIPER/MOTOR/HANDLE
14-Apr	William Adams Pty Ltd					345-6295 COVER LATCH
14-Apr	231	BP			10	CONTINUE/FINISH ASSEMBLING DOOR/PARTS, FIT ONTO MACHINE, CLEAN GLASS OUT OF CABIN/FLOOR, CLEAR OLD FAULT CODES, CHECK DPF TEMP SENSOR ISSUE, TOP UP COOLANT AND HYDRAULIC OIL, CHECK HYDRAULIC LEAK ON FAN MOTOR, CHECK IDLE UP ISSUE, FIT DOOR ONTO CABIN, FIT FAN BELT COVER, CABLE TIE WIRING (OIL; 10L TRANSMAX OFFROAD 10W, 2L CAT COOLANT)
15-Apr	William Adams Pty Ltd					278-8716 KIT SEAL
16-Apr	265	BP				CHECKOVER, FIX COOLANT LEAK



Address: 34 Chetwynd Street,
Loganholme QLD 4129
Website: dieselworks.com.au
E-Mail: sales@dieselworks.com.au

Phone: +61 468 480 866
Mobile: 0468 480 866
ACN: 169 242 424
ABN: 12 169 242 424

Tax Invoice

Invoice No: 4278
Invoice Date: 6/01/2026

Account Type:
Due Date: 9/01/2026

Customer: **Extons**
85 Gillies St,
Benalla, VIC 3672
Cust. PO#:

Kubota V3800 CR-T Rebuild

Date	Component	Price	Units	Ext Price
------	-----------	-------	-------	-----------

29/10/2025	Engine Kubota V3800 CR-T Rebuild Rebuilt Engine with 6 months RTB Warranty	9,950.00	1.00	9,950.00
------------	---	----------	------	----------

In case of any issue, please notify DieselWorks Au Pty Ltd before commencing any work on the engine.
If shipping is required it is the responsibility of the customer.

Warranty is 6 months return to base from the Date of the Invoice unless otherwise specified
Warranty only covers the Long - Bare engine, no accessories included
Warranty covers pistons, rings, bearings, gaskets and parts explicitly listed on the invoice and paid for and the workmanship involved to assemble and test the engine.

Warranty covers parts onsite and parts and labour if returned to base.
Warranty covers parts and labour required to repair the engine itself only.
Warranty excludes onsite labour charges by third party repairer.
Warranty excludes all indirect losses and damages caused by the failure of the engine such as towing, loss of production, etc.

Warranty is void or partial only if:
- Neglect, misuse or lack of adequate maintenance is evident.
- Kept in operation after an issue was detected or should have been obvious (such as overheating or knocking)

29/10/2025	Miscellaneous _ Important Note - Reconditioned Engines	0.00	1.00	0.00
------------	--	------	------	------

The customer is required to:
Check the cooling system. We do not install thermostats as we cannot guarantee the functionality of the cooling system.
If you use an oil cooler that the oil filter mounts to, check your oil cooler and hoses.
If marinised, check your heat exchanger, exhaust elbow, raw water pump and gearbox as well.
Check your fuel lift pump as we bypass the mechanical fuel lift pump.
Check sump bolts.
Replace the oil filter.
Check/replace anodes
Check/replace the fuel filter.
Check/replace the air filter.
Check/replace sensors.
Check/replace hoses.
Check mounting brackets if applicable.
We normally do not install machinery parts. Any parts related to the machine that haven't been installed will be attached to the engine or placed inside a box.
Run the engine with just water for the first 5hrs, then add coolant.
Fuel systems are excluded from warranty due to external and environmental factors beyond our control.
Use the correct oil grade as specified in your applications owner manual.
If you are not sure, normally 15W-40 diesel grade is suitable.



Address: 34 Chetwynd Street,
Loganholme QLD 4129
Website: dieselworks.com.au
E-Mail: sales@dieselworks.com.au

Phone: +61 468 480 866
Mobile: 0468 480 866
ACN: 169 242 424
ABN: 12 169 242 424

Tax Invoice

Invoice No: **4278**
Invoice Date: **6/01/2026**

Account Type:
Due Date: **9/01/2026**

Customer: **Extons**
85 Gillies St,
Benalla, VIC 3672
Cust. PO#:

Kubota V3800 CR-T Rebuild

Date	Component	Price	Units	Ext Price
	Remove all tape and red plugs before running the engine! -Especially at the oil filter and intake if applicable!			
	The engine is return to base only. We do not cover third party labour. If there are any issues with the engine, you need to notify us first as soon as possible. Neglect or misuse voids warranty.			
29/10/2025	_ Miscellaneous _ Important Note - VALVE ADJUSTMENT REQUIR Adjust valve clearance again after approx 3-4hrs of run time. Valve clearance (Cold): 0.15mm	0.00	1.00	0.00
29/10/2025	_ Miscellaneous _ Important Note - Common-Rail - CR Engines Engine assembled but not tested running Do not run DPF cleaning for the first 50 hours after rebuild. Please make sure that the fuel system is properly configured before commissioning engine. If any injectors were replaced, please make sure the injectors are coded to the computer/ECU Over fuelling can cause excessive piston expansion and damage to bearings and as such it is not covered by warranty.	0.00	1.00	0.00
29/10/2025	_ Miscellaneous _ Important Note - Unable to Test Run/Load Test We are unable to test run the engine due to the gear required to run the engine bieng unfeasable to set up. We still warrant the work on the engine, but any issues that can be detected through a test run of the engine such as leaks for example are still warranted but it is not something that we can guarantee against.	0.00	1.00	0.00
29/10/2025	_ Shipping IN/OUT CUSTOMER ORGANISED -	0.00	1.00	0.00
17/11/2025	_ Miscellaneous Core Charge - Crankshaft Damaged Beyond Grind	2,000.00	1.00	2,000.00
17/11/2025	_ Miscellaneous Core Charge - Con-Rod	150.00	1.00	150.00
18/11/2025	_ Miscellaneous Turbo Charger Requires Replacing Turbo Charger Requires Replacing	0.00	1.00	0.00
18/11/2025	_ Miscellaneous Core Charge - Block Repair	450.00	1.00	450.00
18/11/2025	_ Miscellaneous Injector Test Injector #1 - failed - no back leak flow (0 measured) Injector #2 - failed -over delivers slightly under maximum power - no back leak flow (0 measured) Injector #3 - failed -over delivers slightly under maximum power - no back leak flow (0 measured) Injector #4 - failed -over delivers slightly under maximum power - no back leak flow (0 measured)	110.00	4.00	440.00

It is recommended to replace the injectors before comissioning the engine.

Printed On: 6/01/2026

Find us on Facebook!

Page: 2 of Invoice # 4278

Kubota, Yanmar, Shibaura Engines - Please call for other models



Address: 34 Chetwynd Street,
Loganholme QLD 4129
Website: dieselworks.com.au
E-Mail: sales@dieselworks.com.au

Phone: +61 468 480 866
Mobile: 0468 480 866
ACN: 169 242 424
ABN: 12 169 242 424

Tax Invoice

Invoice No: **4278**
Invoice Date: **6/01/2026**

Account Type:
Due Date: **9/01/2026**

Customer: **Extons**
85 Gillies St,
Benalla, VIC 3672
Cust. PO#:

Kubota V3800 CR-T Rebuild

Date	Component	Price	Units	Ext Price
Direct Deposit Details: A/c Name: DieselWorks Australia Pty Ltd Branch: Loganholme BSB: 034-264 (Westpac) Address: A/c No: 370 457				Sub Total: 12,990.00
				GST Paid: 1,299.00
				Invoice Total: 14,289.00
Postal: 34 Chetwynd Street, Loganholme QLD 4129				Received: 0.00
Delivery: 34 Chetwynd Street, Loganholme QLD 4129				Outstanding: 14,289.00

Please Note: Title of goods listed on this invoice do not transfer until the invoice is paid in full and funds have cleared.
Storage Fee after 14 days: Uncollected goods will be charged a \$70 per week storage fee

R.M. TURBOCHARGERS PTY LTD

A.B.N. 42 105 278 073



2 CUMMINS DRIVE
SOMERTON VIC 3062
PH: (03) 9308-0600 FAX: (03) 9308-0700
E-MAIL admin@rmturbochargers.com.au



R.M. TURBOCHARGERS

Garrett
ADVANCING MOTION

Invoice No 00076058

Order No

TAX INVOICE

Date 22/01/2026

BILL TO:

CASH SALE

SHIP TO:

EXTONS PTY LTD
0418 573 175
ian@extons.com.au

Description	Amount Including
OVERHAUL MITSUBISHI TURBOCHARGER TD04 S/N 141001021	\$720.00
*** PLEASE NOTE **** WARRANTY WILL BE VOID IF OIL PIPES NOT REPLACED	

EFT Details NAB BSB 083-784 ACC 81-262-4433
Reference Please use Invoice Number

Freight: \$0.00
GST TOTAL: \$65.45
Total \$720.00
PAID TODAY \$0.00

TOTAL PAYABLE: \$720.00

All goods returned for credit subject to 15% restocking fee

Title of Goods covered by this invoice does not pass ownership till payment made in full and all

"In the event where your overdue account is referred to a collection agency and/or law firm, you will be liable for all costs which would be incurred as if the debt is collected in full, including legal demand costs".

RM Diesel Injectors Pumps Centre

ABN: 36 649 971 716



Tax invoice

Invoice number
00000421

Issue date
06/02/2026

Due date
20/02/2026

Bill to
CUSTOMER

MT11

Description	Tax	Amount (\$) <i>excluding tax</i>
TEM DESCRIPTION KUBOTA 3.8L INJECTORS . REMEFACTRED . ITEM CODE : 1J500 QUANTITY : 4 ITEM PRIEC : 318.18 \$ TOTAL PRIEC : 1272.73 \$	GST	1,272.73



Subtotal (<i>exc. tax</i>)	\$1,272.73
Tax	\$127.27
Total Amount (<i>inc. tax</i>)	\$1,400.00
Total paid	\$0.00
Balance due	\$1,400.00

View your invoice online

[Click here to view](#)

How to pay

Invoice number: **00000421** Due date: **20/02/2026** Balance due: **\$1,400.00**

Bank deposit

Bank: COMMONWEALTH BANK

Name: LUAY ABRO

BSB: 063788

AC#: 10323017

Ref#: 00000421