



Roller Service Report

0301

Company Name: <u>Bild Group</u>	Engine Hours: <u>1506</u>	Unit No: <u>N105</u>
------------------------------------	------------------------------	-------------------------

Service Type :	250 Hours	<u>600 Hours</u>	1000 Hours	2000 Hours	4000 Hours	
TICK OR CIRCLE WHERE APPLICABLE	YES	N/A	Fault Identify			
Cleaning the radiator Module	☒					
Checking, Tensioning the V-belt for the generator system	☒					
Checking oil level in the drive axle	☒					
Checking oil level in the wheel hubs	☒					
Checking the oil level in the exciter housing	☒					
Changing the fresh air filter in the cabin	☒					
Check the parking brake	☒					
Change engine oil	☒					
Change oil filter cartridge	☒					
Replacing fuel filter, bleeding fuel system	☒					
Checking the anti-freeze concentration and the condition of the coolant	☒					
Checking hydraulic lines	☒					☒
Servicing the battery, checking the main battery isolation	☒					
Servicing the air conditioning system	☒					
Checking the ribbed V-belt	☒					
Replacing the air conditioning compressor V-belts	☒					
Checking engine mounts	☒					
Replacing the hydraulic oil filter	☒					
Change the oil in the drive axle	☒					
Change the oil in the wheel hubs	☒					
Change the oil in the exciter housing	☒					
Retightening the fastening of the axle on the frame	☒					
Retightening the wheel nuts	☒					
Checking the ROPS	☒					
Checking the travel lever control	☒					
Cleaning the circulation air filter of the heating	☒					
Servicing the auxiliary heating	☒					
Checking, adjusting the valve clearance	☒					
Changing the hydraulic oil	☒					
Changing coolant	☒					
Replace ribbed V-belt and idler pulley	☒					
Fill the windscreen washer tank	☒					
Checking and cleaning the water separator	☒					

Notes:
Hydraulic Filter leaked - O-Ring was issue - new
O-ring fitted.

Date: 9/5/25

Name: will

Signed: [Signature]