


Lot 16

Perih Heavy Duty Inc
 RR1
 Gilbert Plains, MB R0L 0X0, CA
 perihhd@gmail.com
 204-648-3122



Invoice: 608
Date: 5/30/2022



Remit Payment To
 Perih Heavy Duty Inc
 RR1
 Gilbert Plains, MB R0L 0X0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
1627	Net 30	6/29/2022	Lowell Penner		Perih, Steven	

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Test for Weak Functions

Cause: Customer request

Labor	Correction: Hydraulics / Valve / Test relief pressures for arch and boom. Pressures are on the top end of spec. There were also issues with the RH motor speed sensor. Swapped sensor to the LH side and adjusted. Got machine working. Customer had replaced sensor but I don't think it was adjusted properly. Routed harness and tested all ok. - 5/30/2022	4.50000	\$125.00	\$562.50
-------	--	---------	----------	----------

Subtotal \$562.50

Drive to unit

Labor	Drive to unit (Service Call)	0.75000	\$135.00	\$101.25
-------	------------------------------	---------	----------	----------

Subtotal \$101.25

Unit: VIN: 6150119
 Tigercat 615C
Engine: 6,052 Hours

Labor	\$663.75
Shop Supplies	\$10.00
Pre Tax Total	\$673.75
GST (5.0000% of \$673.75)	\$33.69
PST (7.0000% of \$673.75)	\$47.16
Total	\$754.60
Payments & Credits	\$0.00
Balance Due	\$754.60

GST# 753299528

Perih Heavy Duty Inc

RR1

Gilbert Plains, MB R0L 0X0, CA

perihhd@gmail.com

204-648-3122



Invoice: 543

Date: 2/22/2022

Remit Payment To
Perih Heavy Duty Inc
RR1
Gilbert Plains, MB R0L 0X0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
1576	Net 30	3/24/2022	Lowell Penner		Perih, Steven	

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Repair Leak On Pinion For Front Differential**Cause:** Customer request

Labor	Correction: Front Axle & Steering / Front Axle / Removed stump pan and inspected leak. Leak coming from between spacer and driveshaft yoke. Looked up parts and made list for customer. Customer ordered parts. Came back and removed pinion seal, retainer, o-ring and grease seal. Replaced all components that could leak. Installed drive shaft and cleaned up area. Oil seemed quite dirty, notified customer and they will change. - 2/21/2022	4.00000	\$100.00	\$400.00
-------	--	---------	----------	----------

Subtotal \$400.00**Unit:** VIN: 6150119

Tigercat 615C

Engine: 6,019 Hours**Labor** \$400.00**Shop Supplies** \$15.00**Pre Tax Total** \$415.00**GST (5.0000% of \$415.00)** \$20.75**PST (7.0000% of \$415.00)** \$29.05**Total** \$464.80**Payments & Credits** \$0.00**Balance Due** \$464.80

GST# 753299528