

Work Order History Report

17-Jun-2025

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		Heavy Haulage 51 from Jul19 Drake quad low loader 4*4					
	32733	Prepare for work. Fit ramp cylinder 48358 kms - cylinder supplied under Warranty by Drake	1/03/2013 12:	km	.00	2.50	\$210.50
	33693	Repair Damaged Skid PlateReplace 8 pin deutch plug. Adjust brakes, check lights. 67769 kms	29/03/2013 1	km	.00	3.00	\$448.75
	33959	February tyres	29/03/2013 1	km	.00	.00	\$2711.00
	34638	late costs for 33693	30/04/2013 1	km	.00	.00	\$71.20
	34710	May Tyres	31/05/2013 1	km	.00	.00	\$919.00
	35033	June tyres	30/06/2013 1	km	.00	.00	\$906.00
	34882	mechanical inspection for machinery inspection. replace flashing light. 112597 kms	30/07/2013 1	km	.00	7.00	\$695.64
	35337	Adjust brakes. 114260 kms	31/08/2013 1	km	.00	1.00	\$110.00
	35558	August tyres	9/09/2013 4:1	km	.00	.00	\$3095.00
	36027	October tyres	30/10/2013 1	km	.00	.00	\$3587.00
	36035	Replace mudflaps	30/10/2013 1	km	.00	2.00	\$123.10
	36287	adjust brakes	31/12/2013 1	km	.00	2.00	\$124.00
	36355	November tyres, supply and fit 2 x new tyres pos 13,14, fit 2 x runouts	31/12/2013 1	km	.00	.00	\$1084.00
	36679	January tyres	31/01/2014 1	km	.00	.00	\$1390.00
	36685	Repair broken brake airline fitting and adjust brakes.	31/01/2014 1	km	.00	5.00	\$305.00
	36928	Replace handle on front suspension control valve on L/H front axle pos 1. check wheel bearing, adjust brakes. 190517 kms	1/03/2014 2:2	km	.00	1.50	\$261.00
	37023	March tyres	31/03/2014 1	km	.00	.00	\$4197.00
	37071	Trailer Inspection. 208323 kms	1/04/2014 1:5	km	.00	3.00	\$395.00
	37464	Check over after being bogged, adjust brakes. 227742 kms	31/05/2014 1	km	.00	1.00	\$105.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
	37490	May tyres - tyre fitting pos #3 and #4	31/05/2014 1	km	.00	.00	\$62.00
	37270	Repair axle and lift lock. tie down points. replace 4 grease nipples, replace clearance light, and fit missing tap rod hydraulic, replace battery tiedown strap.	2/06/2014 12:	km	.00	15.00	\$1117.70
	37716	Mechanical Inspection for COI. 239675 kms	30/06/2014 1	km	.00	4.00	\$304.80
	37814	June tyres. pos#11	30/06/2014 1	km	.00	.00	\$31.00
	38111	July tyres - fit tyres pos #3/4/13/14/15/16.	31/07/2014 1	km	.00	.00	\$188.00
	38035	Ajust brakes. repair damaged door & lock, side of float. honda engine seized. 2544960 kms	31/08/2014 1	km	.00	12.50	\$768.00
	38225	August tyres. puncture repair	31/08/2014 1	km	.00	.00	\$50.00
	38368	September repairs, inspect trailer, grease.	30/09/2014 1	km	.00	4.50	\$257.00
	38424	September Tyres. replace blown tyre.	30/09/2014 1	km	.00	.00	\$2530.00
	38561	October repairs, change clearance light, inspect brake and grease lines.	18/10/2014 1	km	.00	2.00	\$187.00
	38600	October tyres. fit 2 new ryres. rotate others	31/10/2014 1	km	.00	.00	\$1107.00
	38753	November tyres, change Pos. 16 tyre. Fit yard stock tyres to Pos. 13/14, rotate pos 13/14 to pos 9/10. - 288312 kms, fit yard stock tyres to Pos 1/2, rotate Pos 1/2 to Pos 5/6, rotate Pos. 5 to Pos. 11 - 296275 kms	30/11/2014 1	km	.00	.00	\$215.00
	39112	January tyres, fit own tyres to Pos. 3,4,13,14,15,16, rotate Pos. 3/4 to Pos. 11/12. - 313434 kms	31/01/2015 1	km	.00	.00	\$201.00
	39017	January repairs, ,service motor, exhaust noisy.	28/02/2015 1	km	.00	4.00	\$322.79
	39287	Adjust brakes. - 328177kms	31/03/2015 1	km	.00	4.00	\$224.00
	39546	Assess brake linings. - 337329 kms	27/04/2015 1	km	.00	9.00	\$1608.00
	39372	March tyres, fit stock tyres to Pos. 1/2/3/4, rotate Pos. 1/2 to 5/6, 3/4 to 11/12. - 328177 kms, Fit 4 x new tyres Pos. 1/2/3/4, rotate Pos 1/2/3/4 to Pos. 7/8/9/10. - 331492 kms	30/04/2015 1	km	.00	.00	\$2194.00
	39485	Repair cracks in tie down points	30/04/2015 1	km	.00	3.50	\$410.59
	39754	Inspection for COI - Due on 19/06/2015, replace booster.	30/06/2015 1	km	.00	12.50	\$763.00
	40006	June tyres - (fit 2 x new own tyres to Pos. 1/2, rotate Pos. 1/2 to Pos. 5/6 - inv 222954),	31/07/2015 1	km	.00	.00	\$77.00
	40102	Repair honda engine for hydraulics. Repair flashing light.	31/07/2015 1	km	.00	4.00	\$537.60

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
	40054	Repair damaged mounting plate for hydraulic motor- pump assemble, mud guard bracket, weld, prepare, paint	3/08/2015 12:	km	.00	6.50	\$471.28
	40221	July tyres, fit own tyre to Pos. 4, rotate Pos. 4 to Pos. 3 -	31/08/2015 1	km	.00	.00	\$39.00
	40257	August tyres, fit 4 x own tyres to Pos. 13/14/15/16, rotate Pos.16 to Pos. 9.	31/08/2015 1	km	.00	.00	\$131.00
	40297	Measure suspension arm movement.	30/09/2015 1	km	.00	4.50	\$334.00
	40418	Repair electric start on Honda engine, replace battery	30/09/2015 1	km	.00	6.50	\$615.00
	40481	September Tyres, Rotate tyres Pos.3-4 to 1-2 & 9-10 with 1-2, disposal costs	30/09/2015 1	km	.00	2.00	\$124.00
	40521	Repair hydraulic line on lift cylinder for r/h ramp, repair 6 x tie down lugs.	31/10/2015 1	km	.00	13.50	\$1193.55
	40541	October tyres, fit 2 x own tyres to Pos. 15/16, rotate Pos 15/16 to Pos. 11/12, Pos 12 to Pos 5, rotate pos 3/4 to Pos. 78, fit own runouts to Pos. 3/4 -	31/10/2015 1	km	.00	.00	\$161.00
	40873	Mechanical inspection & brake adjustment.	7/12/2015 12:	km	.00	4.00	\$398.00
	41079	Repair damaged auxillary engine bracket. Replace fuel tank on engine with s/h unit.	21/01/2016 1	km	.00	10.00	\$566.75
	41103	January tyres, fit 4 x own tyres to Pos. 13/14/15/16, rotate Pos. 15 & 16 to Pos. 5 & 6. -	31/01/2016 1	km	.00	.00	\$139.00
	41310	February tyres, fit 2 x own tyres to Pos. 11/12.	31/03/2016 1	km	.00	.00	\$49.00
	41386	March repairs, adjust brakes.	31/03/2016 1	km	.00	3.00	\$182.00
	41415	April repairs, replace 4 x 10mm load binders, replace mudflap.	30/04/2016 1	km	.00	.50	\$490.55
	41526	April tyres, fit own tyres to Pos. #1/2.	30/04/2016 1	km	.00	.00	\$1069.50
	41624	May repairs, checkover and grease trailer, fit new hubometer. weld cracked tie down points	31/05/2016 1	km	.00	17.50	\$979.90
	41691	May tyres, puncture repair Pos. 9, fit own runouts to Pos. 13/14. - 345635 kms	31/05/2016 1	km	.00	.00	\$194.00
	41693	Mechanical Inspection for COI on 03/06/2016 @ 12:30 pm. - 345635 kms	13/06/2016 1	km	.00	11.25	\$734.50
	41856	June tyres, fit 4 x new tyres to Pos. 7/8/11/12, rotate Pos.12 to 15, Pos. 7/7 to 3/4. - 357958 kms	30/06/2016 1	km	.00	.00	\$2210.00
	41947	Check wheel bearings. Remove all wheel assy's. Remove, clean & inspect bearings. Repack & fit bearings with new seals. Adjust bearing preload, adjust brakes. - 367312 kms	15/07/2016 1	km	.00	23.50	\$1686.20

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
	41986	July repairs : [Checked report of Pos. 6 brake locking up, checked all brakes, checked OK. - 367312], [investigate faulty brake booster - 367992 kms], [checkover trailer, check brake boosters, grease trailer, repair air leak. - 369059 kms]	31/07/2016 1	km	.00	11.00	\$609.55
	42021	July tyres, [fit 2 x own runouts to Pos. 5/6 - 367294 kms]	31/07/2016 1	km	.00	.00	\$112.00
	42117	August repairs...Check suspension arm movement, adjust brakes. - 373510 kms	31/08/2016 1	km	.00	11.00	\$562.00
	42196	September repairs, inspect honda motor for cutting out, replace flashing light. -	30/09/2016 1	km	.00	5.00	\$580.00
	42243	September tyres, [fit 2 x new tyres to Pos. 13/14, fit own stock x 2 - Pos ??, rotate Pos. 13/14 to Pos. 9/10. - 378079 kms], [fit 2 x own tyres to Pos. 15/16.]	30/09/2016 1	km	.00	.00	\$1286.00
	42426	October tyres, [fit own runouts to Pos. 9/10]	31/10/2016 1	km	.00	.00	\$118.00
	42551	25000 km service, replace hubometer, grease, adjust brakes. - 376058 kms , repair cracks around tie down points in deck, repair cracks in axel lift brackets - 376058 kms	2/12/2016 12:	376058.00 km	.00	13.50	\$890.00
	42775	January repairs, [fit new rotating beacon].	20/01/2017 1	km	.00	1.00	\$339.50
	42728	January Tyres, [fit 2 x new tyres]	31/01/2017 1	km	.00	.00	\$830.00
	42947	Late invoice for January tyres, [supply / fit 2 x new tyres]	1/03/2017 12:	km	.00	.00	\$740.00
	43008	Repair cracks in deck tie down point & fit reinforcing plates to support tie down points	1/04/2017 12:	km	.00	4.50	\$731.51
	43104	April repairs Adjust wheel bearings & brakes. Replace l/h air tank, Replace booster, pos 2 axle lock actuator, breather cap on hydraulic tank,	18/04/2017 1	km	.00	27.00	\$1852.02
	43218	May Tyres, replace 3 x 9.5 x17.5 tyres, fitted Hakook tyres	31/05/2017 1	km	.00	3.00	\$1151.15
	43363	June repairs. Check trailer. Adjust brakes. Check wheel bearings. 508748 Ks	3/07/2017 12:	km	.00	15.50	\$959.50
	43532	June Tyre costs, replace tyres on three spare wheels	4/07/2017 12:	km	.00	2.00	\$1054.50
	43511	Segment 1. Replace suspension arm pins, inner & outer pivot bearings, machine bearing bores in frames,Fitted Hub O meter1	1/08/2017 12:	km	.00	118.50	\$9887.90
	43596	Replace damaged rim. Suncoast trucks. Change over tyre, Beerwah tyres. Supply hankook tyres for spares.	17/08/2017 1	km	.00	4.00	\$3159.91
	43760	Replace auxillary motor battery. Battery place.	1/10/2017 12:	km	.00	.00	\$321.26

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
	44023	November tyres. Replace tyres Beerwah tyres.	29/11/2017 1	km	.00	.00	\$781.10
	44133	Reseal pos 1,3,5,7 suspension cylinders. flush out hyd's on trailer - 533353 Kms,	20/12/2017 1	km	.00	3.00	\$1893.38
	43668	Segment 2. Replace suspension arm pins, inner & outer pivot bearings, machine bearing bores in frames - 533353 klms	3/01/2018 12:	km	.00	89.50	\$10565.65
	44215	January tyres. Replace 10 x 9.5/ 17.5 tyres. Beerwah tyres. 533353 Ks.	10/01/2018 1	km	.00	4.00	\$3685.00
	44245	Replace all brake linings / hardware. Repack wheel bearings and replace seals. repair wiring to clearance lights and tail lights. 533353 Ks, Drain and flush hydraulic system, refill, recheck wheel bearings after first run nth,	31/01/2018 1	533350.00 km	.00	63.50	\$4526.10
	44409	February tyres. 6 x Hancock 9.5 x 17.5	28/02/2018 1	km	.00	.00	\$2299.00
	44445	Replace flashing light and mount bracket.539322 Kms	28/02/2018 1	km	.00	5.50	\$628.60
	44504	Repair trailer plug & park lights, repair wiring to flashing light, Weld cracks in tie down points. 539232 Kms, adjust all brakes - 540,146 klms.	22/03/2018 1	km	.00	5.50	\$709.90
	44658	April Pre starts, 547501 Kms, Grease, Adjust brakes, check over, replace 1 x 9.5R17.5 tyre	30/04/2018 1	km	.00	3.00	\$615.65
	44766	Check over for COI 551052 Kms	22/05/2018 1	km	.00	2.00	\$120.80
	44887	June Tyres Repair Nth Qld & Sunshine Coast	30/06/2018 1	km	.00	1.00	\$3178.20
	45532	Tyre rotation - klms, adjust brakes. 377115 Ks. replace broken L/H front marker light - 588662 klms	27/09/2018 1	km	.00	3.25	\$202.50
	45524	Replace 4 x tyres @ Roys discount tyres. repair one flat tyre by M Group	28/09/2018 1	km	.00	.00	\$1450.00
	45633	Supply New Rims & Tyres Re D Gibson	19/10/2018 1	km	.00	.00	\$1605.00
	45618	Service & Repair honda motor, replace battery,change engine oil, remove fuel tank, drain out water, stip down & clean out tank & carby, replace air filter, spark plug, clean out grease tracks, fit new nipples, grease trailer,	23/10/2018 1	km	.00	14.50	\$1145.35
	45750	Replace pos 3 & 4 tyres.	30/11/2018 1	km	.00	2.00	\$850.00
	45997	January Minor repairs, replace R/H front clearance light, repair wiring to L/H rear taillight + fit second hand honda key panel + removed broken bolts on honda motor + fitted new clearance light to LHS - 610,890 klms, weld cracks on tie down points in	18/01/2019 1	km	.00	4.00	\$508.17

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		deck					
	46018	Tyre Replacement 615104 Kms, replace pos 1 , 3 & 4 Tyres.Replace grease lines behind pos 5 tyre & hyd lines l/h ramp, tyre repair x 1	21/01/2019 1	km	.00	15.50	\$3036.00
	46043	Late Parts invoice relating to work order 44133 & 43668	24/01/2019 1:	km	.00	.00	\$587.78
	46319	removed broken grease line fitting on pos 3 swing arm + fitted new grease fitting + greased @ 631154 km	28/03/2019 1	km	.00	1.00	\$94.85
	46328	Replace new tyres & rotate others as required - 631145 klms. fit new tyre to position 3 & 4 , others to spare rack	1/04/2019 12:	km	.00	1.00	\$4285.05
	46442	Replace damaged stub axel on position 7, hub , bearings, seals, brake drum, - 634859 klms , removed dual wheel and hub assembly ,outer bearing is damaged, welded inner and spindle and attempted to remove , POS 1& 5 also loose , adjusted both and filled all hub caps with grease remove bearings off stub axle , lift rear axle, Check Position 7 wheel bearing	14/05/2019 1	km	.00	.00	\$3065.65
	46430	SMU 634 610 Find fault with wiring problem with side lights and rear tail light (Bolt spares) , replaced number plate light and LH clearance light on ramp , checked road travel springs and shoes	14/05/2019 1	634610.00 km	.00	5.50	\$924.50
	46486	Pre machinery Inspection , replace rear safety marker plates, SMU 635594 swapped pos 15 to Pos 11 and Pos 16 to Pos 12 , got new tyres for Pos 15 and 16 .	15/05/2019 1	km	.00	1.00	\$592.36
	46350	4 x 9.5 x 17.5 tyres	1/06/2019 12:	km	.00	.00	\$1400.00
	46644	Inspection and check over 656587 KM , replace hydraulic tank air breather, measure cylinders, removed leaking rear suspension pressure gauges, fit breather from 3248 , bolt on run out tyre	2/07/2019 12:	km	.00	12.00	\$974.79
	46815	Bolt on 4 new tyres 656936km	1/08/2019 12:	km	.00	2.00	\$1917.34
	46847	Inspection of bearings on wheels / change of wheel SMU 660093 , removed grease caps on LH side RTved one grease cap and replaced gaskets on another 2 grease caps, checked bearing play and washed down tyres. Removed wheels and started inspecting wheel bearings. Found POS 1 hub had spun a bearing cone , packed wheel bearings and assemble all POS 2 4 5 6 7 8 , torque set pre loads and grease caps. Greased	21/08/2019 1	km	.00	41.00	\$2167.05

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		entire float , repaired POS 2 & 4 grease fittings for height rams and inspected for cracks					
46870		Replace Position 1 bearing hub & bearings & all 8 hub seals, Repack all wheel bearings and replace reflective stickers on front of trailer SMU 662204 , Fit 2 rear hyd trailer gauges, drill out mounting brackets fit hyd lines.Rewire and replace rear LH power box for lights, replace all connectors, fix clearance light on LH side , replace bolts for hydraulic valve body, adjust all brakes replace both rear pressure gauges. Replace front hazard stickers	22/08/2019 1	km	.00	31.50	\$2386.34
46876		50000 km service SMU 662204	22/08/2019 1	662204.00 km	.00	4.50	\$234.00
46922		Check all wheel bearings adjustment - 667201kms, Repack POS 5 outer bearing hub re tension all bearings replace gaskets and locking tabs as necessary	9/09/2019 12:	km	.00	.00	\$462.25
46921		Fit new tyres 667 201kms (Michelins) on POS 13 (going to stock) and 14 (scrap) 667 201 kms , tighten all hub caps , POS 1 leaking , put bolt in trailer engine cradle , check tensions of other 3	27/09/2019 1	km	.00	2.50	\$390.77
47076		Repair axle lifting brackets on L/H front & rear axle Positions 1 & 7 , cut off bent brackets, weld new ones in place, fit new locking booster to Position 7 axle, fitted new tyres on pos 15 & 16, fit new tyres to pos 1 & 2, moved old tyre from pos 15 to pos 8 , replace pos 2 axle locking valve limit collar @ 687,021 km + Fitted new tyres to pos 3 & 4, moved tyres from pos 3 & 4 to pos 9 & 10 @ 692095 kms	15/11/2019 1	km	.00	15.00	\$2724.24
47269		Swaped pos 5 & 6 into each others positions to trouble shoot tyre wear issue @ 695082 km	3/12/2019 12:	km	.00	1.00	\$1515.25
47404		Repair to Auxiliary motor, replace flags x 2	16/01/2020 1	km	.00	.00	\$45.82
47424		Rotate tyres @ 705,850 kms, fitted new tyres to pos 1,2,3,4,15 and 16, rotated tyres from 1 & 2 to pos 5 & 6, rotated pos 3 & 4 to pos 7 & 8, rotated pos 13 & 14 to pos 9 & 10, rotated pos 15 & 16 to pos 11 & 12, rotated pos 9 & 5 to 13 & 14. strip and fit 3 tyres and rims by roys tyres	20/01/2020 1	km	.00	4.00	\$1442.75
47493		Replace pos # 3/4 axle up lock booster @ 711535kms (booster ordered on w/o 47076)	13/02/2020 1	km	.00	19.50	\$1092.35
47516		Fit new tyres to Positions 21/22/23/24/33 & 34 , rotate Pos,23/24 to 33/34, flip those on rims & move to Position 29 &	29/02/2020 1	km	.00	10.00	\$294.52

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		30, flip tyres on Position 21 & 25, move 21/24 to spare rack					
	47585	Service Honda Motor & replace Stemco Hubometer -719,525 kms	6/03/2020 12:	km	.00	3.00	\$301.65
	47598	Supply 4 x new tyres	1/04/2020 12:	km	.00	1.00	\$1907.00
	47631	Repair ignition switch mounting bracket, tap out top mounting hole in block to 8mm, tighten ignition switch barrel nut - 722,732 kms	1/04/2020 12:	km	.00	6.00	\$240.00
	47634	50000 km service check all wheel bearings adjustment & condition, repair & replace broken grease lines to suspension cylinder mounting pins, replace brake booster on Position 4, trailer plug, repair pos 2 - 4 grease lines, adjust brakes,	8/05/2020 12:	.00 km	.00	16.50	\$1314.10
	47886	Replace Position 23 & 24 tyres - 738,016 kms, rotate 6 tyres & pressure check	26/05/2020 1	km	.00	1.00	\$147.82
	47966	Rotate TBR Tyre X 2 & Fit TBR Tyre X 4 746262 kms. 11/06/2020. Flipped tyres on rims Pos 15/16 - Rotate rims-pos 13/14 to 17/18 - Bolted spares to pos 13/14. Fit new tyres to Position.21/22 & full pressure check - 763,426 kms, Fit spare wheel to Position 30 - 763.699 kms	1/07/2020 12:	km	.00	10.00	\$368.87
	48013	Replace battery for Honda motor - 754,047 kms, rear safety signs on ramps, 4 flags, weld crack at tie down points, repair flat tyre -764570 kms	28/07/2020 1	km	.00	3.50	\$502.02
	48218	Replace blown hydraulic pressure hose from power pack to ramps	24/08/2020 1	km	.00	.00	\$167.15
	48223	Repairs to honda motor 774848 Kms, Skinners wiring burnt out , Pull start assly replaced, replace battery,	27/08/2020 1	km	.00	3.00	\$643.13
	48147	Fit Run out tyres to Position 29/30 - 769,279 klms	31/08/2020 1	km	.00	.00	\$38.02
	48305	Rekit L/H rear deck widening & R/H ramp lift cylinders - 781647 kms, remove & refit cylinders, change hydraulic oil, replace hydraulic oil filter, clean parts	22/09/2020 1	km	.00	12.50	\$2333.94
	48247	September Repairs Tyres - fit run out tyre to Position 31 - 774,848 kms	30/09/2020 1	km	.00	.00	\$19.00
	48288	Replace Honda power pack engine, repair cracks around tie down points	8/10/2020 12:	km	.00	7.00	\$2055.51
	48408	Replace 2 x blown tyres, pressure check all tyres - 186,158 kms	30/10/2020 1	km	.00	2.00	\$144.52
	48449	25000 km service - 791,194 Kms, repair number plate & clearance lights, check wheel bearings, inspect suspension	2/11/2020 12:	791194.00 km	.00	6.50	\$473.70

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		clearance lights, check wheel bearings, inspect suspension bearings for movement					
	48537	Turn tyre on Positions 25 - 32 & fit one run out tyre, supply 3 new tyres Bolt on run out to Pos.11-12	30/11/2020 1	km	.00	.00	\$89.09
	48699	Check over for 2021--808166 Kms, Crack repairs to axle lifts, check air lines, oil lines, lights, grease all, check Honda motor	15/01/2021 1	km	.00	6.00	\$403.15
	48718	Supply 8 New tyres & two new rims, tyre fitting costs	4/02/2021 12:	km	.00	10.00	\$4217.30
	48788	Check trailer for damage after rim on Pos 3. cracked -819572 kms ,Remove & Checked all and found to be OK Fit & tension wheels,	17/02/2021 1	km	.00	3.00	\$444.19
	48911	Supply 3 new rims & 4 tyres & tyre fittings - 835,098 kms	22/04/2021 1	km	.00	.00	\$2935.99
	48951	100000 km service 835098 Kms .Replace all brake drums, shoes, seals, Repack wheel bearings, Remove all wheels Hubs & bearings for cleaning & replace, remove all brake drums & shoes, remove studs from brake drums, Reassemble all, torque all nuts, check lights, total grease unit, repair broken grease line fittings , service honda motor,	23/04/2021 1	808166.00 km	.00	30.50	\$3994.34
	49092	Repair side clearance light, Replace Ramp lift cylinders - 842,395 km, replace R/H side brake relay valve - Late invoice for W/O 48951 brake parts	14/05/2021 1	km	.00	4.75	\$2318.10
	49120	Repair machinery Defects, adjust brakes, repair number plate light wiring, replace rear warning signs on both ramps	18/05/2021 1	km	.00	2.00	\$283.09
	49113	Supply 6 New Tyres & 2 new rims	31/05/2021 1	km	.00	.00	\$3242.91
	49372	Repair cracks in goose neck, sand blast & paint AT - replace air hose from relay valve to brake booster	20/07/2021 1	km	.00	.00	\$5909.82
	49509	Replace 2 tyres & supply 8 tyres	31/08/2021 1	km	.00	.00	\$4418.94
	49595	Replace L/H ramp cylinder - , repair broken hubometer, rear tail light, replace l/h ramp cylinder, top up hyd oil, replace reflectors, repair grease hose,	17/09/2021 1	km	.00	9.00	\$1768.87
	49758	Repair starting fault with Honda motor trace to loose earth, repair cracked deck tie downs, axel lift, bent rod on R/H rear axle locking air chamber, trace & repair air leaks, replace T piece for deck locks R/H/S, water drain L/H air tank, Pos 8 axle lift/lock chamber diaphragm, all mounting bolts for Hydraulic drive to honda power pack, caps for ramp pins, repair number plate light wiring & re mount plate, replace bolts in flashing	30/11/2021 1	km	.00	19.50	\$2053.59

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		light, adjust brakes, drain fuel from honda after ingress of water, replace flashing light, re rivet rear ramp signage					
	49909	Remove seized front dolly king pin, cleaned up and refitted - km	6/12/2021 12:	km	.00	2.50	\$227.08
	49918	Replace tyres x 6	9/12/2021 12:	km	.00	6.00	\$2772.41
	49987	Check all wheel bearings & Inspection 1028749 kms, check all wheel bearings, grease all, check lights, adjust all brakes, replace pos 2 booster, replace reflectors on l/h/s, Honda start battery, hub seal & repack Position 5 hub, Blown hydraulic hose, air fittings, adjust brakes -1032422 km	27/01/2022 1	km	.00	27.50	\$3433.65
	50201	February Tyres - Fit 4 x new tyres to Positions 21/22/35/36 & rotate 21/22 to 25/26	1/03/2022 12:	km	.00	1.00	\$433.73
	50197	25000 km service 1045397 Kms	7/03/2022 12:	10000031.0 km	.00	6.00	\$452.11
	50207	Replace trailer plug, 1043166 Kms, section of harness, number plate light, flashing light, 1051273 Kms Repair clearance light r/h/s,	26/04/2022 1	km	.00	10.50	\$1259.91
	50398	Mechanical Inspection -1055257 Km's - Adjusted brakes & wheel bearings, Check movement in suspension pivots & report, grease all points & repaint all welded repairs.	26/04/2022 1	km	.00	17.50	\$932.25
	50110	Turntable Repair -1,055,257 km, replace worn main tow pin boss, pivot bushes, pins, remove pivot pins, strip down turntable, clean, gouge off boss, weld in new part, reassemble, repair cracked tie down points, Pos.1 axel lift bracket	28/04/2022 1	km	.00	60.00	\$5388.54
	50437	April tyres - supply 12 tyres	29/04/2022 1	km	.00	.00	\$5292.00
	50462	Replace all suspension frame & cylinder bearings & pins - 1057223 kms, remove pins & bearings from frames, clean up bores, install new bearing and pins, reassemble, replace side mark lights, service Honda motor, replace valve extensions	13/05/2022 1	km	.00	177.00	\$16226.50
	50756	Replace Tyres 1051167 kms, fit new tyres to pos 33 & 34, replace stenco hubmeter,	18/07/2022 1	km	.00	2.00	\$227.22
	50935	Manufacture spare wheel holder on goose neck - 1065201 km	29/08/2022 2:	km	.00	1.00	\$115.70
	51015	Repair to lifting leg mechanism on Pos 1 axle, fit hose joiner to service brake air supply 1070762 klms -	19/10/2022 8:	km	.00	7.00	\$604.00
	51215	Replace honda battery, check L/H ramp lever fault not locking in 'float' 1 086 474 kms - replace ramp valve assembly, weld	3/11/2022 12:	km	.00	4.50	\$1288.42

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		new handle on dolly pin, replace P2, P4 inside tyres, fit P2 outside to inside of P4, fit 2x new tyres to P2					
51335		Replace ramp chains	6/12/2022 12:	km	.00	1.00	\$124.15
51629		February Tyres repair costs	3/02/2023 10:	km	.00	.50	\$4064.88
51826		Replace 2 x Tyres - Perth - Bullsbrook Tyres supplied and fitted	9/03/2023 10:	km	.00	1.00	\$710.11
51855		Replace two float tyres - Bullsbrook WA	16/03/2023 7:	km	.00	1.00	\$780.31
51782		Replace broken axle lift brackets on L/h front axle and main lug on L/h rear axle - 1127456 km check all other for cracks, repair wiring harness for LHS clearance lights, grease trailer, adjust brakes, replace RH rear brake slack adjuster	13/04/2023 7:	km	.00	12.50	\$2135.03
52062		Replace broken hydraulic fitting on rear control valve - [Pirtek Wacol]	12/05/2023 1	km	.00	1.00	\$361.11
51861		Machinery inspection - 1139612km, repair defected rear marker plates, adjust all brakes to correct brake imbalance & replace park brake relay valve.	16/05/2023 7:	km	.00	1.00	\$256.00
52344		50000 km service - 1157651kms - Carried out grease service and adjusted brakes. Topped up hydraulic oil.	10/07/2023 2:	1157651.00 km	.00	3.00	\$260.00
52413		Check over and grease + replace L/H ramp cylinder - 1161743 klms - Removed LH ram and switched fittings over. Fitted new ram and bled system.	24/07/2023 1	km	.00	2.00	\$454.25
52498		Replace 2 tyres - 1169622 klm- Replaced Pos 37 & 38 tyres and checked all other tyres pressures.	4/09/2023 11:	km	.00	2.50	\$783.28
52526		Repack all wheel bearings. Check brakes. - 1171162km - Replaced all wheel bearings and packed with grease. Replaced all brake linings and adjusted. Fitted wheels and torqued to spec. Replaced engine oil and spark plug. Greased all points. Replaced hydraulic filter	5/09/2023 9:1	km	.00	67.00	\$8026.84
52743		Replaced POS 15 tyre - 1172965 kms - Removed Pos 15, released air, fitted spare and torqued to spec.	30/10/2023 1	km	.00	2.50	\$587.19
52761		Change out 3 tyres + replace 3 mudflaps - 1176805 klms	13/11/2023 1	km	.00	6.00	\$1592.59
52891		Replace mud flap + replace inside tyre + repair air valve mount - POS 5 - 1184172klms - Drilled out mounting hole and tapped, remounted air valve. Check suspension locking valve issue - found over tightened limiting washer	11/12/2023 1	km	.00	7.50	\$944.79

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost	
	52936	Replace damaged tyres + all outer hub gaskets - 1,190907klms - Replaced POS 11&12 tyres. Adjusted brakes and tested suspension.	3/01/2024 9:2	km	.00	22.50	\$1294.64	
	52965	25000 km service - 119090 klm	1/02/2024 2:5	119090.00 km	.00	8.00	\$716.00	
	53131	Repairs to ramps	4/03/2024 8:1	km	.00	1.00	\$8500.00	
	53227	Pre COI Inspection - 119526km, repaired LH front deck widener cylinder guard, replaced both rear mud flaps, replaced 11 reflectors, replaced missing suspension cylinder retainer bolt bushing on Pos 43/44, adjusted brakes, greased trailer.	20/05/2024 3:	km	.00	14.00	\$1534.64	
	53760	Replace Pos 39/40. 41/42 tyres - 1222283km - Replaced oversize flags.	16/10/2024 7:	km	.00	.00	\$2196.66	
	53849	Wheel Bearing repack 1,239137km - Replaced broken Pos 41 slack adjuster. Replaced LHR suspension hose. Replaced all brake shoes and drums. Replaced all wheel bearings. Replaced 4 tyres (29,30,31,32), Repair main trailer wiring harness. Greased float.	14/11/2024 1	140987.00 km	.00	.00	\$13025.94	
	54071	12500km Service - 1251517kms - Replaced Pos 41 & 42 tyres. Adjusted brakes. Replaced LHF clearance light.	31/01/2025 1	1251517.00 km	.00	.00	\$2050.82	
	54112	Check brakes not releasing - 1253059kms - Found crimped air line, replaced hose. Replaced LHS CA 400 relay Valve	12/03/2025 3:	km	.00	.00	\$2920.96	
	54301	COI Inspection - 1267166 kms, replace 2 dust caps on ramp pivot pins, replaced mudflap on pos 35/36, replaced leaking air hose to brake booster pos 35/36, topped up hydraulic oil, adjusted pos 41/42 wheel bearing, fitted r/o tyre onto pos 29/30, repaired wiring harness to rear left clearance light, rectified brake indifference in 2nd axle. replaced various reflectors	29/05/2025 2:	km	.00	.00	\$1475.99	
No of W/O for 3251		:	181	Asset Total:	3251	0.0	1422.8	\$271,430.25
No of W/O for THH		:	181	Parent Total:	THH	0.0	1422.8	\$271,430.25
Grand Total			181			0.0	1422.8	\$271,430.25