



Mid-Valley Drivetrain & Truck Repair Ltd.

#5-32860 Mission Way
Mission, B.C. V2V 5X9
Canada
Tel: (604) 826-4031
Fax: (604) 826-4004

Invoice
Date:

8354
04/20/2

MOY-2

Sold to:

Mellof Excavating & Landclearing Ltd.
11192 286th Street
Maple Ridge, BC V2W 1L7

Unit #124

Business No.: 852994268 RT0001

Item No	Quantity	Description	Unit Price	Amount
308925-25	1	Clutch	1,221.30	1,221.30
SB200	1	Clutch Brake	41.25	41.25
6306	1	Pilot Bearing	21.76	21.76
1425868	1	Crank Seal	185.07	185.07
2569651	1	Flywheel & Grind	595.00	595.00
S1658	1	Input Shaft	90.75	90.75
81504	1	Input Bearing	61.34	61.34
20550	1	Input Cover	24.75	24.75
16980	1	Snap Ring	2.04	2.04
14750	2	Snap Ring	1.41	2.82
K3480	1	Auxiliary Over Drive Gear	376.44	376.44
4300907	1	Splitter Collar	52.09	52.09
K3288	1	Gasket Kit	61.85	61.85
K1935	1	Slave Kit	44.73	44.73
4306648	2	Collar	32.59	65.18
4304317	1	Collar	46.59	46.59
4304615	1	Main Shaft Key	6.96	6.96
4304510	1	Main Drive Gear	214.15	214.15
4304514	1	Over Drive Main Shaft Gear	170.13	170.13
50W	1	20L - Synthetic Transmission Oil	239.20	239.20
15918	3	Spring	1.38	4.14
12815	4	Bushing	5.56	22.24
106C1498	1	Cross Shaft	9.80	9.80
M1986	1	Cross Shaft	49.07	49.07
5-281X	2	U-Joint	60.34	120.68
5-676X	1	U-Joint	137.54	137.54
1810Front	1	Front Driveshaft (new)	1,538.37	1,538.37
210-635P	1	Reverse Switch	19.18	19.18
K2003	1	Isolator Pin Kit	6.07	6.07
PH3614	1	Transmission Oil Filter	6.97	6.97
35P15-2	2	PTO Shim	2.64	5.28
21406MX	1	5" V Clamp	41.27	41.27
15/40	1	32L - Engine Oil	156.48	156.48
1R1808	1	Oil Filter	50.38	50.38
2568753	1	Fuel Filter	37.62	37.62
FF5319	1	Fuel Filter	16.03	16.03
Labour	25	Vibration issue with clutch. Found parts of the clutch in bottom of clutch housing. Pull transmission, replace clutch, flywheel & crank seal. Look at transmission, found a few worn out parts. Rebuild as required. Send drive shaft out to get yoke repaired. Was unable to repair, had to install new driveshaft. Install transmission. Service truck, grease chassis.	105.00	2,625.00
Shop	1	Shop Supplies	85.00	85.00
		Subtotal:		8,454.50

PAID
JUN 11 2021
4864

Restocking Charge May Be Applied To Returned Parts

Continue