

3/4/2010

Print Sales Receipt

mo4-2

**FRASER VALLEY TRUCK
PARTS**Unit 12 32860 Mission Way
Mission, BC V2V 5X9
Canada1-604-826-2614
Fax 1-604-826-0392
officefvtp@gmail.com
<http://fraservalleytruckparts.com/>Sales Receipt SALES
RECEIPT107

Bill To

CASH CUSTOMER

604-826-2614

Ship To

CASH CUSTOMER

604-826-2614

Sales Receipt SALES RECEIPT107

Sales Person	Brenda Craig	Payment Method	Check
Make, Model and Year	2008 Pete 367	Payment Notes	87566397 TD
Mileage	761801 KM 22578.9 HRS		Bank
Unit #	124	Sold On	01 March 2019
VIN#	764456		

Paid \$40,613.23

Item	Price	Quantity	Line Total
Laptop hook up	100.00	1	100.00
Labour for inframe overhaul and turbos and air to air	6,950.00	1	6,950.00
IPD Inframe overhaul kit	5,250.00	1	5,250.00
Stock #NWC8402-R	4,450.00	1	4,450.00
Engines & Engine Parts / Heads - Engine Make: Caterpillar - Engine Model: C15			
Stock #NWC8402-R	625.00	1	625.00
Core Charge for Stock #NWC8402-R			
Have original injectors tested	500.00	1	500.00
Injectors	1,034.93	6	6,209.58
Injector O-rings	17.95	6	107.70
Cut block with shims	1,895.00	1	1,895.00
High pressure turbo	2,961.25	1	2,961.25
Low pressure turbo	2,640.00	1	2,640.00
Injector Harness Genuine	455.41	1	455.41
Exhaust sleeves	225.00	1	225.00
Exhaust stud kit	185.00	1	185.00
Turbo stud and nut kit	130.00	1	130.00
Paint as needed	14.95	4	59.80
Thermostat	50.00	2	100.00
Oil pan gasket	210.00	1	210.00
Lube pump	855.00	1	855.00
Updated jake studs	12.95	6	77.70
Updated rocker hold down bolts	15.95	12	191.40
Used intake rocker	125.00	1	125.00
Used rocker shaft	300.00	1	300.00
Charge air cooler with 5 year	1,100.00	1	1,100.00
FS1000	26.59	1	26.59
1R-0749	37.95	1	37.95

Item	Price	Quantity	Line Total
1R-1808	55.53	1	55.53
15-40W Oil	4.25	42	178.50
Red Long Life Coolant	4.65	56	260.40

Subtotal 36,261.81

Notes

Truck came in running, but has miss and knocking noise. Hook up laptop check for codes found codes for IVAs and injector current. Remove valve cover found center rocker shaft blown out from cam journal. Replaced all top end bolts and studs with updated hardware. Found turbos pressuring base. Replaced both turbos. Found liners worn when head was off. All main bearings, rod bearings, pistons rings and liners replaced. Injector were sent and tested found to be no good replace with Cat reman injectors. Found injector harness damaged and replaced with new one. found liners fretting into block had block cut with shims. Tested air to air found it was blow out replace with aftermarket with 5 year warranty. Found engine is deleted will not be able to give parts warranty for engine parts. 6 months workmanship warranty will be given determined by FVTP. Take truck for road test.

Provincial Tax @ 7.00 % 2,538.33

Federal Tax @ 5.00 % 1,813.09

Total Tax 4,351.42

Paid **\$40,613.23**

Balance **\$0.00**

GST #70831 372 RT0001

Due Upon Receipt.

No Refunds or exchanges on Electronics

No returns after 30 days and must be returned in same condition it left in.