



Peterbilt Pacific Inc.

Office (Mello) EXCAVATING PETERBILT PACIFIC INC. 19470 96<sup>th</sup> AVENUE SURREY, B.C. V4N 4C2 Phone: (604) 888-1411

M04-2

Customer: MELLOF EXCAVATING & LANDCLEARING LTD

604-716-2252 SHELLEY.

Account # 70706 Phone # 604 716-3032 Invoice Date: 10-27-20

Repair Order No: S180599 CUSTOMER INVOICE

11192 286TH ST MAPLE RIDGE, BC V2W 1L7

Tax ID: Tax ID Date:

Page 1

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2008	Peterbilt / 367	1NPTLB0X08D764456	KE8186	827456	124	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
10-23-20 / 06:46PM	11-22-07	1026	24954.0		3.91	
Engine Model / Serial #	Transmission Model/Serial #	Rear Axle Model/Serial #				
C15 / SDP07419	RTLO18918B / S0655296	D2000F HN02878913 R46-170DH HN02878914				
CPL ARR#	Complete	P.O. Number	Authorization	Service Write		
307-6968	10-27-20			LW*LW		
Memo	JOE . 604-716-3032 mellofexcavating@gmail.com					

- MVI Expires DECEMBER 2020
- SERVICE SPECIAL - PERFORM QUICKCARE SERVICE & INSPECTION

CHANGED ENGINE OIL AND FILTER  
 REPLACED FUEL FILTERS  
 CHECKED FLUID LEVELS (OK)  
 GREASED CHASSIS  
 TESTED LONG LIFE COOLANT: -40F (OK)

TOTAL LABOR	199.95
TOTAL PARTS	107.65
TOTAL GAS/OIL	154.35
TOTAL ECO FEE	3.75
TOTAL EHC-OIL	1.75
TOTAL COUPON DISCOUNT	-25.00

Qty	Part Number	Description	List	Unit	Extended
1	1R1808	FILTER	51.94	43.28	43.28
1	1R0749	FILTER	32.54	27.12	27.12
1	2568753	FILTER	44.70	37.25	37.25
35	222290-990C	15W40BULK	154.35	4.41	154.35
1	1R1808&	ECO-FEE	1.25	1.25	1.25
1	1R0749&	ECO-FEE	1.25	1.25	1.25
1	2568753&	ECO-FEE	1.25	1.25	1.25
35	222290-990C&	EHC-OIL	1.75	0.05	1.75
-1	COUPON DISCOUNT	Z200035	25.00	25.00	-25.00

- CUSTOMER REQUEST - CHECK AND REPAIR FOR REMOTE GREASE LINES MISSING/DAMAGED

REPAIRED BROKEN FITTING AT REMOTE BLOCK  
 CLEARED GREASE LINE THAT WAS NOT HOOKED UP  
 REINSTALLED LINE WITH NEW FITTING  
 TESTED OPERATION - OK

TOTAL LABOR	231.00
TOTAL PARTS	1.61

Qty	Part Number	Description	List	Unit	Extended
1	48-4A	FITTING	1.03	0.86	0.86

Invoice Date: 10-27-20

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2008	Peterbilt / 367	1NP7LBOX08D764456	KE8186	827456	124	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dlr	Axle Ratio	
10-23-20 / 06:46PM	11-22-07	1026	24954.0		3.91	
Engine Model / Serial #	Transmission Model/Serial #	Rear Axle Model/Serial #				
C15 / SDP07419	RTLO18918B / S0655296	D2000F HN02878913 R46-170DH HN02878914				
CPL ARRG	Complete	P.O. Number	Authorization	Service Writer		
307-6968	10-27-20			LW*LW		
<b>Memo</b>	JOE . 604-716-3032 mellofexcavating@gmail.com					

1 1460-4	FITTING	0.17	0.14	0.14
1 1461-4	FITTING	0.73	0.61	0.61

4 CUSTOMER REQUEST - DIAGNOSE AND REPAIR FOR CHECK ENGINE LIGHT ON

HOOKED UP DIAGNOSTIC COMPUTER AND CHECKED FOR FAULT CODES  
 HIGH COUNTS OF CRANKCASE PRESSURE  
 NOTICED ENGINE HAS 2 BLOW BY TUBES AND FILTER MODULE HAS BEEN REMOVED  
 NO FURTHER ACTION TAKEN

TOTAL LABOR 99.95

5 PM DEFICIENCY REPAIR - WATER PUMP IS LEAKING

DRAINED COOLANT AND REMOVED COMPONENTS FOR ACCESS  
 REMOVED WATER PUMP AND CLEANED MATING SURFACE  
 INSTALLED NEW WATER PUMP WITH SEAL KIT  
 REINSTALLED PARTS REMOVED  
 REINSTALLED COOLANT AND STEAM CLEAN  
 RUN ENGINE AND CHECKED FOR LEAKS - OK

TOTAL LABOR 984.00  
 TOTAL PARTS 1,362.40  
 TOTAL GAS/OIL 21.18  
 TOTAL EHC-OIL 2.28  
 TOTAL COUPON DISCOUNT -2.00

Qty	Part Number	Description	List	Unit	Extended
1	10R8660	WATER PMP	1,582.24	1,318.53	1,318.53
2	1121102	O-RING	33.92	16.96	33.92
1	6V1585	SEAL O RI	7.50	6.88	6.88
1	22617-12	#12BOSS	1.19	0.99	0.99
1	TS17R-18	CLAMP	0.92	0.77	0.77
1	HC6-72	CLAMP	1.57	1.31	1.31
2	EC7501	COOLANT-T	21.18	10.59	21.18
2	EC7501&	ECO-FEE	2.28	1.14	2.28
-1	COUPON DISCOUNT	Y201002	2.00	2.00	-2.00

6 PM DEFICIENCY REPAIR - EXHAUST FLEX PIPE IS LEAKING AND THERE IS A HOLE IN PIPE NEAR MUFFLER

REMOVED EXHAUST AND FABRICATED PIPE  
 ASSEMBLED AND INSTALLED ON TRUCK  
 RUN ENGINE AND CHECKED FOR LEAKS - OK

TOTAL LABOR 462.00  
 TOTAL PARTS 71.40  
 TOTAL COUPON DISCOUNT -3.00

Qty	Part Number	Description	List	Unit	Extended
3	EC50PLS	CLAMP-EXH	33.75	11.25	33.75
1	EC50ESTB	CLAMP-EXH	16.85	15.17	15.17

Invoice Date: 10-27-20

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2008	Peterbilt / 367	1NP7LBOX08D764456	KE8186	827456	124	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
10-23-20 / 06:46PM	11-22-07	1026	24954.0		3.91	
Engine Model / Serial #	Transmission Model/Serial #		Rear Axle Model/Serial #			
C15 / SDP07419	RTLO18918B / S0655296		D2000F HN02878913 R46-170DH HN02878914			
CPL ARRG	Complete	P.O. Number		Authorization	Service Writer	
307-6968	10-27-20				LW*LW	
Memo	JOE . 604-716-3032 mellofexcavating@gmail.com					

2	EF50300S409	EXHAUST-F	2.54	1.27	2.54
1	EF50STA60	TUBING-RO	22.16	19.94	19.94
-1	COUPON DISCOUNT	Y200545	3.00	3.00	-3.00

7 PM DEFICIENCY REPAIR - FRONT DRIVE AXLE TORQUE ROD BUSHINGS ARE WORN OUT

QR1 valve has broken mounting point.

CORRECTION:

Replace torque rod & QR1 valve for forward drive axle.

TOTAL LABOR	231.00
TOTAL PARTS	265.85

Qty	Part Number	Description	List	Unit	Extended
1	C65-6025-000000581	ROD - TRA	302.06	251.72	251.72
1	0R229859BXR	VALVE-QR-	16.96	14.13	14.13

8 PM DEFICIENCY REPAIR - TRANSMISSION OIL LEAK AT PTO...OIL LEVEL IS LOW

REMOVED PTO PUMP AND DRAINED OIL  
 REMOVED PTO AND INSPECT  
 FOUND GEARS VERY WORN AND ADAPTER HOUSING BOLTS BROKEN  
 TOOK PTO TO VENDOR TO ACCESS AND PROVIDE REPAIR OPTIONS  
 DISCUSSED WITH CUSTOMER AGREED TO REPLACE PTO  
 INSTALLED NEW PTO AND SHIMMED TO SPECS  
 INSTALLED NEW OIL AND FILTER  
 REPLACED BROKEN TRANSMISSION TEMPERATURE SENSOR  
 REINSTALLED PUMP AND TESTED - OK

TOTAL LABOR	693.00
TOTAL PARTS	1,669.83
TOTAL ECO FEE	0.90
TOTAL EHC-FILTER	0.55

Qty	Part Number	Description	List	Unit	Extended
1	489XLAHX-A3XK	PTO ASSEM	1,511.25	1,316.25	1,316.25
1	Q21-1002	SENDER-TE	92.27	76.89	76.89
1	4304827	ELEMENT-O	38.05	31.71	31.71
18	223079-953C	CHV DELO	244.98	13.61	244.98
18	223079-953C&	ECO-FEE	0.90	0.05	0.90
1	4304827&	ECO-FEE	0.55	0.55	0.55

9 PM DEFICIENCY REPAIR - CLUTCH NEEDS ADJUSTING

ADJUSTED CLUTCH TO SPECS

TOTAL LABOR	79.00
TOTAL COUPON DISCOUNT	-30.00

Invoice Date: 10-27-20

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Number
2008	Peterbilt / 367	1NP7LBOX08D764456	KE8186	827456	124	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
10-23-20 / 06:46PM	11-22-07	1026	24954.0		3.91	
Engine Model / Serial #	Transmission Model/Serial #	Rear Axle Model/Serial #				
C15 / SDP07419	RTLO18918B / S0655296	D2000F HN02878913 R46-170DH HN02878914				
CPL ARRG	Complete	P.O. Number	Authorization	Service Write		
307-6968	10-27-20			LW*LW		
<b>Memo</b>	JOE . 604-716-3032 mellofexcavating@gmail.com					

Qty	Part Number	Description	List	Unit	Extended
-1	COUPON DISCOUNT	Z200058	30.00	30.00	-30.00

10 PM DEFICIENCY REPAIR - REVERSE LIGHTS NOT WORKING

REMOVED SHIFTER FLOOR COVER TO ACCESS SWITCH  
 UNPLUGGED SWITCH AND JUMPER CIRCUIT - NO POWER TO SWITCH  
 CHECKED AND REPLACED MISSING FUSE  
 TESTED OPERATION - OK  
 REINSTALLED FLOOR COVER

TOTAL LABOR	138.60
TOTAL PARTS	1.35

Qty	Part Number	Description	List	Unit	Extended
1	98611-20	20AMP MIN	1.62	1.35	1.35

11 PM DEFICIENCY REPAIR - RIGHT REAR DRIVE AXLE WHEEL SEAL IS LEAKING

REPLACED LEAKING WHEEL SEAL AND OIL CONTAMINATED BRAKES  
 FOUND SPACER/CONE BADLY WORN - REPLACED  
 USED 2 PIECE WHEEL SEAL BECAUSE SPINDLE WAS PITTED  
 REINSTALLED WHEELS AND TORQUED

TOTAL LABOR	523.60
TOTAL PARTS	332.66
TOTAL COUPON DISCOUNT	-8.00

Qty	Part Number	Description	List	Unit	Extended
1	CM10081520	KIT-SEAL	123.43	102.86	102.86
1	03-01568	GASKET-AX	7.33	6.11	6.11
1	60000-018	DRUM-BRAK	112.50	93.75	93.75
1	MKT4709ES2N	KIT-BRAKE	16.02	13.35	13.35
2	RS4709E2PR23M	REMAN SHO	52.88	26.44	52.88
1	392-9131	SEAL	76.45	63.71	63.71
		USING CM10081520 FOR CONE AND 2 PIECE SEAL			
-1	COUPON DISCOUNT	M2002117	8.00	8.00	-8.00

12 PM DEFICIENCY REPAIR - AUDIBLE AIR LEAKING IN CAB

BODY BUILDER VALVE IN CAB IS LEAKING  
 REPLACED LEAKING FITTING FOR TARP CONTROL

TOTAL LABOR	92.40
TOTAL PARTS	9.62

Qty	Part Number	Description	List	Unit	Extended
1	PL1369-4A	ELBOW FTG	11.54	9.62	9.62

SUPPLIES/TECHNOLOGY 357.74

B/O RELEASE SE64336 CONFIRM # 128308

Invoice Date: 10-27-20

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Tag Num
2008	Peterbilt / 367	1NPTLBOX08D764456	KE8186	827456	124	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Sell Dir	Axle Ratio	
10-23-20 / 06:46PM	11-22-07	1026	24954.0		3.91	
Engine Model / Serial #	Transmission Model/Serial #	Rear Axle Model/Serial #				
C15 / SDP07419	RTLO18918B / S0655296	D2000F HN02878913 R46-170DH HN02878914				
CPL ARRG	Complete	P.O. Number	Authorization	Service Write		
307-6968	10-27-20			LW*LW		
<b>Memo</b>	JOE . 604-716-3032 mellofexcavating@gmail.com					

G.S.T. - REG. NO. 888250784RT0001 5 % OF 8,031.37 = 401.57

SALES-PARTS-SERVICE	4070402	3,822.37
SALES-OIL & GREASE	4130402	175.53
SALES-LABOUR	4300403	3,734.50
SUPPLIES/TECHNOLOGY	6620403	357.74
WASTE DISPOSAL	6660403	9.23
DISCOUNT ON SALES	6700402	-68.00
P.S.T. PST-1056-8118	2140400	562.20
G.S.T. 888250784RT00012180101		401.57
PLEASE PAY THIS TOTAL	1110100	8,995.14

I, THE UNDERSIGNED, OWNER OR DULY AUTHORIZED REPRESENTATIVE, HEREBY ACKNOWLEDGE MY INDEBTEDNESS IN THE TOTAL AMOUNT SHOWN ABOVE. I HAVE READ AND UNDERSTOOD THE TERMS AND CONDITIONS LISTED BELOW.

Customer: X Date: \_\_\_\_\_

1. **PAYMENT TERMS:** Due and payable new 15<sup>th</sup> following. It is understood and I agree to pay carrying charges of 2.25% per month (30.6% per annum) on any balance un after the 15<sup>th</sup> of the following month of the date of purchase.

2. **WARRANTY CONSIDERATIONS:** Any portion of this repair order that is designated for warranty considerations will be submitted as a warranty claim to the manufacturer for any reason the manufacturer rejects the claim or a portion of the claim, it will become the immediate responsibility of the owner to pay that portion which is rejected.

3. **WARRANTY LIMITATION:** All service repairs carry a maximum of 30 days warranty from day of completion. Any claims must be made within 5 days of the failure date. Certain parts, products, accessories, and other items used in completing the repair and service work covered in this repair order are manufactured and supplied by others quality and workmanship of which are entirely outside the control of Peterbilt Pacific, Inc. With regard to such parts, products, and accessories, ect. PETERBILT PACIFIC INC MAKES NO WARRANTIES, WHETHER EXPRESSED, IMPLIED, STATUTORY, OR OTHERWISE, INCLUDING ANY WARRANTY OF MERCHANTABILITY OR OF FITNESS FOR A PARTICULAR PURPOSE.

4. **RESPONSIBILITY OF EQUIPMENT:** Peterbilt Pacific Inc. will not be held responsible for the loss or damage to vehicles, or articles left in vehicles, in case of fire, theft, accident, or any other cause beyond their control.

5. **ALL OLD PARTS** removed will be disposed of, unless otherwise specified before repairs started.

6. **THE SIGNATURE** of the owner or duly authorized representative on the original work order request, authorized the repair and service work listed on this repair order, and with the necessary material.

7. **PRIVACY:** Personal information is collected in accordance with applicable privacy legislation and is governed by Peterbilt Pacific Inc. Privacy Policy.