



Cummins South Pacific Pty. Ltd.

ABN NO. 42006332949

BRISBANE
P O BOX 227
ARCHERFIELD QLD 4108
Ph: 07 3710 4700
Fax: 07 3375 3520

WORKSHOP TAX INVOICE

INVOICE NUMBER 1717675
INVOICE DATE 28/08/25
PAGE 1



Engine Model:	SIGNATURE/ISX/QSX	Eng No:	79985597	Equip Make:	KENWORTH
FleetNo:	PM13	Reg No:	VCT13	Cust Ord NO:	1608
Date in Service:	10/10/17	KLMS:		HRS:	46441
Repair Date:	18/08/25	Chassis NO:	459589	Currency:	AUD
C.O.No.	6798693	Work ordNo.	2976579	Facility	130

Complaint:

Pressurising

Cause:

Engine replacement

Correction:

OEM Kilometres/Hrs: 2,028,552klms / 46,441hrs
ECM Kilometres/Hrs: 2,033,293klms / 29,202hrs
Fuel Burn: 1,139,862ltrs

Old ESN: 79985597

New ESN: 80666017

CORRECTION:

- Download ecm & upload files to guidanz
- Drain fluids from engine
- Remove plumbing from engine
- Remove engine
- Spec up new engine & replace required oem parts
- Fit new engine & all removed plumbing
- Fill with fluids
- Uprate engine to 600hp/2050ft lb
- Wash, dyno & road test
- We found fault code 1694 became active - NOx sensor faulty
- Replace NOx sensor
- Carry out road test
- Check over & return to service

Warranty Plus:

5yrs / 1,200,000klms / 18,000hrs / 600,000ltrs

Cummins South Pacific Pty. Ltd. WORKSHOP TAX INVOICE



BRISBANE
 P O BOX 227
 ARCHERFIELD QLD 4108
 Ph: 07 3710 4700
 Fax: 07 3375 3520

INVOICE NUMBER 1717675
INVOICE DATE 28/08/25
PAGE 2

Invoice To
 Account Number 3230502

Description	Operation	Unit price	Qty	Extension
Engine R&R:		\$ 7,750.00		
Engine:		\$86,016.00		
OEM parts:		\$ 2,689.45		
Coolant hose kit:		\$ 750.00		
Warranty plus:		\$ 8,125.00		
Uprate:		\$ 5,230.00		
Account discount:		-\$13,095.05		
Cummins goodwill labour discount:		-\$ 3,424.00		
Cummins goodwill engine discount:		-\$ 7,311.40		
Extra work:				
Diagnostic labour (4hrs):		\$ 856.00		
NOx sensor:		\$ 1,298.21		
TOTAL INVOICE:				\$88,884.21 + gst

Description	Operation	Unit price	Qty	Extension
Material				
52371.02	ENGINE, ISXE5 500 / 1850		1	
80261GL	HOSE DAYCO SILICONE		1	
78250GL	SILICONE HOSE 915MM LE		1	
80264GL-CM	HOSE, HEATER (CM)		50	
4988280	GASKET HYDRAULIC PUMP		1	
275707	AIR GOVERNOR VALVE D-2		1	
DCT110H1RW	TIE-CABLE BRAKE HOSE 19.2		35	
65-90820EA	CABLE TIE 292X3.5MM PER		50	
65-90860EA	CABLE TIE 380X8MM PER EAC		70	
PGXLVITAL-20L	PGXL VITAL ADVANCED COOLA		3	
6PK1590	DAYCO BLUE LABEL BELT		1	
12PK2380	BELT V RIBBED DAYCO POLY		1	
2866337	GASKET AFM DEVICE		2	
1324.05	PREMIUM BLUE 8600 5L OIL		2	
1324.20	PREMIUM BLUE 8600 20L OIL		2	
5462439RX	RECON, NOX SENSOR		1	

Cummins South Pacific Pty. Ltd. **WORKSHOP TAX INVOICE**



BRISBANE
P O BOX 227
ARCHERFIELD QLD 4108
Ph: 07 3710 4700
Fax: 07 3375 3520

INVOICE NUMBER **1717675**
INVOICE DATE **28/08/25**
PAGE **3**

Invoice To
Account Number 3230502



Description	Operation	Unit price	Qty	Extension
-------------	-----------	------------	-----	-----------

Subcontract

5580926	OEM Parts		1	
5581004	Rear lower engine mounts		1	
5581217	Radiator hose clamps		1	

SUB-TOTAL	88884.21
G.S.T	8888.42
INVOICE TOTAL	97772.63



Cummins

39 – 53 Ron Boyle Crescent
Carole Park, Qld 4300
PO Box 227
Archerfield QLD 4108
Service 07 3710 4700

Monday 25th August, 2025

Leslie Refrigerated Transport
PO Box 1476
Irymple VIC 3498

Vehicle Model: Kenworth K200
Chassis # 459589
Rego # VCT13

To Whom it May Concern,

This letter is to advise you that as a recent repair to your vehicle the original ISX engine ESN: 79985597 was replaced with a New Cummins engine ESN: 80666017.

Please be aware that this will require you to make the necessary changes to your vehicle registration and insurances as required.

The original failed ESN: 79985597 replaced by
The New ISX ESN: 80666017 now fitted to this vehicle.

Thank-you for choosing to stay a Cummins Customer we look forward to helping you maintain your new Engine.

Regards

A handwritten signature in black ink, appearing to read 'Mandy Wesener', written over a horizontal dotted line.

Mandy Wesener
Service Administration
Cummins Brisbane BR130.