

CD01-27

## Maintenance History 675

SER# YCE00502

| Work Order ID | Description                                                                                                                         | Sublet Vendor Labor \$ | Part \$    | Total \$   | Hour Reading                 |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------|------------------------|------------|------------|------------------------------|
| 7420          | -FINNING REPAIR,<br>-T/S BOOM DRIFT                                                                                                 | \$841.20               | \$0.00     | \$841.20   | 3169 on 6/1/2015 9:32:12 AM  |
| 7695          | -FINNING REPAIR,<br>-REPLACE HEAVY LIFT SOLENOID (WARRANTY)                                                                         | \$0.00                 | \$0.00     | \$0.00     | 2675 on 4/7/2015 3:16:55 PM  |
| 8711          | -REPLACE SWIVEL GUARDS                                                                                                              | \$0.00                 | \$2,163.12 | \$2,163.12 | 3896 on 9/28/2015 1:47:28 PM |
| 10104         | -FINNING REPAIR,<br>-REPAIR COOLANT LEAK                                                                                            | \$300.45               | \$136.68   | \$437.13   | 3898 on 9/29/2015 8:36:13 AM |
| 10151         | -FINNING REPAIR (WARRANTY)<br>-REPLACE DELTA P SENSOR AND VENTURI TUBE AS PER REHS8197<br>-REPLACE EGR DIFFERENTIAL PRESSURE SENSOR | \$0.00                 | \$0.00     | \$0.00     | 3898 on 9/29/2015 2:07:00 PM |
| 12226         | -REPLACE FRONT UPPER GLASS                                                                                                          | \$0.00                 | \$643.37   | \$643.37   | 5772 on 5/15/2016 8:30:17 AM |
| 12760         | -REPLACE ENGINE OIL FILTER LINES                                                                                                    | \$0.00                 | \$726.56   | \$726.56   | 6003 on 6/26/2016 3:59:06 PM |

|       |                                                                                                                                     |         |            |            |            |                                |
|-------|-------------------------------------------------------------------------------------------------------------------------------------|---------|------------|------------|------------|--------------------------------|
| 13359 | -FINNING REPAIR, (WARRANTY)<br>-REPLACE INJECTION PUMP (PSS2927)<br>-REPLACE #2 INJECTOR                                            | \$0.00  | \$0.00     | \$0.00     | \$0.00     | 5873 on 6/8/2016 2:45:44 PM    |
| 13980 | -FINNING REPAIR, (WARRANTY)<br>-REPLACE MAIN HYD RELIEF VALVE<br>-PERFORM PS44724,<br>-REPLACE HIGH PRESSURE FUEL PUMP RELIEF VALVE | \$0.00  | \$0.00     | \$0.00     | \$0.00     | 5418 on 4/6/2016 2:18:11 PM    |
| 14896 | -REPAIR HYDRAULIC SYSTEM,<br>-REPLACE LINE RELIEFS<br>-REPLACE AUX BALL VALVES                                                      | \$0.00  | \$2,655.36 | \$2,655.36 | \$2,655.36 | 8131 on 4/23/2017 9:51:38 AM   |
| 17378 | -REPAIR ENGINE,<br>-REPLACE #1 & #3 INJECTORS & QUILL TUBES<br>-REPLACE ENGINE OIL DIPSTICK                                         | \$0.00  | \$1,765.07 | \$1,765.07 | \$1,765.07 | 8830 on 8/4/2017 1:19:57 PM    |
| 17469 | -REPLACE FRONT UPPER WINDOW ASSEMBLY (INVENTORY)<br>-REPLACE BROKEN GLASS (BENS)                                                    | \$86.00 | \$226.38   | \$312.38   | \$312.38   | 8950 on 8/14/2017 1:07:17 PM   |
| 17824 | -NOVUS REPAIR,<br>-REPLACE UPPER CAB GLASS                                                                                          | \$85.00 | \$286.69   | \$371.69   | \$371.69   | 9110 on 9/3/2017 3:35:22 PM    |
| 18774 | -REPLACE #5 INJECTOR & QUILL TUBE<br>-REPLACE WIF SENSOR                                                                            | \$0.00  | \$871.37   | \$871.37   | \$871.37   | 10220 on 12/3/2017 11:24:46 AM |

|       |                                                                                                                                                                                                                                                                                                          |            |             |             |                                |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------|-------------|--------------------------------|
| 18883 | -REPLACE STICK CYLINDER                                                                                                                                                                                                                                                                                  | \$0.00     | \$11,440.78 | \$11,440.78 | 10240 on 12/7/2017 7:38:51 AM  |
| 18921 | -EMSCO REPAIR,<br>-PERFORM INSPECTION & REPAIRS,<br>-WASH MACHINE<br>-INSTALL ESPAR<br>-INSTALL PAS<br>-R&I DPF, SENT OUT FOR CLEANING<br>-REPLACE BLOCK HEATER CORD<br>-REPLACE ENGINE OIL LEVEL SENSOR<br>-REPLACE BATTERIES (2)<br>-REPLACE BURNT OUT LIGHTS<br>-REPAIR/REPLACE DAMAGED BOTTOM GUARDS | \$8,610.00 | \$5,309.71  | \$13,919.71 | 10320 on 1/3/2018 11:16:00 AM  |
| 19529 | -FINING REPAIR,<br>-REPLACE DPF                                                                                                                                                                                                                                                                          | \$1,191.55 | \$6,060.30  | \$7,251.85  | 10628 on 5/2/2018 10:41:55 AM  |
| 19563 | -MISC REPAIRS,<br>-REPLACE REMOTE ENGINE OIL FILTER HOSES<br>-REPLACE FRONT UPPER & LOWER GLASS<br>-REPLACE THUMB CYLINDER                                                                                                                                                                               | \$86.00    | \$6,025.59  | \$6,111.59  | 10605 on 4/30/2018 10:09:30 AM |
| 20953 | -REPLACE DPF<br>-REPLACE NOZZLE HEATER WIRE<br>-UNLOCK DPF<br>-REPLACE T/A FILL VALVE                                                                                                                                                                                                                    | \$1,437.65 | \$5,317.83  | \$6,755.48  | 11669 on 11/9/2018 7:49:45 AM  |
| 23243 | -REPLACE BATTERIES X4                                                                                                                                                                                                                                                                                    | \$0.00     | \$1,290.56  | \$1,290.56  | 12881 on 1/8/2020 10:35:27 AM  |

|       |                                                                                                                                       |             |             |              |                                |
|-------|---------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------|--------------|--------------------------------|
| 23318 | -REPLACE ARD HEAD & SPARK PLUG                                                                                                        | \$0.00      | \$2,594.54  | \$2,594.54   | 12868 on 12/17/2019 3:40:15 PM |
| 23637 | -FINNING REPAIR,<br>-T/S WEAK HYDRAULIC OPERATION,<br>-FOUND DEBRIS IN MAIN RELIEF VALVE                                              | \$1,688.00  | \$0.00      | \$0.00       | 12964 on 2/18/2020 11:26:18 AM |
| 23924 | -REPLACE MASTER SWITCH                                                                                                                | \$0.00      | \$176.99    | \$176.99     | 13201 on 5/19/2020 12:30:57 PM |
| 24198 | -REPLACE RH IDLER                                                                                                                     | \$0.00      | \$2,402.53  | \$2,402.53   | 13418 on 6/22/2020 8:13:09 AM  |
| 24547 | -REPLACE LH IDLER & TRACK ADJUSTER                                                                                                    | \$0.00      | \$4,186.60  | \$4,186.60   | 13681 on 8/5/2020 8:49:26 AM   |
| 24560 | -REPLACE INJECTION PUMP                                                                                                               | \$0.00      | \$4,471.51  | \$4,471.51   | 13755 on 8/20/2020 1:52:43 PM  |
| 25124 | -REPAIR FUEL TANK,<br>-WELD UP CRACKED WELD BOSSES                                                                                    | \$0.00      | \$0.00      | \$0.00       | 13861 on 10/7/2020 1:34:15 PM  |
| 25913 | -R&I ENGINE AND HYD PUMP<br>-REPLACE HYDRAULIC OIL<br>-REPLACE PUMP COUPLER<br>-REPLACE WORN HOSES<br>-REPLACE FRONT UPPER WINDSHIELD | \$13,879.64 | \$91,258.18 | \$105,137.82 | 14247 on 6/21/2021 8:20:49 AM  |
| 29938 | -REPLACE COMPLETE UNDERCARRIAGE<br>-REPLACE CAC TUBE AND REMOUNT PAS VALVE<br>-REPAIR COOLANT LEAKS                                   | \$5,629.00  | \$28,816.91 | \$34,445.91  | 15513 on 2/20/2023 3:25:31 PM  |

|         |                                                                                                                                                          |             |              |              |                                 |
|---------|----------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------|--------------|---------------------------------|
| 30700   | -REPLACE RH BOOM AND BUCKET CYLINDERS<br>-REPLACE MAIN STICK/ THUMB PIN & BUSHINGS<br>-MACHINE STICK END FACE<br>-REBUILD TAKE-OFF CYLINDERS (EMPIRE)    | \$8,666.01  | \$6,849.07   | \$15,515.08  | 15532 on 4/19/2023 9:01:30 AM   |
| 31767   | -REPLACE IDLER PULLEY                                                                                                                                    | \$0.00      | \$366.48     | \$366.48     | 15767 on 6/23/2023 9:00:58 AM   |
| 32387   | -REPLACE FRONT LOWER GLASS                                                                                                                               | \$0.00      | \$585.95     | \$585.95     | 16625 on 11/18/2023 10:39:16 AM |
| 32644   | -REPLACE RH BOOM & STICK CYLINDERS (INVENTORY)<br>-RECONDITION BOOM CYLINDER (EMSCO)<br>-RECONDITION STICK CYLINDER (ALL CAN)<br>-REPLACE CARRIER ROLLER | \$6,418.75  | \$1,601.20   | \$8,019.95   | 17387 on 4/3/2024 11:31:41 AM   |
| 33996   | -REPLACE RH JOYSTICK<br>-REPLACE / REPAIR DAMAGED & BRITTLE WIRING HARNESES<br>-REPLACE SWING BEARING LUBE LINES<br>-REPLACE COOLANT TANK                | \$0.00      | \$1,887.24   | \$1,887.24   | 17718 on 5/23/2024 10:39:52 AM  |
| 34032   | -REPLACE LH H-BAR LINK                                                                                                                                   | \$0.00      | \$1,875.00   | \$1,875.00   | 18129 on 7/23/2024 8:41:17 AM   |
| 34100   | -REPLACE ENGINE OIL FILTER HOSES                                                                                                                         | \$0.00      | \$726.49     | \$726.49     | 18415 on 9/23/2024 8:59:32 AM   |
| Totals: |                                                                                                                                                          | \$48,919.25 | \$192,718.06 | \$241,637.31 |                                 |