

CF07-53

- **Work order number: 420**

Date opened: 2024-06-11

Created by: Mike Baker

Unit Number: TK215

Hours/KMs: 136040

Work Requested: Left rear signal light out

Work Completed: Confirmed rear signal not working. Found that light bulb was burnt out. Changed light bulb, confirmed repair.

Work Completed by: Xavier Adria

Date completed: 2024-06-11

Comments:

[View work order](#)

- **Work order number: 544**

Date opened: 2023-09-18

Created by: Teri Hewitt

Unit Number: TK215

Hours/KMs: 131250

Work Requested: Windshield wiper not working on driver's side. Unit needs oil change. Unit needs tidy tank hose.

Work Completed: Changed oil and oil filter. Installed wiper arms and blades. Filled washer fluid. Changed nozzle on tidy tank.

Work Completed by: Jesse Rempel

Date completed: 2023-09-22

Comments:

[View work order](#)

- **Work order number: 2291**

Date opened: 2022-03-21

Created by: Teri Hewitt

Unit Number: TK215

Hours/KMs: 103827

Work Requested: Perform LVI Inspection.

Work Completed: Fabricate antenna bracket and install beacon and 2-way radio, tie into factory aux switches. Clean dash and under seat. Apply unit numbers.

Work Completed by: NH

Date completed: 2022-03-24

Comments:

[View work order](#)

- **Work order number: 3100**

Date opened: 2023-05-03

Created by: Teri Hewitt

Unit Number: TK215

Hours/KMs: 116119

Work Requested: Perform light inspection for service and repairs.

Work Completed: Repair PTO on tamper. Replace key and retorque bolt in crankshaft end. Resolve stalling condition and test unit.

Work Completed by: NH

Date completed: 2023-05-03

Comments:

[View work order](#)

- **Work order number: 3495**

Date opened: 2023-09-22

Created by: Teri Hewitt

Unit Number: TK215

Hours/KMs: 131250

Work Requested: Performed oil and filter change.

Work Completed: Installed wiper arms and new blades. Changed nozzle on tidy tank hose and filled washer fluid and ordered parts.

Work Completed by: Jesse Rempel

Date completed: 2023-09-22

Comments:

[View work order](#)

- **Work order number: 4124**

Date opened: 2023-08-25

Created by: Teri Hewitt

Unit Number: TK215

Hours/KMs: 0

Work Requested: Diagnose fuel leak.

Work Completed: Tank dropped, replace fuel lines. Remove bumper, 5th wheel, slip tank and bed. Diagnose fuel sender fault. Install new fuel pump - fuel level still not working. Perform electrical diagnosis - found broken wire in harness. Repaired and reassembled unit.

Work Completed by: Mike

Date completed: 2023-09-09

Comments:

[View work order](#)

- **Work order number: 4317**

Date opened: 2024-04-17

Created by: Teri Hewitt

Unit Number: TK215

Hours/KMs: 135568

Work Requested: Inspect unit for service and repairs.

Work Completed: Perform engine service. Change engine oil and replace fuel filters. Tie rod at pitman arm shot, front diff pinion seal leaking and unit needs rear brake pads. Clean tar spatter from front right fender and hood. Clean hub flanges and wheels and charge batteries. Remove rear brake pads and free up seized slide pin. Change out tie rod in drag link at pitman arm and change out front diff pinion seal. Install wheels and torque. Install rear brake pads. Finish with truck and trailer, change bracket for fire extinguisher in trailer and move outside.

Work Completed by: Weldon

Date completed: 2024-04-23

Comments:

[View work order](#)