



# Work Order: 10049

<b>Description:</b> 350 Hour Service and Repairs	894 Hours	<b>Date Started:</b> 2018-03-06
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	RD2018-145 Insheet	
<b>Serial#:</b> B93A340DJ07204664		

## Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
4	04/03/18	EMParts	Dyed Diesel Dyed Diesel		EA	181.700	1.29	234.39
154	03/08/18	EMParts	RE171321 Filter-Fuel 30 Micron		EA	1.000	20.46	20.46
155	03/08/18	EMParts	TT221379 Filter-Air Primary		EA	1.000	163.22	163.22
156	03/08/18	EMParts	TT226019 Filter-Cab Air		EA	1.000	113.58	113.58
157	03/08/18	EMParts	TTDC221512 Filter-Fuel Secondary		EA	1.000	28.60	28.60
158	03/08/18	EMParts	TTDC221513 Filter-Oil		EA	1.000	39.46	39.46
410	03/22/18	EMParts	DC221614 Dipstick-Engine Oil		EA	1.000	134.59	134.59
470	03/26/18	EMParts	TT217618 Wiper Blade-24"		EA	1.000	40.01	40.01
543	03/28/18	EMParts	227782 Filter-DEF Fluid		EA	1.000	58.96	58.96
614	03/29/18	EMParts	DC222298 Sensor-Pressure AdBlu (A006153)		EA	1.000	322.16	322.16

Labour Total	0.00
Parts Total	1,155.43
Miscellaneous Total	0.00

## Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
150	03/08/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
151	03/08/18	EMTime	Employee: 2205 Alexander Zavadi		HRS	1.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 Repair Washer Fluid leak and Fill

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
216	04/06/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 4 Top up Coolant and Tighten Clamps



# Work Order: 10049

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
217	04/06/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 5 Replace Dipstick and Wiper Blade

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
218	04/06/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 6 Tilt cab and Inspect

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
219	04/06/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 7 Check Tire Pressures and Diff. Levels

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
220	04/06/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 8 Tighten loose Bolts in Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
221	04/06/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		



# Work Order: 10049

---

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 9 Repair L/H Mirror

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
222	04/06/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		

---

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 10 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
223	04/06/18	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		

---

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 11 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
224	04/06/18	EMTime	Employee: 1074 Jack Lougheed		HRS	8.000		

---

Labour Total	8.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 12 Trouble Shoot and Repair Mirror

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
225	04/06/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	4.000		

---

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 13 Outsheet Inspection





# Work Order: 10128

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 4 Replace Missing Clip For Hydraulic Hose's

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
486	09/27/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 5 Standard Wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
488	09/27/18	EMParts	Wash Standard Wash		S	1.000	0.00	750.00

Labour Total	0.00
Parts Total	0.00
Miscellaneous Total	750.00

<b>Labour Total</b>	<b>3.00</b>
<b>Parts Total</b>	<b>2,306.25</b>
<b>Miscellaneous Total</b>	<b>750.00</b>

<b>Description:</b> Inspections 350 Hour Service and Repairs	1088 Hours	<b>Date Started:</b> 2018-06-19
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	RD-2018-222 Insheet RD-2019-251 Outsheet	
<b>Serial#:</b> B93A340DJ07204664		

## Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
251	08/13/19	EMParts	5W40 Spectra 5W40		I	31.000	5.17	160.33
252	08/13/19	EMParts	Dyed Diesel Dyed Diesel		EA	15.520	1.02	15.79
708	07/30/19	EMParts	RE171321 Filter-Fuel 30 Micron		EA	1.000	14.26	14.26
709	07/30/19	EMParts	TT221379 Filter-Air Primary		EA	1.000	52.94	52.94
710	07/30/19	EMParts	TT226019 Filter-Cab Air		EA	1.000	44.44	44.44
711	07/30/19	EMParts	TTDC221512 Filter-Fuel Secondary		EA	1.000	19.45	19.45
712	07/30/19	EMParts	TTDC221513 Filter-Oil		EA	1.000	26.28	26.28



# Work Order: 10129

---

Labour Total	0.00
Parts Total	333.49
Miscellaneous Total	0.00

## Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
391	06/21/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	2.000		

---

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
754	09/27/19	EMTime	Employee: 2395 Nickolas Schou		HRS	3.500		

---

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 4 Check and adjust t-case and differentials fluid levels

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
753	09/27/19	EMTime	Employee: 2395 Nickolas Schou		HRS	1.500		

---

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 5 T/S leak on steering cylinders

*Replaced hose fittings O-ring on cylinder.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
752	09/27/19	EMTime	Employee: 2395 Nickolas Schou		HRS	2.500		

---

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 6 Repaired weatherstripping on R/S of cab



# Work Order: 10129

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
751	09/27/19	EMTime	Employee: 2395 Nickolas Schou		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 7 Outsheet Inspection

*Found leaking O-Ring on steering cylinder, replaced and test-OK.  
Top up fuel.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
750	09/27/19	EMTime	Employee: 2338 Nolan MacGregor		HRS	3.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

<b>Labour Total</b>	<b>13.50</b>
<b>Parts Total</b>	<b>333.49</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

**Description:** Boost and check batteries 1127 HRS, GRO#5305 **Date Started:** 2020-05-06  
**Equipment:** E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate  
**Serial#:** B93A340DJ07204664

## Segment: 1 parts

## Segment: 2 Boost - check batteries and charging system - ok

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
571	05/06/20	PR	Employee: 2024 Travis Schmidt		HRS	1.000		
1394	05/06/20	PR	Employee: 2024 Travis Schmidt		HRS	-1.000		
1395	05/06/20	PR	Employee: 2024 Travis Schmidt		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00



# Work Order: 11070

<b>Labour Total</b>	<b>1.00</b>
<b>Parts Total</b>	<b>0.00</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

**Description:** Replace Hood Strut and PAS damaged hoses GRO#5033/5039 **Date Started:** 2020-06-09  
**Equipment:** E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate  
**Serial#:** B93A340DJ07204664

### Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1735	06/04/20	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-341294 Line: 1		EA	2.000	13.87	27.74
293	06/09/20	EMParts	191323 Strut-Hood		EA	1.000	131.25	131.25
4767	06/09/20	EMParts	191323 Strut-Hood		EA	-1.000	131.25	-131.25
			PO - Open - #1014672 - 10064 4.62"-4.94" TBOLT SP CLAMP		EA	2.00	13.87	27.74
						<b>Labour Total</b>	<b>0.00</b>	
						<b>Parts Total</b>	<b>55.48</b>	
						<b>Miscellaneous Total</b>	<b>0.00</b>	

### Segment: 2 R&R PAS damaged intake hoses and clamps

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1477	06/04/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
						<b>Labour Total</b>	<b>1.00</b>	
						<b>Parts Total</b>	<b>0.00</b>	
						<b>Miscellaneous Total</b>	<b>0.00</b>	

### Segment: 3 Diagnose no-code derate of power - clear codes and test

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1478	06/09/20	PR	Employee: 1266 Braden Bitzer		HRS	2.000		
						<b>Labour Total</b>	<b>2.00</b>	
						<b>Parts Total</b>	<b>0.00</b>	
						<b>Miscellaneous Total</b>	<b>0.00</b>	
						<b>Labour Total</b>	<b>3.00</b>	
						<b>Parts Total</b>	<b>55.48</b>	
						<b>Miscellaneous Total</b>	<b>0.00</b>	





# Work Order: 11218

<b>Description:</b> Inspection 350 Hour Service and Repairs	1293 Hours	<b>Date Started:</b> 2020-06-19
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	RD-2020-216 Insheet GRO-9114/9185/9256	
<b>Serial#:</b> B93A340DJ07204664		

## Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
121	08/07/20	EMParts	7T8890 Pump-Washer		EA	2.000	55.50	111.00
371	07/08/20	EMParts	AT256144 Seal-V-Ring		EA	1.000	3.30	3.30
372	07/08/20	EMParts	AT259780 Seal-Output		EA	1.000	0.00	0.00
1612	08/21/20	EMParts	Dyed Diesel Dyed Diesel		EA	29.900	0.70	20.93
1613	08/21/20	EMParts	Oil All Plus Hydraulic Oil 10W30		EA	22.000	16.10	354.10
1620	08/21/20	EMParts	TorqueGlide Torque-Glide Synthetic Auto-Tr		EA	2.000	15.39	30.77
1730	07/23/20	EMParts	2678715 Grommet-Washer Pump to Tank		EA	2.000	8.17	16.34
2170	06/25/20	EMParts	277687 Support Lining		EA	2.000	41.41	82.82
2171	06/25/20	EMParts	DC220029 Gasket-Oil Filler Cap		EA	1.000	10.67	10.67
2172	06/25/20	EMParts	RE171321 Filter-Fuel 30 Micron		EA	1.000	14.26	14.26
2173	06/25/20	EMParts	TT221379 Filter-Air Primary		EA	1.000	52.94	52.94
2174	06/25/20	EMParts	TT226019 Filter-Cab Air		EA	1.000	39.14	39.14
2175	06/25/20	EMParts	TTDC221512 Filter-Fuel Secondary		EA	1.000	25.63	25.63
2176	06/25/20	EMParts	TTDC221513 Filter-Oil		EA	1.000	26.28	26.28
2673	06/30/20	EMParts	191323 Strut-Hood		EA	1.000	131.25	131.25

Labour Total	0.00
Parts Total	919.43
Miscellaneous Total	0.00

## Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2064	06/19/20	PR	Employee: 2471 Greg Royer		HRS	2.000		
2419	06/19/20	PR	Employee: 2471 Greg Royer		HRS	-2.000		
2420	06/19/20	PR	Employee: 2471 Greg Royer		HRS	2.000		
3804	06/19/20	PR	Employee: 2471 Greg Royer		HRS	-2.000		
3805	06/19/20	PR	Employee: 2471 Greg Royer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2236	07/22/20	PR	Employee: 2528 Raymond Carlile		HRS	4.500		
2239	07/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		



# Work Order: 11218

2243 07/24/20 PR Employee: 2338 Nolan MacGregor HRS 2.500

---

Labour Total	9.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 4 350 Hour Service Check and Adjut Fluids

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2240	07/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2421	06/24/20	PR	Employee: 2395 Nickolas Schou		HRS	3.000		
2474	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
2726	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.500		
2727	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
3680	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.500		
3681	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
3806	06/24/20	PR	Employee: 2395 Nickolas Schou		HRS	-3.000		
3807	06/24/20	PR	Employee: 2395 Nickolas Schou		HRS	3.000		

---

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 5 Check and Repair Leaks

*Mid Diff. seeping wash and check.  
Hyd. Antenuator seeping wash and check.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
837	07/08/20	PR	Employee: 2395 Nickolas Schou		HRS	6.000		
838	07/09/20	PR	Employee: 2395 Nickolas Schou		HRS	7.500		
839	07/10/20	PR	Employee: 2395 Nickolas Schou		HRS	5.000		
1208	07/13/20	PR	Employee: 2395 Nickolas Schou		HRS	6.000		
1471	07/13/20	PR	Employee: 2395 Nickolas Schou		HRS	-6.000		
1472	07/13/20	PR	Employee: 2395 Nickolas Schou		HRS	6.000		
2234	07/13/20	PR	Employee: 2395 Nickolas Schou		HRS	-6.000		
2235	07/13/20	PR	Employee: 2395 Nickolas Schou		HRS	6.000		
2241	07/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
2244	07/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		
2423	06/25/20	PR	Employee: 2395 Nickolas Schou		HRS	2.000		
2475	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2728	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2729	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
3682	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
3683	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
3808	06/25/20	PR	Employee: 2395 Nickolas Schou		HRS	-2.000		
3809	06/25/20	PR	Employee: 2395 Nickolas Schou		HRS	2.000		



# Work Order: 11218

---

Labour Total	31.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 6 Repair Exhaust support

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2422	06/24/20	PR	Employee: 2395 Nickolas Schou		HRS	1.000		
2476	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2730	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2731	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
3684	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
3685	07/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		

---

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 7 T/S and Repair Codes

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2424	06/25/20	PR	Employee: 2395 Nickolas Schou		HRS	3.500		
3810	06/25/20	PR	Employee: 2395 Nickolas Schou		HRS	-3.500		
3811	06/25/20	PR	Employee: 2395 Nickolas Schou		HRS	3.500		
4148	06/30/20	PR	Employee: 2395 Nickolas Schou		HRS	6.000		
4376	06/30/20	PR	Employee: 2395 Nickolas Schou		HRS	-6.000		
4377	06/30/20	PR	Employee: 2395 Nickolas Schou		HRS	6.000		
4650	06/30/20	PR	Employee: 2395 Nickolas Schou		HRS	-6.000		
4651	06/30/20	PR	Employee: 2395 Nickolas Schou		HRS	6.000		

---

Labour Total	9.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 8 Replace P.A.S.S.

*shocker unit 24volt*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
3812	06/26/20	PR	Employee: 2395 Nickolas Schou		HRS	4.000		
4147	06/29/20	PR	Employee: 2395 Nickolas Schou		HRS	6.000		
4374	06/29/20	PR	Employee: 2395 Nickolas Schou		HRS	-6.000		
4375	06/29/20	PR	Employee: 2395 Nickolas Schou		HRS	6.000		
4648	06/29/20	PR	Employee: 2395 Nickolas Schou		HRS	-6.000		



# Work Order: 11218

4649 06/29/20 PR Employee: 2395 Nickolas Schou HRS 6.000

---

Labour Total	10.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 9 Decal

## Segment: 10 Outsheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2237	07/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		
2242	07/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		

---

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 11 Fix broken speaker

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2238	07/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		

---

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

---

<b>Labour Total</b>	<b>73.50</b>
<b>Parts Total</b>	<b>947.17</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

**Description:** R&R batteries 1358 HRS, GRO 5801 **Date Started:** 2020-12-03  
**Equipment:** E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate  
**Serial#:** B93A340DJ07204664

## Segment: 1 parts

4L WIPER FLUID

batteries replaced due to rush maintenance - 1x GX31A + CORE returned to stock inventory (still works good)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



# Work Order: 11742

66	12/03/20	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-349878 Line: EA	2.000	139.70	279.40	
67	12/03/20	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-349878 Line: EA	2.000	27.00	54.00	
551	09/16/21	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-362051 Line: EA	-1.000	27.00	-27.00	
603	09/17/21	EMParts	GX31A 12v Battery Top Post Group 31	EA	-1.000	166.70	-166.70

Labour Total	0.00
Parts Total	139.70
Miscellaneous Total	0.00

## Segment: 2 R&R batteries

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
140	12/03/20	PR	Employee: 1266 Braden Bitzer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

<b>Labour Total</b>	<b>2.00</b>
<b>Parts Total</b>	<b>167.44</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

**Description:** outsheet checkover - repair exhaust 1492 HRS; GRO 6092/6035/6494 **Date Started:** 2021-03-11  
**Equipment:** E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate  
**Serial#:** B93A340DJ07204664

## Segment: 1 parts

*\*\* recommend removal of DPF for 'proper' delete to avoid unknown future engine de-rate\*\**

4L X WIPER FLUID

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
644	03/11/21	EMParts	60/40 Rad-Cool Antifreeze		EA	4.000	6.27	25.09
2586	03/11/21	EMParts	X004482 Clamp-Exhaust 4"		EA	1.000	8.90	8.90

Labour Total	0.00
Parts Total	33.99
Miscellaneous Total	0.00

## Segment: 2 Outsheet checkover- top up fluids

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



# Work Order: 11955

756	03/11/21	PR	Employee: 1266 Braden Bitzer	HRS	1.500
1116	03/17/21	PR	Employee: 2395 Nickolas Schou	HRS	1.000

---

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

### Segment: 3 repair exhaust to bin with new rear clamp & adjust

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
757	03/11/21	PR	Employee: 1266 Braden Bitzer		HRS	1.000		

---

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

### Segment: 4 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
758	03/12/21	PR	Employee: 2216 Masin Schmidt		HRS	5.500		

---

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

### Segment: 5 Bolt down cab & Check transfer case level - ok

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1115	03/15/21	PR	Employee: 2024 Travis Schmidt		HRS	1.000		

---

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

---

<b>Labour Total</b>	<b>10.00</b>
<b>Parts Total</b>	<b>61.73</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

<b>Description:</b> Repairs oil leak	GRO-8685	<b>Date Started:</b> 2021-05-31
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	No hours reported	
<b>Serial#:</b> B93A340DJ07204664		



# Work Order: 12168

## Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
862	08/18/21	EMParts	3J1907 Seal-O-Ring		EA	1.000	1.58	1.58
						Labour Total	0.00	
						Parts Total	1.58	
						Miscellaneous Total	0.00	

## Segment: 2 Repair oil leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1136	05/28/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		
						Labour Total	2.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						<b>Labour Total</b>	<b>2.00</b>	
						<b>Parts Total</b>	<b>29.32</b>	
						<b>Miscellaneous Total</b>	<b>0.00</b>	

<b>Description:</b> 350 Hour Service <b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate <b>Serial#:</b> B93A340DJ07204664	Unit at CNRL GRO-8281 1641 Hours	<b>Date Started:</b> 2021-06-14
--	--	---------------------------------

## Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
345	06/14/21	EMParts	RE171321 Filter-Fuel 30 Micron		EA	1.000	14.46	14.46
346	06/14/21	EMParts	TT221379 Filter-Air Primary		EA	1.000	56.55	56.55
347	06/14/21	EMParts	TT226019 Filter-Cab Air		EA	1.000	42.21	42.21
348	06/14/21	EMParts	TTDC221512 Filter-Fuel Secondary		EA	1.000	22.62	22.62
349	06/14/21	EMParts	TTDC221513 Filter-Oil		EA	1.000	27.47	27.47
1094	07/30/21	EMParts	5W40 Spectra 5W40		I	28.000	5.22	146.13
						Labour Total	0.00	
						Parts Total	309.44	
						Miscellaneous Total	0.00	

## Segment: 2 350 Hour Service



# Work Order: 12202

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
962	06/16/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 T/S No start

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
963	06/16/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

<b>Labour Total</b>	<b>4.00</b>
<b>Parts Total</b>	<b>337.18</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

<b>Description:</b> T/S, Repair Air Leak and A/C	Unit at CNRL Site.	<b>Date Started:</b> 2021-07-26
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	GRO-8381 1767 hours	
<b>Serial#:</b> B93A340DJ07204664		

## Segment: 1 Parts

2 - 3/4" Hose clamps

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1252	07/29/21	AP	Vendor: 10132 Gregg Distributors LP 017-246219 Line: 1		EA	25.000	0.82	20.50

Labour Total	0.00
Parts Total	20.50
Miscellaneous Total	0.00

## Segment: 2 T/S and Repair Air Leak

Diagnose air leak. Can't find air leak. Supervisor shows me. Order new hose.  
Remove old hose & clamps & replace w/new hose.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1218	07/26/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		
1220	07/29/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		
1888	07/26/21	PR	Employee: 2611 Matthew Walter		HRS	-1.000		





# Work Order: 12321

1889 07/26/21 PR Employee: 2611 Matthew Walter HRS 1.000

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 T/S and Repair A/C

No A/C. Run unit. A/C not working.  
 - Check for coolant flap valve & working. Appears to be working.  
 - Plug off coolant lines w/pliers.  
 - A/C seems to be working. Unsure of issue but blows cold.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1219	07/26/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		
1890	07/26/21	PR	Employee: 2611 Matthew Walter		HRS	-1.000		
1891	07/26/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

<b>Labour Total</b>	<b>3.00</b>
<b>Parts Total</b>	<b>48.24</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

**Description:** 350 Hour Service Unit at CNRL Site. **Date Started:** 2021-08-31  
**Equipment:** E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate 1901 Hours  
**Serial#:** B93A340DJ07204664

## Segment: 1 Parts

Parts PO to WO

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1689	08/31/21	AP	Vendor: 10034 Brandt Tractor Ltd. 08 4871539 Line: 1		EA	1.000	174.80	174.80
1690	08/31/21	AP	Vendor: 10034 Brandt Tractor Ltd. 08 4871539 Line: 2		EA	1.000	138.98	138.98
1691	08/31/21	AP	Vendor: 10034 Brandt Tractor Ltd. 08 4871539 Line: 3		EA	1.000	40.00	40.00
1692	08/31/21	AP	Vendor: 10034 Brandt Tractor Ltd. 08 4871539 Line: 4		EA	1.000	21.01	21.01
1693	08/31/21	AP	Vendor: 10034 Brandt Tractor Ltd. 08 4871539 Line: 5		EA	1.000	36.88	36.88
1694	08/31/21	AP	Vendor: 10034 Brandt Tractor Ltd. 08 4871539 Line: 6		EA	4.000	33.13	132.52
59	08/03/22	EMParts	5W40 Spectra 5W40		I	30.000	5.92	177.64

Labour Total	0.00
Parts Total	721.83
Miscellaneous Total	0.00



# Work Order: 12393

## Segment: 2 350 Hour Service

- 350 Hour Service
- Replace oil & filter
- Fuel filters
- Cab filter
- Air filter
- Grease

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
146	09/01/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00
<b>Labour Total</b>	<b>2.00</b>
<b>Parts Total</b>	<b>749.57</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

<b>Description:</b> Check over unit and get running	Unit at OCL Yard	<b>Date Started:</b> 2022-02-17
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	Unit Picked up 1995 Hours	
<b>Serial#:</b> B93A340DJ07204664		

## Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
444	02/17/22	EMParts	RE171321 Filter-Fuel 30 Micron		EA	1.000	14.89	14.89
445	02/17/22	EMParts	TTDC221512 Filter-Fuel Secondary		EA	1.000	23.44	23.44
477	03/24/22	EMParts	207694 Filter-Fuel 10 Micron		EA	-1.000	19.84	-19.84
478	03/24/22	EMParts	TTDC221512 Filter-Fuel Secondary		EA	-1.000	26.12	-26.12
1037	07/28/22	EMParts	1231PMF Battery-12v Group 31(Top Post)		EA	2.000	130.95	261.90
1038	07/28/22	EMParts	5W40 Spectra 5W40		I	3.000	5.92	17.76

Labour Total	0.00
Parts Total	272.03
Miscellaneous Total	0.00

## Segment: 2 Check over unit and get running

- Replaced batteries, add fuel conditioner.
- Top up engine oils

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
763	03/08/22	PR	Employee: 2395 Nickolas Schou		HRS	1.500		



# Work Order: 12818

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00
<b>Labour Total</b>	<b>1.50</b>
<b>Parts Total</b>	<b>299.77</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

**Description:** R&R exhaust system & outsheet checkover  
**Equipment:** E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate  
**Serial#:** B93A340DJ07204664  
 1998 HRS, GRO  
 9760/9761/9762/9763/9767  
**Date Started:** 2022-03-16

**Segment: 1 parts**

1 X WAK33276 5" EXHAUST CLAMP

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1097	03/08/22	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-368054 Line: EA		EA	1.000	230.65	230.65
			2					
2157	03/03/22	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-367940 Line: EA		EA	1.000	96.88	96.88
			16					
2158	03/17/22	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-368365 Line: EA		EA	1.000	11.40	11.40
			3					
2159	03/17/22	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-368365 Line: EA		EA	1.000	11.40	11.40
			4					
83	05/10/22	EMParts	35775 "Exhaust Clamp 5""		EA	-1.000	11.40	-11.40
396	03/17/22	EMParts	33276 "Exhaust Clamp 5""		EA	1.000	32.89	32.89
397	03/17/22	EMParts	33274 "Exhaust Clamp 4""		EA	1.000	24.41	24.41
470	03/24/22	EMParts	207214 Isolator-Exhust Support		EA	2.000	44.71	89.42
471	03/24/22	EMParts	P158324 PreFilter-Dust Bowl		EA	1.000	60.36	60.36
941	03/22/22	EMParts	60/40 Rad-Cool Antifreeze		EA	2.000	6.27	12.54
942	03/22/22	EMParts	WWFluid Window Washer Fluid -35/-40C (208L drums added to tote)		EA	2.000	1.23	2.47

Labour Total	0.00
Parts Total	561.02
Miscellaneous Total	0.00

**Segment: 2 Remove DPF & modify exhaust system**

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
764	03/16/22	PR	Employee: 1266 Braden Bitzer		HRS	2.000		
765	03/17/22	PR	Employee: 1266 Braden Bitzer		HRS	6.000		
1983	03/22/22	PR	Employee: 1266 Braden Bitzer		HRS	2.500		
1989	03/24/22	PR	Employee: 1266 Braden Bitzer		HRS	0.500		



# Work Order: 12917

---

Labour Total	11.00
Parts Total	0.00
Miscellaneous Total	0.00

**Segment: 3 outsheet checkover**

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1984	03/22/22	PR	Employee: 1266 Braden Bitzer		HRS	2.000		
1990	03/24/22	PR	Employee: 1266 Braden Bitzer		HRS	0.500		

---

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

**Segment: 4 wash & shovel mudd out of box**

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1982	03/21/22	PR	Employee: 2392 Carmen Beck		HRS	3.500		
1985	03/22/22	PR	Employee: 1266 Braden Bitzer		HRS	2.000		
1987	03/23/22	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
1988	03/23/22	PR	Employee: 22 Garrett Nelson		HRS	4.000		
1991	03/24/22	PR	Employee: 22 Garrett Nelson		HRS	2.000		

---

Labour Total	12.50
Parts Total	0.00
Miscellaneous Total	0.00

**Segment: 5 fuel**

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1986	03/22/22	PR	Employee: 2392 Carmen Beck		HRS	1.000		

---

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

---

<b>Labour Total</b>	<b>27.00</b>
<b>Parts Total</b>	<b>588.76</b>
<b>Miscellaneous Total</b>	<b>0.00</b>



# Work Order: 13041

**Description:** R&R hydraulic oil with environmently friendly oil 2001 HRS, GRO 9920 **Date Started:** 2022-04-20  
**Equipment:** E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate  
**Serial#:** B93A340DJ07204664

## Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
908	04/20/22	EMParts	PFNZ4620 Hydraulic Fluid Biodegradable-PowerFlow No-Zinc (18.9L Pail)		EA	10.000	110.93	1,109.32
909	04/20/22	EMParts	TT222389 Filter-Hydraulic		EA	1.000	247.14	247.14
910	04/20/22	EMParts	5P1979 Seal-O-Ring		EA	1.000	10.82	10.82
911	04/20/22	EMParts	TT140744 Seal Kit		EA	1.000	121.97	121.97

Labour Total	0.00
Parts Total	1,489.25
Miscellaneous Total	0.00

## Segment: 2 R&R hydraulic oil with environmently friendly oil

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1793	04/20/22	PR	Employee: 1266 Braden Bitzer		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

<b>Labour Total</b>	<b>3.00</b>
<b>Parts Total</b>	<b>1,516.99</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

**Description:** Inspections and Repairs 2310 Hours **Date Started:** 2022-08-26  
**Equipment:** E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate RD-2022-228 Insheet RD-2022-248 Outsheet EM-2022-135 Outsheet  
**Serial#:** B93A340DJ07204664

## Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
169	10/12/22	EMParts	Oil All Plus Hydraulic Oil 10W30		EA	0.000	17.84	0.00
387	09/21/22	EMParts	140342 Seal-V-Ring		EA	1.000	9.40	9.40
388	09/21/22	EMParts	210737 Seal-Yoke , DS461 Output		EA	1.000	53.72	53.72
389	09/21/22	EMParts	TT207626 Plug-W/Magnet		EA	1.000	49.56	49.56



# Work Order: 13371

---

Labour Total	0.00
Parts Total	112.68
Miscellaneous Total	0.00

## Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1392	09/23/22	PR	Employee: 2471 Greg Royer		HRS	0.500		
1395	09/26/22	PR	Employee: 2471 Greg Royer		HRS	2.000		
2278	08/25/22	PR	Employee: 1575 Paul Nixon		HRS	2.000		

---

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 Wash and clean cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1393	09/23/22	PR	Employee: 2623 Brenton Woolman		HRS	3.500		

---

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 4 T/S and Repair leaks

*Leak at T-Fitting above R/H steering cylinder.*

*Upon further inspection, found that unit was just very dirty under cab and T fitting was in fact not leaking.*

*Found mid diff leaking where diff mounts onto axle housing. Remove final drive covers and axles, drain axle oil.*

*Remove front and rear drive shafts. Remove mid diff from axle housing, clean all mounting surfaces, remove studs and clean all threads. Reinstall studs with loctite.*

*Reinstall diff with new sealant, install drive shafts. Install final drive covers with new sealant. Let dry over night.*

*Fill axle to proper oil level with new oil. Check for leaks, none present.*

*-Paul*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1390	09/21/22	PR	Employee: 1575 Paul Nixon		HRS	5.500		
1391	09/22/22	PR	Employee: 1575 Paul Nixon		HRS	8.000		
1394	09/23/22	PR	Employee: 1575 Paul Nixon		HRS	2.500		

---

Labour Total	16.00
Parts Total	0.00
Miscellaneous Total	0.00



# Work Order: 13371

## Segment: 5 Remove extra beacon and harness

Unit had extra beacon mounted behind cab with harness run poorly through cab.

Remove harness and old/damaged beacon.

-Paul

<b>Labour Total</b>	<b>24.00</b>
<b>Parts Total</b>	<b>140.42</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

<b>Description:</b> Rental Return-Emsco	2310 Hours	<b>Date Started:</b> 2022-08-30
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	RD-2022-228 Insheet RD-2022-248 Outsheet EM-2022-135 Outsheet	
<b>Serial#:</b> B93A340DJ07204664		

## Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
168	10/12/22	EMParts	Oil All Plus Hydraulic Oil 10W30		EA	20.000	17.84	356.86
881	09/22/22	EMParts	208050 Mtg Headlight LHS RO		EA	1.000	277.12	277.12
882	09/22/22	EMParts	226685 Glass Mirror		EA	1.000	174.04	174.04
883	09/22/22	EMParts	Dyed Diesel Dyed Diesel		EA	22.710	1.54	34.97
884	09/22/22	EMParts	TT226019 Filter-Cab Air		EA	1.000	45.92	45.92
885	09/22/22	EMParts	X004482 Clamp-Exhaust 4" Flat		EA	1.000	8.90	8.90

<b>Labour Total</b>	<b>0.00</b>
<b>Parts Total</b>	<b>897.81</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

## Segment: 2 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
125	09/01/22	PR	Employee: 2623 Brenton Woolman		HRS	9.000		
2276	08/30/22	PR	Employee: 2623 Brenton Woolman		HRS	2.500		
2277	08/31/22	PR	Employee: 2623 Brenton Woolman		HRS	9.000		

<b>Labour Total</b>	<b>20.50</b>
<b>Parts Total</b>	<b>0.00</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

## Segment: 3 Repair plugs, lights and panels



**GCS Energy Services Ltd.**

# Work Order: 13383

Cab 12v plug-in loose and popping out.  
 R/H cab light out.  
 Backup Camera very scratched up.  
 Cab Air Filter plugged.  
 Clean Air Filter Bowls.  
 L/H Power mirror cracked/hole in it.  
 L/H Headlight cover damaged and has a hole in it.  
 H-Vac cover cut and scratched up.  
 Service over due alarm on monitor.

Remove dash panel to gain access to backside of 12V plug, threaded lock back into place.  
 Replace R/H cab light bulbs  
 Backup camera lens scratched but still works fine-Noted  
 Replaced cab air filter  
 Removed and cleaned engine air filter bowls  
 Remove and replace L/H power mirror glass  
 Remove and replace L/H headlight cover/bumper as it had a hole in it.  
 H-vac cover scratched, had paint touched up by Brenton.  
 Went into monitor and reset the service due alarm.  
 -Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1383	09/20/22	PR	Employee: 1575 Paul Nixon		HRS	1.000		
1386	09/21/22	PR	Employee: 1575 Paul Nixon		HRS	2.000		
1389	09/22/22	PR	Employee: 1575 Paul Nixon		HRS	1.000		
						Labour Total		4.00
						Parts Total		0.00
						Miscellaneous Total		0.00

## Segment: 4 Install missing exhaust clamp

Exhaust clamp missing on pipe from muffler to bin box heater.

Removed old damaged clamp and installed new clamp.  
 -Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1387	09/21/22	PR	Employee: 1575 Paul Nixon		HRS	0.500		
						Labour Total		0.50
						Parts Total		0.00
						Miscellaneous Total		0.00

## Segment: 5 Top up Fluids

Topped up hyd oil level (20L of Oil All Plus).  
 -Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1384	09/20/22	PR	Employee: 1575 Paul Nixon		HRS	0.500		





# Work Order: 13383

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 6 Remove renter decals

Removed all renter decals and numbers, cleaned off glue residue.  
-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1385	09/20/22	PR	Employee: 1575 Paul Nixon		HRS	1.000		
1388	09/21/22	PR	Employee: 1575 Paul Nixon		HRS	0.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

<b>Labour Total</b>	<b>27.00</b>
<b>Parts Total</b>	<b>925.55</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

<b>Description:</b> Inspections and Repairs	2415 Hours	<b>Date Started:</b> 2022-11-24
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	RD-2022-286 Insheet RD-2023-104 Outsheet	
<b>Serial#:</b> B93A340DJ07204664		

## Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
32	02/02/23	EMParts	221173 Seal-Lip Type (Input Yoke)		EA	1.000	56.02	56.02
331	02/14/23	EMParts	TorqueGlide Torque-Glide Synthetic Auto-Tr		EA	5.000	0.02	0.11
350	02/15/23	EMParts	Dyed Diesel Dyed Diesel		EA	16.660	1.39	23.17
562	12/16/22	EMParts	BS8000 Radar		EA	1.000	879.58	879.58

Labour Total	0.00
Parts Total	958.88
Miscellaneous Total	0.00

## Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
207	02/02/23	PR	Employee: 3063 Jordan Yasinski		HRS	2.000		
1273	11/23/22	PR	Employee: 1575 Paul Nixon		HRS	2.500		



# Work Order: 13676

---

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 Repair P.A.S.S.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
864	12/15/22	PR	Employee: 2873 Isaac Simpkin		HRS	1.000		

---

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 4 Repair Leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
208	02/02/23	PR	Employee: 3063 Jordan Yasinski		HRS	6.000		
863	12/13/22	PR	Employee: 2873 Isaac Simpkin		HRS	0.500		
865	12/15/22	PR	Employee: 2873 Isaac Simpkin		HRS	1.500		

---

Labour Total	8.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 5 Repair Gromets and A/C Cover

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
209	02/02/23	PR	Employee: 3063 Jordan Yasinski		HRS	0.500		
866	12/15/22	PR	Employee: 2873 Isaac Simpkin		HRS	0.500		

---

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 6 Install Radar

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
867	12/16/22	PR	Employee: 2873 Isaac Simpkin		HRS	3.500		
868	12/19/22	PR	Employee: 2873 Isaac Simpkin		HRS	5.500		



# Work Order: 13676

Labour Total	9.00
Parts Total	0.00
Miscellaneous Total	0.00
<b>Labour Total</b>	<b>23.50</b>
<b>Parts Total</b>	<b>986.62</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

<b>Description:</b> Rental Return Emsco	2415 Hours	<b>Date Started:</b> 2022-11-24
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	RD-2022-286 Insheet RD-2023-104 Outsheet	
<b>Serial#:</b> B93A340DJ07204664		

## Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2149	02/27/23	AP	Vendor: 10401 RBC Avion Visa Feb 23_L Dahl Line: 4		EA	1.000	199.99	199.99
2150	02/27/23	AP	Vendor: 10401 RBC Avion Visa Feb 23_L Dahl Line: 5		EA	1.000	50.00	50.00
33	12/02/22	EMParts	207166 Curtain-Wheel Well		EA	1.000	298.68	298.68
34	12/02/22	EMParts	208050 L/H Headlight/Bumper Cover		EA	1.000	277.12	277.12
35	12/02/22	EMParts	226685 Glass Mirror		EA	1.000	174.04	174.04
36	12/02/22	EMParts	TT226019 Filter-Cab Air		EA	1.000	55.22	55.22
37	12/02/22	EMParts	X004482 Clamp-Exhaust 4" Flat		EA	1.000	8.90	8.90
39	12/02/22	EMParts	Dyed Diesel Dyed Diesel		EA	17.410	1.28	22.34
53	02/02/23	EMParts	AT450372 Latch		EA	1.000	68.79	68.79
326	02/14/23	EMParts	VBV770M Monitor-Single Input		EA	1.000	523.43	523.43
327	02/14/23	EMParts	VBV791C Camera		EA	1.000	215.71	215.71
328	02/14/23	EMParts	VBVL405 Camera Cable 5m		EA	3.000	14.62	43.86
982	01/30/23	EMParts	191642 Bracket-Rear Camera Rock Truck		EA	1.000	78.07	78.07
			PO - Open - #1023919 - 10416 4 1/2" Hose		LS	0.00	0.00	60.84
						Labour Total	0.00	
						Parts Total	2,076.99	
						Miscellaneous Total	0.00	

## Segment: 2 Wash and Clean Cab

Unit is very dirty.  
Unit was smoked in.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1848	01/26/23	PR	Employee: 2623 Brenton Woolman		HRS	0.500		
1849	01/27/23	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
1850	01/30/23	PR	Employee: 2623 Brenton Woolman		HRS	6.000		
1851	01/31/23	PR	Employee: 2623 Brenton Woolman		HRS	7.500		



# Work Order: 13677

---

Labour Total	23.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 Repair Exhaust

*Exhaust broken out at the box to cab.  
Straighten Pivot Pipe.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
853	12/12/22	PR	Employee: 2873 Isaac Simpkin		HRS	2.500		

---

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 4 Clean air filter bowls and replace air hose

*Clean air filter bowls.  
Intercooler boot at P.A.S.S ripped, boost leak.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
855	12/13/22	PR	Employee: 2873 Isaac Simpkin		HRS	3.000		

---

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 5 Repair Radio, steps, belly pan, mirror and mud guards

*Radio seems to work but speakers do not. (Replaced Radio)  
L/F Bumper/headlight cover cracked.  
Engine belly pans bent up at hinges.  
Remove renters decals.  
Bottom L/H Step bent inwards.  
R/H Mirror has a piece broken/missing.  
L/H inner mud flap ripped and falling down.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
206	02/02/23	PR	Employee: 3063 Jordan Yasinski		HRS	1.000		
522	12/11/24	PR	Employee: 3119 Shawn Dittmer		HRS	1.000		
854	12/12/22	PR	Employee: 2873 Isaac Simpkin		HRS	2.000		
856	12/13/22	PR	Employee: 2873 Isaac Simpkin		HRS	3.500		
857	12/14/22	PR	Employee: 2873 Isaac Simpkin		HRS	7.500		



# Work Order: 13677

Labour Total	15.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 6 Replace removed factory Camera and monitor

Factory Mounted Camera and monitor were Removed by Customer.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
205	02/01/23	PR	Employee: 3063 Jordan Yasinski		HRS	2.000		
858	12/14/22	PR	Employee: 2873 Isaac Simpkin		HRS	1.500		
859	12/15/22	PR	Employee: 2873 Isaac Simpkin		HRS	6.000		
860	12/16/22	PR	Employee: 2873 Isaac Simpkin		HRS	3.500		
861	12/19/22	PR	Employee: 2873 Isaac Simpkin		HRS	4.000		
862	12/20/22	PR	Employee: 2873 Isaac Simpkin		HRS	8.500		

Labour Total	25.50
Parts Total	0.00
Miscellaneous Total	0.00

<b>Labour Total</b>	<b>69.50</b>
<b>Parts Total</b>	<b>2,104.73</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

<b>Description:</b> Replace Exhaust Flex Pipe and Grease Line	Unit at Hardisty Pit.	<b>Date Started:</b> 2023-04-25
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	Hours: 2577	
	Next service hours: 2927	
<b>Serial#:</b> B93A340DJ07204664	GRO#10707/10699/10727/10351/10445/10454	

## Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
225	06/06/23	AP	Vendor: 10338 Wajax Equipment 2023120066328 Line: 1		EA	1.000	99.98	99.98
393	05/16/23	AP	Vendor: 10338 Wajax Equipment 2023120057357 Line: 1		EA	1.000	322.03	322.03
1714	05/31/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-385323 Line: 1		LS	0.000	0.00	7.88
1715	05/31/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-385371 Line: 1		LS	0.000	0.00	60.16
2216	05/16/23	AP	Vendor: 10338 Wajax Equipment 2023120057357 Line: 2		EA	-1.000	322.03	-322.03
2217	05/16/23	AP	Vendor: 10338 Wajax Equipment 2023120057357 Line: 3		EA	1.000	322.03	322.03
2296	06/06/23	AP	Vendor: 10338 Wajax Equipment 2023120066328 Line: 2		EA	-1.000	99.98	-99.98
2297	06/06/23	AP	Vendor: 10338 Wajax Equipment 2023120066328 Line: 3		EA	1.000	99.98	99.98
27	01/03/24	EMParts	184728 Tube-Bin Cylinders		EA	-1.000	102.48	-102.48
36	06/01/23	EMParts	140115 Seal-O-Ring		EA	1.000	0.00	0.00
37	06/01/23	EMParts	140353 Seal-O-Ring		EA	1.000	0.00	0.00
38	06/01/23	EMParts	140416 Ring-Backup		EA	2.000	0.00	0.00
39	06/01/23	EMParts	140474 Seal-Rod		EA	1.000	0.00	0.00
40	06/01/23	EMParts	140613 Seal-Wiper		EA	1.000	0.00	0.00
41	06/01/23	EMParts	140618 Seal-Piston		EA	1.000	0.00	0.00
42	06/01/23	EMParts	140619 Ring-Wear		EA	2.000	0.00	0.00



# Work Order: 14035

43	06/01/23	EMParts	140634	Seal-U	EA	1.000	0.00	0.00
44	06/01/23	EMParts	140702	Ring-Wear	EA	2.000	0.00	0.00
47	05/02/23	EMParts	184631	Blk Pipe LH 5 R/Chass R/	EA	1.000	59.53	59.53
67	07/10/23	EMParts	100430	Pin-Cotter(3/16"x4")	EA	1.000	1.14	1.14
68	07/10/23	EMParts	140201	Seal-O-Ring	EA	1.000	0.60	0.60
90	05/03/23	EMParts	277749	Exhaust-Flex Pipe	EA	1.000	1,274.40	1,274.40
150	06/06/23	EMParts	210105	Indicator-Level	EA	1.000	40.48	40.48
189	06/07/23	EMParts	208320	Black Decal Hydraulic Leve	EA	1.000	73.31	73.31
465	05/18/23	EMParts	277749	Exhaust-Flex Pipe	EA	-1.000	1,603.03	-1,603.03
PO - Open - #1024706 - 10338 Black pipe top hyd tip B40					EA	1.00	99.98	99.98

Labour Total	0.00
Parts Total	333.98
Miscellaneous Total	0.00

## Segment: 2 Replace Grease Line

*-replace crushed grease line supplied by Red Deer*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2557	05/02/23	PR	Employee: 3103 Dallas Wood		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 Replace Exhaust Flex Pipe

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2558	05/02/23	PR	Employee: 3103 Dallas Wood		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 4 Repair Seat

*seat shock broken  
 -remove seat out of deere 350 rock truck  
 -remove seat, install 350 seat into Bell, install broken bell seat into deere 350*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2559	05/11/23	PR	Employee: 3103 Dallas Wood		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00



# Work Order: 14035

## Segment: 5 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
953	05/25/23	PR	Employee: 22 Garrett Nelson		HRS	2.000		
1964	06/01/23	PR	Employee: 22 Garrett Nelson		HRS	4.000		
Labour Total						6.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

## Segment: 6 Check over unit and order parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
952	05/24/23	PR	Employee: 3110 Callum Deditch		HRS	1.000		
1962	05/31/23	PR	Employee: 3110 Callum Deditch		HRS	10.000		
1965	06/01/23	PR	Employee: 3103 Dallas Wood		HRS	3.000		
Labour Total						14.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

## Segment: 7 Remove Steering Cylinder and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
954	05/26/23	PR	Employee: 2024 Travis Schmidt		HRS	1.000		
955	05/26/23	PR	Employee: 3110 Callum Deditch		HRS	5.000		
1959	05/29/23	PR	Employee: 3103 Dallas Wood		HRS	1.000		
1960	05/29/23	PR	Employee: 3110 Callum Deditch		HRS	2.000		
1961	05/30/23	PR	Employee: 3103 Dallas Wood		HRS	2.500		
Labour Total						11.50		
Parts Total						0.00		
Miscellaneous Total						0.00		

## Segment: 8 help with rock truck steering rams

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1963	05/31/23	PR	Employee: 2024 Travis Schmidt		HRS	1.500		



# Work Order: 14035

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00
<b>Labour Total</b>	<b>38.00</b>
<b>Parts Total</b>	<b>422.56</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

<b>Description:</b> Inspection, 4000 Hour and Repairs	3422 Hours	<b>Date Started:</b> 2023-11-21
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	RD-2023-318 Insheet RD-2024-178 Outsheet	
<b>Serial#:</b> B93A340DJ07204664		

## Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
434	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995111 Line: 2		EA	-2.000	128.95	-257.90
435	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995111 Line: 3		EA	2.000	132.95	265.90
436	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995075 Line: 1		EA	2.000	128.95	257.90
437	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995387 Line: 1		EA	-2.000	22.50	-45.00
490	01/16/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7255111.001 Line: 1		EA	2.000	44.52	89.04
1738	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995111 Line: 4		EA	2.000	128.95	257.90
1739	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995111 Line: 5		EA	-2.000	132.95	-265.90
1740	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995111 Line: 6		EA	-2.000	128.95	-257.90
1741	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995111 Line: 7		EA	2.000	132.95	265.90
1742	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995075 Line: 2		EA	-2.000	128.95	-257.90
1743	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995075 Line: 3		EA	2.000	128.95	257.90
1744	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995387 Line: 2		EA	2.000	22.50	45.00
1745	07/23/24	AP	Vendor: 10117 Fort Garry Industries Ltd. F1995387 Line: 3		EA	-2.000	22.50	-45.00
109	04/09/24	EMParts	Dyed Diesel Dyed Diesel		EA	34.070	1.28	43.57
189	01/11/24	EMParts	T116789 Seal-O-Ring		EA	2.000	3.80	7.60
206	01/12/24	EMParts	DC221650 Valve Cover Gasket W/Filler		EA	1.000	32.85	32.85
207	01/12/24	EMParts	DC221651 Valve Cover Gasket		EA	5.000	16.41	82.05
270	06/14/24	EMParts	5W40 Spectra 5W40		I	30.000	7.70	231.05
271	06/14/24	EMParts	60/40 Rad-Cool Antifreeze		EA	25.000	6.38	159.40
272	06/14/24	EMParts	Oil All Hydraulic Oil 10W30		EA	327.000	3.98	1,300.50
273	06/14/24	EMParts	TorqueGlide Torque-Glide Synthetic Auto-Tr		EA	35.000	19.51	682.85
808	11/21/23	EMParts	100430 Pin-Cotter(3/16"x4")		EA	1.000	1.14	1.14
809	11/21/23	EMParts	140115 Seal-O-Ring(5A33D97A8N70)		EA	1.000	3.84	3.84
810	11/21/23	EMParts	140201 Seal-O-Ring		EA	1.000	0.60	0.60
811	11/21/23	EMParts	140353 Seal-O-Ring(4AOD100AON70)		EA	1.000	3.72	3.72
812	11/21/23	EMParts	140416 Ring-Backup(D97 79xD108.47 N90)		EA	2.000	3.15	6.29
813	11/21/23	EMParts	140474 Seal-Rod(70x85.5x6-N)		EA	1.000	63.00	63.00
814	11/21/23	EMParts	140613 Seal-Wiper(70x82.6x8)		EA	1.000	34.16	34.16
815	11/21/23	EMParts	140618 Seal-Piston(110x89x7)		EA	1.000	73.44	73.44
816	11/21/23	EMParts	140619 Ring-Wear(W/Band Piston D110x1)		EA	2.000	20.49	40.98
817	11/21/23	EMParts	140634 Seal-U(70x80x11.4 T2)		EA	1.000	36.40	36.40
818	11/21/23	EMParts	140702 Ring-Wear(W/Band Rod D70x25xT5)		EA	2.000	36.49	72.98
819	11/21/23	EMParts	220010 Filter-Hydraulic/WDB		EA	3.000	13.26	39.79
820	11/21/23	EMParts	221669 Blk Breather filter 1mic		EA	1.000	53.50	53.50
821	11/21/23	EMParts	2465010 Filter-Air Secondary		EA	1.000	138.21	138.21
822	11/21/23	EMParts	P550127 Filter-Fuel / Breather		EA	6.000	12.86	77.16
823	11/21/23	EMParts	RE171321 Filter-Fuel 30 Micron		EA	1.000	27.78	27.78





# Work Order: 14526

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
824	11/21/23	EMParts	TT226019 Filter-Cab Air	EA		1.000	63.32	63.32
825	11/21/23	EMParts	TTDC221512 Filter-Fuel Secondary	EA		1.000	36.42	36.42
887	11/22/23	EMParts	2465009 Filter-Air Primary	EA		1.000	71.60	71.60
888	11/22/23	EMParts	5P1979 Seal-O-Ring	EA		1.000	14.18	14.18
			PO - Open - #1027909 - 10117 GA31S Battery	EA		2.00	128.95	257.90
			PO - Open - #1027909 - 10117 GA31S battery return credit	EA		-2.00	128.95	-257.90
			PO - Open - #1027909 - 10117 GA31A battery	EA		2.00	132.95	265.90
			PO - Open - #1027909 - 10117 Core return	EA		-2.00	22.50	-45.00
						Labour Total	0.00	
						Parts Total	6,165.97	
						Miscellaneous Total	0.00	

## Segment: 2 Inspections

*Outsheet inspection.  
 Top up fluids (T-Case, trans, rear diff)  
 Clean air filter bowls  
 Bolt down cab  
 Air up middle RH tire, tighten valve stem  
 Pictures and park unit up front.  
 -Paul*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1355	05/30/24	PR	Employee: 3103 Dallas Wood		HRS	1.500		
						Labour Total	1.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

## Segment: 3 Wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
638	07/09/24	PR	Employee: 2623 Brenton Woolman		HRS	0.500		
639	07/09/24	PR	Employee: 3103 Dallas Wood		HRS	2.000		
						Labour Total	2.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

## Segment: 4 Repair Leaks

*Steel Line for box cylinders bent.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
776	01/12/24	PR	Employee: 3103 Dallas Wood		HRS	1.000		
778	01/15/24	PR	Employee: 3103 Dallas Wood		HRS	4.500		



# Work Order: 14526

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 5 4000 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
775	01/11/24	PR	Employee: 3103 Dallas Wood		HRS	8.500		
777	01/12/24	PR	Employee: 3103 Dallas Wood		HRS	6.500		
779	01/15/24	PR	Employee: 3103 Dallas Wood		HRS	4.000		
781	01/17/24	PR	Employee: 3103 Dallas Wood		HRS	4.000		

Labour Total	23.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 6 Repair Panels, exhaust, line and Batteries

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
652	05/17/24	PR	Employee: 3109 Cameron Ellsworth		HRS	0.500		
780	01/16/24	PR	Employee: 3103 Dallas Wood		HRS	5.000		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 7 Repair flat tire

<b>Labour Total</b>	<b>38.00</b>
<b>Parts Total</b>	<b>6,354.53</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

<b>Description:</b> Rental Return Emsco	3422 Hours	<b>Date Started:</b> 2023-11-21
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	RD-2023-318 Insheet RD-2024-178 Outsheet	
<b>Serial#:</b> B93A340DJ07204664		

## Segment: 1 Parts

## Segment: 2 Wash and Clean Cab

*Unit is very dirty.*



# Work Order: 14527

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
651	05/17/24	PR	Employee: 2623 Brenton Woolman		HRS	8.000		
1353	05/28/24	PR	Employee: 2623 Brenton Woolman		HRS	5.500		
1354	05/29/24	PR	Employee: 2623 Brenton Woolman		HRS	5.500		
						Labour Total		19.00
						Parts Total		0.00
						Miscellaneous Total		0.00

### Segment: 3 Repair mudflaps and Decals

R/H mudflap ripped a bit can be rebolted.  
Remove renters decals at rear of unit.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
774	01/16/24	PR	Employee: 3103 Dallas Wood		HRS	0.500		
						Labour Total		0.50
						Parts Total		0.00
						Miscellaneous Total		0.00
						<b>Labour Total</b>		<b>19.50</b>
						<b>Parts Total</b>		<b>409.46</b>
						<b>Miscellaneous Total</b>		<b>0.00</b>

<b>Description:</b> Inspection, 350 Hour Service & Repair Broken I	Unit at BlackRod Site moved to Red Deer Shop.	<b>Date Started:</b> 2024-09-12
<b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate	3705 Hours	
<b>Serial#:</b> B93A340DJ07204664	GRO# 10365	
	RD-2024-212 Insheet	
	RD-2024-219 Outsheet	

### Segment: 1 Parts

- (1) 218241 Light Housing-Used
- (1) Fuel Tank/DEF Plate 200.00(Kodiak Inv#16879)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
810	10/29/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7602438.001 Line: 1		LS	0.000	0.00	14.58
811	10/24/24	AP	Vendor: 21901 Kodiak Global 16879 Line: 1		EA	1.000	200.00	200.00
1248	10/28/24	AP	Vendor: 33285 Northland Radiator Service Ltd. 211316 Line: 1		LS	0.000	0.00	256.95
1325	09/26/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7565572.001 Line: 1		EA	1.000	42.70	42.70
15	11/01/24	EMParts	BN016976 Gasket-Synthetic Fuel Tank Cov		EA	1.000	157.41	157.41
17	10/02/24	EMParts	277957 HeadLight Dust Cover		EA	1.000	212.97	212.97
101	11/12/24	EMParts	5W40 Spectra Xtreme 5W40 (CK-4)		I	32.000	7.81	249.97
150	09/12/24	EMParts	AT256886 Nut-Flanged		EA	1.000	20.91	20.91
151	09/12/24	EMParts	AT257099 Seal-O-Ring(3x85mm N70)		EA	1.000	2.82	2.82
152	09/12/24	EMParts	DC140041 Seal-Dust PTO		EA	1.000	18.34	18.34



# Work Order: 15073

Line	Date	Source	Part Description	UM	Qty	Price	Total
153	09/12/24	EMParts	DC221206 Ring Bearing-Pto	EA	1.000	255.06	255.06
154	09/12/24	EMParts	TT140911 Lip Seal-Viton(57x72x8mm DBL)	EA	1.000	7.86	7.86
155	09/12/24	EMParts	TT290419 Drive Shaft - PTO	EA	1.000	311.57	311.57
233	09/17/24	EMParts	DC100433 Nut-PTO	EA	1.000	40.94	40.94
234	09/17/24	EMParts	DC140158 Seal-Timing Gear Cover	EA	1.000	93.11	93.11
235	09/17/24	EMParts	AT257091 Seal-O-Ring	EA	1.000	41.84	41.84
236	09/17/24	EMParts	TT140912 Seal-O-Ring	EA	1.000	97.56	97.56
243	09/18/24	EMParts	208051 R/H Headlight/Bumper Cover	EA	1.000	277.24	277.24
244	09/18/24	EMParts	226127 Lens-Headlight R/H	EA	1.000	92.96	92.96
245	09/18/24	EMParts	TT207832 Cover-Headlight Frame	EA	1.000	57.02	57.02
255	09/18/24	EMParts	100430 Pin-Cotter(3/16"x4")	EA	1.000	1.14	1.14
256	09/18/24	EMParts	140115 Seal-O-Ring(5A33D97A8N70)	EA	1.000	0.80	0.80
257	09/18/24	EMParts	140201 Seal-O-Ring	EA	1.000	1.45	1.45
258	09/18/24	EMParts	140353 Seal-O-Ring(4AOD100AON70)	EA	1.000	3.98	3.98
259	09/18/24	EMParts	140416 Ring-Backup(D97 79xD108.47 N90)	EA	2.000	1.97	3.95
260	09/18/24	EMParts	140474 Seal-Rod(70x85.5x6-N)	EA	1.000	46.68	46.68
261	09/18/24	EMParts	140613 Seal-Wiper(70x82.6x8)	EA	1.000	33.25	33.25
262	09/18/24	EMParts	140618 Seal-Piston(110x89x7)	EA	1.000	30.80	30.80
263	09/18/24	EMParts	140619 Ring-Wear(W/Band Piston D110x1	EA	2.000	23.50	47.00
264	09/18/24	EMParts	140634 Seal-U(70x80x11.4 T2)	EA	1.000	26.61	26.61
265	09/18/24	EMParts	140702 Ring-Wear(W/Band Rod D70x25xT5	EA	2.000	30.79	61.58
481	09/19/24	EMParts	A4572340105 Shaft-PTO	EA	1.000	219.32	219.32
482	09/19/24	EMParts	DC150118 Bearing-PTO	EA	1.000	227.82	227.82
483	09/19/24	EMParts	DC150120 Bearing-PTO	EA	1.000	174.18	174.18
484	09/19/24	EMParts	N005412200006 Bearing-PTO	EA	1.000	134.74	134.74
496	09/20/24	EMParts	DC221512 Filter-Fuel Secondary	EA	1.000	31.24	31.24
497	09/20/24	EMParts	DC221513 Filter-Oil	EA	1.000	30.50	30.50
498	09/20/24	EMParts	RE171321 Filter-Fuel 30 Micron	EA	1.000	26.50	26.50
499	09/20/24	EMParts	TT221379 Filter-Air Primary	EA	1.000	73.35	73.35
500	09/20/24	EMParts	TT226019 Filter-Cab Air	EA	1.000	64.68	64.68
554	09/23/24	EMParts	AT255736 Washer	EA	2.000	7.67	15.34
575	09/25/24	EMParts	AT257088 Seal-Dust	EA	1.000	18.48	18.48
576	09/25/24	EMParts	TTDC222109 Gasket-Crankcase Vent	EA	1.000	63.44	63.44
592	09/26/24	EMParts	DC221614 Dipstick-Engine Oil	EA	1.000	222.55	222.55
			PO - Open - #1028342 - 10416 hose assembly	EA	1.00	42.70	42.70
			PO - Open - #1028436 - 21901 Fuel Tank Cover Plate	EA	1.00	200.00	200.00
					Labour Total	0.00	
					Parts Total	4,253.89	
					Miscellaneous Total	0.00	

## Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
258	11/06/24	PR	Employee: 3103 Dallas Wood		HRS	2.500		
399	09/11/24	PR	Employee: 3103 Dallas Wood		HRS	2.500		
						Labour Total	5.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

## Segment: 3 Wash and Clean Cab



# Work Order: 15073

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
256	11/04/24	PR	Employee: 2623 Brenton Woolman		HRS	8.500		
257	11/05/24	PR	Employee: 2623 Brenton Woolman		HRS	3.000		
						Labour Total		11.50
						Parts Total		0.00
						Miscellaneous Total		0.00

## Segment: 4 Repair Broken PTO Driveshaft

*PTO Shaft broke at u-joint and bent Shaft on PTO Drive.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
648	10/15/24	PR	Employee: 3108 Zachary Dean		HRS	9.000		
816	09/16/24	PR	Employee: 3108 Zachary Dean		HRS	4.500		
817	09/17/24	PR	Employee: 3108 Zachary Dean		HRS	1.500		
818	09/18/24	PR	Employee: 2623 Brenton Woolman		HRS	1.000		
819	09/19/24	PR	Employee: 3103 Dallas Wood		HRS	0.500		
820	09/19/24	PR	Employee: 3108 Zachary Dean		HRS	7.000		
821	09/20/24	PR	Employee: 3103 Dallas Wood		HRS	8.500		
823	09/23/24	PR	Employee: 3103 Dallas Wood		HRS	6.000		
825	09/25/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
						Labour Total		47.50
						Parts Total		0.00
						Miscellaneous Total		0.00

## Segment: 5 Repair Panels, lights

*R/H Headlight smashed.  
Front grille, bumper dented-pressed against cooler.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
650	10/22/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
651	10/23/24	PR	Employee: 3108 Zachary Dean		HRS	7.000		
652	10/24/24	PR	Employee: 3108 Zachary Dean		HRS	4.500		
653	10/25/24	PR	Employee: 3108 Zachary Dean		HRS	1.500		
822	09/20/24	PR	Employee: 3103 Dallas Wood		HRS	1.000		
824	09/24/24	PR	Employee: 3108 Zachary Dean		HRS	8.000		
						Labour Total		31.50
						Parts Total		0.00
						Miscellaneous Total		0.00

## Segment: 6 Repair Leaks



**GCS Energy Services Ltd.**

# Work Order: 15073

*R/H Steering Cylinder Leaking.  
 Exhaust Clamp has hole in it.  
 Hose coming off valve is sweating (Port B O-Ring)  
 Hydraulic Hose off last pump is rubbed to metal.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
649	10/16/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
1330	10/28/24	PR	Employee: 3108 Zachary Dean		HRS	5.000		
1331	10/29/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
1332	10/30/24	PR	Employee: 3108 Zachary Dean		HRS	5.000		

Labour Total	29.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 7 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
826	09/26/24	PR	Employee: 3108 Zachary Dean		HRS	4.500		

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

<b>Labour Total</b>	<b>129.00</b>
<b>Parts Total</b>	<b>4,663.35</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

**Description:** Repair Exhaust and Leaks      849 Hours      **Date Started:** 2017-09-11  
**Equipment:** E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate      RD-2017-285 Insheet  
 Rental Return - Netook Construction  
 No Charges as per Jennifer Email  
**Serial#:** B93A340DJ07204664

## Segment: 1 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
173	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 2 Reindex exhaust flex hose and straighten guide



# Work Order: Z10014

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
174	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 Check top up all axle oil levels, adj. tire pressures

6L- 75W-90  
5L- Wiper fluid

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
175	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 4 Check wiper reservoir and repair leak

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
176	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 5 R&R PASS and replaced ripped boot

3"- 5" air to air tube

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
177	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 6 Outsheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
178	01/07/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		



# Work Order: Z10014

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 7 Top Up Hyd. oil , remove fire extg.

15L - Oil all plus

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
179	01/07/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

<b>Labour Total</b>	<b>9.00</b>
<b>Parts Total</b>	<b>652.16</b>
<b>Miscellaneous Total</b>	<b>0.00</b>

**Description:** Inspections and Repairs      785 Hours      **Date Started:** 2018-01-10  
**Equipment:** E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate      RD-2017-271 Insheet  
**Serial#:** B93A340DJ07204664

## Segment: 1 Parts

- 2.5 L 75W-90
- 5L Washer fluid
- 13L DEF
- 1 - TT226019 - Cab air filter
- 1 - TT221379 - Primary air filter
- 4 - BL277687 - Lining F

## Segment: 2 Insheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
284	01/10/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 3 Top up fluids, fix washer pump

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------





# Work Order: Z10025

285      01/10/18   EMTime      Employee: 1575 Paul Nixon      HRS      1.500

---

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 4 Replace eng. primary air filter and cab air filter

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
286	01/10/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.500		

---

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 5 Remove exhaust flex pipe, reinstall hw and guide rod

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
287	01/10/18	EMTime	Employee: 1575 Paul Nixon		HRS	2.000		

---

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 6 Check all fluid levels

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
288	01/10/18	EMTime	Employee: 1575 Paul Nixon		HRS	2.000		

---

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

## Segment: 7 Filled up DEF fluid tank, grease unit

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
289	01/10/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.000		

---

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00



# Work Order: Z10025

## Segment: 8 Outsheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
290	01/10/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		
						Labour Total		1.50
						Parts Total		0.00
						Miscellaneous Total		0.00

## Segment: 9 Washed and cleaned cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
291	01/10/18	EMTime	Employee: 1074 Jack Lougheed		HRS	10.000		
						Labour Total		10.00
						Parts Total		0.00
						Miscellaneous Total		0.00
						<b>Labour Total</b>		<b>20.50</b>
						<b>Parts Total</b>		<b>652.16</b>
						<b>Miscellaneous Total</b>		<b>0.00</b>

<b>Description:</b> Inspections, 1000 Hour Service and Repairs <b>Equipment:</b> E597 Bell B40D 40 Tonne Articulated Dump Truck w/End Gate <b>Serial#:</b> B93A340DJ07204664	Missing GRO's 729 Hours RD-2017-206 Insheet	<b>Date Started:</b> 2017-05-10
--	---	---------------------------------

## Segment: 1 Parts and Service



# Work Order: Z10115

- 1-AT338873 Transmission Dipstick Kit (657.00ea)
- 1-AT256393 Seal (10.37ea)
- 1-Quick Drain Kit (77.50ea)
- 2-Grease Wips (30.97ea)
- 2-277687 Lining (28.81ea)
- 1-277686 Support (66.65ea)
- 1-TT221379 Air Filter
- 1-TT221378 Air Filter
- 1-TT226019 Cab Air Filter
- 1-TTDC221513 Oil Filter
- 1-RE171321 Fuel Filter
- 1-TTDC221512 Fuel Filter
- 1-1261815 Fuel Tank Breather
- 1-227782 DEF Filter
- 1-TT222389 Hyd Return Filter
- 1-5P1979 O-Ring
- 1-227951 Lip Seal
- 1-TT222219 Transfer Case Filter
- 1-AL260130 Transmission Filter Kit
- 6-P550127 Breathers
- 1-TTDC222053 Crankcase Breather
- 3-P551551 Breather/Filter15L-50/50 Coolant
- 15L-Torque Glide

## Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
568	02/26/19	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		
						Labour Total		2.00
						Parts Total		0.00
						Miscellaneous Total		0.00

## Segment: 3 Top Up Coolant

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
567	02/26/19	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		
						Labour Total		0.50
						Parts Total		0.00
						Miscellaneous Total		0.00

## Segment: 4 Top up Fluids and Grease Unit

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
565	02/26/19	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		



# Work Order: Z10115

---

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

**Segment: 5 Install Grease Wips and Bolt Down Cab**

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
564	02/26/19	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

---

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

**Segment: 6 1000 Hour Service**

NO GRO

**Segment: 7 Install Transmission Dipstick Kit**

NO GRO

**Segment: 8 Install Engine Quick Drain**

NO GRO

**Segment: 9 Outsheet Inspection**

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
566	02/26/19	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		

---

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

---

<b>Labour Total</b>	<b>5.00</b>
<b>Parts Total</b>	<b>652.16</b>
<b>Miscellaneous Total</b>	<b>0.00</b>