



Work Order: 12591

EB10-70

Description: Inspections and Repairs	4970 Hours	Date Started: 2021-11-15
Equipment: E594 Caterpillar 930K Wheel Loader	RD-2021-295 Insheet RD-2021-302 Outsheet	
Serial#: CAT0930KERHN00564		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2010	11/16/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947846217 Line: 1		EA	1.000	123.88	123.88
2011	11/16/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947846217 Line: 2		EA	1.000	177.95	177.95
2012	11/16/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947846217 Line: 4		EA	1.000	51.21	51.21
2013	11/18/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947850592 Line: 1		EA	1.000	286.45	286.45
2017	11/16/21	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6374117.001 Line: 1		EA	8.000	63.94	511.52
2019	11/18/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947852407 Line: 1		EA	1.000	188.25	188.25
2020	11/19/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 985033360 Line: 1		EA	-1.000	286.45	-286.45
2296	11/18/21	AP	Vendor: 10132 Gregg Distributors LP 059-409016 Line: 2		LS	0.000	0.00	27.00
261	11/15/21	EMParts	1231PMF Battery-12v Group 31(Top Post)		EA	4.000	129.95	519.80
262	11/15/21	EMParts	Dyed Diesel Dyed Diesel		EA	47.700	1.02	48.89
569	11/18/21	EMParts	3471668 Camera		EA	1.000	923.23	923.23
593	08/15/22	EMParts	H3-24V-70W H3 24V 70W Halogen Bulb		EA	1.000	3.75	3.75
594	08/15/22	EMParts	Dyed Diesel Dyed Diesel		EA	59.056	1.54	91.15
813	10/20/22	EMParts	Dyed Diesel Dyed Diesel		EA	-47.700	1.54	-73.45

Labour Total	0.00
Parts Total	2,593.18
Miscellaneous Total	0.00

Segment: 2 Insheet and Outsheet Inspections

Add 12.6 G diesel (47.06 L).
Unit came with key, spill kit & fire extinguisher.
Insheet.
Add fuel.
Unit came with fire extinguisher, spill kit & key.
No unit number on forks or bucket.
Adjusted tire pressures in shop. Removed battery covers.

Outsheet Inspection.
- Run machine.
- Check fluids.
- Check lights. RH low beam out (replace).
- Check Repairs.
- Add fuel & conditioner.
- Get pictures.
- Grease.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
855	11/15/21	PR	Employee: 2471 Greg Royer		HRS	2.500		



GCS Energy Services Ltd.

Work Order: 12591

1032 11/19/21 PR Employee: 2611 Matthew Walter HRS 2.500

Labour Total	5.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
863	11/18/21	PR	Employee: 2623 Brenton Woolman		HRS	7.500		
866	11/19/21	PR	Employee: 2623 Brenton Woolman		HRS	2.500		

Labour Total	10.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair Doors, seats, panels and Decals

- No unit number on forks or bucket.
- Buckets overflow. Deflector bent. No side bits.
- Forks lock pin missing handle on right fork.
- Back up camera does not work. (blue screen).
- Stay back decals need replacing.
- Seat is ripped.
- Tires are weather cracked. Adjusted pressures. (55psi front) (50psi rear).
- Need a new operators manual.
- Right side compartment rear strut lock broken.
- Intake dust bowl needs cleaning.
- Cab door latch tough to open. Adjust or lube.
- Compartment latches/handles need lube.
- Hydraulic lock switch in cab & attachment release switch not legible.
- Battery box cover has a broken bolt.
- Remove old stay back decals and install new.
- Cut broken bolt off and put for battery box lid. Weld new nut.
- Cleaned out intake dust bowl.
- Replaced right side compartment strut with lock.
- Removed front wheel fenders.
- Diag no back up camera. Found camera to be failed.
- Install new fork lock pin.
- Pull forks into shop and weld unit number on.
- Pull bucket into shop to do the same. Prep.
- Weld unit number on bucket.
- Install new back-up camera on unit and test. Camera works correctly. Install correct sized fuse in camera terminal. Install grill trim and secure wires.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
856	11/15/21	PR	Employee: 2471 Greg Royer		HRS	1.000		
858	11/16/21	PR	Employee: 2471 Greg Royer		HRS	1.000		
860	11/17/21	PR	Employee: 2471 Greg Royer		HRS	3.000		
864	11/18/21	PR	Employee: 2471 Greg Royer		HRS	1.500		



Work Order: 12591

Labour Total	6.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Replace Batteries

- Attachment lock cylinder hoses weathered, cracked & damaged.
- Tilt cylinder leaking. (not leaking).
- Right side aux coupler hose rubbing. Adjust/add protection.
- Oil build up around front diff input yoke. (Grease/leak from other).
- Rear diff slightly over filled.
- Left & right side batteries leaking/corroding. Replace.
- Verify source of leaks. Tilt cylinder and accumulator valve.
- Replaced batteries on left & right side. Cleaned terminals. Cleaned up work area.
- Removed old aux hard lines. Measured out new hose length needed. Fab up bulk head brackets and weld onto existing brackets. Install bulkhead and coupler fittings.
- Removed 6 weathered, damaged, dd hoses to be sent out for attachment/release/lock pin cylinders.
- Remove, re-seal, reinstall adjustable valve going to accumulators.
- Install new hoses for attachment release cylinders. Also installed new aux hoses with new clamps.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
857	11/15/21	PR	Employee: 2471 Greg Royer		HRS	3.000		
859	11/16/21	PR	Employee: 2471 Greg Royer		HRS	4.000		
861	11/17/21	PR	Employee: 2471 Greg Royer		HRS	2.000		

Labour Total	9.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 T/S and Repair Leaks

- Silver adjustable valve going to accumulators leaking. (Clean/verify).
- Hydraulic pump off gear train leaking at mount flange. (monitor).
- Fan motor shaft seal starting to seep. (monitor).

Segment: 7 T/S Engine idle surge

- Engine has a surge at low idle.
- Research possible fuel issues causing engine surge. Removed fuel pump suction solenoid and replaced with new. Plug in computer and complete fuel pump calibration. Pull unit out and verify repair. Unit is performing much better with no surging.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
867	11/19/21	PR	Employee: 2471 Greg Royer		HRS	3.500		



Work Order: 12591

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Install tire chains

- Install tire chains.
- Install tire chains and tensioners. Test and adjust as needed.
- Moved front fence out further.
- Tighten up tire chain tensioners as needed and tire wire boomers. Pull unit out and operational test everything. C
- Clear up work area and paperwork.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
862	11/17/21	PR	Employee: 2471 Greg Royer		HRS	5.500		
865	11/18/21	PR	Employee: 2471 Greg Royer		HRS	2.000		

Labour Total	7.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	41.50
Parts Total	2,593.18
Miscellaneous Total	0.00

Description: 250 Hour Service	Unit at Hargreaves Site.	Date Started: 2022-02-24
Equipment: E594 Caterpillar 930K Wheel Loader	5423 Hours.	
Serial#: CAT0930KERHN00564		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
54	08/02/22	EMParts	5W40 Spectra 5W40		I	18.750	5.92	111.02
651	02/25/22	EMParts	2229020 Filter-Air Primary		EA	1.000	37.21	37.21
652	02/25/22	EMParts	3391048 Kit-Crankcase Breather		EA	1.000	38.55	38.55
653	02/25/22	EMParts	3535058 Filter-Cab Air		EA	1.000	39.33	39.33
654	02/25/22	EMParts	3608960 Filter-Fuel		EA	1.000	20.42	20.42
655	02/25/22	EMParts	3622915 Seal-Breather		EA	1.000	29.39	29.39
656	02/25/22	EMParts	3657606 Filter-Cab Air		EA	1.000	40.49	40.49
657	02/25/22	EMParts	4621171 Filter-Oil		EA	1.000	14.67	14.67
658	02/25/22	EMParts	4794131 Filter-Fuel/Water		EA	1.000	30.51	30.51

Labour Total	0.00
Parts Total	361.59
Miscellaneous Total	0.00

Segment: 2 250 Hour Service



Work Order: 12842

250 Hour Service.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
238	03/02/22	PR	Employee: 2395 Nickolas Schou		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Adjust tire chains

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1981	03/20/22	PR	Employee: 2395 Nickolas Schou		HRS	3.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	5.50
Parts Total	361.59
Miscellaneous Total	0.00

Description: 250 Hour Service and Hydraulic issue	Unit at Hargreaves BC Site.	Date Started: 2022-07-07
Equipment: E594 Caterpillar 930K Wheel Loader	5644 Hours	
	Unit Hipped to Red Deer	
Serial#: CAT0930KERHN00564		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
74	07/07/22	EMParts	2229020 Filter-Air Primary		EA	1.000	37.21	37.21
75	07/07/22	EMParts	3535058 Filter-Cab Air		EA	1.000	35.82	35.82
76	07/07/22	EMParts	3608960 Filter-Fuel		EA	1.000	20.47	20.47
77	07/07/22	EMParts	3657606 Filter-Cab Air		EA	1.000	33.49	33.49
78	07/07/22	EMParts	4621171 Filter-Oil		EA	1.000	14.35	14.35
79	07/07/22	EMParts	4794131 Filter-Fuel/Water		EA	1.000	30.55	30.55
589	07/27/22	EMParts	5W40 Spectra 5W40		I	18.000	5.92	106.58
1125	07/30/22	EMParts	3597245 Valve Gp		EA	1.000	280.16	280.16
1126	07/30/22	EMParts	3736989 Valve GP		EA	1.000	86.71	86.71

Labour Total	0.00
Parts Total	645.34
Miscellaneous Total	0.00

Segment: 2 250 Hour Service



Work Order: 13243

250 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
859	07/13/22	PR	Employee: 2395 Nickolas Schou		HRS	2.500		
						Labour Total		2.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 3 T/S loader hyd. issues, no lift

Unit had low lift power when warm. Ran through troubleshooting tree and diagnosed relief valve failure in hydraulic valve bank. Awaiting part for install.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
668	09/13/22	PR	Employee: 2395 Nickolas Schou		HRS	3.500		
860	07/18/22	PR	Employee: 2395 Nickolas Schou		HRS	7.500		
1377	09/27/22	PR	Employee: 2623 Brenton Woolman		HRS	7.500		
1378	09/28/22	PR	Employee: 2623 Brenton Woolman		HRS	6.500		
						Labour Total		25.00
						Parts Total		0.00
						Miscellaneous Total		0.00
						Labour Total		27.50
						Parts Total		645.34
						Miscellaneous Total		0.00

Description:	Inspections, 4000 Hour Service, New Tires and	5797 Hours	Date Started:	2022-10-13
Equipment:	E594 Caterpillar 930K Wheel Loader	RD-2022-289 Insheet		
		RD-2024-167 Insheet		
		RD-2024-190 Outsheets		
Serial#:	CAT0930KERHN00564			

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
80	05/01/24	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949922268 Line: 1		EA	1.000	53.91	53.91
465	05/21/24	AP	Vendor: 10407 Onsite Machining Solutions Ltd. 5430 Line: 1		LS	0.000	0.00	1,341.61
599	12/06/22	AP	Vendor: 32626 North Country Tire Distributors E266768 Line: 1		EA	4.000	1,953.78	7,815.12
657	06/28/24	AP	Vendor: 10132 Gregg Distributors LP 059-657806 Line: 1		EA	1.000	39.54	39.54
1247	05/06/24	AP	Vendor: 10407 Onsite Machining Solutions Ltd. 5400 Line: 1		LS	0.000	0.00	255.00
1304	06/28/24	AP	Vendor: 10132 Gregg Distributors LP 059-657806 Line: 2		EA	-1.000	39.54	-39.54
1305	06/28/24	AP	Vendor: 10132 Gregg Distributors LP 059-657806 Line: 3		EA	1.000	39.54	39.54
1511	05/01/24	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949922268 Line: 2		EA	-1.000	53.91	-53.91
1512	05/01/24	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949922268 Line: 3		EA	1.000	53.91	53.91
1535	05/01/24	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949922268 Line: 2		EA	1.000	53.91	53.91



GCS Energy Services Ltd.

Work Order: 13537

1536	05/01/24	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949922268 Line: 2	EA	-1.000	53.91	-53.91
1700	02/02/23	AP	Vendor: 10321 Union Tractor Ltd. 040-227371 Line: 2	EA	1.000	242.76	242.76
1701	02/16/23	AP	Vendor: 10321 Union Tractor Ltd. 040-227561 Line: 1	EA	-1.000	234.87	-234.87
1943	04/29/24	AP	Vendor: 10401 RBC Avion Visa Apr 24_P Nixon Line: 5	EA	1.000	43.29	43.29
2425	12/06/22	AP	Vendor: 10321 Union Tractor Ltd. 040-226769 Line: 1	EA	1.000	234.87	234.87
5	05/01/24	EMParts	3691255 Tensioner, belt	EA	1.000	227.93	227.93
12	02/01/23	EMParts	Dyed Diesel Dyed Diesel	EA	140.060	1.28	179.69
14	02/01/23	EMParts	4T8091 Cutting Edge Corner end 1"T	EA	1.000	98.03	98.03
41	12/02/22	EMParts	2229020 Filter-Air Primary	EA	1.000	9.75	9.75
42	12/02/22	EMParts	2229021 Filter-Air Secondary	EA	1.000	82.00	82.00
43	12/02/22	EMParts	3535058 Filter-Cab Air	EA	1.000	85.31	85.31
44	12/02/22	EMParts	3657606 Filter-Cab Air	EA	1.000	81.43	81.43
45	12/02/22	EMParts	3931101 Strainer-Fuel	EA	1.000	54.13	54.13
47	12/02/22	EMParts	1446691 Filter-Hydraulic/Transmission	EA	1.000	129.38	129.38
48	12/02/22	EMParts	3481861 Filter-Hydraulic/Transmission	EA	1.000	48.08	48.08
51	01/09/23	EMParts	350101CK High back seat cover	EA	1.000	234.87	234.87
52	01/09/23	EMParts	7M8485 Seal-O-Ring	EA	1.000	2.87	2.87
77	01/10/23	EMParts	3508936 Solenoid	EA	4.000	401.44	1,605.76
125	01/11/23	EMParts	1924491 Disc	EA	3.000	35.80	107.40
126	01/11/23	EMParts	1924492 Ball	EA	3.000	0.81	2.43
127	01/11/23	EMParts	2807870 Gasket	EA	2.000	37.28	74.56
128	01/11/23	EMParts	3081838 Seal kit	EA	1.000	75.96	75.96
129	01/11/23	EMParts	3496064 Seal Kit	EA	4.000	130.26	521.04
130	01/11/23	EMParts	3736992 Seal Kit	EA	3.000	113.77	341.31
131	01/11/23	EMParts	3737041 Seal Kit	EA	3.000	40.62	121.86
132	01/11/23	EMParts	6V5138 Seal	EA	3.000	2.24	6.72
133	01/11/23	EMParts	6V8400 Seal-O-Ring Face -20	EA	1.000	3.30	3.30
180	03/08/24	EMParts	4T8091 Cutting Edge Corner end 1"T X 6.25"W X 13.5"L; 2 hole	EA	1.000	63.01	63.01
207	08/19/24	EMParts	TO4 Spectra Xtreme TO-4 MG All Season 10W30	EA	3.000	6.82	20.46
314	07/22/24	EMParts	3801887 Flasher As	EA	1.000	292.26	292.26
616	06/27/24	EMParts	1173787 Knob-Retaining	EA	2.000	4.39	8.78
617	06/27/24	EMParts	3470794 Lamp Assembly-Dome	EA	1.000	85.94	85.94
760	07/26/24	EMParts	TO4 Spectra Xtreme TO-4 MG All Sea	EA	59.000	6.82	402.29
761	07/26/24	EMParts	Dyed Diesel Dyed Diesel	EA	75.710	1.28	96.83
837	04/24/24	EMParts	2229020 Filter-Air Primary	EA	1.000	20.43	20.43
838	04/24/24	EMParts	2229021 Filter-Air Secondary	EA	1.000	64.22	64.22
863	04/25/24	EMParts	3391048 Kit-Crankcase Breather	EA	1.000	65.46	65.46
864	04/25/24	EMParts	3622915 Seal-Breather	EA	1.000	41.36	41.36
865	04/25/24	EMParts	3481861 Filter-Hydraulic/Transmission	EA	1.000	80.63	80.63
866	04/25/24	EMParts	1446691 Filter-Hydraulic/Transmission	EA	1.000	51.75	51.75
906	04/25/24	EMParts	5016695 Seal Kit	EA	1.000	329.35	329.35
907	04/25/24	EMParts	5016697 Seal Kit	EA	1.000	413.55	413.55
909	04/26/24	EMParts	2242263 Valve - Dust	EA	1.000	45.04	45.04
910	04/26/24	EMParts	3508742 Belt	EA	1.000	127.45	127.45
911	04/26/24	EMParts	4532020 Seal Kit	EA	1.000	521.18	521.18
912	04/26/24	EMParts	618531 bearing- driveshaft	EA	1.000	253.33	253.33
			PO - Open - #1027471 - 10111 cat hydraulic oil additive	EA	1.00	53.91	53.91
			PO - Open - #1027478 - 10407 disassemble 2 wheel loaders cylinders and ins	LS	0.00	0.00	1,341.61
			PO - Open - #1027478 - 10407 prep one pump shaft for spray weld	LS	0.00	0.00	255.00
			PO - Open - #1027749 - 10132 1-1/2 x 8-1/2 Hitch Pin	EA	1.00	39.54	39.54

Labour Total 0.00

Parts Total 18,575.76

Miscellaneous Total 0.00

Segment: 2 Inspections



Work Order: 13537

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1122	07/25/24	PR	Employee: 3108 Zachary Dean		HRS	3.000		
1218	04/24/24	PR	Employee: 3110 Callum Deditch		HRS	2.500		
2417	11/28/22	PR	Employee: 3063 Jordan Yasinski		HRS	6.000		
2164	01/27/23	AP	Vendor: 10401 RBC Avion Visa Jan 23_L Dahl Line: 29		LS	0.000	0.00	804.00
						Labour Total		11.50
						Parts Total		804.00
						Miscellaneous Total		0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1203	06/27/24	PR	Employee: 2623 Brenton Woolman		HRS	3.000		
						Labour Total		3.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 4 T/S and Repair weak hydraulics

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
455	12/02/22	PR	Employee: 1575 Paul Nixon		HRS	4.500		
456	12/05/22	PR	Employee: 1575 Paul Nixon		HRS	4.000		
788	01/20/23	PR	Employee: 1575 Paul Nixon		HRS	4.000		
849	12/12/22	PR	Employee: 1575 Paul Nixon		HRS	1.500		
850	12/13/22	PR	Employee: 1575 Paul Nixon		HRS	5.000		
1214	04/19/24	PR	Employee: 3110 Callum Deditch		HRS	0.500		
1215	04/22/24	PR	Employee: 3110 Callum Deditch		HRS	5.000		
1216	04/23/24	PR	Employee: 3110 Callum Deditch		HRS	8.500		
1219	04/24/24	PR	Employee: 3110 Callum Deditch		HRS	1.000		
1220	04/25/24	PR	Employee: 3110 Callum Deditch		HRS	2.500		
1846	01/25/23	PR	Employee: 1575 Paul Nixon		HRS	1.000		
1847	01/26/23	PR	Employee: 1575 Paul Nixon		HRS	4.000		
2259	01/03/23	PR	Employee: 1575 Paul Nixon		HRS	3.000		
2260	01/04/23	PR	Employee: 1575 Paul Nixon		HRS	2.000		
2261	01/05/23	PR	Employee: 1575 Paul Nixon		HRS	5.000		
						Labour Total		51.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 5 Repair panels/steps/hinges



Work Order: 13537

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1221	04/25/24	PR	Employee: 3110 Callum Deditch		HRS	1.500		
1224	04/26/24	PR	Employee: 3110 Callum Deditch		HRS	3.500		
1500	04/29/24	PR	Employee: 3110 Callum Deditch		HRS	8.500		
2418	11/28/22	PR	Employee: 3063 Jordan Yasinski		HRS	1.000		

Labour Total 14.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 6 Install fuel screen

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
789	01/20/23	PR	Employee: 1575 Paul Nixon		HRS	1.000		

Labour Total 1.00

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 7 Replace bucket cutting edge

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
837	02/13/23	PR	Employee: 2873 Isaac Simpkin		HRS	2.500		

Labour Total 2.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 8 4000 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
121	07/03/24	PR	Employee: 2623 Brenton Woolman		HRS	2.500		
308	05/03/24	PR	Employee: 3110 Callum Deditch		HRS	2.000		
1222	04/25/24	PR	Employee: 3110 Callum Deditch		HRS	3.000		

Labour Total 7.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 9 Repair leaks



Work Order: 13537

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
307	05/02/24	PR	Employee: 3110 Callum Deditch		HRS	4.000		
1217	04/23/24	PR	Employee: 3103 Dallas Wood		HRS	2.500		
1223	04/25/24	PR	Employee: 3103 Dallas Wood		HRS	1.500		

Labour Total	8.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Repair driveline bearings

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
306	05/01/24	PR	Employee: 3110 Callum Deditch		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 11 T/S and Repair Codes

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
120	07/02/24	PR	Employee: 3108 Zachary Dean		HRS	5.000		
122	07/05/24	PR	Employee: 3108 Zachary Dean		HRS	8.000		
635	07/11/24	PR	Employee: 3108 Zachary Dean		HRS	3.000		
636	07/16/24	PR	Employee: 3108 Zachary Dean		HRS	2.000		
1121	07/22/24	PR	Employee: 3108 Zachary Dean		HRS	3.500		
1199	06/24/24	PR	Employee: 3108 Zachary Dean		HRS	6.000		
1200	06/25/24	PR	Employee: 3108 Zachary Dean		HRS	2.500		
1201	06/26/24	PR	Employee: 3108 Zachary Dean		HRS	9.500		
1202	06/27/24	PR	Employee: 3108 Zachary Dean		HRS	5.000		

Labour Total	44.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	146.50
Parts Total	19,379.76
Miscellaneous Total	0.00



Work Order: 15299

Description: Reg Maintenance	GRO13753/13764	Date Started: 2025-04-07
Equipment: E594 Caterpillar 930K Wheel Loader	5961 hours April 2025	
Serial#: CAT0930KERHN00564		

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
39	04/07/25	EMParts	27004 Beacon-Xenon 3 Bolt		EA	1.000	300.00	300.00

Labour Total	0.00
Parts Total	300.00
Miscellaneous Total	0.00

Segment: 2 Complete In-Sheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
273	04/07/25	PR	Employee: 3119 Shawn Dittmer		HRS	4.000		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Replace rotating light

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
274	04/10/25	PR	Employee: 3119 Shawn Dittmer		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	5.00
Parts Total	1,990.06
Miscellaneous Total	0.00

