



Work Order: 12101

EB10-75

Description: Inspections 2007 Hours. Date Started: 2021-04-30
 Equipment: E660 Caterpillar 349F Excavator Longstick 45'6"
 Serial#: CAT0349FVHPD20046

Segment: 1 Perform inspection on unit

Has fire extinguisher.
 Tooth & straight-cut edge buckets.
 Washed

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1973	04/26/21	PR	Employee: 2611 Matthew Waller		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Description: 250 Hours Service CNRL Date Started: 2021-06-10
 Equipment: E660 Caterpillar 349F Excavator Longstick 45'6" GRO-8692/8343
 Serial#: CAT0349FVHPD20046 2180/2431 Hours

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
560	08/13/21	EMParts	5W40 Spectra 5W40		I	40.000	5.22	208.76
775	05/25/21	EMParts	1421340 Filter-Air Primary		EA	1.000	70.65	70.65
776	05/25/21	EMParts	1R0749 Filter-Fuel Advanced Efficiency		EA	2.000	19.78	39.56
777	05/25/21	EMParts	1R1808 Filter-Oil Advanced Efficiency		EA	1.000	30.83	30.83
778	05/25/21	EMParts	3261643 Filter-Fuel Advanced Efficiency		EA	1.000	39.11	39.11
779	05/25/21	EMParts	3276618 Filter-Cab Air		EA	1.000	31.73	31.73
780	05/25/21	EMParts	3639402 Filter-Cab Air		EA	1.000	32.78	32.78
863	08/18/21	EMParts	5W40 Spectra 5W40		I	40.500	5.22	211.37

Labour Total	0.00
Parts Total	664.79
Miscellaneous Total	0.00

Segment: 2 250 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



Work Order: 12188

714	07/16/21	PR	Employee: 2611 Matthew Walter	HRS	2.000
1895	05/31/21	PR	Employee: 2611 Matthew Walter	HRS	2.500

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair broken cab window

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
713	07/15/21	PR	Employee: 2611 Matthew Walter		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	5.00
Parts Total	664.79
Miscellaneous Total	0.00

Description: *** Duplicate from 12188 - DO NOT USE ***	CNRL	Date Started: 2021-06-10
Equipment: E660 Caterpillar 349F Excavator Longstick 45'6"		
Serial#: CAT0349FVHPD20046		

Segment: 1 Parts

Segment: 2 250 Hours Service

Labour Total	0.00
Parts Total	0.00
Miscellaneous Total	0.00

Description: 250 Hour Service	Unit at CNRL Site	Date Started: 2021-08-26
Equipment: E660 Caterpillar 349F Excavator Longstick 45'6"	2618 Hours.	
Serial#: CAT0349FVHPD20046		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
15	08/02/22	EMParts	5W40 Spectra 5W40		I	38.000	5.92	225.01
1194	08/27/21	EMParts	1421340 Filter-Air Primary		EA	1.000	48.31	48.31



Work Order: 12387

1195	08/27/21	EMParts	1R0749 Filter-Fuel Advanced Efficiency	EA	2.000	19.24	38.48
1196	08/27/21	EMParts	1R1808 Filter-Oil Advanced Efficiency	EA	1.000	30.50	30.50
1197	08/27/21	EMParts	3261643 Filter-Fuel Advanced Efficiency	EA	1.000	38.98	38.98
1198	08/27/21	EMParts	3276618 Filter-Cab Air	EA	1.000	21.56	21.56
1199	08/27/21	EMParts	3639402 Filter-Cab Air	EA	1.000	23.69	23.69

Labour Total	0.00
Parts Total	426.53
Miscellaneous Total	0.00

Segment: 2 250 Hour Service

- 250 Hour Service*
- Change engine oil & filter
 - Fuel filters
 - Air filters
 - Cab filters
 - Check hyd.gearbox off engine
 - Grease

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
149	09/01/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	2.00
Parts Total	426.53
Miscellaneous Total	0.00

Description: Inspections and Repairs	GRO-9349/11872/11873/11893	Date Started: 2021-10-25
Equipment: E660 Caterpillar 349F Excavator Longstick 45'6"	2712 Hours	
Serial#: CAT0349FVHPD20046	RD-2021-282 Insheet	
	EM-2021-107 Outsheets	

Segment: 1 Parts

- 2 - jugs of DEF*
1 - jug washer fluid

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1114	10/25/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947798132 Line: 4	EA	1.000	813.57		813.57
1115	10/25/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947798132 Line: 5	EA	1.000	893.25		893.25
1116	10/25/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947798132 Line: 6	EA	1.000	69.06		69.06
1117	10/26/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947799804 Line: 2	EA	1.000	64.00		64.00
1118	10/26/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947799804 Line: 3	EA	1.000	45.88		45.88



Work Order: 12517

1143	10/26/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947799803 Line: 1	EA	1.000	651.62	651.62
1144	10/27/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947803101 Line: 1	EA	1.000	127.03	127.03
2017	11/02/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 985029416 Line: 1	EA	-1.000	64.00	-64.00
2018	11/02/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 985029416 Line: 2	EA	-1.000	45.88	-45.88
2430	10/25/21	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6350361.001 Line: 1	LS	0.000	0.00	182.88
57	11/03/21	EMParts	4487682 Grease Seal-Split(400 Series)	EA	1.000	67.20	67.20
622	11/19/21	EMParts	5W40 Spectra 5W40	I	0.500	6.47	3.23
714	10/25/21	EMParts	Dyed Diesel Dyed Diesel	EA	206.300	1.02	211.44

Labour Total	0.00
Parts Total	3,019.28
Miscellaneous Total	0.00

Segment: 2 Insheet and Outsheet Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
175	11/02/21	PR	Employee: 2395 Nickolas Schou		HRS	2.500		
929	10/22/21	PR	Employee: 1575 Paul Nixon		HRS	2.500		
1265	10/22/21	PR	Employee: 1575 Paul Nixon		HRS	-2.500		
1266	10/22/21	PR	Employee: 1575 Paul Nixon		HRS	2.500		

Labour Total	5.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab/Paint

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
174	11/01/21	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
176	11/02/21	PR	Employee: 2623 Brenton Woolman		HRS	8.000		
177	11/03/21	PR	Employee: 2623 Brenton Woolman		HRS	1.500		
930	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		
1267	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	-1.500		
1268	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		
2150	10/27/21	PR	Employee: 2623 Brenton Woolman		HRS	1.500		
2151	10/28/21	PR	Employee: 2623 Brenton Woolman		HRS	8.000		
2152	10/29/21	PR	Employee: 2623 Brenton Woolman		HRS	10.500		

Labour Total	40.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 T/S and Repair Leaks



Work Order: 12517

Hydraulic pump splitter box oil low-not on dipstick.
 R/H Swing motor dipstick wet at threads into gear box.
 Suspect on L/H line at base boom closest to cab o-ring leaking.
 L/H rear line on rotary manifold leaking at crimp.
 Both lines on front of L/H Swing motor leaking at crimps.
 No Aux. Couplers.
 Top up washer fluid and test.
 Missing Grease ring on end of stick R/H Side.
 No Fuel Screen.
 DEF Low.
 Check Ether Bottle

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
931	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	2.500		
1269	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	-2.500		
1270	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	2.500		
1275	10/26/21	PR	Employee: 2611 Matthew Walter		HRS	3.500		
						Labour Total		6.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 5 Repair doors, seats, panels and decals

Remove extra decals.
 Safety whip missing on pilot lever.
 Tidy up camera and radar wiring.
 Replace front wiper.
 Remove tape from radar boxes.
 Remove R from unit #
 Bottom R/H Corner of front window looks like its missing something.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
932	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	4.500		
1271	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	-4.500		
1272	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	4.500		
1276	10/26/21	PR	Employee: 2611 Matthew Walter		HRS	2.500		
						Labour Total		7.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 6 T/S and Repair P.A.S.S.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
933	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		
1273	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	-1.500		
1274	10/25/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		



Work Order: 12517

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 T/S and Repair Stick contacting boom

Segment: 8 Check and Adjust Track Tension

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1277	10/26/21	PR	Employee: 2611 Matthew Walter		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	60.50
Parts Total	3,019.28
Miscellaneous Total	0.00

Description: Inspections and Repairs Equipment: E660 Caterpillar 349F Excavator Longstick 45'6" Serial#: CAT0349FVHPD20046	3712 Hours RD-2022-145 Insheet RD-2022-120 Outsheets	Date Started: 2022-04-07
---	--	---------------------------------

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1153	07/20/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 985096386 Line: 1		EA	-8.000	7.98	-63.84
1154	07/20/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 985096386 Line: 2		EA	-8.000	1.36	-10.88
2023	07/08/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 948396603 Line: 1		EA	2.000	4.49	8.98
2024	07/08/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 948396603 Line: 2		EA	2.000	1.93	3.86
2025	07/08/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 948396603 Line: 3		EA	2.000	5.31	10.62
2026	07/08/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 948396603 Line: 4		EA	1.000	2.17	2.17
2027	07/08/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 948396603 Line: 5		EA	1.000	2.53	2.53
2028	07/11/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 948400731 Line: 1		EA	2.000	668.67	1,337.34
2029	07/11/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 948400731 Line: 2		EA	2.000	1,776.66	3,553.32
2030	07/11/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 948400731 Line: 3		EA	1.000	26.47	26.47
2031	07/11/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 948400731 Line: 4		EA	1.000	18.52	18.52
25	07/06/22	EMParts	2264755 Seal-Front Crankshaft		EA	1.000	116.63	116.63
26	07/06/22	EMParts	2552272 Seal Group-Duo Cone		EA	1.000	596.95	596.95



Work Order: 12983

27	07/06/22	EMParts	4958959 Nut-Track	EA	8,000	1.36	10.88
28	07/06/22	EMParts	4S5924 Seal-O-Ring	EA	1,000	22.33	22.33
29	07/06/22	EMParts	6T2638 Bolt-Track	EA	8,000	7.98	63.84
30	07/06/22	EMParts	8C5240 Seal-O-Ring	EA	1,000	24.78	24.78

Labour Total	0.00
Parts Total	5,724.50
Miscellaneous Total	0.00

Segment: 2 Insheet and Outsheet inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
695	04/07/22	PR	Employee: 1575 Paul Nixon		HRS	2.000		
880	07/13/22	PR	Employee: 2471 Greg Royer		HRS	2.000		
881	07/13/22	PR	Employee: 2915 Scott Scrivener		HRS	1.500		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Washand Clean Cabs

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
696	04/08/22	PR	Employee: 2623 Brenton Woolman		HRS	2.000		
697	04/11/22	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
698	04/12/22	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
699	04/13/22	PR	Employee: 2623 Brenton Woolman		HRS	2.000		
882	07/13/22	PR	Employee: 2623 Brenton Woolman		HRS	1.500		
884	07/14/22	PR	Employee: 2623 Brenton Woolman		HRS	9.000		

Labour Total	33.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 T/S and Repair Leaks

Front Main Crank Seal Leaking.
Oil Pan/Valve cover sweating, not enough to fix yet.
Upper/Lower radiator hose at water pump leaking-Tighten
L/H Final Drive duo cone seal leaking badly.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
311	07/05/22	PR	Employee: 2471 Greg Royer		HRS	1.000		
312	07/06/22	PR	Employee: 2471 Greg Royer		HRS	9.000		
313	07/08/22	PR	Employee: 2471 Greg Royer		HRS	9.500		
878	07/11/22	PR	Employee: 2471 Greg Royer		HRS	9.500		



Work Order: 12983

879	07/12/22	PR	Employee: 2471 Greg Royer	HRS	8.500
883	07/13/22	PR	Employee: 2471 Greg Royer	HRS	1.000

Labour Total	38.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Add unit numbers to bucket's

Labour Total	77.50
Parts Total	5,724.50
Miscellaneous Total	0.00

Description: Rental Return Emsco	3712 Hours	Date Started: 2022-04-07
Equipment: E660 Caterpillar 349F Excavator Longstick 45'6"	RD-2022-145 Insheet RD-2022-120 Outsheets	
Serial#: CAT0349FVHPD20046		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
148	07/08/22	AP	Vendor: 33133 633515 Alberta Ltd o/a Lockhart Oilfield Services		LS	0.000	0.00	250.00
			21075 Line: 1					
23	07/06/22	EMParts	3276618 Filter-Cab Air		EA	1.000	19.29	19.29
24	07/06/22	EMParts	3639402 Filter-Cab Air		EA	1.000	22.81	22.81

Labour Total	0.00
Parts Total	292.10
Miscellaneous Total	0.00

Segment: 2 Wash and Clean Cab

Segment: 3 Install Counter Weights

Lockhart Oilfield Services Inv#21075 (250.00) to torque counter weight Hardware.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
307	07/06/22	PR	Employee: 1575 Paul Nixon		HRS	2.000		
309	07/07/22	PR	Employee: 2471 Greg Royer		HRS	1.000		
876	07/11/22	PR	Employee: 2395 Nickolas Schou		HRS	1.500		



Work Order: 12984

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair Panels, tubes and valves

Bucket Cylinder Gouged.
 R/H Aux line valve on end of stick square shaft bent.
 Mechanics wire on muffler.
 Both Aux Valves on bottom of stick smashed back and tubes bent.
 Right front bottom corner of cab dented in.
 Replace Cab Airs Filters.
 Tool Box Step Bent.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
308	07/06/22	PR	Employee: 2471 Greg Royer		HRS	0.500		
310	07/07/22	PR	Employee: 2471 Greg Royer		HRS	8.500		
877	07/12/22	PR	Employee: 2471 Greg Royer		HRS	1.000		

Labour Total	10.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	14.50
Parts Total	292.10
Miscellaneous Total	0.00

Description: Inspections and Repairs	5551 Hours	Date Started: 2023-08-29
Equipment: E660 Caterpillar 349F Excavator Longstick 45'6"	RD-2023-267 Insheet RD-2024-179 Outsheet	
Serial#: CAT0349FVHPD20046		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
341	11/08/23	AP	Vendor: 10132 Gregg Distributors LP 059-594173 Line: 1		EA	1.000	196.66	196.66
620	06/12/24	AP	Vendor: 10508 Red Deer Fasteners & Tools Ltd. H78749 Line: 1		EA	6.000	16.79	100.74
727	11/10/23	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7192940.001 Line: 1		EA	1.000	35.96	35.96
979	10/18/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949503656 Line: 3		EA	1.000	419.27	419.27
980	10/18/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949503656 Line: 4		EA	2.000	462.97	925.94
999	10/20/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949508896 Line: 3		EA	1.000	442.28	442.28
1014	10/24/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949516200 Line: 1		EA	4.000	19.60	78.40
1015	10/24/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949516200 Line: 2		EA	20.000	0.27	5.40
1016	10/24/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949516188 Line: 1		EA	1.000	93.72	93.72
1017	10/24/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949516188 Line: 2		EA	1.000	75.96	75.96



Work Order: 14288

1018	10/24/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949516188 Line: 3	EA	1.000	1,793.15	1,793.15
1064	11/16/23	AP	Vendor: 10508 Red Deer Fasteners & Tools Ltd. H64302 Line: 1	EA	6.000	16.79	100.74
1065	11/16/23	AP	Vendor: 10508 Red Deer Fasteners & Tools Ltd. H64302 Line: 2	EA	6.000	16.79	100.74
1310	06/12/24	AP	Vendor: 10508 Red Deer Fasteners & Tools Ltd. H78749 Line: 2	EA	-6.000	16.79	-100.74
1311	06/12/24	AP	Vendor: 10508 Red Deer Fasteners & Tools Ltd. H78749 Line: 3	EA	6.000	16.79	100.74
1370	10/26/23	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7175384.001 Line: 1	LS	0.000	0.00	1,307.96
50	12/04/23	EMParts	3423683 Floor Mat (349F)	EA	1.000	792.31	792.31
60	11/02/23	EMParts	4487682 Grease Seal-Split(400 Series)	EA	2.000	40.30	80.61
172	03/08/24	EMParts	2953099 Spark Plug-AfterTreatment	EA	1.000	18.36	18.36
236	11/14/23	EMParts	1243296 Sprocket	EA	1.000	485.37	485.37
237	11/14/23	EMParts	8T0380 Capscrew	EA	20.000	9.67	193.30
238	11/14/23	EMParts	SI652 Track nut, square	EA	8.000	1.74	13.92
240	11/14/23	EMParts	1504741 Bolt-track	EA	8.000	5.69	45.50
243	11/14/23	EMParts	4285778 Pan-spill	EA	1.000	30.72	30.72
244	11/14/23	EMParts	4538124 Grommet	EA	1.000	20.55	20.55
598	06/27/24	EMParts	2808618 Hammer-Emergency	EA	1.000	65.01	65.01
599	06/27/24	EMParts	OMT Operators Manual	EA	1.000	150.00	150.00
880	07/30/24	EMParts	7N0296 Ether Cyinder-18oz	EA	1.000	123.34	123.34
929	10/24/23	EMParts	2792589 Pulley-8 Grove	EA	1.000	238.69	238.69
930	10/24/23	EMParts	3039933 Strainer-Fuel	EA	1.000	167.22	167.22
944	10/24/23	EMParts	2953099 Spark Plug-AfterTreatment	EA	1.000	18.35	18.35
959	10/25/23	EMParts	3502822 Belt-Serpentine	EA	1.000	210.62	210.62
960	10/25/23	EMParts	3590188 Belt-Serpentine	EA	1.000	241.20	241.20
961	10/25/23	EMParts	3783187 Filter-Def	EA	1.000	60.10	60.10
			PO - Open - #1027673 - 10508 flat black paint	EA	6.00	16.79	100.74

Labour Total	0.00
Parts Total	8,732.83
Miscellaneous Total	0.00

Segment: 2 Inspections

Repair rubbed thru fan wiring harness.
-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
596	10/05/23	PR	Employee: 3110 Callum Deditch		HRS	1.500		
1537	08/24/23	PR	Employee: 1575 Paul Nixon		HRS	3.000		

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair Leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1627	10/20/23	PR	Employee: 3110 Callum Deditch		HRS	2.500		
1631	10/24/23	PR	Employee: 3110 Callum Deditch		HRS	3.500		
1633	10/27/23	PR	Employee: 3110 Callum Deditch		HRS	3.000		



Work Order: 14288

Labour Total	9.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair panels, buckets, cracks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1621	10/17/23	PR	Employee: 3110 Callum Deditch		HRS	1.500		
1624	10/19/23	PR	Employee: 3103 Dallas Wood		HRS	0.500		
1625	10/19/23	PR	Employee: 3110 Callum Deditch		HRS	6.500		
1628	10/20/23	PR	Employee: 3110 Callum Deditch		HRS	1.500		
1629	10/23/23	PR	Employee: 3110 Callum Deditch		HRS	5.000		

Labour Total	15.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Replace grease rings, belts, check tracks, top up fluids

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1622	10/18/23	PR	Employee: 3110 Callum Deditch		HRS	1.500		
1630	10/23/23	PR	Employee: 3110 Callum Deditch		HRS	2.000		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Scheduled repairs to emissions system

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1623	10/18/23	PR	Employee: 3110 Callum Deditch		HRS	4.500		
1626	10/19/23	PR	Employee: 3110 Callum Deditch		HRS	1.500		
1632	10/25/23	PR	Employee: 3110 Callum Deditch		HRS	5.000		

Labour Total	11.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Repair LH final drive sprocket coming loose

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
507	11/03/23	PR	Employee: 3103 Dallas Wood		HRS	1.500		



Work Order: 14288

508	11/06/23	PR	Employee: 3103 Dallas Wood	HRS	7.000
509	11/07/23	PR	Employee: 3103 Dallas Wood	HRS	2.000
510	11/08/23	PR	Employee: 3103 Dallas Wood	HRS	3.500
511	11/09/23	PR	Employee: 3103 Dallas Wood	HRS	9.500
512	11/10/23	PR	Employee: 3103 Dallas Wood	HRS	2.000

Labour Total	25.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Wash after repairs, paint, install panels

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
528	06/11/24	PR	Employee: 2623 Brenton Woolman		HRS	3.000		
529	06/12/24	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
530	06/13/24	PR	Employee: 2623 Brenton Woolman		HRS	5.500		
1210	06/25/24	PR	Employee: 2623 Brenton Woolman		HRS	0.500		

Labour Total	18.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Install Counterweights

Labour Total	87.00
Parts Total	8,732.83
Miscellaneous Total	0.00

Description: Rental Return - EMSCO	5551 Hours	Date Started: 2023-08-29
Equipment: E660 Caterpillar 349F Excavator Longstick 45'6"	RD-2023-267 Insheet RD-2024-179 Outsheets	
Serial#: CAT0349FVHPD20046		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
919	11/16/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949567412 Line: 1		EA	3.000	21.84	65.52
2523	11/16/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949567412 Line: 2		EA	-3.000	21.84	-65.52
2524	11/16/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 949567412 Line: 3		EA	3.000	21.84	65.52
101	09/08/23	EMParts	1421340 Filter-Air Primary		EA	1.000	124.95	124.95
102	09/08/23	EMParts	3276618 Filter-Cab Air		EA	1.000	42.37	42.37
103	09/08/23	EMParts	3639402 Filter-Cab Air		EA	1.000	47.48	47.48
104	09/08/23	EMParts	7N0296 Ether Cylinder-18oz		EA	1.000	121.41	121.41
105	09/08/23	EMParts	BS8000 Radar		EA	1.000	2,262.33	2,262.33



Work Order: 14289

106 09/08/23 EMParts BSBKT01 Mount-Radar Monitor EA 1.000 16.36 16.36

Labour Total	0.00
Parts Total	2,680.42
Miscellaneous Total	0.00

Segment: 2 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
660	09/13/23	PR	Employee: 2623 Brenton Woolman		HRS	8.500		
661	09/14/23	PR	Employee: 2623 Brenton Woolman		HRS	9.000		
662	09/15/23	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
1568	09/18/23	PR	Employee: 2623 Brenton Woolman		HRS	5.500		

Labour Total	32.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair radar brackets

Segment: 4 Repair counterweight, remove bent clevis, repair dents

*Counterweight has hole and deep gouges in it.
 Bent clevis in lifting eye on h-link.
 Lower toolbox step bent.
 Cab dented below front window.
 One bent belly pan below battery comp.
 Grease ring groove on stick is dented/smashed steel.
 Paint counterweight.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1376	11/16/23	PR	Employee: 2623 Brenton Woolman		HRS	8.500		
1377	11/17/23	PR	Employee: 2623 Brenton Woolman		HRS	1.000		
1611	10/17/23	PR	Employee: 3110 Callum Deditch		HRS	2.000		
1613	10/18/23	PR	Employee: 3109 Cameron Ellsworth		HRS	2.000		
1614	10/18/23	PR	Employee: 3110 Callum Deditch		HRS	0.500		
1618	10/20/23	PR	Employee: 3110 Callum Deditch		HRS	5.000		
1620	10/24/23	PR	Employee: 3110 Callum Deditch		HRS	1.500		

Labour Total	20.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Replace fuel screen, top up fluids



GCS Energy Services Ltd.

Work Order: 14289

Replace fuel screen.
Replace ether bottle.
Replace cab air filters, engine primary air filter.
Clean air filter bowl.
Top up wiper fluid.
Top up DEF.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1615	10/18/23	PR	Employee: 3110 Callum Deditch		HRS	0.500		
1619	10/20/23	PR	Employee: 3110 Callum Deditch		HRS	0.500		
Labour Total						1.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 6 Remove renter decals

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1612	10/17/23	PR	Employee: 3110 Callum Deditch		HRS	0.500		
Labour Total						0.50		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 7 Repair aux tubes/clamps

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1616	10/18/23	PR	Employee: 3103 Dallas Wood		HRS	1.000		
1617	10/18/23	PR	Employee: 3110 Callum Deditch		HRS	2.500		
Labour Total						3.50		
Parts Total						0.00		
Miscellaneous Total						0.00		
Labour Total						58.00		
Parts Total						2,781.16		
Miscellaneous Total						0.00		