



Work Order: 11488

EB10-134

Description: Repair Oil Leak	381 Hours	Date Started: 2020-09-04
Equipment: E680 Hyundai HX330L	GRO#9762	
Serial#: HHKHK901HL0000454		

Segment: 1 Parts and Service

Segment: 2 Repair Hyd Oil Leak

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
167	09/02/20	PR	Employee: 1577 Dylan Grant		HRS	1.000		
						Labour Total	1.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	1.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Description: Inspection, 250 Hour Service and Repairs	GRO-8040/9448/9449/8109/8110	Date Started: 2020-09-25
Equipment: E680 Hyundai HX330L	544 Hours	
Serial#: HHKHK901HL0000454		
RD-2020-288 Insheet		
RD-2020-348 Outsheets		

Segment: 1 Parts and Service

Need to Add 11KA71040 Fuel Filter

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
66	11/05/20	EMParts	11NA70110 Filter-Oil		EA	1.000	48.39	48.39
67	11/05/20	EMParts	LF9009 Filter-Oil		EA	-1.000	48.39	-48.39
161	10/08/20	EMParts	11K691440 Filter-Cab Air Inlet		EA	1.000	24.09	24.09
162	10/08/20	EMParts	11KA71040 Filter-Fuel/Water		EA	1.000	67.35	67.35
163	10/08/20	EMParts	11NA70110 Filter-Oil		EA	1.000	48.39	48.39
164	10/08/20	EMParts	11Q771010 Filter-Fuel		EA	1.000	97.72	97.72
165	10/08/20	EMParts	31K601320 Filter-Hydraulic Drain		EA	1.000	50.45	50.45
166	10/08/20	EMParts	31Q620340P Filter-Pilot Line		EA	1.000	50.85	50.85
167	10/08/20	EMParts	31RF10300 Filter-Hydraulic		EA	2.000	83.89	167.78
171	10/09/20	EMParts	11K691451 Filter-Cab Air (Fresh)		EA	1.000	44.45	44.45
172	10/09/20	EMParts	11Q910181 Filter-Primary Air		EA	1.000	410.87	410.87
209	10/14/20	EMParts	C201VV16 Coupler-Female Aux. 1"		EA	1.000	55.74	55.74
210	10/14/20	EMParts	C202VV16 Coupler-Male Aux. 1"		EA	1.000	31.92	31.92
387	12/17/20	EMParts	5W40 Spectra 5W40		I	30.000	5.22	156.47
388	12/17/20	EMParts	75W90 Certop SN 75W90 Gear Lube		EA	0.000	13.43	0.00
389	12/17/20	EMParts	Oil All Plus Hydraulic Oil 10W30		EA	0.000	17.84	0.00
1119	11/30/20	EMParts	WF2074 Filter-Coolant		EA	1.000	27.12	27.12
1252	12/22/20	EMParts	75W90 Certop SN 75W90 Gear Lube		EA	31.000	13.43	416.20



Work Order: 11547

1253	12/22/20	EMParts	Oil All Plus Hydraulic Oil 10W30	EA	20.000	17.84	356.86
1580	09/25/20	EMParts	Dyed Diesel Dyed Diesel	EA	189.270	0.70	131.71

Labour Total	0.00
Parts Total	2,137.97
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2567	09/25/20	PR	Employee: 2471 Greg Royer		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Bring unit into wash bay, wash and clean cab. Clean up wash bay once unit moved outside.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1514	12/14/20	PR	Employee: 1575 Paul Nixon		HRS	4.500		

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Check, Adjust Pressures and Cycle times

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2568	09/25/20	PR	Employee: 2471 Greg Royer		HRS	1.500		
2569	09/28/20	PR	Employee: 2471 Greg Royer		HRS	1.000		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 250 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
104	10/01/20	PR	Employee: 2611 Matthew Walter		HRS	1.000		
105	10/02/20	PR	Employee: 2611 Matthew Walter		HRS	6.500		
429	10/06/20	PR	Employee: 2611 Matthew Walter		HRS	1.500		



Work Order: 11547

798 10/09/20 PR Employee: 2611 Matthew Walter HRS 1.000

Labour Total	10.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Decal Unit and tighten lifting Eye

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
106	10/02/20	PR	Employee: 2611 Matthew Walter		HRS	2.000		
430	10/06/20	PR	Employee: 2611 Matthew Walter		HRS	0.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Weld Bucket

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2570	09/30/20	PR	Employee: 2395 Nickolas Schou		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Install hyd couplers

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
107	10/02/20	PR	Employee: 2611 Matthew Walter		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Outsheet Inspection

Perform out sheet inspection. Top up fluid levels, swing oil took a long time to fill. Replace coolant filter. Grease unit. Run outside, pictures and park in line up.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1515	12/14/20	PR	Employee: 1575 Paul Nixon		HRS	4.000		
1516	12/15/20	PR	Employee: 1575 Paul Nixon		HRS	2.000		



Work Order: 11547

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	30.00
Parts Total	2,137.97
Miscellaneous Total	0.00

Description: Service	Unit at TMX Site	Date Started: 2021-06-23
Equipment: E680 Hyundai HX330L	GRO-8735	
	841 Hours	
Serial#: HHKHK901HL0000454		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
841	06/23/21	EMParts	11K691440 Filter-Cab Air Inlet		EA	1,000	21.15	21.15
842	06/23/21	EMParts	11K691451 Filter-Cab Air (Fresh)		EA	1,000	41.51	41.51
843	06/23/21	EMParts	11Q910181 Filter-Primary Air		EA	1,000	257.42	257.42
844	06/23/21	EMParts	FF63009 Filter-Fuel		EA	1,000	43.95	43.95
845	06/23/21	EMParts	FS19950 Filter-Fuel/Water		EA	1,000	66.78	66.78
846	06/23/21	EMParts	LF9009 Filter-Oil		EA	1,000	48.39	48.39

Labour Total	0.00
Parts Total	479.20
Miscellaneous Total	0.00

Segment: 2 Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1300	06/25/21	PR	Employee: 2395 Nickolas Schou		HRS	2,000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	2.00
Parts Total	479.20
Miscellaneous Total	0.00

Description: Service	Unit at TMX Site.	Date Started: 2021-09-14
Equipment: E680 Hyundai HX330L	GRO-11804	
	1228 Hours	
Serial#: HHKHK901HL0000454		



Work Order: 12409

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
268	09/14/21	EMParts	11K691440 Filter-Cab Air Inlet		EA	1.000	12.50	12.50
269	09/14/21	EMParts	11K691451 Filter-Cab Air (Fresh)		EA	1.000	12.50	12.50
270	09/14/21	EMParts	11Q910181 Filter-Primary Air(AF55015)		EA	1.000	173.83	173.83
271	09/14/21	EMParts	FF63009 Filter-Fuel		EA	1.000	40.45	40.45
272	09/14/21	EMParts	FS19950 Filter-Fuel/Water		EA	1.000	69.75	69.75
273	09/14/21	EMParts	LF9009 Filter-Oil		EA	1.000	48.17	48.17
584	11/19/21	EMParts	5W40 Spectra 5W40		I	33.000	6.47	213.48
585	11/19/21	EMParts	75W90 Certop SN 75W90 Gear Lube		EA	1.000	9.48	9.48

Labour Total	0.00
Parts Total	580.16
Miscellaneous Total	0.00

Segment: 2 Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
768	09/15/21	PR	Employee: 2395 Nickolas Schou		HRS	1.500		
769	09/16/21	PR	Employee: 2395 Nickolas Schou		HRS	1.000		
934	10/20/21	PR	Employee: 2611 Matthew Walter		HRS	0.500		
1278	10/20/21	PR	Employee: 2611 Matthew Walter		HRS	-0.500		
1279	10/20/21	PR	Employee: 2611 Matthew Walter		HRS	0.500		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	3.00
Parts Total	580.16
Miscellaneous Total	0.00

Description: Weld Corks, Service and Check engine light Equipment: E680 Hyundai HX330L Serial#: HHKHK901HL0000454	Unit at TMX Edmonton Site 1650 Hours.	Date Started: 2021-12-06
--	--	---------------------------------

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
74	02/07/22	EMParts	AF55015 Filter-Primary Air		EA	1.000	312.05	312.05
191	12/07/21	EMParts	11K691440 Filter-Cab Air Inlet		EA	1.000	19.22	19.22
192	12/07/21	EMParts	11K691451 Filter-Cab Air (Fresh)		EA	1.000	43.64	43.64
193	12/07/21	EMParts	AF55015 Filter-Primary Air		EA	1.000	308.83	308.83
194	12/07/21	EMParts	FF63054NN Filter-Fuel		EA	1.000	56.13	56.13



GCS Energy Services Ltd.

Work Order: 12663

195	12/07/21	EMParts	FS19950 Filter-Fuel/Water	EA	1.000	69.75	69.75
196	12/07/21	EMParts	LF9009 Filter-Oil	EA	1.000	48.17	48.17
310	12/13/21	EMParts	AF55015 Filter-Primary Air	EA	-1.000	308.83	-308.83
321	08/10/22	EMParts	5W40 Spectra 5W40	I	32.000	5.92	189.48
585	02/23/22	EMParts	AF55309 Filter-Air Secondary	EA	1.000	67.41	67.41

Labour Total	0.00
Parts Total	805.85
Miscellaneous Total	0.00

Segment: 2 Weld Corks on Tracks

350 Hour Service. Change engine oil & filter. Air filters, cab filters
& fuel filters.
Weld Corks.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
138	12/04/21	PR	Employee: 2395 Nickolas Schou		HRS	5.500		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
568	12/10/21	PR	Employee: 2611 Matthew Walter		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 T/S and Repair Check Engine Light

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
987	02/10/22	PR	Employee: 2611 Matthew Walter		HRS	0.500		
1815	01/27/22	PR	Employee: 2611 Matthew Walter		HRS	0.500		
2027	02/24/22	PR	Employee: 2611 Matthew Walter		HRS	0.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 12663

Labour Total	7.50
Parts Total	805.85
Miscellaneous Total	0.00

Description: Replace bucket cutting edge 2100 Hours. **Date Started:** 2022-03-21
Equipment: E680 Hyundai HX330L
Serial#: HHKHK901HL0000454

Segment: 1 Parts

Segment: 2 Replace cutting edge

Replace worn cutting edge w/serrated edge. Cut bolts and installed new. Torque down.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
822	03/17/22	PR	Employee: 2611 Matthew Walter		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Description: 350 Hour Service **Date Started:** 2022-03-22
Equipment: E680 Hyundai HX330L
Serial#: HHKHK901HL0000454

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
405	03/22/22	EMParts	11K691440 Filter-Cab Air Inlet		EA	1.000	12.50	12.50
406	03/22/22	EMParts	11KA71040 Filter-Fuel/Water		EA	1.000	67.35	67.35
407	03/22/22	EMParts	AF55015 Filter-Primary Air		EA	1.000	209.93	209.93
408	03/22/22	EMParts	FF63054NN Filter-Fuel		EA	1.000	57.24	57.24
409	03/22/22	EMParts	LF9009 Filter-Oil		EA	1.000	49.22	49.22

Labour Total	0.00
Parts Total	396.24
Miscellaneous Total	0.00

Segment: 2 350 Hour Service



Work Order: 12928

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2034	03/23/22	PR	Employee: 2395 Nickolas Schou		HRS	1.500		
2035	03/24/22	PR	Employee: 2395 Nickolas Schou		HRS	1.000		

Labour Total 2.50

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 2.50

Parts Total 396.24

Miscellaneous Total 0.00

Description: 350 Hour Service 2453 Hours. Date Started: 2022-06-17
 Equipment: E680 Hyundai HX330L
 Serial#: HHKHK901HL0000454

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
647	06/17/22	EMParts	11K691440 Filter-Cab Air Inlet		EA	1.000	12.50	12.50
648	06/17/22	EMParts	11K691451 Filter-Cab Air (Fresh)		EA	1.000	59.30	59.30
649	06/17/22	EMParts	11KA71040 Filter-Fuel/Water		EA	1.000	94.67	94.67
650	06/17/22	EMParts	AF55015 Filter-Primary Air		EA	1.000	152.64	152.64
651	06/17/22	EMParts	FF63054NN Filter-Fuel		EA	1.000	58.44	58.44
652	06/17/22	EMParts	LF9009 Filter-Oil		EA	1.000	49.22	49.22
1056	07/28/22	EMParts	5W40 Spectra 5W40		I	34.000	5.92	201.32

Labour Total 0.00

Parts Total 628.09

Miscellaneous Total 0.00

Segment: 2 350 Hour Service

350 Hour Service.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1400	06/21/22	PR	Employee: 2471 Greg Royer		HRS	2.000		

Labour Total 2.00

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 3 Check out Unit



Work Order: 13189

Went to unit for complaint of loosing swing oil. During inspection had no oil on dip stick, was told it was filled previous day. All along bottom of house oily residue leaking out. Suspect leaking oil is being lost in swing housing. Inspect swing bearing grease tub condition. Complaint of runny grease. Grease was quite runny and swing oil low. Topped up every few days. Took sample.
 *Circle air vent broken on display column by right foot.
 *Screws missing holding inner cab filter on.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1401	06/21/22	PR	Employee: 2471 Greg Royer		HRS	1.000		
2388	06/28/22	PR	Employee: 2395 Nickolas Schou		HRS	1.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	4.00
Parts Total	628.09
Miscellaneous Total	0.00

Description: Engine Oil Sample Equipment: E680 Hyundai HX330L Serial#: HHKHK901HL0000454	Date Started: 2022-09-19
---	---------------------------------

Segment: 1 Parts

Segment: 2 Take engine oil sample at customer yard

Oil Sample.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
730	09/14/22	PR	Employee: 2915 Scott Scrivener		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 13758

Description: Inspections and Repairs
Equipment: E680 Hyundai HX330L

2555 Hours
RD-2022-296 Insheet
RD-2023-121 Outsheet

Date Started: 2023-01-04

Serial#: HHKHK901HL0000454

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1694	01/04/23	AP	Vendor: 10321 Union Tractor Ltd. 040-227089 Line: 2		EA	2.000	52.65	105.30
1695	01/04/23	AP	Vendor: 10321 Union Tractor Ltd. 040-227089 Line: 3		EA	2.000	-52.65	-105.30
2151	02/27/23	AP	Vendor: 10401 RBC Avion Visa Feb 23_L Dahl Line: 21		EA	4.000	15.64	62.56
7	03/02/23	EMParts	60/40 Rad-Cool Antifreeze		EA	1.500	5.19	7.79
8	03/02/23	EMParts	75W90 Certop SN 75W90 Gear Lube		EA	39.250	9.22	361.72
15	01/04/23	EMParts	904D Battery-12v-4D		EA	2.000	206.50	413.00
18	02/02/23	EMParts	Dyed Diesel Dyed Diesel		EA	431.540	1.28	553.65
263	03/15/23	EMParts	Dyed Diesel Dyed Diesel		EA	60.950	1.32	80.42
381	01/23/23	EMParts	71Q642600 Handle-Tool Box		EA	1.000	42.45	42.45
442	01/24/23	EMParts	71Q623660 Vent		EA	1.000	24.62	24.62

Labour Total	0.00
Parts Total	1,546.21
Miscellaneous Total	0.00

Segment: 2 Inspections

Outsheet unit.
Swing gearbox was overfilled and leaking once brought inside and warmed up. Drained excess oil and refilled to proper level.
Top up coolant.
Top up RH final drive.
Top up fuel (16.1G).
Pictures and park up front.
-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
167	03/01/23	PR	Employee: 1575 Paul Nixon		HRS	3.500		
2264	01/05/23	PR	Employee: 3063 Jordan Yasinski		HRS	2.500		

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash/Clean cab, paint counterweight

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
168	03/01/23	PR	Employee: 2623 Brenton Woolman		HRS	0.500		
1871	02/28/23	PR	Employee: 2623 Brenton Woolman		HRS	4.000		
1872	01/25/23	PR	Employee: 2623 Brenton Woolman		HRS	9.000		



Work Order: 13758

1873 01/26/23 PR Employee: 2623 Brenton Woolman HRS 9.000

Labour Total	22.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Replace batteries

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2263	01/04/23	PR	Employee: 1575 Paul Nixon		HRS	1.000		
2265	01/06/23	PR	Employee: 3063 Jordan Yasinski		HRS	0.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Repair ash tray, louver, handles

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
810	01/12/23	PR	Employee: 2873 Isaac Simpkin		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Top up fluids, grease, track tension adjust

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
811	01/12/23	PR	Employee: 2873 Isaac Simpkin		HRS	4.500		
813	01/13/23	PR	Employee: 2873 Isaac Simpkin		HRS	2.500		

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Torque swing gear hardware

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
812	01/12/23	PR	Employee: 2873 Isaac Simpkin		HRS	2.000		



Work Order: 13758

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 T/S and repair hyd leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
871	02/09/23	PR	Employee: 1575 Paul Nixon		HRS	1.000		
872	02/15/23	PR	Employee: 2873 Isaac Simpkin		HRS	1.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	43.00
Parts Total	1,546.21
Miscellaneous Total	0.00

Description: Reg Maintenance	Date Started: 2023-07-24
Equipment: E680 Hyundai HX330L	
Serial#: HHKHK901HL0000454	

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1139	07/24/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-387627 Line: 1 EA			2.000	9.46	18.92
1140	07/24/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-387627 Line: 2 EA			10.000	3.88	38.80

Labour Total	0.00
Parts Total	57.72
Miscellaneous Total	0.00

Segment: 2 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1494	07/24/23	PR	Employee: 22 Garrett Nelson		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 14230

Segment: 3 Hyd oil leak

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1495	07/24/23	PR	Employee: 2024 Travis Schmidt		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 4 check for leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1496	07/24/23	PR	Employee: 2024 Travis Schmidt		HRS	0.500		
						Labour Total		0.50
						Parts Total		0.00
						Miscellaneous Total		0.00
						Labour Total		3.50
						Parts Total		57.72
						Miscellaneous Total		0.00

Description: Inspections and Repairs	2845 Hours	Date Started: 2023-11-03
Equipment: E680 Hyundai HX330L	RD-2023-300 Insheet	
	RD-2024-211 Outsheet	
Serial#: HHKHK901HL0000454		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
891	02/02/24	AP	Vendor: 10132 Gregg Distributors LP 059-616750 Line: 1		EA	1.000	10.70	10.70
892	02/02/24	AP	Vendor: 10132 Gregg Distributors LP 059-616750 Line: 2		EA	1.000	4.78	4.78
11	02/01/24	EMParts	11K691440 Filter-Cab Air Inlet		EA	1.000	19.76	19.76
12	02/01/24	EMParts	11K691451 Filter-Cab Air (Fresh)		EA	1.000	12.50	12.50
240	09/18/24	EMParts	60/40 Rad-Cool Antifreeze		EA	2.000	6.70	13.41
241	09/18/24	EMParts	75W90 Certop SN 75W90 Gear Lube		EA	3.500	10.27	35.94
242	09/18/24	EMParts	DEF DEF (10L Jug)		EA	2.000	18.19	36.38
						Labour Total		0.00
						Parts Total		133.47
						Miscellaneous Total		0.00

Segment: 2 Inspections



Work Order: 14475

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
852	09/17/24	PR	Employee: 3103 Dallas Wood		HRS	6.000		

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash/paint

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
419	09/05/24	PR	Employee: 2623 Brenton Woolman		HRS	4.000		
420	09/06/24	PR	Employee: 2623 Brenton Woolman		HRS	8.000		
421	09/09/24	PR	Employee: 2623 Brenton Woolman		HRS	5.500		

Labour Total	17.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
122	02/01/24	PR	Employee: 3109 Cameron Ellsworth		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Change cab air filters and adjust mirrors

Segment: 6 Check and adjust track tension

Labour Total	26.00
Parts Total	133.47
Miscellaneous Total	0.00

Description: Rental Return Legacy	2845 Hours	Date Started: 2023-11-03
Equipment: E680 Hyundai HX330L	RD-2023-300 Insheet	
	RD-2024-211 Outsheat	
Seria #: HHKHK901HL0000454		



Work Order: 14476

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
13	02/01/24	EMParts	31M902080 Strainer-Fuel		EA	1.000	130.53	130.53
76	11/03/23	EMParts	C201VV16 Coupler-Female Aux. 1"		EA	1.000	59.10	59.10
77	11/03/23	EMParts	C202VV16 Coupler-Male Aux. 1"		EA	1.000	33.84	33.84
78	11/03/23	EMParts	Dyed Diesel Dyed Diesel		EA	75.710	1.49	112.50

Labour Total	0.00
Parts Total	335.97
Miscellaneous Total	0.00

Segment: 2 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
416	09/03/24	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
417	09/04/24	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
418	09/05/24	PR	Employee: 2623 Brenton Woolman		HRS	5.500		
1348	08/29/24	PR	Employee: 2623 Brenton Woolman		HRS	8.500		

Labour Total	33.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Top Up Fluids

Swing oil at bottom of Dipstick.
 DEF at 3/4.
 Wiper fluid empty.
 Coolant low.
 Hydraulic oil slightly low.

Segment: 4 Repair Couplers, door

L/H Aux. coupler wet, both couplers have been struck.
 DEF Cover/Hatch bent.
 No Fuel Screen.
 Big dent at bottom of cub.
 Remove Renters decals.
 Hydraulic compartment door dented.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
121	02/01/24	PR	Employee: 3109 Cameron Ellsworth		HRS	3.500		



Work Order: 14476

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	36.50
Parts Total	335.97
Miscellaneous Total	0.00

Description: Replace Batteries

Date Started: 2025-07-23

Equipment: E680 Hyundai HX330L

Serial#: HHKHK901HL0000454

Segment: 1 Parts

Segment: 2 Replace Batteries

Labour Total	0.00
Parts Total	0.00
Miscellaneous Total	0.00