



Work Order: 12427

EB10-138

Description: Outsheet & wash	16.3 HRS, GRO 8306/8363	Date Started: 2021-09-20
Equipment: E683 Hyundai HL955TM Loader		
Serial#: HHKHW501AL0000173		

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
886	09/20/21	EMParts	SAF RBP Rubber Bump Pads F/Fire extinguisher brackets		EA	4.000	1.18	4.72

Labour Total	0.00
Parts Total	4.72
Miscellaneous Total	0.00

Segment: 2 wash

Segment: 3 outsheet inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1423	09/21/21	PR	Employee: 2024 Travis Schmidt		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 R&R fire extinguisher brackets insulators

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1135	09/20/21	PR	Employee: 1266 Braden Bitzer		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	1.00
Parts Total	4.72
Miscellaneous Total	0.00



Work Order: 12563

Description: 250 Hour Service and Sample	500 Hours.	Date Started: 2021-11-05
Equipment: E683 Hyundai HL955TM Loader		
Serial#: HHKHW501AL0000173		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
70	11/05/21	EMParts	11LL45181 Filter-Primary Air(AF55014)		EA	1.000	252.29	252.29
71	11/05/21	EMParts	31LM10310 Filter-Pilot Line Element		EA	1.000	56.89	56.89
72	11/05/21	EMParts	31RF10450 Filter-Hydraulic Return		EA	1.000	77.10	77.10
73	11/05/21	EMParts	71WD32210 Filter-Cab Air		EA	1.000	41.92	41.92
74	11/05/21	EMParts	Basickit Oil Sample		EA	5.000	37.15	185.75
75	11/05/21	EMParts	FF63054NN Filter-Fuel		EA	1.000	56.71	56.71
76	11/05/21	EMParts	FS19950 Filter-Fuel/Water		EA	1.000	69.75	69.75
77	11/05/21	EMParts	LF3970 Filter-Oil		EA	1.000	15.45	15.45
78	11/05/21	EMParts	XKBU00144 Filter-Cab Air		EA	1.000	60.52	60.52
79	11/05/21	EMParts	ZGAQ02400 Filter-Transmission		EA	1.000	94.96	94.96
292	08/09/22	EMParts	5W40 Spectra 5W40		I	20.000	5.92	118.42

Labour Total	0.00
Parts Total	1,029.76
Miscellaneous Total	0.00

Segment: 2 250 Hour Service and Sample

Change all Filters and 5 Oil Sample's. Changed engine oil.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1910	11/26/21	PR	Employee: 2395 Nickolas Schou		HRS	4.000		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	4.00
Parts Total	1,029.76
Miscellaneous Total	0.00

Description: 350 Hour Service and Leak	Unit At Blue River BC Site.	Date Started: 2022-07-12
Equipment: E683 Hyundai HL955TM Loader	470 Hours.	
Serial#: HHKHW501AL0000173		

Segment: 1 Parts



Work Order: 13263

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
102	07/12/22	EMParts	11KA71040 Filter-Fuel/Water		EA	1.000	98.21	98.21
103	07/12/22	EMParts	71WD32210 Filter-Cab Air		EA	1.000	53.49	53.49
104	07/12/22	EMParts	AF55014 Filter-Primary Air		EA	1.000	137.20	137.20
105	07/12/22	EMParts	FF63054NN Filter-Fuel		EA	1.000	58.44	58.44
106	07/12/22	EMParts	LF3970 Filter-Oil		EA	1.000	16.89	16.89
107	07/12/22	EMParts	XKBU00144 Filter-Cab Air		EA	1.000	76.80	76.80

Labour Total	0.00
Parts Total	441.03
Miscellaneous Total	0.00

Segment: 2 350 Hour Service

Segment: 3 Leaking hose

Segment: 4 Repair grease fittings

Grease unit and replace zerks.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
887	07/17/22	PR	Employee: 2395 Nickolas Schou		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	1.00
Parts Total	441.03
Miscellaneous Total	0.00

Description: Repair leaks Unit At TMX Edmonton Site. Date Started: 2022-09-06
 Equipment: E683 Hyundai HL955TM Loader
 Serial#: HHKHW501AL0000173

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1135	09/06/22	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6699503.001 Line: 1		EA	2.000	201.03	402.06
2542	09/27/22	AP	Vendor: 10401 RBC Avion Visa Sept 22_Lance D Line: 27		EA	2.000	13.77	27.54
2561	09/06/22	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6699503.001 Line: 2		EA	-2.000	201.03	-402.06
226	09/13/22	EMParts	11KA71040 Filter-Fuel/Water		EA	1.000	98.21	98.21



GCS Energy Services Ltd.

Work Order: 13409

227	09/13/22	EMParts	71WD32210 Filter-Cab Air	EA	1.000	32.99	32.99
228	09/13/22	EMParts	XKBU00144 Filter-Cab Air	EA	1.000	76.80	76.80
1009	09/28/22	EMParts	93016BH1616 Male NPT Male Orfs Bulhead Ada	EA	2.000	38.45	76.90
1010	09/28/22	EMParts	C201VV16 Coupler-Female Aux. 1"	EA	1.000	59.10	59.10
1011	09/28/22	EMParts	C202VV16 Coupler-Male Aux. 1"	EA	1.000	33.84	33.84
1012	09/28/22	EMParts	C208VV16 Plug-VV Series 1"	EA	1.000	23.32	23.32
1013	09/28/22	EMParts	C209VV16 Cap-VV series 1"	EA	1.000	28.66	28.66
			PO - Open - #1022352 - 10416 Hose Assembly	EA	2.00	201.03	402.06

Labour Total	0.00
Parts Total	859.42
Miscellaneous Total	0.00

Segment: 2 Repair leaks

Aux hoses install.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
136	09/03/22	PR	Employee: 2915 Scott Scrivener		HRS	0.500		
733	09/16/22	PR	Employee: 2915 Scott Scrivener		HRS	0.500		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Replace Filters

Replace cab & fuel filters.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
734	09/16/22	PR	Employee: 2915 Scott Scrivener		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair quick attach

*Built & install temporary pin for quick attach cylinder.
Install quick couplers. Hook up grapple & test. Remove pin notifiers to prevent roll pins from breaking.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
635	10/04/22	PR	Employee: 2915 Scott Scrivener		HRS	2.000		
1476	09/19/22	PR	Employee: 2915 Scott Scrivener		HRS	1.500		
1477	09/23/22	PR	Employee: 2915 Scott Scrivener		HRS	2.500		



Work Order: 13409

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	8.00
Parts Total	859.42
Miscellaneous Total	0.00

Description: IN/OUTSHEET INSPECTION - SERVICE 535 HRS, GRO 7610 Date Started: 2022-09-13
 Equipment: E683 Hyundai HL955TM Loader
 Serial#: HHKHW501AL0000173

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2293	09/13/22	AP	Vendor: 33099 Alberta AG Centre PICPAK Line: 1		EA	1.000	14.44	14.44
2294	09/13/22	AP	Vendor: 33099 Alberta AG Centre PICPAK Line: 2		EA	1.000	67.06	67.06
2295	09/13/22	AP	Vendor: 33099 Alberta AG Centre PICPAK Line: 3		EA	1.000	130.07	130.07
333	09/13/22	EMParts	5W40 Spectra 5W40		I	18.000	5.34	96.13

Labour Total	0.00
Parts Total	307.70
Miscellaneous Total	0.00

Segment: 2 in/outsheet inspection & Service

Segment: 3 Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
731	09/13/22	PR	Employee: 2024 Travis Schmidt		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
732	09/13/22	PR	Employee: 2024 Travis Schmidt		HRS	1.000		



Work Order: 13450

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	3.00
Parts Total	709.76
Miscellaneous Total	0.00

Description: Replace Lights
Equipment: E683 Hyundai HL955TM Loader
Serial#: HHKHW501AL0000173
Unit at TMX Edmonton Site. **Date Started:** 2022-10-17

Segment: 1 Parts

Segment: 2 Repair lights

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
636	10/12/22	PR	Employee: 2915 Scott Scrivener		HRS	0.500		
637	10/13/22	PR	Employee: 2915 Scott Scrivener		HRS	0.500		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	1.00
Parts Total	402.06
Miscellaneous Total	0.00

Description: 350 Hour Service
Equipment: E683 Hyundai HL955TM Loader
Serial#: HHKHW501AL0000173
Unit at TMX Edmonton Site. **Date Started:** 2022-10-21

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
157	11/09/22	EMParts	5W40 Spectra 5W40		I	20.000	7.01	140.16
837	10/21/22	EMParts	71WD32210 Filter-Cab Air		EA	1.000	32.99	32.99
838	10/21/22	EMParts	AF55014 Filter-Primary Air		EA	1.000	137.20	137.20
839	10/21/22	EMParts	FF63054NN Filter-Fuel		EA	1.000	62.01	62.01
840	10/21/22	EMParts	FS19950 Filter-Fuel/Water		EA	1.000	79.08	79.08
841	10/21/22	EMParts	LF3970 Filter-Oil		EA	1.000	16.93	16.93
842	10/21/22	EMParts	XKBU00144 Filter-Cab Air		EA	1.000	76.80	76.80



Work Order: 13566

Labour Total	0.00
Parts Total	545.17
Miscellaneous Total	0.00

Segment: 2 350 Hour Service

350 Hour Service.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2009	10/26/22	PR	Employee: 2915 Scott Scrivener		HRS	2,500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	2.50
Parts Total	947.23
Miscellaneous Total	0.00

Description: Replace Q/A Roll pins Equipment: E683 Hyundai HL955TM Loader Serial#: HHKHW501AL0000173	Unit at TMX Edmonton Site.	Date Started: 2022-11-04
---	----------------------------	---------------------------------

Segment: 1 Parts

Segment: 2 Replace Roll Pins, test Q/A

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
683	11/04/22	PR	Employee: 2915 Scott Scrivener		HRS	1.000		
1330	11/16/22	PR	Employee: 2915 Scott Scrivener		HRS	1.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair seat belt

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1331	11/16/22	PR	Employee: 2915 Scott Scrivener		HRS	1.000		



Work Order: 13626

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	3.50
Parts Total	402.06
Miscellaneous Total	0.00

Description: 350 Hour Service	Unit at TMX Edmonton Site.	Date Started: 2022-11-29
Equipment: E683 Hyundai HL955TM Loader	Hours 1308	
	Next service hours 1658	
Serial#: HHKHW501AL0000173	GRO#11303	

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
887	11/29/22	EMParts	11KA71040 Filter-Fuel/Water		EA	1.000	47.17	47.17
888	11/29/22	EMParts	71WD32210 Filter-Cab Air		EA	1.000	12.50	12.50
889	11/29/22	EMParts	AF55014 Filter-Primary Air		EA	1.000	137.20	137.20
890	11/29/22	EMParts	FS19950 Filter-Fuel/Water		EA	1.000	79.08	79.08
891	11/29/22	EMParts	LF3970 Filter-Oil		EA	1.000	16.93	16.93
892	11/29/22	EMParts	XKBU00144 Filter-Cab Air		EA	1.000	12.50	12.50
964	01/30/23	EMParts	5W40 Spectra 5W40		I	22.000	7.01	154.18

Labour Total	0.00
Parts Total	459.56
Miscellaneous Total	0.00

Segment: 2 350 Hour Service

replace grease, zerks not taking grease

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2445	11/30/22	PR	Employee: 2915 Scott Scrivener		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	2.50
Parts Total	861.62
Miscellaneous Total	0.00



Work Order: 13799

Description: 350 Hour Service	Unit at TMX site	Date Started: 2023-01-19
Equipment: E683 Hyundai HL955TM Loader	Hours 1809	
	Next Service Hours 2159	
Serial#: HHKHW501AL0000173	GRO#10504	

Segment: 1 Parts

H4 24V X 1
Mini Bulb X1

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
290	01/19/23	EMParts	71WD32210 Filter-Cab Air		EA	1.000	12.50	12.50
291	01/19/23	EMParts	AF55014 Filter-Primary Air		EA	1.000	143.72	143.72
292	01/19/23	EMParts	FF63054NN Filter-Fuel		EA	1.000	62.72	62.72
293	01/19/23	EMParts	FS19950 Filter-Fuel/Water		EA	1.000	79.08	79.08
294	01/19/23	EMParts	LF3970 Filter-Oil		EA	1.000	18.05	18.05
295	01/19/23	EMParts	XKBU00144 Filter-Cab Air		EA	1.000	12.50	12.50
999	01/30/23	EMParts	5W40 Spectra 5W40		I	19.000	7.19	136.62
1000	01/30/23	EMParts	H3-24V-70W H3 24V 70W Halogen Bulb		EA	2.000	0.27	0.54

Labour Total	0.00
Parts Total	465.73
Miscellaneous Total	0.00

Segment: 2 350 hour service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1875	01/24/23	PR	Employee: 2915 Scott Scrivener		HRS	2.000		
1876	01/25/23	PR	Employee: 2915 Scott Scrivener		HRS	0.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 T/S Grapple

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1877	01/25/23	PR	Employee: 2915 Scott Scrivener		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair lights



Work Order: 13799

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1878	01/26/23	PR	Employee: 2915 Scott Scrivener		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	3.50
Parts Total	867.79
Miscellaneous Total	0.00

Description: Repair Aux. Couplers
Equipment: E683 Hyundai HL955TM Loader
Serial#: HHKHW501AL0000173
 Unit at TMX Site GRO#11485
Date Started: 2023-02-07

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
120	02/07/23	EMParts	050931212 Adapter-#12 Female JIC x #12 M		EA	2.000	7.90	15.80
121	02/07/23	EMParts	848BHFS1212 Bulkhead-#12 Male NPT x #12 Fe		EA	2.000	9.60	19.20
122	02/07/23	EMParts	C201VV12 3/4" Female Coupler (VV Series		EA	2.000	37.50	75.00
123	02/07/23	EMParts	C202VV12 3/4" Male Coupler (VV Series)		EA	2.000	21.66	43.32

Labour Total	0.00
Parts Total	153.32
Miscellaneous Total	0.00

Segment: 2 Repair Aux. Coupler

-remove leaking aux lines cap off, send parts with loader

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
875	02/09/23	PR	Employee: 2915 Scott Scrivener		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	1.00
Parts Total	555.38
Miscellaneous Total	0.00



Work Order: 13911

Description: regular maintenance	Date Started: 2023-02-24
Equipment: E683 Hyundai HL955TM Loader	
Serial#: HHKHW501AL0000173	

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
858	10/04/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-390554 Line: 1	EA		2.000	31.10	62.20
859	10/04/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-390554 Line: 2	EA		6.000	6.00	36.00
860	10/04/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-390554 Line: 3	EA		2.000	18.00	36.00
861	10/04/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-390554 Line: 4	EA		2.000	19.85	39.70
						Labour Total	0.00	
						Parts Total	173.90	
						Miscellaneous Total	0.00	

Segment: 2 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
599	10/03/23	PR	Employee: 22 Garrett Nelson		HRS	2.000		
600	10/04/23	PR	Employee: 22 Garrett Nelson		HRS	0.500		
1872	02/23/23	PR	Employee: 22 Garrett Nelson		HRS	6.000		
						Labour Total	8.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 3 Complete In/Out Sheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
664	09/15/23	PR	Employee: 3119 Shawn Dittmer		HRS	1.000		
						Labour Total	1.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 4 Repair camera wiring

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
665	09/15/23	PR	Employee: 3119 Shawn Dittmer		HRS	4.000		



Work Order: 13911

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 install front attachment hoses

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
601	10/04/23	PR	Employee: 3119 Shawn Dittmer		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	16.50
Parts Total	575.96
Miscellaneous Total	0.00

Description: Reg Maintenance	GRO#7639/7715/7718/11784	Date Started: 2024-03-21
Equipment: E683 Hyundai HL955TM Loader	2035 hours	
Serial# HHKHW501AL0000173		

Segment: 1 parts

1x FST-VVINPw1-NPT-F quick coupler

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
8	06/03/24	EMParts	71Q623660 Vent-Round (2 1/2")		EA	1.000	14.57	14.57
277	07/09/24	EMParts	217618 Wiper Blade		EA	1.000	60.11	60.11

Labour Total	0.00
Parts Total	74.68
Miscellaneous Total	0.00

Segment: 2 test batteries

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1292	03/18/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00



GCS Energy Services Ltd.

Work Order: 14789

Segment: 3 grease/inspect

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
228	06/03/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 replace quick coupler/air nozzle

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
229	06/06/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
674	07/11/24	PR	Employee: 22 Garrett Nelson		HRS	2.000		
675	07/12/24	PR	Employee: 22 Garrett Nelson		HRS	2.000		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Complete In/Out Sheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
673	07/09/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	12.00
Parts Total	476.74
Miscellaneous Total	0.00



Work Order: 14953

Description: Repair Quick Attach and 350 Hour Service	Unit at BlackRod Job#702	Date Started: 2024-07-12
Equipment: E683 Hyundai HL955TM Loader	Hours:	
	Next Service Hours:	
Serial#: HHKHW501AL0000173	GRO#10333/10342/10336	

Segment: 1 Parts

1 X-4 Jic cap
-Zac
2 zerks
-Zac

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
140	09/03/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7538152.001 Line: 1		EA	2.000	7.30	14.60
443	07/12/24	AP	Vendor: 33157 Chinook Equipment 03-24340 Line: 1		EA	4.000	10.46	41.84
580	08/19/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7521211.001 Line: 2		EA	2.000	41.46	82.92
614	08/19/24	AP	Vendor: 33157 Chinook Equipment 03-26150 Line: 1		EA	1.000	88.35	88.35
1133	08/23/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7528414.001 Line: 2		EA	2.000	104.64	209.28
1668	08/19/24	AP	Vendor: 33157 Chinook Equipment 03-26150 Line: 2		EA	-1.000	88.35	-88.35
1669	08/19/24	AP	Vendor: 33157 Chinook Equipment 03-26150 Line: 3		EA	1.000	88.35	88.35
1736	07/12/24	AP	Vendor: 33157 Chinook Equipment 03-24340 Line: 2		EA	-4.000	10.46	-41.84
1737	07/12/24	AP	Vendor: 33157 Chinook Equipment 03-24340 Line: 3		EA	4.000	10.46	41.84
			PO - Open - #1027847 - 33157 dowel pin		EA	4.00	10.46	41.84
			PO - Open - #1028086 - 33157 21WD31170- lamp flasher		EA	1.00	88.35	88.35
Labour Total						0.00		
Parts Total						567.18		
Miscellaneous Total						0.00		

Segment: 2 Repair Quick Attach

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
676	07/12/24	PR	Employee: 3108 Zachary Dean		HRS	1.000		
Labour Total						1.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 3 350HR Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1147	07/31/24	PR	Employee: 3108 Zachary Dean		HRS	3.000		
Labour Total						3.00		
Parts Total						0.00		
Miscellaneous Total						0.00		



Work Order: 14953

Segment: 4 Repair Lights/door lights/camera

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1351	08/21/24	PR	Employee: 3108 Zachary Dean		HRS	1.500		
1352	08/28/24	PR	Employee: 3108 Zachary Dean		HRS	0.500		

Labour Total 2.00

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 6.00

Parts Total 969.24

Miscellaneous Total 0.00

Description: 350 Hour Service	Unit at BlackRod Job#702	Date Started: 2024-07-26
Equipment: E683 Hyundai HL955TM Loader	Hours 2108	
Serial#: HHKHW501AL0000173	Next service hours 2458	
	GRO#10221	

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2	08/01/24	EMParts	5W40 Spectra Xtreme 5W40 (CK-4)		I	18.000	7.70	138.63
773	07/26/24	EMParts	71WD32210 Filter-Cab Air		EA	1.000	12.50	12.50
774	07/26/24	EMParts	AF55014 Filter-Primary Air		EA	1.000	71.63	71.63
775	07/26/24	EMParts	FF63054NN Filter-Fuel		EA	1.000	68.18	68.18
776	07/26/24	EMParts	FS19950 Filter-Fuel/Water		EA	1.000	91.60	91.60
777	07/26/24	EMParts	LF3970 Filter-Oil		EA	1.000	20.51	20.51
778	07/26/24	EMParts	XKBU00144 Filter-Cab Air		EA	1.000	36.75	36.75

Labour Total 0.00

Parts Total 439.80

Miscellaneous Total 0.00

Segment: 2 350 Hour Service

Labour Total 0.00

Parts Total 972.05

Miscellaneous Total 0.00

Description: Replace cutting edges, wiper arm and blade	Unit at BlackRod site.	Date Started: 2024-09-12
Equipment: E683 Hyundai HL955TM Loader	Hours: 2295	
Serial#: HHKHW501AL0000173	Next service:2458	
	GRO#10378	



Work Order: 15076

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
228	09/13/24	AP	Vendor: 10321 Union Tractor Ltd. 040-233354 Line: 2		EA	14.000	3.13	43.83
229	09/13/24	AP	Vendor: 10321 Union Tractor Ltd. 040-233354 Line: 3		EA	14.000	1.51	21.14
230	09/13/24	AP	Vendor: 10321 Union Tractor Ltd. 040-233354 Line: 6		EA	14.000	1.40	19.54
217	09/16/24	EMParts	21LM37021 Wiper Arm Assembly and Blade		EA	1.000	411.40	411.40
218	09/16/24	EMParts	61LM00310MT Edge-Cutting		EA	1.000	1,102.36	1,102.36
219	09/16/24	EMParts	61LM00320MT End Bit-Cutting		EA	2.000	381.12	762.24
						Labour Total	0.00	
						Parts Total	2,360.51	
						Miscellaneous Total	0.00	

Segment: 2 Replace Cutting Edges

Segment: 3 Replace Wiper Arm and Blade

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
423	09/10/24	PR	Employee: 3103 Dallas Wood		HRS	0.500		
						Labour Total	0.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 4 Repair/replace hoses

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
424	09/11/24	PR	Employee: 3103 Dallas Wood		HRS	2.000		
855	09/17/24	PR	Employee: 3108 Zachary Dean		HRS	4.000		
856	09/26/24	PR	Employee: 3103 Dallas Wood		HRS	2.000		
						Labour Total	8.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	8.50	
						Parts Total	2,892.76	
						Miscellaneous Total	0.00	



Work Order: 15116

Description: 350 Hour Service	Unit at BlackRod Site.	Date Started: 2024-10-07
Equipment: E683 Hyundai HL955TM Loader	Hours: 2435	
	Next Service Hours: 2785	
Serial#: HHKHW501AL0000173	GRO# 8979	

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
42	10/07/24	EMParts	71WD32210 Filter-Cab Air		EA	1.000	39.84	39.84
43	10/07/24	EMParts	AF55014 Filter-Primary Air		EA	1.000	71.63	71.63
44	10/07/24	EMParts	FF63054NN Filter-Fuel		EA	1.000	68.18	68.18
45	10/07/24	EMParts	FS19950 Filter-Fuel/Water		EA	1.000	91.60	91.60
46	10/07/24	EMParts	LF3970 Filter-Oil		EA	1.000	20.51	20.51
47	10/07/24	EMParts	XKBU00144 Filter-Cab Air		EA	1.000	69.19	69.19
72	10/10/24	EMParts	5W40 Spectra Xtreme 5W40 (CK-4)		I	18.000	7.94	142.91
						Labour Total	0.00	
						Parts Total	503.86	
						Miscellaneous Total	0.00	

Segment: 2 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
297	10/08/24	PR	Employee: 3103 Dallas Wood		HRS	1.000		
						Labour Total	1.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	1.00	
						Parts Total	1,036.11	
						Miscellaneous Total	0.00	

Description: Reg Maintenance	GRO#13223/13554/13639	Date Started: 2024-11-14
Equipment: E683 Hyundai HL955TM Loader	2636 hours Nov 27 2024	
Serial#: HHKHW501AL0000173		

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
175	11/14/24	EMParts	71WD10520 Vent-Round Air		EA	2.000	57.88	115.76



Work Order: 15152

Labour Total	0.00
Parts Total	115.76
Miscellaneous Total	0.00

Segment: 2 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
702	11/13/24	PR	Employee: 22 Garrett Nelson		HRS	3.000		
704	11/15/24	PR	Employee: 22 Garrett Nelson		HRS	2.000		

Labour Total	5.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Complete In sheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
703	11/13/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 swap out hyd couplers used

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1484	11/25/24	PR	Employee: 2024 Travis Schmidt		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Replace LHS air vent

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1485	11/27/24	PR	Employee: 3119 Shawn Dittmer		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 15152

Labour Total	8.50
Parts Total	648.01
Miscellaneous Total	0.00

Description: Reg Maintenance	GRO13413/13415/13425/13770/1380	Date Started: 2025-03-24
Equipment: E683 Hyundai HL955TM Loader	5/13824/13888/12290	
Serial#: HHKHW501AL0000173	2712 hours April 2025	
	Warrenty Level Sensor Paul	
	2735 hours June 2025	

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
383	04/07/25	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-410128 Line: 5	EA		2.000	33.88	67.76
576	05/15/25	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-411605 Line: 3	LS		0.000	0.00	44.74
577	05/15/25	AP	Vendor: 10146 Hardisty Hardware 2016 Ltd. 57404 Line: 2	EA		1.000	24.99	24.99
1285	04/07/25	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-410128 Line: 5	EA		2.000	33.88	67.76
1288	04/07/25	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-410128 Line: 5	EA		-2.000	33.88	-67.76
243	05/15/25	EMParts	DEF-9.46 Diesel Exhaust Fluid (9.46 L Jug)	EA		2.000	17.87	35.74
244	05/20/25	EMParts	DEF-9.46 Diesel Exhaust Fluid (9.46 L Jug)	EA		-18.000	17.87	-321.62
442	04/22/25	EMParts	DEF-9.46 Diesel Exhaust Fluid (9.46 L Jug)	EA		20.000	17.87	357.36
450	03/25/25	EMParts	S471910452 Dowel Pin-Q/A Loader	EA		2.000	10.46	20.92
		PO - Open - #1029170 - 10064	Diesel Exhaust Fluid	LS		0.00	0.00	44.74
						Labour Total	0.00	
						Parts Total	274.63	
						Miscellaneous Total	0.00	

Segment: 2 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
442	06/10/25	PR	Employee: 3119 Shawn Dittmer	HRS		1.500		
444	06/13/25	PR	Employee: 22 Garrett Nelson	HRS		1.500		
688	03/21/25	PR	Employee: 3142 Trina Schmidt	HRS		1.000		
691	03/25/25	PR	Employee: 3142 Trina Schmidt	HRS		1.500		
						Labour Total	5.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 3 Inspect

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
443	06/10/25	PR	Employee: 3119 Shawn Dittmer	HRS		1.500		
689	03/21/25	PR	Employee: 3119 Shawn Dittmer	HRS		5.000		



GCS Energy Services Ltd.

Work Order: 15283

1127 04/29/25 PR Employee: 3119 Shawn Dittmer HRS 4.500

Labour Total	11.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 weld plates to protect bucket

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
690	03/24/25	PR	Employee: 3119 Shawn Dittmer		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Complete In-Sheet/trouble shoot DEF codes

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
300	04/03/25	PR	Employee: 3119 Shawn Dittmer		HRS	3.500		
602	04/22/25	PR	Employee: 3119 Shawn Dittmer		HRS	5.000		
1006	06/27/25	PR	Employee: 3119 Shawn Dittmer		HRS	3.000		

Labour Total	11.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Install Warrenty level sensor

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
429	05/15/25	PR	Employee: 3119 Shawn Dittmer		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Trouble shoot fault code

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1160	05/27/25	PR	Employee: 3119 Shawn Dittmer		HRS	1.000		



Work Order: 15283

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	33.50
Parts Total	806.88
Miscellaneous Total	0.00

1940

1941

1942

1943

1944

1945

1946

1947

1948

1949

1950

1951

1952

1953

1954

1955

1956

1957