



Work Order: 11215

EB10-140

Description: Inspections and Repairs	Code to Start 0619	Date Started: 2020-06-19
Equipment: E619 John Deere 644K Loader	5402 Hours	
	RD-2020-214 Insheet	
	RD-2020-233 Outsheets	
Serial#: 1DW644KPCED666091	GRO-9291/9722/9262	

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
3420	06/30/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4585768 Line: 1		EA	-1.000	11.56	-11.56
3421	06/30/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4585768 Line: 2		EA	-1.000	15.66	-15.66
3422	06/30/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4585768 Line: 3		EA	-8.000	3.42	-27.36
3423	06/30/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4585768 Line: 4		EA	-3.000	7.91	-23.73
3424	06/30/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4585768 Line: 5		EA	-1.000	75.46	-75.46
3425	06/30/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4585768 Line: 6		EA	-1.000	79.09	-79.09
4529	06/22/20	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5840727.001 Line: 1		LS	0.000	0.00	24.00
715	08/16/20	EMParts	Dyed Diesel Dyed Diesel		EA	105.240	0.70	73.66
716	08/16/20	EMParts	Oil All Hydraulic Oil 10W30		EA	176.000	5.81	1,021.79
717	08/16/20	EMParts	TO4 Spectra Xtreme TO-4 All season		EA	24.000	5.59	134.18
1230	07/20/20	EMParts	AT379617 Antenna		EA	1.000	62.77	62.77
1766	06/19/20	EMParts	R522690 Gasket-Fan Pump to Engine Cove		EA	1.000	10.93	10.93
1793	06/22/20	EMParts	AH128449 Filter-Hydraulic		EA	2.000	63.56	127.12
1794	06/22/20	EMParts	AHC11572 Seal Kit-Steering Cylinder		EA	1.000	149.79	149.79
1795	06/22/20	EMParts	AHC20488 Seal Kit-Steering Cylinder		EA	1.000	162.50	162.50
1796	06/22/20	EMParts	AM39653 Filter-Oil		EA	1.000	9.38	9.38
1797	06/22/20	EMParts	AT335977 Hyd. Return Filter		EA	1.000	221.45	221.45
1798	06/22/20	EMParts	AT362406 Light Assembly-Singal(LED)		EA	1.000	193.40	193.40
1799	06/22/20	EMParts	AT468647 Filter-Transmission		EA	1.000	66.22	66.22
1800	06/22/20	EMParts	AT470620 Wiper Blade		EA	1.000	65.87	65.87
1801	06/22/20	EMParts	T116416 Seal-O-Ring		EA	8.000	3.42	27.36
1802	06/22/20	EMParts	T170196 Seal-O-Ring		EA	6.000	7.91	47.46
1803	06/22/20	EMParts	T182196 Gasket-Transmission		EA	2.000	11.56	23.12
1804	06/22/20	EMParts	T182254 Gasket-Transmission Modual		EA	2.000	12.83	25.66
1805	06/22/20	EMParts	T242459 Plate		EA	1.000	79.09	79.09
1806	06/22/20	EMParts	T242465 Plate		EA	1.000	75.46	75.46
1807	06/22/20	EMParts	T242467 Seal-O-Ring		EA	2.000	7.17	14.34
2095	06/23/20	EMParts	T129611 Seal-O-Ring		EA	1.000	4.65	4.65
2096	06/23/20	EMParts	Z29864 Seal-O-Ring		EA	1.000	4.00	4.00

Labour Total	0.00
Parts Total	2,391.34
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
3817	06/19/20	PR	Employee: 1577 Dylan Grant		HRS	2.000		



Work Order: 11215

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2432	06/24/20	PR	Employee: 2528 Raymond Carlile		HRS	8.000		
2591	06/24/20	PR	Employee: 2528 Raymond Carlile		HRS	-8.000		
2592	06/24/20	PR	Employee: 2528 Raymond Carlile		HRS	8.000		
3830	06/24/20	PR	Employee: 2528 Raymond Carlile		HRS	-8.000		
3831	06/24/20	PR	Employee: 2528 Raymond Carlile		HRS	8.000		

Labour Total	8.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 4000 Hour Service(No Eng)Check, Adjust Levels and Pressures

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2427	06/22/20	PR	Employee: 1575 Paul Nixon		HRS	5.500		
2583	06/22/20	PR	Employee: 1575 Paul Nixon		HRS	-5.500		
2584	06/22/20	PR	Employee: 1575 Paul Nixon		HRS	5.500		
3820	06/22/20	PR	Employee: 1575 Paul Nixon		HRS	-5.500		
3821	06/22/20	PR	Employee: 1575 Paul Nixon		HRS	5.500		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Check and Repair Leaks

Park Brake Input leaking.
 Possible leak under L/F Accumulator.
 Engine L/H Aux/Fan Pump Leaking.
 Hoses rubbing on inside of air cooler.
 Leak above L/H Boom Cylinder (Hose)
 Leak on Transmission control valve.
 R/H Steering Cylinder Leaking.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2428	06/22/20	PR	Employee: 1575 Paul Nixon		HRS	3.500		
2429	06/23/20	PR	Employee: 1575 Paul Nixon		HRS	6.500		
2585	06/22/20	PR	Employee: 1575 Paul Nixon		HRS	-3.500		
2586	06/22/20	PR	Employee: 1575 Paul Nixon		HRS	3.500		
2587	06/23/20	PR	Employee: 1575 Paul Nixon		HRS	-6.500		



GCS Energy Services Ltd.

Work Order: 11215

2588	06/23/20	PR	Employee: 1575 Paul Nixon	HRS	6.500
3822	06/22/20	PR	Employee: 1575 Paul Nixon	HRS	-3.500
3823	06/22/20	PR	Employee: 1575 Paul Nixon	HRS	3.500
3824	06/23/20	PR	Employee: 1575 Paul Nixon	HRS	-6.500
3825	06/23/20	PR	Employee: 1575 Paul Nixon	HRS	6.500

Labour Total	10.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Check and repair Body Panels

*R/R Engine compartment lower door out of adjustment.
Antenna Broken
1 Rubber bushing missing on inner door latch.
Replace Wiper Blade.
Decal unit and remove rental decals.
R/H Cab window taped in.
L/F Signal half working.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2065	06/19/20	PR	Employee: 1575 Paul Nixon		HRS	4.000		
2425	06/19/20	PR	Employee: 1575 Paul Nixon		HRS	-4.000		
2426	06/19/20	PR	Employee: 1575 Paul Nixon		HRS	4.000		
2430	06/23/20	PR	Employee: 1575 Paul Nixon		HRS	1.500		
2581	06/19/20	PR	Employee: 1575 Paul Nixon		HRS	-4.000		
2582	06/19/20	PR	Employee: 1575 Paul Nixon		HRS	4.000		
2589	06/23/20	PR	Employee: 1575 Paul Nixon		HRS	-1.500		
2590	06/23/20	PR	Employee: 1575 Paul Nixon		HRS	1.500		
3818	06/19/20	PR	Employee: 1575 Paul Nixon		HRS	-4.000		
3819	06/19/20	PR	Employee: 1575 Paul Nixon		HRS	4.000		
3826	06/23/20	PR	Employee: 1575 Paul Nixon		HRS	-1.500		
3827	06/23/20	PR	Employee: 1575 Paul Nixon		HRS	1.500		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Check and Repair Pins and Bushings

*Q/A Pins Stick.
Grapple Pin Squeel.*

Segment: 8 T/S and Repair P.A.S.S.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2431	06/23/20	PR	Employee: 1575 Paul Nixon		HRS	1.000		
3828	06/23/20	PR	Employee: 1575 Paul Nixon		HRS	-1.000		



GCS Energy Services Ltd.

Work Order: 11215

3829 06/23/20 PR Employee: 1575 Paul Nixon

HRS 1.000

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Weld Unit Numbers on to Attachments

Segment: 10 Outsheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2433	06/25/20	PR	Employee: 2471 Greg Royer		HRS	2.000		
3832	06/25/20	PR	Employee: 2471 Greg Royer		HRS	-2.000		
3833	06/25/20	PR	Employee: 2471 Greg Royer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	34.00
Parts Total	2,391.34
Miscellaneous Total	0.00

Description: Repair Leaking Coupler
Equipment: E619 John Deere 644K Loader
Serial#: 1DW644KPCED666091

Date Started: 2020-08-07

Segment: 1 Parts and Service

Segment: 2 Replace leaking coupler

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
3466	07/31/20	PR	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 11397

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Description: Inspection, 350 Hour Service and Repairs	Repair Damaged Door was done on site	Date Started: 2020-08-27
Equipment: E619 John Deere 644K Loader	5599 Hours	
Serial#: 1DW644KPCED666091	RD-2020-274 Insheet	
	RD-2020-295 Outsheets	
	GRO-9758 - 5570 Hours	

Segment: 1 Parts and Service

70G Diesel from Tote

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
487	10/01/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4588503 Line: 1		EA	-1.000	484.09	-484.09
488	10/01/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4588503 Line: 2		EA	-1.000	193.87	-193.87
489	10/01/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4588503 Line: 3		EA	-1.000	74.21	-74.21
490	10/01/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4588503 Line: 4		EA	-1.000	72.47	-72.47
929	10/14/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4588857 Line: 1		EA	-2.000	6.44	-12.88
930	10/14/20	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4588857 Line: 2		EA	-1.000	6.81	-6.81
3450	08/29/20	AP	Vendor: 10034 Brandt Tractor Ltd. 4587474 Line: 1		EA	1.000	6.83	6.83
3451	08/29/20	AP	Vendor: 10034 Brandt Tractor Ltd. 4587474 Line: 2		EA	1.000	4.20	4.20
8	10/01/20	EMParts	AT468647 Filter-Transmission		EA	1.000	63.48	63.48
18	10/05/20	EMParts	AT318789 Seal Kit		EA	1.000	178.84	178.84
19	10/05/20	EMParts	T350654 Gasket		EA	2.000	19.93	39.85
40	10/07/20	EMParts	5W40 Spectra 5W40		I	26.110	5.22	136.18
41	10/07/20	EMParts	H3-24V-70W H3 24V 70W Halogen Bulb		EA	1.000	3.73	3.73
42	10/07/20	EMParts	Oil All Hydraulic Oil 10W30		EA	13.060	5.81	75.82
43	10/07/20	EMParts	R502513 Seal-O-Ring		EA	1.000	12.39	12.39
214	09/09/20	EMParts	AT226229 Gas Cylinder-Grill		EA	1.000	54.33	54.33
215	09/09/20	EMParts	T182758 Clip		EA	1.000	2.95	2.95
1136	09/24/20	EMParts	AHC15497 Seal Kit - Cylinder		EA	1.000	484.09	484.09
1137	09/24/20	EMParts	AHC16724 Seal Kit - Cylinder		EA	1.000	193.87	193.87
1138	09/24/20	EMParts	AT191102 Filter-Cab Air		EA	1.000	13.55	13.55
1139	09/24/20	EMParts	AT223493 Filter-Fuel Inline		EA	1.000	9.88	9.88
1140	09/24/20	EMParts	AT300487 Filter-Air Primary		EA	1.000	35.78	35.78
1141	09/24/20	EMParts	AT307501 Filter-Cab Air Recirculating		EA	1.000	13.14	13.14
1142	09/24/20	EMParts	RE43497 Switch-Heater		EA	1.000	71.40	71.40
1143	09/24/20	EMParts	RE504836 Filter-Oil		EA	1.000	19.73	19.73
1144	09/24/20	EMParts	RE522878 Filter-Fuel		EA	1.000	42.85	42.85
1145	09/24/20	EMParts	RE541922 Filter-Fuel / Water Separator		EA	1.000	44.56	44.56
1146	09/24/20	EMParts	T350654 Gasket		EA	1.000	19.93	19.93
1566	09/25/20	EMParts	AT323022 Harness-Jumper		EA	1.000	72.47	72.47
1567	09/25/20	EMParts	AT357991 Steering Gp		EA	1.000	148.81	148.81
1568	09/25/20	EMParts	AT482674 Steering Gp		EA	1.000	475.49	475.49
1569	09/25/20	EMParts	AT509822 Motor-Wiper		EA	1.000	296.07	296.07
1570	09/25/20	EMParts	T167754 Gasket-Wiper Motor		EA	1.000	43.03	43.03
1716	09/29/20	EMParts	T350654 Gasket		EA	1.000	19.93	19.93
1755	09/29/20	EMParts	T107883 Seal-O-Ring		EA	1.000	6.44	6.44
1756	09/29/20	EMParts	T242459 Plate		EA	1.000	79.09	79.09
1757	09/29/20	EMParts	T242465 Plate		EA	1.000	75.46	75.46
1758	09/29/20	EMParts	T242467 Seal-O-Ring		EA	2.000	8.91	17.82
1759	09/29/20	EMParts	T76938 Seal-O-Ring Face -16		EA	2.000	6.80	13.60
1760	09/29/20	EMParts	T78612 Seal-O-Ring Face -20		EA	1.000	7.80	7.80
1761	09/29/20	EMParts	U12331 Seal-O-Ring		EA	1.000	7.71	7.71



Work Order: 11464

Labour Total	0.00
Parts Total	1,946.77
Miscellaneous Total	0.00

Segment: 2 Straighten Door

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
964	09/18/20	PR	Employee: 2338 Nolan MacGregor		HRS	4.000		
3386	08/28/20	PR	Employee: 1577 Dylan Grant		HRS	0.500		
3387	08/28/20	PR	Employee: 2395 Nickolas Schou		HRS	3.000		
3388	08/31/20	PR	Employee: 1577 Dylan Grant		HRS	1.000		

Labour Total	8.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash/clean cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2540	09/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
2543	09/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	7.000		

Labour Total	10.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Insheet inspection

Segment: 5 350HR service, adjust fluids, tire pressure, grease

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
965	09/18/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		
1442	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
1446	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
1539	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.000		
1540	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
1547	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.000		
1548	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
1678	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.000		
1679	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
1686	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.000		
1687	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		



Work Order: 11464

2513	09/21/20	PR	Employee: 2338 Nolan MacGregor	HRS	-3.000
2514	09/21/20	PR	Employee: 2338 Nolan MacGregor	HRS	3.000
2521	09/22/20	PR	Employee: 2338 Nolan MacGregor	HRS	-3.000
2522	09/22/20	PR	Employee: 2338 Nolan MacGregor	HRS	3.000

Labour Total	8.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Electrical repair: Wipers, horn, lights

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
966	09/18/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
1449	09/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	5.500		
1553	09/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	-5.500		
1554	09/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	5.500		
1692	09/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	-5.500		
1693	09/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	5.500		
1696	09/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	6.000		
1698	09/25/20	PR	Employee: 2338 Nolan MacGregor		HRS	7.000		
2527	09/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	-5.500		
2528	09/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	5.500		
2531	09/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	-6.000		
2532	09/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	6.000		
2535	09/25/20	PR	Employee: 2338 Nolan MacGregor		HRS	-7.000		
2536	09/25/20	PR	Employee: 2338 Nolan MacGregor		HRS	7.000		
2539	09/28/20	PR	Employee: 2338 Nolan MacGregor		HRS	9.000		
2541	09/29/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		

Labour Total	30.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Repair hydraulic and engine oil leaks

Remove side panels from transmission, pull vacuum and remove all hyd pump lines except suction tube. Pull hyd pump back to gain access to transmission control valve.
 Remove control valve, clean, replace gasket plates, reinstall. Replace hyd pump mount o-ring, install pump and all lines. Run/test, get up to temp, no signs of leaks.
 Remove fan pump, found leaking from pump weep hole. Disassemble, cleaned shaft on pump, had to disassemble axle pumps in order to take apart fan pump.
 Clean all parts, reseal fan pump, use sealant on axle pump faces, reassemble and install, connect lines. Run/test for leaks, none present.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
101	10/01/20	PR	Employee: 1575 Paul Nixon		HRS	8.500		
102	10/02/20	PR	Employee: 1575 Paul Nixon		HRS	3.000		
405	10/05/20	PR	Employee: 1575 Paul Nixon		HRS	5.500		



Work Order: 11464

407	10/06/20	PR	Employee: 1575 Paul Nixon	HRS	1.000
1443	09/21/20	PR	Employee: 2338 Nolan MacGregor	HRS	3.000
1447	09/22/20	PR	Employee: 2338 Nolan MacGregor	HRS	2.000
1450	09/23/20	PR	Employee: 2338 Nolan MacGregor	HRS	1.500
1541	09/21/20	PR	Employee: 2338 Nolan MacGregor	HRS	-3.000
1542	09/21/20	PR	Employee: 2338 Nolan MacGregor	HRS	3.000
1549	09/22/20	PR	Employee: 2338 Nolan MacGregor	HRS	-2.000
1550	09/22/20	PR	Employee: 2338 Nolan MacGregor	HRS	2.000
1555	09/23/20	PR	Employee: 2338 Nolan MacGregor	HRS	-1.500
1556	09/23/20	PR	Employee: 2338 Nolan MacGregor	HRS	1.500
1680	09/21/20	PR	Employee: 2338 Nolan MacGregor	HRS	-3.000
1681	09/21/20	PR	Employee: 2338 Nolan MacGregor	HRS	3.000
1688	09/22/20	PR	Employee: 2338 Nolan MacGregor	HRS	-2.000
1689	09/22/20	PR	Employee: 2338 Nolan MacGregor	HRS	2.000
1694	09/23/20	PR	Employee: 2338 Nolan MacGregor	HRS	-1.500
1695	09/23/20	PR	Employee: 2338 Nolan MacGregor	HRS	1.500
1697	09/24/20	PR	Employee: 2338 Nolan MacGregor	HRS	2.500
1699	09/25/20	PR	Employee: 2338 Nolan MacGregor	HRS	1.500
2515	09/21/20	PR	Employee: 2338 Nolan MacGregor	HRS	-3.000
2516	09/21/20	PR	Employee: 2338 Nolan MacGregor	HRS	3.000
2523	09/22/20	PR	Employee: 2338 Nolan MacGregor	HRS	-2.000
2524	09/22/20	PR	Employee: 2338 Nolan MacGregor	HRS	2.000
2529	09/23/20	PR	Employee: 2338 Nolan MacGregor	HRS	-1.500
2530	09/23/20	PR	Employee: 2338 Nolan MacGregor	HRS	1.500
2533	09/24/20	PR	Employee: 2338 Nolan MacGregor	HRS	-2.500
2534	09/24/20	PR	Employee: 2338 Nolan MacGregor	HRS	2.500
2537	09/25/20	PR	Employee: 2338 Nolan MacGregor	HRS	-1.500
2538	09/25/20	PR	Employee: 2338 Nolan MacGregor	HRS	1.500
2542	09/29/20	PR	Employee: 2338 Nolan MacGregor	HRS	4.000
2544	09/30/20	PR	Employee: 1575 Paul Nixon	HRS	1.500
2545	09/30/20	PR	Employee: 2338 Nolan MacGregor	HRS	0.500

Labour Total	34.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Repair seat hard to move, adjust mirrors

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
967	09/18/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
1444	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
1543	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
1544	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
1682	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
1683	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
2517	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
2518	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		



Work Order: 11464

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Repair bent steps, mudflaps, door latches, covers

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
968	09/18/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
1445	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
1448	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
1545	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.500		
1546	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
1551	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.000		
1552	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
1684	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.500		
1685	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
1690	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.000		
1691	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
2519	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.500		
2520	09/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
2525	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.000		
2526	09/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
2546	09/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Outsheet

Outsheet/checkover/pictures. Adjust steering column tilt shock. Fuel up unit with leftover fuel in red slip tank. Park up front.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
406	10/06/20	PR	Employee: 1575 Paul Nixon		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	100.50
Parts Total	1,946.77
Miscellaneous Total	0.00



Work Order: 11658

Description: Boost	GRO 7046/7245	Date Started: 2020-10-23
Equipment: E619 John Deere 644K Loader		
Serial#: 1DW644KPCED666091		

Segment: 1 parts

Segment: 2 Boost Batteries

Scott Sadler Replaced Batteries March 2021
2x GX31A Battery (Iron Creek) (\$110.00 + \$27.00 Core)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1277	10/23/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
						Labour Total	1.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 3 program control settings to turn off security start passcode

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1280	11/26/20	PR	Employee: 1266 Braden Bitzer		HRS	0.500		
						Labour Total	0.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	1.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Description: Diagnose Transmission overheat - R&R oil filter	5881 HRS, GRO 9133	Date Started: 2022-01-19
Equipment: E619 John Deere 644K Loader		
Serial#: 1DW644KPCED666091		

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
434	01/19/22	EMParts	AT336140 Filter-Transmission		EA	1.000	14.67	14.67
435	01/19/22	EMParts	TO4 Spectra Xtreme TO-4 All season		EA	10.000	6.23	62.32



Work Order: 12761

Labour Total	0.00
Parts Total	76.99
Miscellaneous Total	0.00

Segment: 2 Diagnose Transmission overheating - R&R oil filter & add oil

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
861	01/19/22	PR	Employee: 1266 Braden Bitzer		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	1.00
Parts Total	76.99
Miscellaneous Total	0.00

Description: Outsheet checkover & service 5921 HRS, GRO 9756 Date Started: 2022-03-09
 Equipment: E619 John Deere 644K Loader
 Serial#: 1DW644KPCED666091

Segment: 1 PARTS

2 x grommet
 1 x cotter pin

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
367	03/15/22	EMParts	RE504836 Filter-Oil		EA	1.000	22.45	22.45
368	03/15/22	EMParts	RE522878 Filter-Fuel		EA	1.000	35.75	35.75
369	03/15/22	EMParts	RE541922 Filter-Fuel / Water Separator		EA	1.000	38.69	38.69
370	03/15/22	EMParts	AT191102 Filter-Cab Air		EA	1.000	14.98	14.97
371	03/15/22	EMParts	AT307501 Filter-Cab Air Recirculating		EA	1.000	13.89	13.89
372	03/15/22	EMParts	AT300487 Filter-Air Primary		EA	1.000	88.30	88.30
373	03/15/22	EMParts	5W40 Spectra 5W40		I	26.000	5.34	138.85
374	03/15/22	EMParts	WWFluid Window Washer Fluid -35/-40C (208L drums added to tote)		EA	4.000	1.23	4.93
375	03/15/22	EMParts	60/40 Rad-Cool Antifreeze		EA	2.000	6.27	12.54
376	03/15/22	EMParts	AT223493 Filter-Fuel Inline		EA	1.000	9.94	9.94

Labour Total	0.00
Parts Total	380.31
Miscellaneous Total	0.00

Segment: 2 WASH

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
795	03/09/22	PR	Employee: 2392 Carmen Beck		HRS	1.000		



GCS Energy Services Ltd.

Work Order: 12905

796	03/10/22 PR	Employee: 2392 Carmen Beck	HRS	2.000
797	03/15/22 PR	Employee: 2392 Carmen Beck	HRS	2.000

Labour Total	5.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Outsheet checkover & Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
798	03/15/22 PR		Employee: 1266 Braden Bitzer		HRS	7.500		

Labour Total	7.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	12.50
Parts Total	380.31
Miscellaneous Total	0.00

Description: Inspections and Repairs	6225 Hours	Date Started: 2022-06-29
Equipment: E619 John Deere 644K Loader	6271 Next service Due	
	RD-2022-185 Insheet	
	RD-2022-195 Outsheets	
Serial#: 1DW644KPCED666091		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
524	07/12/22 AP		Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6636491.001		LS	0.000	0.00	44.22
74	08/03/22 EMParts		Dyed Diesel Dyed Diesel		EA	18.170	1.54	28.05

Labour Total	0.00
Parts Total	72.27
Miscellaneous Total	0.00

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
868	07/14/22 PR		Employee: 2471 Greg Royer		HRS	3.000		
2373	06/29/22 PR		Employee: 2395 Nickolas Schou		HRS	2.000		



Work Order: 13232

Labour Total	5.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Segment: 4 T/S codes

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
866	07/12/22	PR	Employee: 2873 Isaac Simpkin		HRS	5.000		

Labour Total	5.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Replace bucket hardware

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
867	07/12/22	PR	Employee: 2873 Isaac Simpkin		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	11.50
Parts Total	72.27
Miscellaneous Total	0.00

Description: Rental Return-Emsco	6225 Hours	Date Started: 2022-06-30
Equipment: E619 John Deere 644K Loader	6271 Next service Due	
	RD-2022-185 Insheet	
	RD-2022-195 Outsheet	
Serial#: 1DW644KPCED666091		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
75	08/03/22	EMParts	5W40 Spectra 5W40		I	26.000	5.92	153.95
156	07/14/22	EMParts	AT191102 Filter-Cab Air		EA	1.000	12.55	12.55
157	07/14/22	EMParts	AT223493 Filter-Fuel Inline (Alt#P55177		EA	1.000	11.77	11.77
158	07/14/22	EMParts	AT300487 Filter-Air Primary		EA	1.000	56.79	56.79
159	07/14/22	EMParts	AT307501 Filter-Cab Air Recirculating		EA	1.000	11.41	11.41
160	07/14/22	EMParts	Dyed Diesel Dyed Diesel		EA	172.240	1.54	265.85
161	07/14/22	EMParts	RE504836 Filter-Oil		EA	1.000	24.97	24.97
162	07/14/22	EMParts	RE522878 Filter-Fuel		EA	1.000	35.71	35.71



GCS Energy Services Ltd.

Work Order: 13234

163	07/14/22	EMParts	RE541922 Filter-Fuel / Water Separator	EA	1,000	39.53	39.53
166	07/14/22	EMParts	AH162914 Strainer-Fuel	EA	1,000	90.88	90.88
167	07/14/22	EMParts	AL76568 Knob	EA	1,000	24.70	24.70
168	07/14/22	EMParts	AT460262 Cover-Battery Disconnect	EA	1,000	126.33	126.33

Labour Total	0.00
Parts Total	854.44
Miscellaneous Total	0.00

Segment: 2 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
300	07/04/22	PR	Employee: 2623 Brenton Woolman		HRS	5.000		
2372	06/30/22	PR	Employee: 2623 Brenton Woolman		HRS	8.500		

Labour Total	13.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
863	07/11/22	PR	Employee: 2873 Isaac Simpkin		HRS	3.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Replace Aux. Couplers and Reinstall Hose Wrap on Hose's

*Has Different style Aux coupler on, originals are in cab.
Re-install hose wrap on quick connect lines.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
864	07/12/22	PR	Employee: 2873 Isaac Simpkin		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Install Fuel Screen, Fan Knob and Disconnet Door

*No Fuel Screen.
Master Disconnect access panel door damaged.
Fan Control Knob missing.*



Work Order: 13234

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
865	07/13/22	PR	Employee: 2873 Isaac Simpkin		HRS	2.500		

Labour Total 2.50

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 21.50

Parts Total 854.44

Miscellaneous Total 0.00

Description: Checkover& install blade for snow removal 6265 HRS, GRO **Date Started:** 2022-11-08
Equipment: E619 John Deere 644K Loader 7739/7899/7866/7914/
Serial#: 1DW644KPCED666091

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
260	11/08/22	EMParts	Oil All Hydraulic Oil 10W30		EA	8.000	5.82	46.52
838	11/28/22	EMParts	3600008 Cord-Block Heater 90* connecto		EA	1.000	38.32	38.32
1483	11/29/22	EMParts	Oil All Hydraulic Oil 10W30		EA	8.000	5.82	46.52

Labour Total 0.00

Parts Total 131.36

Miscellaneous Total 0.00

Segment: 2 install blade, Checkover hyd hoses & top up oil

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
633	11/08/22	PR	Employee: 2024 Travis Schmidt		HRS	1.500		

Labour Total 1.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 3 R&R block heater cord & plug

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
469	12/02/22	PR	Employee: 2024 Travis Schmidt		HRS	0.500		
1284	11/25/22	PR	Employee: 2024 Travis Schmidt		HRS	0.500		



Work Order: 13633

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Mount cardboard as winter cover around oil cooler

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2424	11/29/22	PR	Employee: 1266 Braden Bitzer		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	3.00
Parts Total	131.36
Miscellaneous Total	0.00

Description: Repair Leaks	Unit in Hardisty	Date Started: 2023-06-19
Equipment: E619 John Deere 644K Loader		
Serial#: 1DW644KPCED666091		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
342	06/19/23	EMParts	DZ104989 Line-Fuel		EA	1.000	118.85	118.85

Labour Total	0.00
Parts Total	118.85
Miscellaneous Total	0.00

Segment: 2 Replace Leaking fuel line to pump

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
284	12/12/23	EMAdj	Troy Schmidt 7/24/23		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 14160

Labour Total	0.50
Parts Total	118.85
Miscellaneous Total	0.00

Description: Reg Maintenance
 Equipment: E619 John Deere 644K Loader
 Serial#: 1DW644KPCED666091

Date Started: 2023-07-26

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1212	07/25/23	EMParts	60/40 Rad-Cool Antifreeze		EA	3.000	6.79	20.36
1213	07/25/23	EMParts	DAY 80232GL 3/4"IDxFT GOLD RADIATOR COOLANT HEATER HOSE		ft	6.000	4.99	29.94

Labour Total	0.00
Parts Total	50.30
Miscellaneous Total	0.00

Segment: 2 R&R fuel line (time & parts on WO#14160)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1476	07/24/23	PR	Employee: 28 Troy Schmidt		HRS	0.500		
283	12/12/23	EMAdj	Troy schmidt 7/24/23		HRS	-0.500		

Labour Total	0.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 R&R split coolant line

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1477	07/25/23	PR	Employee: 28 Troy Schmidt		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 repair fire Ext bracket

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
540	12/04/23	PR	Employee: 2024 Travis Schmidt		HRS	0.500		



Work Order: 14235

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	3.50
Parts Total	50.30
Miscellaneous Total	0.00

Description: Reg Maintenance	GRO#11193/11148/7627/7713	Date Started: 2024-03-01
Equipment: E619 John Deere 644K Loader	HOURS:6581	
Serial# 1DW644KPCED666091	Next Service 6881 hours	

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1250	06/20/24	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-480358 Line: 1	EA		4.000	3.87	15.48
47	03/05/24	EMParts	AR50411 Wiring L		EA	1.000	45.51	45.51
48	03/05/24	EMParts	RE42139 Block Heater		EA	1.000	174.28	174.28
1432	05/31/24	EMParts	AT300487 Filter-Air Primary		EA	1.000	70.07	70.07
1433	05/31/24	EMParts	AT307501 Filter-Cab Air Recirculating		EA	1.000	17.22	17.22
1434	05/31/24	EMParts	AT191102 Filter-Cab Air		EA	1.000	15.57	15.57
1435	05/31/24	EMParts	RE504836 Filter-Oil		EA	1.000	22.45	22.45
1436	05/31/24	EMParts	RE522878 Filter-Fuel		EA	1.000	53.17	53.17
1437	05/31/24	EMParts	RE541922 Filter-Fuel / Water Separator		EA	1.000	54.58	54.58
1438	05/31/24	EMParts	AT223493 Filter-Fuel Inline (P551770 Alt#)		EA	1.000	12.91	12.91

Labour Total	0.00
Parts Total	481.24
Miscellaneous Total	0.00

Segment: 2 Change cutting edges/remove rear pedestals

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1826	02/29/24	PR	Employee: 3119 Shawn Dittmer		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 fix skid shoe

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



Work Order: 14762

1827 02/29/24 PR Employee: 28 Troy Schmidt HRS 1.500

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 drain coolant/replace block heater

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
632	03/08/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Service/Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1357	05/31/24	PR	Employee: 3119 Shawn Dittmer		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	9.50
Parts Total	481.24
Miscellaneous Total	0.00

Description: Reg Maintenance	GRO#13583/13587	Date Started: 2024-12-05
Equipment: E619 John Deere 644K Loader	6633 hours	
Serial#: 1DW644KPCED666091		

Segment: 1 parts

Segment: 2 grease took 3 tubes

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
326	12/05/24	PR	Employee: 2024 Travis Schmidt		HRS	1.500		



Work Order: 15185

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 cut & drill broken skid plate

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
525	12/10/24	PR	Employee: 2024 Travis Schmidt		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Description: Reg Maintenance	GRO13806/13825/13876/12254/1227	Date Started: 2025-05-01
Equipment: E619 John Deere 644K Loader	3	
Serial#: 1DW644KPCED666091	6671 hours April 2025	

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
43	05/02/25	EMParts	51M7089 Seal-O-Ring		EA	1.000	4.76	4.76
44	05/02/25	EMParts	AT162848 Receiver-Dryer		EA	1.000	0.00	0.00
45	05/02/25	EMParts	AT451825 Hose Assembly-A/C Compressor		EA	1.000	329.70	329.70
46	05/02/25	EMParts	R183409 Seal-O-Ring		EA	2.000	5.30	10.60
47	05/02/25	EMParts	R183410 Seal-O-Ring		EA	1.000	6.70	6.70
64	06/05/25	EMParts	AT451825 Hose Assembly-A/C Compressor to Condenser		EA	1.000	329.70	329.70
65	06/05/25	EMParts	R183410 Seal-O-Ring		EA	1.000	5.11	5.11
66	06/05/25	EMParts	51M7089 Seal-O-Ring		EA	1.000	4.76	4.76
301	05/26/25	EMParts	AT322830 Hose Assembly-A/C		EA	1.000	298.04	298.04
302	05/26/25	EMParts	R183409 Seal-O-Ring		EA	2.000	4.03	8.06

Labour Total	0.00
Parts Total	997.43
Miscellaneous Total	0.00

Segment: 2 Inspect

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1124	04/30/25	PR	Employee: 3119 Shawn Dittmer		HRS	8.000		



Work Order: 15338

Labour Total	8.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 R&R air dryer

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
426	05/15/25	PR	Employee: 3119 Shawn Dittmer		HRS	1.500		
427	05/16/25	PR	Employee: 3119 Shawn Dittmer		HRS	7.000		

Labour Total	8.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 wash/cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
428	05/21/25	PR	Employee: 3185 Cameron Sakaluk		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 R&R A/C lines

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
152	06/04/25	PR	Employee: 3119 Shawn Dittmer		HRS	3.000		
423	06/13/25	PR	Employee: 3119 Shawn Dittmer		HRS	3.500		

Labour Total	6.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Replace cover plates

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
424	06/16/25	PR	Employee: 3119 Shawn Dittmer		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 15338

Labour Total	28.00
Parts Total	997.43
Miscellaneous Total	0.00