



Work Order: 10081

EB10-215

Description: 350 Hour Service and Repairs	682 Hours	Date Started: 2018-05-02
Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer	RD-2108-187 Insheet RD-2018-239 Outsheet	
Serial#: 901583531016		

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
71	05/07/18	EMParts	Dyed Diesel Dyed Diesel		EA	10.220	1.10	11.28
119	08/13/18	EMParts	50/50 Rad-Cool Antifreeze		EA	4.000	5.00	20.00
142	07/06/18	EMParts	1174416 Filter-Oil		EA	1.000	5.05	5.05
143	07/06/18	EMParts	2229020 Filter-Air Primary		EA	1.000	37.18	37.18
144	07/06/18	EMParts	4130241 Filter-Fuel / Water Seperator		EA	1.000	122.64	122.64
145	07/06/18	EMParts	4131534 Filter-Fuel		EA	1.000	128.33	128.33
146	07/06/18	EMParts	24505 Lock-Out Lever Kit		EA	1.000	11.01	11.01
147	07/06/18	EMParts	2484 Master Disconnect Switch		EA	1.000	39.04	39.04
148	07/06/18	EMParts	5576205 Dash Vent		EA	1.000	45.81	45.81
149	07/06/18	EMParts	05751196 Interior Light		EA	1.000	155.90	155.90
203	07/11/18	EMParts	AT349466 Grease Seal-Split(200 Series)		EA	1.000	50.59	50.59

Labour Total	0.00
Parts Total	626.83
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
72	05/07/18	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
111	08/13/18	EMTime	Employee: 1074 Jack Lougheed		HRS	6.500		

Labour Total	6.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Straighten abd Adjust Drum Scrapers



GCS Energy Services Ltd.

Work Order: 10081

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
112	08/13/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	4.000		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Top up Coolant

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
113	08/13/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Install Master Disconnect Switch

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
114	08/13/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	6.000		

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
115	08/13/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Repair Emergency stop switch, Replace louver and Fuses

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
116	08/13/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	2.000		



Work Order: 10081

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Replace Hydraulic hose's for Pump and Steering

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
117	08/13/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Outsheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
118	08/13/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	26.00
Parts Total	626.83
Miscellaneous Total	0.00

Description: Repair Hose Leaks Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer Serial#: 901583531016	743 Hours GRO#7570	Date Started: 2019-04-02
--	-----------------------	---------------------------------

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
206	04/05/19	AP	Vendor: 10132 Gregg Distributors LP 017-023088 Line: 1		LS	0.000	0.00	96.38
247	04/02/19	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4570933 Line: 3		LS	0.000	0.00	35.00
37	04/02/19	EMParts	05550662 Hose Assembly		EA	1.000	121.05	121.05
38	04/02/19	EMParts	05550873 Hose Assembly		EA	1.000	57.39	57.39
201	04/08/19	EMParts	05550873 Hose Assembly		EA	-1.000	57.39	-57.39

Labour Total	0.00
Parts Total	252.43
Miscellaneous Total	0.00



GCS Energy Services Ltd.

Work Order: 10381

Segment: 2 Replace Hydraulic Drain Hose

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
196	04/08/19	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 3 Replace Diff. Pilot Hose

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
197	04/08/19	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 4 Change Hydraulic Fluid

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
198	04/08/19	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 5 Boost Unit and Test Batteries

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
199	04/08/19	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 6 Have new diff pilot hose made

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
200	04/08/19	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		



Work Order: 10381

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	5.00
Parts Total	252.43
Miscellaneous Total	0.00

Description: Inspection's and Repairs	743 Hours	Date Started: 2019-10-24
Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer	RD-2019-280 Insheet RD-2019-296 Outsheets	
Serial#: 901583531016		

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
170	11/04/19	AP	Vendor: 10651 Ko-Hen Electronics Supply Ltd. 0000387682 Line: 1		EA	1.000	20.79	20.79
1400	10/23/19	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5614874.001 Line: 1		EA	1.000	122.64	122.64
1401	10/25/19	AP	Vendor: 10132 Gregg Distributors LP 059-254322 Line: 3		EA	2.000	0.49	0.98
39	11/04/19	EMParts	50/50 Rad-Cool Antifreeze		EA	1.000	5.40	5.40
40	11/04/19	EMParts	Dyed Diesel Dyed Diesel		EA	115.450	0.83	95.29
66	11/05/19	EMParts	55014 Switch-SPST 12V 25 Amp		EA	1.000	6.80	6.80
96	11/05/19	EMParts	TO4 Spectra Xtreme TO-4 All season		EA	8.000	5.73	45.82
411	10/24/19	EMParts	9X2045 Screw-Truss Head (M6x1x20mm)		EA	2.000	1.42	2.84

Labour Total	0.00
Parts Total	300.56
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
95	11/05/19	EMTime	Employee: 2338 Nolan MacGregor		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
94	11/05/19	EMTime	Employee: 1074 Jack Loughheed		HRS	6.000		



Work Order: 10554

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Drained Hydraulic fluid, replace main hose and refill

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
93	11/05/19	EMTime	Employee: 2395 Nickolas Schou		HRS	4.500		

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Top up coolant

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
92	11/05/19	EMTime	Employee: 2395 Nickolas Schou		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Check Diff. and Drum Fluid level

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
91	11/05/19	EMTime	Employee: 2395 Nickolas Schou		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Test unit for leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
90	11/05/19	EMTime	Employee: 2395 Nickolas Schou		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 T/S P.A.S.S. and Repair



Work Order: 10554

Found switch missing, wires taped up.
Install switch, replace blown fuse and test.
Works fine

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
88	11/05/19	EMTime	Employee: 1575 Paul Nixon		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 9 Outsheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
89	11/05/19	EMTime	Employee: 1575 Paul Nixon		HRS	2.000		
						Labour Total		2.00
						Parts Total		0.00
						Miscellaneous Total		0.00
						Labour Total		19.50
						Parts Total		300.56
						Miscellaneous Total		0.00

Description: Repair Leaks Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer Serial#: 901583531016	750 HRS, GRO#5477/5478/5489/5309/5315/5280/ 5282	Date Started: 2020-04-30
---	---	---------------------------------

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
14	05/04/20	EMParts	05550662 Hose Assembly		EA	1.000	121.05	121.05
16	05/04/20	EMParts	05551712 Hose Assembly		EA	2.000	379.15	758.30
17	05/04/20	EMParts	05554763 Hose Assembly		EA	1.000	318.15	318.15
18	05/04/20	EMParts	05554764 Hose Assembly(124Plus-12x143"O		EA	1.000	320.46	320.46
354	05/11/20	EMParts	Zink Free Multoil 5w20 Zink-Free Hydraulic Oil		EA	10.000	5.46	54.56
355	05/11/20	EMParts	58080120 Pillow Block		EA	1.000	68.90	68.90
1354	04/30/20	EMParts	05554906 Hose Assembly(G103-08x27.5"OAL		EA	2.000	24.08	48.16
3018	04/30/20	EMParts	60/40 Rad-Cool Antifreeze		EA	7.000	6.02	42.15
						Labour Total		0.00
						Parts Total		1,731.73
						Miscellaneous Total		0.00



Work Order: 11039

Segment: 2 Checkover and outsheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1566	04/29/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
1568	04/30/20	PR	Employee: 1266 Braden Bitzer		HRS	2.000		
2716	04/29/20	PR	Employee: 1266 Braden Bitzer		HRS	-1.000		
2717	04/29/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
2720	04/30/20	PR	Employee: 1266 Braden Bitzer		HRS	-2.000		
2721	04/30/20	PR	Employee: 1266 Braden Bitzer		HRS	2.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair PAS

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1567	04/29/20	PR	Employee: 1266 Braden Bitzer		HRS	0.500		
2718	04/29/20	PR	Employee: 1266 Braden Bitzer		HRS	-0.500		
2719	04/29/20	PR	Employee: 1266 Braden Bitzer		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 R&R hydraulic hoses

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
284	05/05/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
552	05/05/20	PR	Employee: 1266 Braden Bitzer		HRS	-1.000		
553	05/05/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
554	05/08/20	PR	Employee: 2024 Travis Schmidt		HRS	4.000		
555	05/11/20	PR	Employee: 1266 Braden Bitzer		HRS	3.500		
1327	05/05/20	PR	Employee: 1266 Braden Bitzer		HRS	-1.000		
1328	05/05/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
1329	05/08/20	PR	Employee: 2024 Travis Schmidt		HRS	-4.000		
1330	05/08/20	PR	Employee: 2024 Travis Schmidt		HRS	4.000		
1331	05/11/20	PR	Employee: 1266 Braden Bitzer		HRS	-3.500		
1332	05/11/20	PR	Employee: 1266 Braden Bitzer		HRS	3.500		
1333	05/11/20	PR	Employee: 2024 Travis Schmidt		HRS	1.000		
1569	04/30/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
2722	04/30/20	PR	Employee: 1266 Braden Bitzer		HRS	-1.000		
2723	04/30/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		



Work Order: 11039

Labour Total	10.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
556	05/12/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
1334	05/11/20	PR	Employee: 2216 Masin Schmidt		HRS	0.500		
1335	05/12/20	PR	Employee: 1266 Braden Bitzer		HRS	-1.000		
1336	05/12/20	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
2724	04/30/20	PR	Employee: 2392 Carmen Beck		HRS	1.000		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Found engine light problem - zip tied harness together

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
557	05/12/20	PR	Employee: 1266 Braden Bitzer		HRS	0.500		
1337	05/12/20	PR	Employee: 1266 Braden Bitzer		HRS	-0.500		
1338	05/12/20	PR	Employee: 1266 Braden Bitzer		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	17.00
Parts Total	1,731.73
Miscellaneous Total	0.00

Description: Repair blown fuse for PAS 757 HRS, GRO#5363 **Date Started:** 2020-05-27
Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer
Serial#: 901583531016

Segment: 1 parts

1 x ATC-25 25A fuse

Segment: 2 Diagnose PAS not tripping - R&R 20A fuse

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



GCS Energy Services Ltd.

Work Order: 11141

2219	05/27/20	PR	Employee: 1266 Braden Bitzer	HRS	1.000
2780	05/27/20	PR	Employee: 1266 Braden Bitzer	HRS	-1.000
2781	05/27/20	PR	Employee: 1266 Braden Bitzer	HRS	1.000

Labour Total 1.00

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 1.00

Parts Total 0.00

Miscellaneous Total 0.00

Description: Checkover & Repair hyd leak

Date Started: 2021-09-24

Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer

Serial#: 901583531016

Segment: 1 parts

2L x wiper fluid

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1158	09/28/21	AP	Vendor: 21172 SMS Equipment Inc. PSI/71156008 Line: 4		EA	1.000	25.51	25.51
960	09/24/21	EMParts	5W40 Spectra 5W40		I	2.000	5.34	10.68
961	09/24/21	EMParts	60/40 Rad-Cool Antifreeze		EA	4.000	6.27	25.09
2265	09/28/21	EMParts	06312234 V-Belt (A/C)		EA	-1.000	25.51	-25.51

Labour Total 0.00

Parts Total 35.77

Miscellaneous Total 0.00

Segment: 2 Checkover & top up fluids

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1113	09/24/21	PR	Employee: 1266 Braden Bitzer		HRS	1.000		

Labour Total 1.00

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 3 Repair RF motor mount bracket & A/C compressor mount

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1114	09/24/21	PR	Employee: 1266 Braden Bitzer		HRS	1.000		
1116	09/27/21	PR	Employee: 1266 Braden Bitzer		HRS	2.000		



Work Order: 12441

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Tighten hyd drain & tank hose to fix leak

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1115	09/24/21	PR	Employee: 1266 Braden Bitzer		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 outsheet checkover

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1117	09/27/21	PR	Employee: 1266 Braden Bitzer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 WASH

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1404	09/27/21	PR	Employee: 2392 Carmen Beck		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	9.00
Parts Total	35.77
Miscellaneous Total	0.00

Description: T/S and Repair Broken Belt	Unit at Darfield BC Site	Date Started: 2021-11-19
Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer	943 Hours.	
Serial#: 901583531016		

Segment: 1 Parts



Work Order: 12604

Segment: 2 T/S and Repair Broken fan belt

Replace belt. Boost batteries. Tested okay.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1894	11/26/21	PR	Employee: 2395 Nickolas Schou		HRS	1.500		
						Labour Total	1.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	1.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Description: T/S and Repair Starting Issue
Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer
Serial#: 901583531016
 Unit at Darfield BC Site.
 971 Hours.
Date Started: 2022-02-24

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
24	04/05/22	EMParts	58260382 Switch-Proximity Park Brake (N.O.)		EA	-1.000	271.01	-271.01
64	08/03/22	EMParts	Oil All Hydraulic Oil 10W30		EA	5.000	5.75	28.75
659	02/25/22	EMParts	05566565 Switch-Proximity Park Brake (N		EA	1.000	257.48	257.48
660	02/25/22	EMParts	58260382 Switch-Proximity Park Brake (N		EA	1.000	407.28	407.28
						Labour Total	0.00	
						Parts Total	422.50	
						Miscellaneous Total	0.00	

Segment: 2 T/S and Repair Starting Issue

Hard time starting unit doesn't recognize it's in park.
 Replace park brake sensor.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
743	03/16/22	PR	Employee: 2395 Nickolas Schou		HRS	2.500		
						Labour Total	2.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	



Work Order: 12845

Segment: 3 Repair hyd leaks

Replace hydraulic line under packer.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
97	04/01/22	PR	Employee: 2395 Nickolas Schou		HRS	5.000		

Labour Total 5.00

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 7.50

Parts Total 422.50

Miscellaneous Total 0.00

Description: 350 Hour Service
Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer
Serial#: 901583531016
 Unit at BlackPool BC Site. 1005
Date Started: 2022-06-06

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
127	06/06/22	EMParts	05710631 Filter-Oil		EA	1.000	20.08	20.08
128	06/06/22	EMParts	08820065 Filter-Fuel		EA	1.000	156.69	156.69
129	06/06/22	EMParts	08820067 Filter-Fuel		EA	1.000	180.63	180.63
130	06/06/22	EMParts	2229020 Filter-Air Primary		EA	1.000	37.21	37.21
582	07/27/22	EMParts	5W40 Spectra 5W40		I	8.000	5.92	47.37

Labour Total 0.00

Parts Total 441.98

Miscellaneous Total 0.00

Segment: 2 350 Hour Service

350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
472	06/08/22	PR	Employee: 2395 Nickolas Schou		HRS	2.500		

Labour Total 2.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 3 Repair Door Handle



Work Order: 13162

Segment: 4 Replace hyd hose

Replace hydraulic return line from cooler to reservoir.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
473	06/09/22	PR	Employee: 2395 Nickolas Schou		HRS	1.000		
						Labour Total	1.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 5 Repair A/C compressor mounting bolts

A/C compressor had 2 broken mounting bolts, removed compressor, drilled out bolts, tapped holds and re-installed.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
474	06/09/22	PR	Employee: 2395 Nickolas Schou		HRS	1.500		
						Labour Total	1.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	5.00	
						Parts Total	441.98	
						Miscellaneous Total	0.00	

Description: Inspections and Repairs	1045 Hours	Date Started: 2022-09-12
Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer	RD-2022-226 Insheet RD-2022-252 Outsheet	
Serial#: 901583531016		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1115	09/15/22	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6710272.001 Line: 1		EA	2.000	21.42	42.84
63	10/06/22	EMParts	60/40 Rad-Cool Antifreeze		EA	4.000	6.05	24.19
64	10/06/22	EMParts	Dyed Diesel Dyed Diesel		EA	127.291	1.54	196.02
65	10/06/22	EMParts	Zink Free Multoil 5w20 Zink-Free Hydraul		EA	4.000	6.25	24.98
						Labour Total	0.00	
						Parts Total	288.03	
						Miscellaneous Total	0.00	



Work Order: 13420

Segment: 2 Inspections

*Insheet Inspection.
Outsheet Inspection. Top up fuel. Park unit up front.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
596	10/05/22	PR	Employee: 2471 Greg Royer		HRS	2.000		
648	09/07/22	PR	Employee: 2873 Isaac Simpkin		HRS	2.000		
652	09/16/22	PR	Employee: 2873 Isaac Simpkin		HRS	0.500		
						Labour Total	4.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 3 Wash and Clean Cab

*Exterior outer air filter dirty. Needs to be blown out. Not bad enough to replace.
Front drum is very dirty/muddy. Under cab is oily & full of grime & engine.
Bay full of grime/oily residue.
Cab is dusty/dirty.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
650	09/15/22	PR	Employee: 2623 Brenton Woolman		HRS	6.500		
						Labour Total	6.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 4 Check, adjust fluids and Repair leaks

*Fuel lines to fuel filter cracked. Need to be replaced. 05554906.
Rubbing line off valve bank R side needs to be wrapped.
Hyd cooler line & area covered in oily residue & grime. Clean & verify.
Coolant needs top up.
Hyd fluid needs top up.
Few grimey/oily lines under cab. Clean & verify.
Valve bank looks wet. Clean & verify.
Pin for fire extinguisher bracket broken. Needs replacement.
Wiper fluid need top up.
Check diff fluid. Clean & verify oily residue on lines & valve bank.
Top up fluids.
Wrap rubbing lines.
Blow out exterior outer air filter.
Check front & rear planetaries.
Replace pin for fire extinguisher & remove extinguisher & spill kit.
Replace fuel lines.
Check diff fluid.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
649	09/07/22	PR	Employee: 2873 Isaac Simpkin		HRS	1.500		
651	09/15/22	PR	Employee: 2873 Isaac Simpkin		HRS	0.500		



Work Order: 13420

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	13.00
Parts Total	288.03
Miscellaneous Total	0.00

Description: Reg Maintenance	Date Started: 2023-09-25
Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer	
Serial#: 901583531016	

Segment: 1 parts

Segment: 2 complete In/Out inspection as per sheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1500	09/22/23	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		
						Labour Total		2.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 3 wash/bleach

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1501	09/22/23	PR	Employee: 22 Garrett Nelson		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00
						Labour Total		3.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Description: Reg Maintenance	GRO11905/13633	Date Started: 2024-08-09
Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer	1380 hours Nov 20 2024	
Serial#: 901583531016		



Work Order: 15003

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
125	08/06/24	EMParts	2229021 Filter-Air Secondary		EA	1.000	36.63	36.63
126	08/06/24	EMParts	2229020 Filter-Air Primary		EA	1.000	37.18	37.18
127	08/06/24	EMParts	PH2816 Lubrifiner oil filter		EA	1.000	8.25	8.25
128	08/06/24	EMParts	4130241 Filter-Fuel / Water Seperator		EA	1.000	122.64	122.64
129	08/06/24	EMParts	4131534 Filter-Fuel		EA	1.000	128.33	128.33
130	08/06/24	EMParts	5W40 Spectra Xtreme 5W40 (CK-4)		I	7.000	5.52	38.65
						Labour Total	0.00	
						Parts Total	371.68	
						Miscellaneous Total	0.00	

Segment: 2 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
420	08/06/24	PR	Employee: 3142 Trina Schmidt		HRS	2.000		
664	11/19/24	PR	Employee: 3185 Cameron Sakaluk		HRS	3.000		
666	11/21/24	PR	Employee: 22 Garrett Nelson		HRS	1.500		
						Labour Total	6.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 3 Complete Service & Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
421	08/06/24	PR	Employee: 3119 Shawn Dittmer		HRS	5.000		
665	11/20/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		
						Labour Total	7.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	13.50	
						Parts Total	371.68	
						Miscellaneous Total	0.00	

Description: Reg Maintenance	GRO12278	Date Started: 2025-06-20
Equipment: E539 Bomag BW211D-40 84" Smooth Drum Packer	1381 hours	
Serial#: 901583531016		



GCS Energy Services Ltd.

Work Order: 15404

Segment: 1 parts

Segment: 2 Recharge A/C

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
413	06/18/25	PR	Employee: 3119 Shawn Dittmer		HRS	2.500		

Labour Total	2.50
--------------	------

Parts Total	0.00
-------------	------

Miscellaneous Total	0.00
---------------------	------

Labour Total	2.50
--------------	------

Parts Total	0.00
-------------	------

Miscellaneous Total	0.00
---------------------	------