



Work Order: 10502

EB10-221

Description: T/S air restriction code	2066 Hours	Date Started: 2019-08-28
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer	GRO#9778	
Serial#: CATCS56BLL8H00470		

Segment: 1 Parts and Service

Segment: 2 Inspected unit for air restriction, cleared code & no fault

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
135	09/10/19	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
						Labour Total	1.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	1.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Description: boost equipment	GRO#7225	Date Started: 2020-02-18
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer		
Serial#: CATCS56BLL8H00470		

Segment: 1 parts

ether

Segment: 2 Boost with loader and ether start

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1308	02/18/20	EMTime	Employee: 1266 Braden Bitzer		HRS	1.000		
						Labour Total	1.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	1.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	



Work Order: 10804

Description: Inspections, 250 Hour Service and Repairs	2253 Hours	Date Started: 2020-02-21
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer	RD-2020-131 Insheet RD-2020-160 Outsheet GRO-9739/9014/9588/9661	
Serial#: CATCS56BLL8H00470		

Segment: 1 Parts and Service

Hours-2253

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
31	03/03/20	EMParts	1807487 Filter-Cab Air		EA	1.000	43.01	43.01
32	03/03/20	EMParts	2567902 Filter-Air Primary		EA	1.000	30.88	30.88
33	03/03/20	EMParts	3608960 Filter-Fuel		EA	1.000	25.64	25.64
34	03/03/20	EMParts	3636572 Filter-Fuel/Water Seperator		EA	1.000	19.46	19.46
35	03/03/20	EMParts	7W2326 Filter-Oil		EA	1.000	19.72	19.72
944	08/19/20	EMParts	5W40 Spectra 5W40		I	11.500	5.22	59.98
1133	04/27/20	EMParts	3479981 Tube-Crankcase Breather		EA	1.000	150.42	150.42

Labour Total 0.00

Parts Total 349.11

Miscellaneous Total 0.00

Segment: 2 Insheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1414	02/21/20	EMTime	Employee: 2395 Nickolas Schou		HRS	1.500		

Labour Total 1.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1448	04/28/20	PR	Employee: 1074 Jack Loughed		HRS	1.500		
2774	04/28/20	PR	Employee: 1074 Jack Loughed		HRS	-1.500		
2775	04/28/20	PR	Employee: 1074 Jack Loughed		HRS	1.500		
1553	02/25/20	EMTime	Employee: 1074 Jack Loughed		HRS	4.000		
1555	02/26/20	EMTime	Employee: 1074 Jack Loughed		HRS	4.000		

Labour Total 9.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 4 Check and adjust Scraper



Work Order: 10804

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1400	04/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		
1403	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2752	04/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	-2.000		
2753	04/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		
2758	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2759	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		

Labour Total 3.00

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 5 250 Hour Service, Check and Adjust Fluid Levels

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1399	04/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
1401	04/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	4.000		
1404	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
1407	04/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
2750	04/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.000		
2751	04/21/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
2754	04/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	-4.000		
2755	04/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	4.000		
2760	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
2761	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
2766	04/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	-3.000		
2767	04/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		

Labour Total 10.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 6 Free up Hood Latch and attach Leash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1402	04/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
1408	04/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2756	04/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2757	04/22/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2768	04/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2769	04/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		



Work Order: 10804

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 T/S and Repair Coolant/Oil Leak

R/S Engine Below air filter and on oil filter.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1405	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
1409	04/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
1577	04/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
2762	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2763	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2770	04/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.500		
2771	04/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
2772	04/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	-0.500		
2773	04/27/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 T/S and Code

Propel level-Abnormal update rate.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1406	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
2764	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	-1.000		
2765	04/23/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Outsheat

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1578	04/28/20	PR	Employee: 1577 Dylan Grant		HRS	2.000		
2776	04/28/20	PR	Employee: 1577 Dylan Grant		HRS	-2.000		
2777	04/28/20	PR	Employee: 1577 Dylan Grant		HRS	2.000		



Work Order: 10804

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	32.50
Parts Total	349.11
Miscellaneous Total	0.00

Description: T/S Hard Starting	GRO-9542	Date Started: 2020-07-13
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer	2365 Hours	
Serial#: CATCS56BLL8H00470		

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1501	07/14/20	AP	Vendor: 10830 UAP Inc. 561111092 Line: 4		EA	4.000	2.35	9.40
1502	07/14/20	AP	Vendor: 10830 UAP Inc. 561111097 Line: 3		EA	-2.000	30.00	-60.00
1503	07/14/20	AP	Vendor: 10830 UAP Inc. 561111079 Line: 2		EA	2.000	30.00	60.00
3	08/04/20	EMParts	4794133 Filter-Fuel/Watter Seperator		EA	-1.000	29.34	-29.34
4	08/04/20	EMParts	3608960 Filter-Fuel		EA	-1.000	22.59	-22.59
490	07/13/20	EMParts	3608960 Filter-Fuel		EA	1.000	22.59	22.59
491	07/13/20	EMParts	3636572 Filter-Fuel/Water Seperator		EA	1.000	19.46	19.46
1292	07/21/20	EMParts	GX31S 12v Battery Top Stud Group 31		EA	2.000	129.73	259.46

Labour Total	0.00
Parts Total	258.98
Miscellaneous Total	0.00

Segment: 2 T/S Hard starting

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1470	07/14/20	PR	Employee: 1577 Dylan Grant		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	2.50
Parts Total	258.98
Miscellaneous Total	0.00



Work Order: 11415

Description: 250 Hour Service	GRO-9418	Date Started: 2020-08-13
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer	2492 Hours	
Serial#: CATCS56BLL8H00470		

Segment: 1 Part and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
593	08/13/20	EMParts	1807487 Filter-Cab Air		EA	1.000	31.97	31.97
594	08/13/20	EMParts	2567902 Filter-Air Primary		EA	1.000	31.58	31.58
595	08/13/20	EMParts	3608960 Filter-Fuel		EA	1.000	22.59	22.59
596	08/13/20	EMParts	4794133 Filter-Fuel/Watter Seperator		EA	1.000	29.34	29.34
597	08/13/20	EMParts	7W2326 Filter-Oil		EA	1.000	19.72	19.72
3788	09/22/20	EMParts	5W40 Spectra 5W40		I	11.000	5.22	57.37
						Labour Total	0.00	
						Parts Total	192.57	
						Miscellaneous Total	0.00	

Segment: 2 250 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1487	08/14/20	PR	Employee: 1577 Dylan Grant		HRS	1.500		
						Labour Total	1.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	1.50	
						Parts Total	192.57	
						Miscellaneous Total	0.00	

Description: Inspections, 3000 Hour Service and Repairs	GRO-8800/8932/8933/8934	Date Started: 2020-11-06
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer	GRO-8935/8936/8973/8553	
Serial#: CATCS56BLL8H00470	2671 Hours	
	RD-2021-110 Insheet	
	RD-2021-149 Outsheat	

Segment: 1 Parts

4L Washer fluid
26L ISO 150 Mobil One
20 long zip ties
1 24V light bulb 07201122

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
914	03/03/21	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S6084553.001 Line: 1		LS	0.000	0.00	698.74



GCS Energy Services Ltd.

Work Order: 11679

1303	03/12/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 984974979 Line: 1	EA	-1.000	118.82	-118.82
1992	02/24/21	AP	Vendor: 10111 Finning (Canada) a division of Finning International 947303541 Line: 6	EA	1.000	68.06	68.06
2019	03/01/21	AP	Vendor: 10401 RBC Avion Visa Feb 21_Lance Line: 12	LS	0.000	0.00	107.40
2595	03/29/21	AP	Vendor: 10401 RBC Avion Visa Mar 21_Lance Line: 1	LS	0.000	0.00	4.76
2596	03/29/21	AP	Vendor: 10401 RBC Avion Visa Mar 21_Lance Line: 2	LS	0.000	0.00	18.90
26	02/01/21	EMParts	3652985 Belt-Serpentine	EA	1.000	90.88	90.88
27	02/01/21	EMParts	9P7121 Fuel Tank Screen	EA	1.000	38.71	38.71
221	03/09/21	EMParts	1807487 Filter-Cab Air	EA	1.000	25.86	25.86
222	03/09/21	EMParts	1833873 Breather-Transmission	EA	1.000	21.71	21.71
223	03/09/21	EMParts	2567902 Filter-Air Primary	EA	1.000	32.00	32.00
224	03/09/21	EMParts	3338052 Seal	EA	1.000	64.41	64.41
225	03/09/21	EMParts	3418536 Seal	EA	4.000	32.84	131.36
226	03/09/21	EMParts	3481861 Filter-Hydraulic/Transmission	EA	1.000	48.22	48.22
227	03/09/21	EMParts	3608960 Filter-Fuel	EA	1.000	20.62	20.62
228	03/09/21	EMParts	4794133 Filter-Fuel/Watter Seperator	EA	1.000	28.77	28.77
229	03/09/21	EMParts	4872348 Seal Kit-Steering	EA	1.000	118.51	118.51
230	03/09/21	EMParts	7W2326 Filter-Oil	EA	1.000	19.72	19.72
231	03/09/21	EMParts	2258524 Bolt-Banjo	EA	1.000	8.60	8.60
232	03/09/21	EMParts	2258526 Washer-Copper	EA	2.000	8.51	17.02
233	03/09/21	EMParts	3327624 Gasket	EA	1.000	14.41	14.41
234	03/09/21	EMParts	3469507 Gasket	EA	2.000	16.80	33.60
235	03/09/21	EMParts	3604064 Gasket	EA	1.000	7.19	7.19
236	03/09/21	EMParts	3836120 Line Assembly-Fuel	EA	1.000	101.08	101.08
237	03/09/21	EMParts	3836123 Line Assembly-Fuel	EA	1.000	170.68	170.68
238	03/09/21	EMParts	4371330 Seal Kit	EA	1.000	118.82	118.82
494	01/21/21	EMParts	Dyed Diesel Dyed Diesel	EA	45.420	2.62	119.03
675	06/21/21	EMParts	5W40 Spectra 5W40	I	11.500	5.22	60.02
676	06/21/21	EMParts	60/40 Rad-Cool Antifreeze	EA	2.000	5.85	11.70
677	06/21/21	EMParts	7J9108 Seal-O-Ring	EA	3.000	2.07	6.21
678	06/21/21	EMParts	Oil All Plus Hydraulic Oil 10W30	EA	52.000	17.84	927.83
679	06/21/21	EMParts	TO4 Spectra Xtreme TO-4 All season	EA	32.000	5.48	175.33
680	06/21/21	EMParts	Dyed Diesel Dyed Diesel	EA	28.769	0.87	25.17
870	08/19/21	EMParts	3391048 Kit-Crankcase Breather	EA	1.000	38.22	38.22
871	08/19/21	EMParts	3622915 Seal-Breather	EA	1.000	29.39	29.39
986	03/23/21	EMParts	3538578 Gasket	EA	1.000	8.87	8.87
1005	03/24/21	EMParts	3975684 Pump-Water	EA	1.000	525.00	525.00
1013	03/24/21	EMParts	HDVB3 20LB Vehicle Bracket	EA	1.000	44.95	44.95

Labour Total	0.00
Parts Total	3,862.93
Miscellaneous Total	0.00

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
881	03/16/21	PR	Employee: 2471 Greg Royer		HRS	2.000		
906	01/20/21	PR	Employee: 2611 Matthew Walter		HRS	3.500		
1111	03/19/21	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		



Work Order: 11679

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
878	03/09/21	PR	Employee: 2623 Brenton Woolman		HRS	3.000		
879	03/10/21	PR	Employee: 2623 Brenton Woolman		HRS	2.000		
1112	03/19/21	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 3000 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1107	03/17/21	PR	Employee: 2338 Nolan MacGregor		HRS	1.000		
1160	02/24/21	PR	Employee: 2611 Matthew Walter		HRS	3.000		
1925	02/25/21	PR	Employee: 2611 Matthew Walter		HRS	8.500		

Labour Total	12.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 T/S and Repair Leaks

R/H Drum to Pivot lines cracked.
 R/H line at drum cracked.
 R/H Steering Cylinder sweating.
 Leaks around valve cover

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
142	03/01/21	PR	Employee: 2611 Matthew Walter		HRS	6.500		
145	03/03/21	PR	Employee: 2611 Matthew Walter		HRS	3.500		
146	03/04/21	PR	Employee: 2611 Matthew Walter		HRS	8.500		
880	03/12/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		
1927	02/26/21	PR	Employee: 2611 Matthew Walter		HRS	9.500		

Labour Total	29.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 T/S, Repair Door, hood and lights



GCS Energy Services Ltd.

Work Order: 11679

Rear hood handle doesn't spring return
Far R/F light out.
L/H Door weather stripping coming off.
Hood has trouble latching.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
143	03/01/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		
1108	03/17/21	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		
1161	02/24/21	PR	Employee: 2611 Matthew Walter		HRS	0.500		
1926	02/25/21	PR	Employee: 2611 Matthew Walter		HRS	0.500		

Labour Total 2.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 7 Replace Belt

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1162	02/24/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		

Labour Total 1.00

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 8 Adjust Drum Scrapers

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
144	03/01/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		

Labour Total 2.00

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 9 T/S and Replace Water Pump

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1109	03/17/21	PR	Employee: 2338 Nolan MacGregor		HRS	3.000		
1110	03/18/21	PR	Employee: 2338 Nolan MacGregor		HRS	4.000		
1113	03/19/21	PR	Employee: 2338 Nolan MacGregor		HRS	2.000		



Work Order: 11679

Labour Total	9.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	69.50
Parts Total	3,862.93
Miscellaneous Total	0.00

Description: outsheet checkover 2677 HRS, GRO 8247 **Date Started:** 2021-06-24
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer
Serial#: CATCS56BLL8H00470

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1102	06/24/21	EMParts	60/40 Rad-Cool Antifreeze		EA	3.000	6.27	18.81

Labour Total	0.00
Parts Total	18.81
Miscellaneous Total	0.00

Segment: 2 outsheet checkover - top up fluids & grease

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1292	06/24/21	PR	Employee: 1266 Braden Bitzer		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	1.00
Parts Total	18.81
Miscellaneous Total	0.00

Description: Inspections and Repairs 2852 Hours **Date Started:** 2021-12-14
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer RD-2021-321 Insheet RD-2022-172 Outsheet
Serial#: CATCS56BLL8H00470

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



GCS Energy Services Ltd.

Work Order: 12699

749	06/13/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 948333892 Line: 3	EA	1.000	6.55	6.55
2632	08/06/22	AP	Vendor: 10111 Finning (Canada) a division of Finning International 962260876 Line: 1	LS	0.000	0.00	1,274.63
210	06/14/22	EMParts	0336041 Seal-O-Ring	EA	1.000	10.71	10.71
211	06/14/22	EMParts	1807487 Filter-Cab Air	EA	1.000	24.90	24.90
212	06/14/22	EMParts	2227890 Switch Assembly	EA	1.000	73.33	73.33
213	06/14/22	EMParts	2549108 Switch Assembly	EA	1.000	65.47	65.47
214	06/14/22	EMParts	2567902 Filter-Air Primary	EA	1.000	32.66	32.66
215	06/14/22	EMParts	3608960 Filter-Fuel	EA	1.000	20.47	20.47
216	06/14/22	EMParts	4794133 Filter-Fuel/Watter Separator	EA	1.000	29.10	29.10
217	06/14/22	EMParts	5245506 Display Goup-Monitor	EA	1.000	1,047.44	1,047.44
218	06/14/22	EMParts	7W2326 Filter-Oil	EA	1.000	19.72	19.72

Labour Total	0.00
Parts Total	3,806.38
Miscellaneous Total	0.00

Segment: 2 Insheet and Outsheet Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1060	12/14/21	PR	Employee: 2395 Nickolas Schou		HRS	1.000		
1364	06/16/22	PR	Employee: 2471 Greg Royer		HRS	2.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
485	06/10/22	PR	Employee: 2623 Brenton Woolman		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 250 Hour Service

250 Hour engine service - Fuel filters, oil filter and oil, cab air filter and engine primary air filter.
Grease unit, check over fluids, top up oil in LH drum drive motor.
-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
483	06/09/22	PR	Employee: 1575 Paul Nixon		HRS	2.500		



Work Order: 12699

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Repair Panels, Monitors, Scrapers and Lights

Monitor in dash lights up but has no display.
Adjust wiper spray to cover window.
Weather stripping on door coming off.
Adjust drum scrapers.

Swap monitor with one from other unit, worked fine. Order and install new monitor, would not light up. Had to have Finning come in and program monitor/flash ECM software.
Adjusted wiper sprayer as best I could so it contacted most of window.
Used weatherstrip adhesive to reattach weather stripping that was falling off.
Adjusted front drum scraper.
-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
484	06/09/22	PR	Employee: 1575 Paul Nixon		HRS	3.000		
1363	06/13/22	PR	Employee: 1575 Paul Nixon		HRS	1.000		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Repair Leaks

Rear axle fill plug leaking.
Re-secure hydraulic lines off L/S drum motor.

Zip tied hyd hoses securely for LH drum drive motor.
-Paul

Labour Total	13.00
Parts Total	3,806.38
Miscellaneous Total	0.00

Description: Rental Return Emsco	2852 Hours	Date Started: 2021-12-14
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer	2922 Hours Next service due RD-2021-321 Insheet	
Serial#: CATCS56BLL8H00470		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
38	02/02/22	EMParts	3640868 Plate		EA	1.000	76.08	76.08
39	02/02/22	EMParts	9U8263 Cover		EA	1.000	7.05	7.05



Work Order: 12700

Labour Total	0.00
Parts Total	83.13
Miscellaneous Total	0.00

Segment: 2 Wash

Segment: 3 Replace Headliner cover and Top up Washer Fluid

Reinstall radio block off plate in headliner.
Top up washer fluid.
-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
482	06/09/22	PR	Employee: 1575 Paul Nixon		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Remove Customer Decals

Remove pipeline decals.
-Paul

Labour Total	0.50
Parts Total	83.13
Miscellaneous Total	0.00

Description: Replace Wiper Blade	Date Started: 2022-09-27
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer	
Serial#: CATCS56BLL8H00470	

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
989	09/27/22	EMParts	1466433 Wiper Blade-20"		EA	1.000	64.98	64.98

Labour Total	0.00
Parts Total	64.98
Miscellaneous Total	0.00

Segment: 2 Repair wipers

Replace rear wiper.



Work Order: 13489

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1376	09/27/22	PR	Employee: 2915 Scott Scrivener		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	0.50
Parts Total	64.98
Miscellaneous Total	0.00

Description: 250 Hour Service Unit at Emerson Site. **Date Started:** 2023-07-04
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer
Serial#: CATCS56BLL8H00470

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2502	09/27/23	AP	Vendor: 10401 RBC Avion Visa Sept 23_L Dahl Line: 9	LS		0.000	0.00	758.92
2541	09/27/23	AP	Vendor: 10401 RBC Avion Visa Sept 23_L Dahl Line: 9	LS		0.000	0.00	-758.92
2542	09/27/23	AP	Vendor: 10401 RBC Avion Visa Sept 23_L Dahl Line: 9	LS		0.000	0.00	758.92
2611	10/27/23	AP	Vendor: 10401 RBC Avion Visa Oct 23_L Dahl Line: 23	LS		0.000	0.00	247.19
6	07/04/23	EMParts	1807487 Filter-Cab Air	EA		1.000	44.84	44.84
7	07/04/23	EMParts	2567902 Filter-Air Primary	EA		1.000	67.08	67.08
8	07/04/23	EMParts	3608960 Filter-Fuel	EA		1.000	20.47	20.47
9	07/04/23	EMParts	4794133 Filter-Fuel/Watter Seperator	EA		1.000	35.25	35.25
10	07/04/23	EMParts	7W2326 Filter-Oil	EA		1.000	19.78	19.78
416	08/17/23	EMParts	5W40 Spectra 5W40	I		18.000	7.52	135.30
			PO - Open - #1025972 - 10401 hyd hose install	LS		0.00	0.00	796.86
			Labour Total			0.00		
			Parts Total			2,125.69		
			Miscellaneous Total			0.00		

Segment: 2 250 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
239	07/05/23	PR	Employee: 3110 Callum Deditch		HRS	3.000		
			Labour Total			3.00		
			Parts Total			0.00		
			Miscellaneous Total			0.00		

Segment: 3 Repair leaks



Work Order: 14182

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1526	09/21/23	PR	Employee: 3110 Callum Deditch		HRS	1.500		
1527	09/22/23	PR	Employee: 3110 Callum Deditch		HRS	1.000		
1528	09/27/23	PR	Employee: 3110 Callum Deditch		HRS	2.000		

Labour Total 4.50

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 7.50

Parts Total 2,125.69

Miscellaneous Total 0.00

Description: 250 Hour Service Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer Serial#: CATCS56BLL8H00470	Unit at Emerson Site. Hours: 3335 Next service hours: 3585 GRO#3931	Date Started: 2023-11-20
---	--	---------------------------------

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
739	11/20/23	EMParts	1807487 Filter-Cab Air		EA	1.000	38.30	38.30
740	11/20/23	EMParts	2567902 Filter-Air Primary		EA	1.000	79.58	79.58
741	11/20/23	EMParts	3608960 Filter-Fuel		EA	1.000	25.19	25.19
742	11/20/23	EMParts	4794133 Filter-Fuel/Watter Seperator		EA	1.000	35.70	35.70
743	11/20/23	EMParts	7W2326 Filter-Oil		EA	1.000	19.72	19.72
982	11/27/23	EMParts	5W40 Spectra 5W40		I	12.000	7.70	92.42

Labour Total 0.00

Parts Total 290.91

Miscellaneous Total 0.00

Segment: 2 250 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1337	11/22/23	PR	Employee: 3108 Zachary Dean		HRS	3.000		

Labour Total 3.00

Parts Total 0.00

Miscellaneous Total 0.00



Work Order: 14519

Labour Total	3.00
Parts Total	1,087.77
Miscellaneous Total	0.00

Description: Reg Maintennace	GRO13026/13704/13707	Date Started: 2024-08-30
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer	3554 hours In sheet Inspection Jan 14 2025	
Serial#: CATCS56BLL8H00470		

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
99	01/14/25	EMParts	6V7419 Wiper Blade		EA	1.000	71.68	71.68
						Labour Total	0.00	
						Parts Total	71.68	
						Miscellaneous Total	0.00	

Segment: 2 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1319	08/28/24	PR	Employee: 22 Garrett Nelson		HRS	3.000		
						Labour Total	3.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 3 Complete inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
363	01/14/25	PR	Employee: 3119 Shawn Dittmer		HRS	3.000		
1320	08/28/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		
						Labour Total	5.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 4 Replace wiper blade

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
364	01/15/25	PR	Employee: 3119 Shawn Dittmer		HRS	1.000		



Work Order: 15046

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	9.00
Parts Total	868.54
Miscellaneous Total	0.00

Description: Repair Scraper bolts and Codes	Hours:3502	Date Started: 2024-10-09
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer	Next Service Hours: 3785 GRO# 8984/8990	
Serial#: CATCS56BLL8H00470		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
89	10/10/24	EMParts	2567903 Filter-Air Secondary		EA	1.000	52.42	52.42
90	10/10/24	EMParts	4705708 Hose Assembly-Air Intake		EA	1.000	380.77	380.77

Labour Total	0.00
Parts Total	433.19
Miscellaneous Total	0.00

Segment: 2 Repair broken bolts on drum scraper

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
288	10/02/24	PR	Employee: 3108 Zachary Dean		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 T/S Codes

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
289	10/08/24	PR	Employee: 3103 Dallas Wood		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Replace Secondary Air Filter and Intake Hose



Work Order: 15119

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
645	10/22/24	PR	Employee: 3103 Dallas Wood		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	3.50
Parts Total	1,230.05
Miscellaneous Total	0.00

Description: Reg Maintenance GRO12280 **Date Started:** 2025-06-20
Equipment: E584 Caterpillar CS56 84" Vibrating Smooth Drum Packer
Serial#: CATCS56BLL8H00470

Segment: 1 parts

Segment: 2 Re charge A/C

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
421	06/18/25	PR	Employee: 3119 Shawn Dittmer		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	2.50
Parts Total	796.86
Miscellaneous Total	0.00