



Work Order: 10163

EBID-283

Description: Change Belts and Tensioner 2320 Hours Date Started: 2018-07-30
 Equipment: E570 Bobcat T590 Tracked Skidsteer GRO#7258
 Serial#: A3NR12137

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
279	08/17/18	EMParts	7143498 Compressor Belt		EA	1.000	31.11	31.11
280	08/17/18	EMParts	7146391 Drive belt		EA	1.000	74.46	74.46
327	08/22/18	EMParts	6735884 Idler Ass		EA	1.000	466.51	466.51

Labour Total 0.00
 Parts Total 572.08
 Miscellaneous Total 0.00

Segment: 2 Change Alt. belt, Tensioner and A/C Belt

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
277	08/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	2.500		

Labour Total 2.50
 Parts Total 0.00
 Miscellaneous Total 0.00

Segment: 3 Free up Quick Attach Pin

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
278	08/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	0.500		

Labour Total 0.50
 Parts Total 0.00
 Miscellaneous Total 0.00
 Labour Total 3.00
 Parts Total 572.08
 Miscellaneous Total 0.00

Description: 350 Hour Service Date Started: 2018-08-22
 Equipment: E570 Bobcat T590 Tracked Skidsteer
 Serial#: A3NR12137



Work Order: 10171

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
151	09/11/18	EMParts	5W40 Spectra 5W40		I	9.000	5.16	46.45
393	08/22/18	EMParts	6666375 Filter-Air Primary		EA	1.000	39.88	39.88
394	08/22/18	EMParts	6666376 Filter-Air Secondary		EA	1.000	38.40	38.40
395	08/22/18	EMParts	6667352 Fuel/ Water Seperator		EA	1.000	13.49	13.49
396	08/22/18	EMParts	6675517 Oil Filter		EA	1.000	18.45	18.45
397	08/22/18	EMParts	7176099 Filter-Cab Air		EA	2.000	26.18	52.36

Labour Total 0.00

Parts Total 209.03

Miscellaneous Total 0.00

Segment: 2 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
102	09/10/18	EMTime	Employee: 2205 Alexander Zavadii		HRS	1.500		

Labour Total 1.50

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 1.50

Parts Total 209.03

Miscellaneous Total 0.00

Description: Adjust Drive Belt 2432 Hours Date Started: 2018-10-17
 Equipment: E570 Bobcat T590 Tracked Skidsteer GRO#7399
 Serial#: A3NR12137

Segment: 1 Adjust Drive Belt

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
541	10/19/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		

Labour Total 1.50

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 2 Repair Stripped Bolt



Work Order: 10224

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
542	10/19/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total 0.50

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 2.00

Parts Total 0.00

Miscellaneous Total 0.00

Description: Replace Drive Belt
Equipment: E570 Bobcat T590 Tracked Skidsteer
Serial#: A3NR12137
Parts Taken to Site
Date Started: 2018-10-23

Segment: 1 Parts and service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
606	10/23/18	EMParts	7146391 Drive belt		EA	1.000	74.46	74.46
730	10/29/18	EMParts	7146391 Drive belt		EA	-1.000	73.39	-73.39

Labour Total 0.00

Parts Total 1.07

Miscellaneous Total 0.00

Labour Total 0.00

Parts Total 1.07

Miscellaneous Total 0.00

Description: 350 Hour Service and Replace Drive Belt
Equipment: E570 Bobcat T590 Tracked Skidsteer
Serial#: A3NR12137
2700 Hours
GRO#7539
Date Started: 2019-01-24

Segment: 1 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
458	01/22/19	EMParts	6666375 Filter-Air Primary		EA	1.000	26.59	26.59
459	01/22/19	EMParts	6667352 Fuel/ Water Separator		EA	1.000	13.49	13.49
460	01/22/19	EMParts	6675517 Oil Filter		EA	1.000	18.45	18.45
461	01/22/19	EMParts	7176099 Filter-Cab Air		EA	2.000	22.76	45.52
683	01/29/19	EMParts	5W40 Spectra 5W40		I	10.000	5.17	51.72
679	01/29/19	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		



Work Order: 10319

Labour Total	1.50
Parts Total	155.77
Miscellaneous Total	0.00

Segment: 2 Trouble Shoot Starter Lock out Bad Connection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
680	01/29/19	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Replace Drive Belt

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
681	01/29/19	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair Broken Bolts on Quick Attach

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
682	01/29/19	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	4.50
Parts Total	155.77
Miscellaneous Total	0.00

Description: Inspections, 3000 Hour Service and Repairs	2703 Hours	Date Started: 2019-04-26
Equipment: E570 Bobcat T590 Tracked Skidsteer	RD-2019-186 Insheet RD-2020-145 Outsheet GRO-7761/7734/9678/9008	
Serial#: A3NR12137		

Segment: 1 Parts and Service



GCS Energy Services Ltd.

Work Order: 10402

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
120	03/04/20	AP	Vendor: 10055 Calmont Equipment P03658 Line: 1		EA	-2.000	18.31	-36.62
171	03/05/20	AP	Vendor: 10132 Gregg Distributors LP 059-281492 Line: 1		EA	3.000	0.97	2.91
317	04/06/20	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5762310.001 Line: 1		LS	0.000	0.00	90.34
2291	03/27/20	AP	Vendor: 10401 RBC Avion Visa MAR/20 Lance Line: 28		EA	1.000	203.86	203.86
3	05/01/19	EMParts	6692337 Filter-Hydraulic		EA	1.000	60.09	60.09
4	05/01/19	EMParts	7024037 Filter-Hydraulic		EA	1.000	49.63	49.63
5	05/01/19	EMParts	7135489 Seal Kit- Arm Cylinder		EA	2.000	60.00	120.00
6	05/01/19	EMParts	7199903 Seal Kit-Bucket Cylinder		EA	2.000	74.27	148.54
338	04/09/20	EMParts	60/40 Rad-Cool Antifreeze		EA	8.800	5.90	51.91
339	04/09/20	EMParts	886 Bulb-Halogen		EA	1.000	8.66	8.66
340	04/09/20	EMParts	Dyed Diesel Dyed Diesel		EA	42.780	0.90	38.49
442	04/14/20	EMParts	Oil All Hydraulic Oil 10W30		EA	30.000	5.81	174.17
1479	02/25/20	EMParts	6727753 Gasket-Exhaust		EA	1.000	6.07	6.07
1480	02/25/20	EMParts	7000598 Seal-O-Ring		EA	1.000	3.92	3.92
1481	02/25/20	EMParts	896H1CHCR1U0312DVC Relay-SPDT 12VDC N/O 50A, N/C		EA	1.000	8.50	8.50
1510	02/26/20	EMParts	17C652 Bolt-3/8"x3 1/4" GR8		EA	1.000	4.24	4.24
1511	02/26/20	EMParts	225855 Seal		EA	4.000	12.97	51.88
1512	02/26/20	EMParts	619021 Washer		EA	1.000	1.72	1.72
1513	02/26/20	EMParts	6805453 Bushing		EA	2.000	18.31	36.62
1514	02/26/20	EMParts	7214598 Rod-Bucket Cylinder		EA	2.000	486.80	973.60
1515	02/26/20	EMParts	7221255 Spring		EA	1.000	4.30	4.30
1516	02/26/20	EMParts	85D6 Nut-Lock		EA	1.000	2.67	2.67

Labour Total	0.00
Parts Total	2,005.50
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2	05/01/19	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
680	01/28/20	EMTime	Employee: 1074 Jack Lougheed		HRS	7.000		

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 10402

Segment: 4 T/S and repair Exhaust leak

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
337	03/03/20	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		
341	03/04/20	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		
1561	02/24/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
Labour Total						5.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 5 T/S and repair P.A.S.S.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
617	04/07/20	EMTime	Employee: 2338 Nolan MacGregor		HRS	0.250		
621	04/08/20	EMTime	Employee: 2338 Nolan MacGregor		HRS	1.000		
Labour Total						1.25		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 6 Reseal Both Boom Cylinders

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
343	03/04/20	EMTime	Employee: 1577 Dylan Grant		HRS	3.000		
Labour Total						3.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 7 Reseal Both Tilt Cylinders

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
336	03/03/20	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		
340	03/04/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
1565	02/25/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		
Labour Total						4.50		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 8 T/S, Repair Started relay code and Harness



Work Order: 10402

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1562	02/24/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 T/S and Repair Q/A

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
813	03/12/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
1564	02/25/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Straighten front step

Segment: 11 Adjust wiper arm

Segment: 12 T/S rough idle and engine misfire

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
347	03/05/20	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 13 Check and adjust fluids

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
348	03/05/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 14 Repair broken bolts



Work Order: 10402

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
625	04/09/20	EMTime	Employee: 2338 Nolan MacGregor		HRS	1.500		
1768	02/26/20	EMTime	Employee: 1577 Dylan Grant		HRS	3.000		
						Labour Total		4.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 15 Replace Fuel line

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
342	03/04/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 16 Run and test

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
349	03/05/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
814	03/12/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
						Labour Total		2.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 17 T/S Charging system and replace alternator

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
350	03/05/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
811	03/12/20	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		
						Labour Total		3.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 18 Adjust AC pump

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
812	03/12/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
943	03/13/20	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		



Work Order: 10402

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 19 Repair lights

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
72	04/02/20	EMTime	Employee: 2338 Nolan MacGregor		HRS	1.000		
74	04/03/20	EMTime	Employee: 2338 Nolan MacGregor		HRS	4.000		
612	04/06/20	EMTime	Employee: 2338 Nolan MacGregor		HRS	2.000		

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 20 Test and Replace Coolant

Segment: 21 Replace Hose Assenbly

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
618	04/07/20	EMTime	Employee: 2338 Nolan MacGregor		HRS	0.250		

Labour Total	0.25
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 22 Outsheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
616	04/07/20	EMTime	Employee: 2338 Nolan MacGregor		HRS	0.500		
624	04/09/20	EMTime	Employee: 2338 Nolan MacGregor		HRS	1.000		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	49.50
Parts Total	2,005.50
Miscellaneous Total	0.00



Work Order: 11398

Description: Adjust drive belt	GRO-9401	Date Started: 2020-08-07
Equipment: E570 Bobcat T590 Tracked Skidsteer	2747 Hours	
Serial#: A3NR12137		

Segment: 1 Parts and Service

Segment: 2 Adjust loose drive belt

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
173	08/04/20	PR	Employee: 1577 Dylan Grant		HRS	0.500		
						Labour Total	0.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	0.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Description: Inspections and Repairs	GRO-8128/8228/8803	Date Started: 2020-10-07
Equipment: E570 Bobcat T590 Tracked Skidsteer	2828 Hours	
Serial#: A3NR12137	RD-2020-297 Insheet	
	RD-2020-338 Outsheet	

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1369	11/24/20	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5992492.001		LS	0.000	0.00	90.01
1	12/01/20	EMParts	Line: 1					
2	12/01/20	EMParts	6652792 Nut		EA	3.000	2.08	6.24
3	12/01/20	EMParts	6680570 Gasket-Turbo Drain		EA	1.000	6.51	6.51
4	12/01/20	EMParts	6689331 Sealing Washer		EA	1.000	3.00	3.00
5	12/01/20	EMParts	6727753 Gasket-Exhaust		EA	1.000	6.07	6.07
6	12/01/20	EMParts	7000642 Sealing Washer		EA	1.000	3.11	3.11
7	12/01/20	EMParts	7000659 Gasket-Exhaust Manifold		EA	1.000	31.45	31.45
8	12/01/20	EMParts	7000678 Gasket-Turbo Charger		EA	1.000	6.94	6.94
9	12/01/20	EMParts	7000754 Manifold-Exhaust		EA	1.000	614.91	614.91
30	12/01/20	EMParts	7031316 Stud		EA	4.000	3.29	13.16
47	11/04/20	EMParts	7000679 Gasket-Turbo Exhaust		EA	1.000	20.94	20.94
50	11/04/20	EMParts	6666376 Filter-Air Secondary		EA	1.000	38.40	38.40
51	11/04/20	EMParts	6625298 V-Belt-A/C		EA	1.000	14.60	14.60
68	11/05/20	EMParts	7143498 Compressor Belt		EA	1.000	32.04	32.04
180	10/09/20	EMParts	HDVB3 20LB Vehicle Bracket		EA	1.000	42.52	42.52
226	10/14/20	EMParts	Dyed Diesel Dyed Diesel		EA	49.210	0.70	34.25
227	10/14/20	EMParts	6666375 Filter-Air Primary		EA	1.000	15.03	15.03
228	10/14/20	EMParts	6667352 Fuel/ Water Separator		EA	1.000	12.68	12.68
			6672276 Lens-Red Tail		EA	1.000	20.17	20.17



GCS Energy Services Ltd.

Work Order: 11593

229	10/14/20	EMParts	6675517 Filter-Oil	EA	1.000	17.94	17.94
230	10/14/20	EMParts	7021791 Cord-Block Heater	EA	1.000	37.06	37.06
231	10/14/20	EMParts	7135489 Seal Kit- Arm Cylinder	EA	2.000	81.65	163.30
232	10/14/20	EMParts	7176099 Filter-Cab Air	EA	2.000	14.21	28.42
233	10/14/20	EMParts	7197082 Cover-Fuse Panel	EA	1.000	27.13	27.13
234	10/14/20	EMParts	7199903 Seal Kit-Bucket Cylinder	EA	2.000	111.10	222.20
385	11/17/20	EMParts	6586718 Head-Tilt Cylinder	EA	1.000	191.90	191.90
1003	11/26/20	EMParts	07590815 Stud	EA	4.000	13.42	53.68
1004	11/26/20	EMParts	OS-AT252133 Capscrew	EA	1.000	0.00	0.00
1194	12/18/20	EMParts	5W40 Spectra 5W40	I	10.430	5.22	54.40
1195	12/18/20	EMParts	60/40 Rad-Cool Antifreeze	EA	10.000	4.52	45.22
1196	12/18/20	EMParts	Oil All Hydraulic Oil 10W30	EA	6.457	4.18	27.02
1197	12/18/20	EMParts	Dyed Diesel Dyed Diesel	EA	15.899	2.62	41.67

Labour Total	0.00
Parts Total	1,921.97
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
398	10/07/20	PR	Employee: 2395 Nickolas Schou		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
189	11/03/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		
1078	11/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	4.500		
2214	10/30/20	PR	Employee: 2338 Nolan MacGregor		HRS	4.500		

Labour Total	11.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Check, adjust, Replace componets,Filters and Fluid Levels

*Replace Primary, Secondary and Cab Air Filters
Fix Wiper Spray nozzle and attach line.
Alternator belt loose*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
190	11/03/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.500		
192	11/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	3.500		



Work Order: 11593

195 11/05/20 PR Employee: 2338 Nolan MacGregor HRS 1.000

Labour Total	8.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Repair Panels and Lights

*L/R Tail Light Broken and loose wiring on reverse light.
Replace Block Heater Cord.
Straighten front step.
Fuse panel cover missing.
Door Seals poorly by latch.
F/E Bracket Broken.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
191	11/03/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		
193	11/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		
665	11/12/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 T/S and Repair Leaks

*All Lift and tilt Cylinders leaking.
Dipstick sweating.
L/H Boom Cylinder bottom hose sweating at steel line connection.
A/C Needs Recharging.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
196	11/05/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
199	11/06/20	PR	Employee: 2338 Nolan MacGregor		HRS	8.500		
662	11/10/20	PR	Employee: 2338 Nolan MacGregor		HRS	8.500		
663	11/10/20	PR	Employee: 2395 Nickolas Schou		HRS	4.500		
664	11/11/20	PR	Employee: 2338 Nolan MacGregor		HRS	5.000		
666	11/12/20	PR	Employee: 2338 Nolan MacGregor		HRS	1.500		
1077	11/20/20	PR	Employee: 2338 Nolan MacGregor		HRS	6.500		
1079	11/24/20	PR	Employee: 2338 Nolan MacGregor		HRS	4.000		

Labour Total	40.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 T/S and Repair P.A.S.S.

*Tighten clamps around P.A.S.S.
Power Wire in Bad condition.*



Work Order: 11593

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
194	11/04/20	PR	Employee: 2338 Nolan MacGregor		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 T/S and Repair Joy Stick

L/H Joystick boot ripped and spring are worn.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
197	11/05/20	PR	Employee: 2338 Nolan MacGregor		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Check and Adjust track Tension

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
198	11/05/20	PR	Employee: 2338 Nolan MacGregor		HRS	5.500		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Repair Bucket bottom

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
262	12/01/20	PR	Employee: 2395 Nickolas Schou		HRS	7.000		
1276	11/26/20	PR	Employee: 2395 Nickolas Schou		HRS	4.500		
2184	11/30/20	PR	Employee: 2395 Nickolas Schou		HRS	6.000		

Labour Total	17.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 11 Outsheet Inspection and Replace Broken Exhaust Manifold

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
263	12/02/20	PR	Employee: 2395 Nickolas Schou		HRS	3.000		



Work Order: 11593

264	12/03/20	PR	Employee: 2395 Nickolas Schou	HRS	4.000
1275	11/25/20	PR	Employee: 2395 Nickolas Schou	HRS	1.000
1277	11/26/20	PR	Employee: 2395 Nickolas Schou	HRS	5.000

Labour Total	13.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	106.00
Parts Total	1,921.97
Miscellaneous Total	0.00

Description: Checkover & R&R Battery	2839 HRS; GRO 6420	Date Started: 2021-02-12
Equipment: E570 Bobcat T590 Tracked Skidsteer		
Serial#: A3NR12137		

Segment: 1 parts

(removed 1x 7000714 dipstick from WO#11907, added to HD stock since unit is already at jobsite)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1042	02/12/21	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-352607 Line: EA			1.000	146.07	146.07
1043	02/12/21	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-352607 Line: EA			1.000	18.00	18.00
1845	02/01/22	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-367027 Line: EA			-1.000	15.00	-15.00

Labour Total	0.00
Parts Total	149.07
Miscellaneous Total	0.00

Segment: 2 R&R battery

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
660	02/12/21	PR	Employee: 1266 Braden Bitzer		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Checkover - grease & top up fluids

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
661	02/12/21	PR	Employee: 1266 Braden Bitzer		HRS	1.000		



Work Order: 11907

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	2.00
Parts Total	149.07
Miscellaneous Total	0.00

Description: T/S, Repair throttle, door and 350 Hour Service
Equipment: E570 Bobcat T590 Tracked Skidsteer
Serial#: A3NR12137

Unit at CNRL
GRO-8696/8293/8396
3062 Hours

Date Started: 2021-06-10

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1280	07/28/21	AP	Vendor: 10055 Calmont Equipment P05168 Line: 1		EA	1.000	15.44	15.44
1281	07/28/21	AP	Vendor: 10055 Calmont Equipment P05168 Line: 2		EA	1.000	2.45	2.45
13	08/03/21	EMParts	6666375 Filter-Air Primary		EA	1.000	15.03	15.03
14	08/03/21	EMParts	6667352 Fuel/ Water Separator		EA	1.000	12.76	12.76
15	08/03/21	EMParts	6675517 Filter-Oil		EA	1.000	17.95	17.95
16	08/03/21	EMParts	7176099 Filter-Cab Air		EA	2.000	14.12	28.23
392	08/11/21	EMParts	5W40 Spectra 5W40		I	10.000	5.22	52.19
605	06/18/21	EMParts	6644965 Ball Joints-Throttle Cable		EA	4.000	23.55	94.20
606	06/18/21	EMParts	7213427 Cable-Throttle		EA	1.000	134.53	134.53
607	06/18/21	EMParts	7213434 Cable-Throttle		EA	1.000	83.77	83.77
1088	06/29/21	EMParts	7011181 Air Spring Kit-Seat		EA	1.000	142.95	142.95
1089	06/29/21	EMParts	7011182 Lever Kit-Seat		EA	1.000	29.44	29.44

Labour Total	0.00
Parts Total	628.94
Miscellaneous Total	0.00

Segment: 2 T/S throttle issue

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1215	07/28/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		
1891	05/31/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair rear door



Work Order: 12186

Segment: 4 T/S and Repair A/C

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
960	06/21/21	PR	Employee: 2611 Matthew Walter		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 5 T/S and Repair Seat

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
700	07/16/21	PR	Employee: 2611 Matthew Walter		HRS	4.000		
961	06/21/21	PR	Employee: 2611 Matthew Walter		HRS	0.500		
1216	07/28/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		
1217	07/29/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		
1886	07/29/21	PR	Employee: 2611 Matthew Walter		HRS	-2.000		
1887	07/29/21	PR	Employee: 2611 Matthew Walter		HRS	2.000		
						Labour Total		8.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 6 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1214	07/27/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		
1884	07/27/21	PR	Employee: 2611 Matthew Walter		HRS	-1.500		
1885	07/27/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		
						Labour Total		1.50
						Parts Total		0.00
						Miscellaneous Total		0.00
						Labour Total		13.00
						Parts Total		628.94
						Miscellaneous Total		0.00



Work Order: 12617

Description: regular maintenance and repairs	3284 Hours	Date Started: 2021-11-16
Equipment: E570 Bobcat T590 Tracked Skidsteer	RD-2017-322 Insheet	
	GRO	
Serial#: A3NR12137	9080/9100/9105/9226//9231/9234/92	
	37/9243/9857	

Segment: 1 parts

1 x 7003487 hydraulic filler screen

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
30	03/01/22	AP	Vendor: 10055 Calmont Equipment P12394 Line: 1		EA	2.000	104.51	209.02
31	03/01/22	AP	Vendor: 10055 Calmont Equipment P12394 Line: 2		EA	-2.000	104.51	-209.02
2098	02/14/22	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-367396 Line: 1		EA	2.000	69.64	139.28
2158	02/28/22	AP	Vendor: 10401 RBC Avion Visa Feb 22_Max D Line: 9		EA	1.000	320.62	320.62
2159	02/28/22	AP	Vendor: 10401 RBC Avion Visa Feb 22_Max D Line: 10		EA	1.000	132.49	132.49
2160	02/28/22	AP	Vendor: 10401 RBC Avion Visa Feb 22_Max D Line: 11		EA	1.000	31.80	31.80
2252	03/28/22	AP	Vendor: 10401 RBC Avion Visa Mar22_MDevey Line: 2		EA	1.000	82.85	82.85
1	03/01/22	EMParts	7193725 Hinge-Door		EA	2.000	70.00	140.00
43	02/03/22	EMParts	6685190 Starter		EA	1.000	237.47	237.47
44	02/03/22	EMParts	7011178 Seat switch and cover		EA	1.000	76.10	76.10
45	02/03/22	EMParts	7135489 Seal Kit- Arm Cylinder		EA	2.000	77.37	154.74
46	02/03/22	EMParts	Oil All Hydraulic Oil 10W30		EA	5.000	5.78	28.88
75	02/07/22	EMParts	6988661 Antenna		EA	1.000	44.26	44.26
76	02/07/22	EMParts	6685190 Starter		EA	-1.000	237.47	-237.47
86	03/08/22	EMParts	25K30118 Seal-O-Ring		EA	2.000	3.60	7.20
87	03/08/22	EMParts	6577954 Pin-Tilt Cylinder to Q/A		EA	2.000	59.37	118.74
88	03/08/22	EMParts	6631067 Seal		EA	2.000	18.30	36.60
89	03/08/22	EMParts	6730997 Bushing		EA	2.000	28.61	57.22
90	03/08/22	EMParts	7135590 Pin-Taper Arm to Q/A		EA	2.000	91.95	183.90
382	02/11/22	EMParts	17C652 Bolt-3/8"x3 1/4" GR8		EA	2.000	4.66	9.32
383	02/11/22	EMParts	619021 Washer		EA	2.000	1.65	3.30
384	02/11/22	EMParts	6666375 Filter-Air Primary		EA	1.000	15.58	15.58
385	02/11/22	EMParts	6667352 Fuel/ Water Separator		EA	1.000	13.35	13.35
386	02/11/22	EMParts	6675517 Filter-Oil		EA	1.000	19.05	19.05
387	02/11/22	EMParts	6702958 Bushing-Q/A Pivot		EA	2.000	9.16	18.32
388	02/11/22	EMParts	7176099 Filter-Cab Air		EA	2.000	14.34	28.68
389	02/11/22	EMParts	7221255 Spring-Q/A		EA	2.000	4.30	8.60
390	02/11/22	EMParts	85D6 Nut-Lock 3/8" NC (Stover)		EA	2.000	2.53	5.06
391	02/11/22	EMParts	7166679 Sprocket-Drive Motor		EA	2.000	390.33	780.66

Labour Total	0.00
Parts Total	2,456.60
Miscellaneous Total	0.00

Segment: 2 wash

Could not start unit to do running checks.
In sheet.
Add hydraulic oil.
Try to get unit started. Charge on battery, starter just clicks away.
Does not turn over.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



GCS Energy Services Ltd.

Work Order: 12617

313	02/02/22	PR	Employee: 2471 Greg Royer	HRS	2.500
314	02/04/22	PR	Employee: 2024 Travis Schmidt	HRS	0.500
852	11/16/21	PR	Employee: 2392 Carmen Beck	HRS	2.000

Labour Total	5.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Insheet Inspection

Segment: 4 R&R hyd breather screen

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
315	02/04/22	PR	Employee: 2024 Travis Schmidt		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 T/S and Repair Leaks

*Check and Verify.
Drive motor Hose's leaking.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
950	02/14/22	PR	Employee: 2611 Matthew Walter		HRS	1.500		
953	02/15/22	PR	Employee: 2611 Matthew Walter		HRS	2.500		
956	02/16/22	PR	Employee: 2611 Matthew Walter		HRS	3.000		

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 T/S and Repair Seat, replace broken antenna

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
957	02/16/22	PR	Employee: 2611 Matthew Walter		HRS	2.000		
962	02/17/22	PR	Employee: 2611 Matthew Walter		HRS	1.000		
964	02/18/22	PR	Employee: 2611 Matthew Walter		HRS	3.000		



Work Order: 12617

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Check and Repair U/C

*Sprocket worn(Check and Verify)
If Sprocket are Replace Change Final Drive Fluids.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
951	02/14/22	PR	Employee: 2611 Matthew Walter		HRS	4.000		
954	02/15/22	PR	Employee: 2024 Travis Schmidt		HRS	1.000		
955	02/15/22	PR	Employee: 2611 Matthew Walter		HRS	4.500		
958	02/16/22	PR	Employee: 2024 Travis Schmidt		HRS	0.500		
959	02/16/22	PR	Employee: 2611 Matthew Walter		HRS	2.000		

Labour Total	12.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
952	02/14/22	PR	Employee: 2611 Matthew Walter		HRS	1.000		
960	02/16/22	PR	Employee: 2611 Matthew Walter		HRS	1.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Repair Q/A , repair boom stop plates

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
961	02/16/22	PR	Employee: 2611 Matthew Walter		HRS	0.500		
963	02/17/22	PR	Employee: 2611 Matthew Walter		HRS	8.000		
965	02/18/22	PR	Employee: 2611 Matthew Walter		HRS	1.500		

Labour Total	10.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 R&R door hinges & seal

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



GCS Energy Services Ltd.

Work Order: 12617

233	03/03/22	PR	Employee: 2024 Travis Schmidt	HRS	0.500
752	03/08/22	PR	Employee: 2024 Travis Schmidt	HRS	0.500
755	03/10/22	PR	Employee: 2024 Travis Schmidt	HRS	0.500

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 11 Remove & clean front mounting plate & pin bores

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
753	03/08/22	PR	Employee: 2024 Travis Schmidt		HRS	2.500		
754	03/09/22	PR	Employee: 2024 Travis Schmidt		HRS	1.500		
756	03/10/22	PR	Employee: 2024 Travis Schmidt		HRS	0.500		
759	03/17/22	PR	Employee: 2024 Travis Schmidt		HRS	1.500		

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 12 R&R bushings

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
757	03/10/22	PR	Employee: 2024 Travis Schmidt		HRS	1.000		
758	03/11/22	PR	Employee: 2024 Travis Schmidt		HRS	2.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	54.00
Parts Total	2,456.60
Miscellaneous Total	0.00

Description: Inspections and Repairs	3293 Hours	Date Started: 2022-04-08
Equipment: E570 Bobcat T590 Tracked Skidsteer	RD-2022-151 Insheet	
	RD-2022-162 Outsheet	
Serial#: A3NR12137		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
992	05/06/22	AP	Vendor: 10055 Calmont Equipment P13341 Line: 2		EA	1.000	85.15	85.15
993	05/06/22	AP	Vendor: 10055 Calmont Equipment P13341 Line: 3		EA	1.000	77.45	77.45



GCS Energy Services Ltd.

Work Order: 12993

994	05/06/22	AP	Vendor: 10055 Calmont Equipment P13341 Line: 4	EA	1.000	44.96	44.96
1008	05/26/22	AP	Vendor: 10055 Calmont Equipment P13602 Line: 3	EA	-1.000	19.86	-19.86
29	05/05/22	EMParts	Dyed Diesel Dyed Diesel	EA	46.180	1.39	64.07
93	06/03/22	EMParts	6800686 Head-Lift Cylinder	EA	1.000	309.01	309.01
94	06/03/22	EMParts	7135489 Seal Kit- Arm Cylinder	EA	1.000	80.89	80.89
155	08/06/22	EMParts	Oil All Hydraulic Oil 10W30	EA	17.000	5.75	97.75
156	08/06/22	EMParts	Dyed Diesel Dyed Diesel	EA	13.250	1.54	20.45
177	06/09/22	EMParts	6668742 Switch - Travel	EA	0.000	19.86	0.00
627	06/16/22	EMParts	7001710	EA	1.000	18.72	18.72
629	06/16/22	EMParts	7199903 Seal Kit-Bucket Cylinder	EA	1.000	98.92	98.92
725	05/19/22	EMParts	742537 Dryer-A/C	EA	1.000	36.87	36.87
726	05/19/22	EMParts	7591352Q Compressor-A/C	EA	1.000	483.55	483.55

Labour Total 0.00

Parts Total 1,397.93

Miscellaneous Total 0.00

Segment: 2 Inspections

*Insheet Inspection.
Add fuel.
Install 150/H toggle switch.
Outsheet Inspection.
Top up hydraulic oil & fuel.
Right boom cylinder still leaking.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
298	07/08/22	PR	Employee: 2873 Isaac Simpkin		HRS	1.500		
1357	06/17/22	PR	Employee: 2471 Greg Royer		HRS	1.500		
2072	05/30/22	PR	Employee: 2471 Greg Royer		HRS	3.000		

Labour Total 6.00

Parts Total 0.00

Miscellaneous Total 0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
478	06/08/22	PR	Employee: 2623 Brenton Woolman		HRS	1.000		
1780	05/26/22	PR	Employee: 2623 Brenton Woolman		HRS	0.500		
1789	04/22/22	PR	Employee: 2471 Greg Royer		HRS	2.500		
1790	04/25/22	PR	Employee: 2623 Brenton Woolman		HRS	0.500		
1791	04/26/22	PR	Employee: 2623 Brenton Woolman		HRS	8.500		

Labour Total 13.00

Parts Total 0.00

Miscellaneous Total 0.00



GCS Energy Services Ltd.

Work Order: 12993

Segment: 4 Repair Leaks and Fan motor noise

*Both Boom Cylinders Leaking.
Hydraulic Fan seems noisy. Almost like failed bearing.
Left attachment had pivot hole egged out.
L/H Boom hoses seem to seep-wash/verify.
Hydraulic fluid low.
Inspect weeping hoses, hyd fan, R& L boom cylinders.
Inspected hyd fan/bearing. Installed new attachment handle. Tested & inspected L boom hoses for leaks.
Removed bucket cylinder.
Install/rebuild cylinder.
Clean up area & tools.
Test repairs for any leaks or malfunctions.
Removed drive belt tensioner for replacement.
Install drive belt tensioner.
Rebuild failed cylinder. Replace cap/cylinder head.
Test for leaks. Fill hyd.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
476	06/06/22	PR	Employee: 2873 Isaac Simpkin		HRS	2.000		
477	06/07/22	PR	Employee: 2873 Isaac Simpkin		HRS	1.500		
487	05/11/22	PR	Employee: 2873 Isaac Simpkin		HRS	4.500		
489	05/12/22	PR	Employee: 2873 Isaac Simpkin		HRS	1.500		
1774	05/16/22	PR	Employee: 2873 Isaac Simpkin		HRS	1.000		
1775	05/17/22	PR	Employee: 2873 Isaac Simpkin		HRS	3.500		
1779	05/25/22	PR	Employee: 2873 Isaac Simpkin		HRS	3.000		
1781	05/26/22	PR	Employee: 2873 Isaac Simpkin		HRS	0.500		
						Labour Total	17.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 5 Repair Panels and Doors

*Engine door dented in at top.
Front wiper needs replacing.
Drive/lift function missing top cover.
Wiper spray don't work.
Cab door doesn't shut sometimes pivot pin seem sloppy.
Cab trim falling by toe caps.
L/H Q/A Pin lift handle egged out.
Tracks cracking. Adjust tracks.
Replaced wiper blade. Filled & tested wiper spray function. Inspected door pins, approved spray adhesive on falling toe cap trim.
Replaced door prop/shock for cab.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
488	05/11/22	PR	Employee: 2873 Isaac Simpkin		HRS	4.000		
1776	05/20/22	PR	Employee: 2873 Isaac Simpkin		HRS	0.500		



Work Order: 12993

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 T/S and Repair A/C

A/C compressor failed.
 Tested A/C system for proper refrigerant level and functionality. Inspected A/C compressor. Prep for removal.
 Removed A/C compressor.
 Install A/C compressor. Fill hyd tank & test for leaks.
 Top up hyd fluid.
 Install air dryer. Filled A/C.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
490	05/12/22	PR	Employee: 2873 Isaac Simpkin		HRS	4.500		
1777	05/20/22	PR	Employee: 2873 Isaac Simpkin		HRS	5.500		
1778	05/24/22	PR	Employee: 2873 Isaac Simpkin		HRS	2.500		

Labour Total	12.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Bit of blue smoke on start up

Bit of blue smoke on start up.

Labour Total	53.50
Parts Total	1,397.93
Miscellaneous Total	0.00

Description: Inspections and Repairs	3304 Hours	Date Started: 2022-07-11
Equipment: E570 Bobcat T590 Tracked Skidsteer	RD-2022-192 Insheet RD-2022-212 Outsheet	
Serial#: A3NR12137		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1852	07/15/22	AP	Vendor: 10055 Calmont Equipment P14143 Line: 7		EA	1.000	25.00	25.00
2615	08/11/22	AP	Vendor: 10055 Calmont Equipment P14415 Line: 1		EA	-2.000	118.98	-237.96
2616	08/11/22	AP	Vendor: 10055 Calmont Equipment P14415 Line: 2		EA	-2.000	138.48	-276.96
2617	08/11/22	AP	Vendor: 10055 Calmont Equipment P14415 Line: 3		EA	-4.000	60.73	-242.92
2618	08/11/22	AP	Vendor: 10055 Calmont Equipment P14415 Line: 4		EA	-2.000	72.43	-144.86
2619	08/11/22	AP	Vendor: 10055 Calmont Equipment P14415 Line: 5		EA	-4.000	29.87	-119.48
160	08/08/22	EMParts	6666376 Filter-Air Secondary		EA	1.000	12.50	12.50
165	08/08/22	EMParts	6577954 Pin-Tilt Cylinder to Q/A		EA	4.000	60.73	242.92
166	08/08/22	EMParts	6730997 Bushing		EA	4.000	29.27	117.08
167	08/08/22	EMParts	6731139 Pin-Pivot		EA	2.000	84.43	168.86



GCS Energy Services Ltd.

Work Order: 13260

168	08/08/22	EMParts	7148022 Bushing-Pivot	EA	2.000	138.48	276.96
169	08/08/22	EMParts	7163427 Pin-Pivot	EA	2.000	72.43	144.86
170	08/08/22	EMParts	7259010 Bushing-Pivot	EA	2.000	118.98	237.96
171	08/08/22	EMParts	75W90 Certop SN 75W90 Gear Lube	EA	2.000	9.48	18.96
172	08/08/22	EMParts	Dyed Diesel Dyed Diesel	EA	33.310	1.54	51.41

Labour Total	0.00
Parts Total	274.33
Miscellaneous Total	0.00

Segment: 2 Inspections

*Insheet/Outsheet inspections.
Install new inner air filter. Set track and great unit.
Top up washer fluid and fuel.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
481	08/04/22	PR	Employee: 2915 Scott Scrivener		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
482	08/04/22	PR	Employee: 2623 Brenton Woolman		HRS	1.500		
849	07/15/22	PR	Employee: 2623 Brenton Woolman		HRS	1.000		
850	07/18/22	PR	Employee: 2623 Brenton Woolman		HRS	6.500		

Labour Total	9.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 T/S and Repair Leaks

*Front R side bucket cyl hose needs to be wrapped.
R side lift cyl bottom hose leaking/wet @crimp.
Oily residue on bottom lift cyl hyd hoses L side.
Oily residue on fuel tank. Nothing is usually leaking.
Test for leaks. Verify areas of play. Clean-up park equipment.*

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
848	07/11/22	PR	Employee: 2873 Isaac Simpkin		HRS	4.500		
1258	03/19/24	PR	Employee: 3103 Dallas Wood		HRS	2.500		



Work Order: 13260

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Inspect and advise on U/C

Undercarriage extremely dirty, replaced full of mud/dirt.
 Rides rough.
 Tested idlers for play in barring's.
 Removed track & idler for repair. R&L slides, removed sprockets & change planetary oil.
 Washed both tracks, cleaned up bay.
 Installed tracks & adjusted tension.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
851	07/19/22	PR	Employee: 2873 Isaac Simpkin		HRS	2.000		
852	07/20/22	PR	Employee: 2873 Isaac Simpkin		HRS	5.000		
853	07/21/22	PR	Employee: 2873 Isaac Simpkin		HRS	2.500		
1982	07/27/22	PR	Employee: 2395 Nickolas Schou		HRS	3.500		
1983	07/29/22	PR	Employee: 2873 Isaac Simpkin		HRS	4.500		

Labour Total	17.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 T/S and repair boom and bucket pins/bushings

R & L boom has lots of play.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
483	08/05/22	PR	Employee: 2915 Scott Scrivener		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	37.00
Parts Total	274.33
Miscellaneous Total	0.00

Description: T/S and Repair leak	Unit at BC Site.	Date Started: 2022-08-29
Equipment: E570 Bobcat T590 Tracked Skidsteer		
Serial#: A3NR12137		

Segment: 1 Parts



GCS Energy Services Ltd.

Work Order: 13377

Segment: 2 T/S and Repair Parts

Find and repair leak. Lift cab, found leak left final release track tension. Remove track & sprocket and guards. Remove line fitting - pitted from corrosion (remove cap/plug lines). Drive to Valmont. Build base. Drive back to site and reassemble top up fluid. Check for leaks and none found.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
605	10/05/22	PR	Employee: 2915 Scott Scrivener		HRS	1.000		
2271	08/26/22	PR	Employee: 2915 Scott Scrivener		HRS	8.000		

Labour Total 9.00

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 9.00

Parts Total 0.00

Miscellaneous Total 0.00

Description: Inspections and Repairs	Next Service Hours: 3684	Date Started: 2023-05-15
Equipment: E570 Bobcat T590 Tracked Skidsteer	GRO#10692/10915	
Serial#: A3NR12137		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
902	09/20/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-389999 Line: 1	EA		1.000	183.84	183.84
903	09/20/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-389999 Line: 2	EA		-1.000	15.00	-15.00
904	09/20/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-390014 Line: 1	EA		2.000	4.31	8.62
905	09/20/23	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-390023 Line: 1	EA		1.000	4.58	4.58
990	09/21/23	AP	Vendor: 10055 Calmont Equipment P19467 Line: 2	EA		1.000	23.83	23.83
792	09/21/23	EMParts	6661353 Housing-Lamp	EA		2.000	77.38	154.76
793	09/21/23	EMParts	6672276 Lens-Red Tail	EA		2.000	19.48	38.96
1047	09/20/23	EMParts	7176099 Filter-Cab Air	EA		2.000	47.59	95.18
1048	09/20/23	EMParts	6667352 Fuel/ Water Separator	EA		1.000	26.02	26.02
2477	09/21/23	EMParts	6672276 Lens-Red Tail	EA		-2.000	19.48	-38.96
2478	09/21/23	EMParts	6661353 Housing-Lamp	EA		-2.000	77.38	-154.76
2479	09/21/23	EMParts	5W40 Spectra 5W40	I		6.000	5.52	33.12
2480	09/20/23	EMParts	6666375 Filter-Air Primary	EA		1.000	32.25	32.25
2481	09/20/23	EMParts	6666376 Filter-Air Secondary	EA		1.000	37.81	37.81

Labour Total 0.00

Parts Total 430.25

Miscellaneous Total 0.00



Work Order: 14088

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2544	05/12/23	PR	Employee: 3103 Dallas Wood		HRS	3.000		
						Labour Total	3.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 3 put on loader & chain to forks to bring into shop

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1509	09/20/23	PR	Employee: 2024 Travis Schmidt		HRS	0.500		
						Labour Total	0.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 4 service, fixed back door

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1510	09/20/23	PR	Employee: 3119 Shawn Dittmer		HRS	4.000		
1037	10/27/23	EMAdj	Bobcat S300 Skidsteer		HRS	3.000		
						Labour Total	7.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 5 replace RHS rear lense

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1511	09/28/23	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		
						Labour Total	2.00	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	12.50	
						Parts Total	430.25	
						Miscellaneous Total	0.00	



GCS Energy Services Ltd.

Work Order: 15032

Description: Reg Maintenance	GRO11951/13133/13136/13222/1363	Date Started: 2024-08-26
Equipment: E570 Bobcat T590 Tracked Skidsteer	4/13632	
Serial#: A3NR12137	3485 hours	

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
148	10/10/24	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-404769 Line: EA			1.000	276.37	276.37
149	10/10/24	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-404769 Line: EA			1.000	40.00	40.00
150	10/10/24	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-404769 Line: LS			0.000	0.00	-40.00
537	11/13/24	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-405885 Line: LS			0.000	0.00	74.18
933	11/27/24	AP	Vendor: 10401 RBC Avion Visa Nov 24/Max Line: 4		LS	0.000	0.00	625.05
1351	11/20/24	AP	Vendor: 33118 Lightning Express 798910 Line: 1		LS	0.000	0.00	19.05
1456	08/20/24	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-402837 Line: EA			1.000	6.32	6.32
472	11/13/24	EMParts	Oil All Oil All Xtreme 10W30		EA	5.000	4.57	22.85
		PO - Open - #1028507 - 10064	hose/fittings		LS	0.00	0.00	74.18
Labour Total						0.00		
Parts Total						1,098.00		
Miscellaneous Total						0.00		

Segment: 2 wash

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
668	11/18/24	PR	Employee: 22 Garrett Nelson		HRS	1.000		
669	11/19/24	PR	Employee: 22 Garrett Nelson		HRS	2.000		
1313	08/20/24	PR	Employee: 3119 Shawn Dittmer		HRS	1.000		
Labour Total						4.00		
Parts Total						0.00		
Miscellaneous Total						0.00		

Segment: 3 In/Out Sheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1314	08/20/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		
Labour Total						2.00		
Parts Total						0.00		
Miscellaneous Total						0.00		



Work Order: 15032

Segment: 4 replace alternator/used battery

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
285	10/10/24	PR	Employee: 3119 Shawn Dittmer		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 5 trouble no start issue

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
284	10/09/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		
						Labour Total		2.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 6 Hyd leak fix with new hyd hose

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
667	11/13/24	PR	Employee: 3119 Shawn Dittmer		HRS	5.000		
						Labour Total		5.00
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 7 Install Positive shut off

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
670	11/20/24	PR	Employee: 3119 Shawn Dittmer		HRS	5.000		
671	11/21/24	PR	Employee: 3119 Shawn Dittmer		HRS	5.000		
						Labour Total		10.00
						Parts Total		0.00
						Miscellaneous Total		0.00
						Labour Total		24.00
						Parts Total		1,098.00
						Miscellaneous Total		0.00



Work Order: Z1007

Description: Change Pallet Fork Lock	2209 Hours	Date Started: 2018-06-19
Equipment: E570 Bobcat T590 Tracked Skidsteer	GRO#6952	
Serial#: A3NR12137		

Segment: 1 Change Pallet Fork Lock

1-6680122 Lock Kit (45.66ea)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
438	06/25/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		
						Labour Total		1.00
						Parts Total		0.00
						Miscellaneous Total		0.00
						Labour Total		1.00
						Parts Total		74.18
						Miscellaneous Total		0.00

Description: 350 Hour Service	2033 Hours	Date Started: 2018-01-07
Equipment: E570 Bobcat T590 Tracked Skidsteer	RD-2017-233 Insheet	
Serial#: A3NR12137		

Segment: 1 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
163	01/07/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		
						Labour Total		1.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 2 drained, dried and resealed tail light assembly

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
164	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	0.500		
						Labour Total		0.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 3 R&R Reseal both boom cylinders, top up hyd oil & Test



Work Order: Z10013

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
165	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	5.000		

Labour Total	5.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
166	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Top up wiper fluid , move spill kit

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
167	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Reroute crankcase vent line to turbo intake

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
168	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Adjusted tracks (sprockets worn)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
169	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	0.500		



GCS Energy Services Ltd.

Work Order: Z10013

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 R&R Sprockets, Service Final Drives and Adjust Tracks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
170	01/07/18	EMTime	Employee: 1575 Paul Nixon		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Washed and cleaned cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
171	01/07/18	EMTime	Employee: 1074 Jack Loughheed		HRS	6.500		

Labour Total	6.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Outsheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
172	01/07/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 11 Parts

6L - Oil All Plus
 9.5L - 5W-40
 2L - Wiper Fluid
 2 - 7135489 - Kit, seal (59.83/EA)
 2 - 7166679 - Sprocket (311.13/EA)
 1 - 6666375 - Air Primary
 1 - 6666376 - Air Secondary
 2 - 7176099 - Cab (2)
 1 - 6675517 - Oil
 1 - 6667352 - Fuel/Water



Work Order: Z10013

Labour Total	21.50
Parts Total	74.18
Miscellaneous Total	0.00

