

SC6 – 621G

Repair History

<u>2020 Repairs</u>
• Repair/rebuild ejector cylinder. Replace H-link bushings. Install new bushing into hitch. Replace steering pins and bushings • Replace grease lines • Repair and weld cracks on bowl • Install new fuel priming pump • Reseal transmission
<u>2021 Repairs</u>
• Replace front differential group • Bail repair • Replace starter gasket • Transmission rebuild • Replace ejector rollers • Install new engine wiring harness. Install new belts. Replace primary and secondary timing sensors. Repair exhaust pipe • Reseal front right final drive
<u>2022 Repairs</u>
• Replace scraper park brake pressure switch • Replace leaking hydraulic hose • Install new circuit breaker • Replace seatbelt • Install new engine speed sensor • Replace ejector pipe
<u>2023 Repairs</u>
• Repair/weld rear bumper • Replace sight glass on hydraulic tank • Replace front pedal bushings. Rebuild fuel pedal. Install new AM/FM radio. Repair/weld handrail • Replace ejector rollers. Replace broken slack adjuster. Replace broken window. • Repair/rebuild steering cylinder • Fabricate new steps for rear end • Replace A/C pressure sensor • Install new engine harness and batteries • Replace speed sensors and coolant temperature sensor and thermostats • Install new intake sensor
<u>2024 Repairs</u>
• Replace left hand step assembly and left side mirror • Replace blown hydraulic hose • Replace ejector roller
<u>2025 Repairs</u>
• Replace leaking cushion hitch hose • Replace upper and lower left hand ejector rollers • Replace turbo inlet pressure sensor