K012-7

# SC3 – 621G Repair History

### 2020 Repairs

- Stinger repair
- Repair/rebuild apron cylinder
- Install new bushing in rear neck
- Install new batteries
- Replace temperature control switch

## 2021 Repairs

- Install new floormat
- Replace brake check valve and solenoid valve
- Install new trunnion balls and caps. Repair hitch
- Install new batteries
- Replace leaking hydraulic line
- Replace two broken windows
- Install new seat in cab
- Replace ejector hose

#### 2022 Repairs

- Rebuild front right final drive
- Replace left hand duo cone seal
- Replace cushion hitch solenoid
- Install new soft shift harness and park brake sensor
- Replace starter and air dryer assembly
- Repair seat swivel
- Replace engine belt, A/C belt and alternator belt
- Repair and weld broken handrail

## 2023 Repairs

- Replace lower quarter window glass
- Install new freeze switch
- Replace hydraulic hard pipe and bowl cylinder return line
- Install new ECM and mounts
- Install new sliding glass window
- Replace leaking transmission hose

#### 2024 Repairs

- Replace rear right hand brake pot
- Install new steps
- Replace ejector hose
- Replace implement pump cartridge and reseal
- Install new starter
- Replace torque convertor cooler line
- Replace apron cylinder
- Install new upshift/downshift solenoid and transmission position sensor
- Install new A/C compressor, receiver dryer and accumulator
- Replace apron dog bone pin

### 2025 Repairs

- Machine Inspection Repairs Install new foot pedal bushings. Repair hydraulic leaks. Replace hood latch. Repair electrical to taillights. Replace fittings for air compressor. Repair/weld guardrail.
- Transmission rebuild

- Repair/rebuild ejector cylinder. Replace ejector rollers. Replace bearings in servo-cylinder. Weld lifting eye on apron. Replace lift cylinder lower pins and bushings.
- Reseal valve covers, set valves and injectors. Replace thermostats, gaskets and fuel valve. Install new muffler
- Install new H-link pins and bushings. Replace steering pins and bushings
- Replace bowl harness and rear light wiring harness
- Replace bearings in final drive
- Install new evaporator and condenser
- Repair leak on scraper control valve
- Install new exhaust manifolds and replace broken studs on cylinder head
- Replace cushion hitch accumulator