

Tandem19 Repair History

2020 Repairs

- CVIP Inspection – Replace windshields. Replace torque rod and bushings.
- Replace airbag
- Replace broken shock absorber
- Replace coolant lines and replace seals to air compressor
- Replace water valve
- Install new wiper blade arm

2021 Repairs

- CVIP Inspection – Replace left front spring pin bushings. Install new drum and shoes.
- Replace leaking coolant lines
- Install new wiper arm assembly
- Replace leveling valve
- Driveshaft repair – replace yoke and bearing
- Install new shocks, torque rod, bushings and tie rod assembly. Complete wheel alignment
- Installed new speedometer

2022 Repairs

- CVIP Inspection – Replace engine damper. Install new front s-cams and s-cam bushings. Replace steering line. Replace steering shaft u-joint. Replace input and output pinon seal. Install new torque rod on rear upper side. Replace slack adjuster and brake lines. Replace airbags. Repair and rewire Webasto. Replace rivets on fan shroud. Replace engine mount. Install new air tank brackets. Replace A/C and heater controller. Install new blower resistor. Install new tailgate and build up pins. Fit new floor and weld. Repair coolant leak. Install new wiper blades and arm assembly.
- Install new fan belt
- Install new fuel level sender
- Replace torque rod
- Install new speed sensor

2023 Repairs

- Replace tarp circuit breaker
- Replace below and clamps
- Install new engine bolt
- CVIP Inspection – Replace right side leaf spring pins and bushings. Install new windshields. Replace torque rods on #2 axles. Replace power steering lines. Install new leaf spring on left side. Replace rubber bumpers on rear axle. Replace front slack adjusters and air lines. Install new studs on hubs. Repair exhaust. Replace leaking front shock.
- Install new axle shaft, seals and gaskets
- Replace upper rad hose and clamps
- Install new engine belt and tensioner

2024 Repairs

- Install new AM/FM radio
- Replace axle gasket
- Install new batteries and battery hold down bolts
- Replace LH headlight assembly and headlight harness
- Install new leveling valve
- Install new rear shocks and mounts
- Install new A/C compressor and belt. Replace engine air filter housing
- Replace high- and low-pressure A/C sensors and replace fan override switch

- CVIP Inspection – Replace airbags. Replace power steering line. Replace top u-joint and gaskets. Replace dust shield. Replace #2 left wheel seal. Install new mudflap brackets. Repair exhaust stack and install new clamps. Replace transmission seal and transmission solenoid. Repair leaking PTO. Install new bushings in torque arms. Replace driver side windshield.
- Replace rear shocks
- Installed new throttle pedal position sensor
- Replace hood support rubbers. Replace tarp bar and tarp. Install new bumper mounts and spacers. Weld new box lugs
- Install new air compressor
- Replace lift cylinder hose
- Install new hydraulic pump and spool valve
- Install new air dryer
- Replace wiper switch and heated mirror switch
- Install new engine oil pressure sensor, crank speed sensor
- Install new batteries and replace starter

2025 Repairs

- Replace airbag
- Replace duct assembly. Install new freeze control thermostat switch. Replace A/C harness for thermal expansion valve