

RT15 – 410E

Repair History

<u>2020 Repairs</u>
• Install new EGR valve • Replace guard wrap on bottom rad hose • Replace leaking hydraulic hose
<u>2021 Repairs</u>
• Replace leaking hydraulic hose • Install new driveshaft, redress yoke splines, install new bearing and seal • Replace transmission seal • Install new dosing valve • Install new starter • Replace seat shock • Repair/weld cracks on box sideboards
<u>2022 Repairs</u>
• Repair seat air compressor • Install block heater and cord • Install new seat in cab • Replace eight hydraulic hoses • Install new seatbelt • Replace A/C pressure switch • Install new hood shock • Replace upper rad hose • Replace high pressure fuel pump • Replace cab and engine door shocks and latch • Replace leaking hydraulic hose • Install new engine fan belt • Replace leaking coolant line
<u>2023 Repairs</u>
• Install new box lift cylinder bushing • Install new coolant tank and replace lower rad hose • Install new starter • Replace manual selector valve • Replace right side mirror
<u>2024 Repairs</u>
• Install new door lock and handle • Install two new suspension blocks • Install new starter • Install new lift cylinder bushings • Install updated freeze switch and harness. Replace broken louver in cab • Replace ground cable to frame and replace ground cable from starter to frame • Install new blower motor and replace belt and tensioner • Install new EGR cooler and EGR pipe
<u>2025 Repairs</u>
• Tailgate installation • Replace and wire in new left hand mirror • Replace hose to box lift cylinder • Replace bin up relief valve • Tailgate arm repair

- Replace box up relief valve and main relief valve, calibrate box