



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #15
Invoice Number:
PO Number:

WORK ORDER






















EE25-3






















WORK ORDER DETAILS

Issue Date:	Fri, Apr 29, 2022 2:41 PM	#39 2017 Kenworth W900
Scheduled Start Date:		VIN/SN: 1XKWD40X9HJ988599
Actual Start Date:	Tue, May 3, 2022	License Plate:
Expected Completion Date:		Operator: N/A
Actual Completion Date:	Tue, May 31, 2022 8:07 AM	Type: Tandem
Duration:	28 days	Group:
Repair Priority Class:	N/A	Odometer: 732,257km
Status:	Completed	Secondary Meter:
Issued By:	JOE NEMEC	
Assigned to:		
Vendor:		
Labels:		




















LINE ITEMS

Item	Labor	Parts	Subtotal
Perform Truck Preventative Maintenance Inspection	\$50.00	\$7.00	\$57.00
Chad Caouette (Contact)	2 hrs \$25.00		\$50.00
FGR12716002A (Part) · Main JETCO 2" AMBER LED	1 ea \$7.00		\$7.00
#77 · [Inspection] Work Lights Generated by the failed inspection item "Work Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Chad Caouette on May 2, 2022 at 7:32 AM MDT			
#76 · [Inspection] Two wire at truck not connected re connect wires in plug Generated by the failed inspection item "Trailer Cord and Pins" on the "Truck Preventative Maintenance Checklist" form submitted by Chad Caouette on May 2, 2022 at 7:32 AM MDT			
Coolant Hose Replacement Replace worn coolant hoses	\$101.92	\$199.46	\$301.38
Rickylynn Peters (Contact)	0.94 hrs \$21.50		\$20.21

Item		Labor	Parts	Subtotal
 Rickylynn Peters (Contact)	0.25 hrs			\$5.38
 Replaced coolant lines	\$21.50			
 Rickylynn Peters (Contact)	3.55 hrs			\$76.33
	\$21.50			
 GWKF50-6308 (Part) · Main	1 ea			\$34.58
COOLANT HOSE STRAIGHT	\$34.58			
 GWKF50-1548 S/AS S27992 (Part)	1 ea			\$17.92
HOSE 2.5" 45DEG COOLA	\$17.92			
 GWKF50-1050-1020 (Part)	1 ea			\$91.64
HOSE-RADIATOR 16X1020	\$91.64			
 GWKF04-6006 (Part) · Main	1 ea			\$55.32
COOLANT HOSE 2.5" 90 S/AS 56175250	\$55.32			
 Airbag Replacement		\$70.88	\$0.00	\$70.88
Replace airbag				
 Roper Gorgichuk (Contact)				\$0.00
 Removed wheels. Removed old airbag. Descaled and paint surfaces installed new air bag. Checked for air leaks				
	0 hrs			
	\$34.00			
 Roper Gorgichuk (Contact)	2.07 hrs			\$70.38
	\$34.00			
 Chad Caouette (Contact)	0.02 hrs			\$0.50
	\$25.00			
 #84 · A3 LHS airbag showing threads front of axle				
 Airbag Replacement		\$31.50	\$456.12	\$487.62
Replace airbag				
 Chad Caouette (Contact)	1.26 hrs			\$31.50
	\$25.00			
 GWKAS95410 (Part) · Main	3 ea			\$456.12
AIR BAG 8 BAG	\$152.04			
 #83 · Air bag A2 RHS bag weathered back of axle				
 Airbag Replacement		\$63.75	\$0.00	\$63.75
Replace airbag				
 Chad Caouette (Contact)	1.27 hrs			\$31.75
	\$25.00			
 Chad Caouette (Contact)	1.28 hrs			\$32.00
	\$25.00			
 Airbag Replacement		\$99.00	\$0.00	\$99.00
Replace airbag				

Item	Labor	Parts	Subtotal
<div>  Chad Caouette (Contact) </div>			\$31.75
	1.27 hrs \$25.00		
<div>  Chad Caouette (Contact) </div>	1.27 hrs		\$31.75
<div>  Replaced airbag </div>	\$25.00		
<div>  Chad Caouette (Contact) </div>	1.42 hrs		\$35.50
<div>  Replaced airbag </div>	\$25.00		
<div>  #82 - Air bags on A2 LHS showing threads at back of axle Showing threads and wheathered </div>			
<div>  Tire/Wheel (Miscellaneous) </div>	\$8.60	\$0.00	\$8.60
<div>  Rickylynn Peters (Contact) </div>	0.4 hrs		\$8.60
<div>  Replaced cracked rim with new rim. </div>	\$21.50		
<div>  Grease Unit </div>	\$55.59	\$0.00	\$55.59
Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.			
<div>  Rickylynn Peters (Contact) </div>	2.19 hrs		\$47.09
<div>  </div>	\$21.50		
<div>  Chad Caouette (Contact) </div>	0.34 hrs		\$8.50
	\$25.00		
<div>  Air System Leaks </div>	\$6.50	\$0.00	\$6.50
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
<div>  Chad Caouette (Contact) </div>	0.26 hrs		\$6.50
<div>  Drain valve on rear tank needs to be changed </div>	\$25.00		
<div>  Windshield Wiper Blade Replacement </div>	\$16.75	\$0.00	\$16.75
<div>  Chad Caouette (Contact) </div>	0.67 hrs		\$16.75
	\$25.00		
<div>  Engine Oil & Filter Replacement </div>	\$0.00	\$0.00	\$0.00
<div>  Check Diff and Trans Oil </div>	\$2.00	\$0.00	\$2.00
<div>  Ross Cowell (Contact) </div>	0.07 hrs		\$2.00
	\$28.50		
<div>  Tire Condition and Pressure Inspection </div>	\$7.96	\$0.00	\$7.96
Check all tires			
<div>  Rickylynn Peters (Contact) </div>	0.37 hrs		\$7.96
<div>  Tire pressures all good. </div>	\$21.50		
<div>  Torque Wheels </div>	\$7.10	\$0.00	\$7.10
Verify wheels are properly torqued			

Item	Labor	Parts	Subtotal
<div> <div></div> <div>Rickylynn Peters (Contact)</div> </div> <div> <div></div> <div>All good and torqued after tire rotation.</div> </div>	0.12 hrs \$21.50		\$2.58
<div> <div></div> <div>Rickylynn Peters (Contact)</div> </div> <div> <div></div> <div>Torque was all good.</div> </div>	0.21 hrs \$21.50		\$4.52
<div> <div></div> <div>Rickylynn Peters (Contact)</div> </div>	0 hrs \$21.50		\$0.00
<div> <div></div> <div>Inspect and Service Trailer Hitch</div> <div>Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.</div> </div>	\$0.00	\$0.00	\$0.00
<div> <div></div> <div>JOE NEMEC (Contact)</div> </div>	0 hrs \$90.00		\$0.00
<div> <div></div> <div>Walk Around Inspection</div> </div>	\$0.00	\$0.00	\$0.00
<div> <div></div> <div>Remove injectors and pressure test cooling system</div> <div>Remove injectors and pressure test cooling system to check injector cups for leakage.</div> </div>	\$212.33	\$55.14	\$267.47
<div> <div></div> <div>Ross Cowell (Contact)</div> </div>	2.88 hrs \$28.50		\$82.08
<div> <div></div> <div>Ross Cowell (Contact)</div> </div>	4.37 hrs \$28.50		\$124.55
<div> <div></div> <div>Ross Cowell (Contact)</div> </div>	0.2 hrs \$28.50		\$5.70
<div> <div></div> <div>GWK3347939 (Part) · Main</div> <div>INJECTOR O-RING SEAL</div> </div>	6 ea \$5.00		\$30.00
<div> <div></div> <div>GWK2872717CUM (Part) · Main</div> <div>INJECTOR SEAL CUMMIN</div> </div>	6 ea \$4.19		\$25.14
<div> <div></div> <div>#75 · [Inspection] Coolant Level</div> <div>Generated by the failed inspection item "Coolant Level" on the "Truck Preventative Maintenance Checklist" form submitted by Chad Caouette on May 2, 2022 at 7:32 AM MDT</div> </div>			
<div> <div></div> <div>Airbag Replacement</div> <div>Replace airbag</div> </div>	\$0.00	\$0.00	\$0.00
<div> <div></div> <div>Rotate Drive Tires</div> <div>Rotate Drive Tires.</div> </div>	\$38.49	\$345.00	\$383.49
<div> <div></div> <div>Rickylynn Peters (Contact)</div> </div>	0.64 hrs \$21.50		\$13.76


Item		Labor	Parts	Subtotal
 Rickylynn Peters (Contact)				\$19.57
 Buffed up all the mounting surfaces and found one cracked rim on A2 LH inside rim, reinstalled tires in an X pattern.				
		0.91 hrs		
		\$21.50		
 Rickylynn Peters (Contact)		0.24 hrs		\$5.16
		\$21.50		
 AWSGA98U637 (Part) · Main		1 ea		\$345.00
RIM DURABRITE 24.5 X		\$345.00		
 Engine Camshaft Replacement	Replace cam	\$643.28	\$379.12	\$1,022.40
 Ross Cowell (Contact)		2.34 hrs		\$66.69
		\$28.50		
 Ross Cowell (Contact)		2.46 hrs		\$70.11
		\$28.50		
 MICHAEL ABLOG (Contact)		2.36 hrs		\$68.44
		\$29.00		
 MICHAEL ABLOG (Contact)		4.25 hrs		\$123.25
		\$29.00		
 Ross Cowell (Contact)		4.28 hrs		\$121.98
		\$28.50		
 MICHAEL ABLOG (Contact)		4.86 hrs		\$140.94
		\$29.00		
 Ross Cowell (Contact)		1.82 hrs		\$51.87
		\$28.50		
 GWK3679932 (Part)		1 ea		\$10.52
CAMSHAFT COVER GASKET S/AS 5719778CUM		\$10.52		
 GWK5594276 (Part) · Main		1 ea		\$26.13
CAM POSITION SENSOR		\$26.13		
 GWK4299125 (Part)		1 ea		\$16.49
CAMSHAFT COVER REAR O		\$16.49		
 GWK5579467 (Part) · Main		1 ea		\$325.98
ROCKER LEVER KIT. Discontinued.		\$325.98		
 Engine Rebuild		\$3,416.18	\$11,057.48	\$14,473.66
 Exhaust valves too high in head to adjust. Removed cylinder head for replacement and decided to perform in frame repair based on hours on unit. Cut counterbores and installed shims to achieve 0.012" liner heights. Installed 150mm non-apr PAI rebuild kit with a reman cummins head. Also replaced front structure as it was starting to leak and had wear on the sealing surface.				
 Roper Gorgichuk (Contact)		3.04 hrs		\$103.36
		\$34.00		

Item	Labor	Parts	Subtotal
👤 Roper Gorgichuk (Contact)	8.71 hrs \$34.00		\$296.14
👤 JOE NEMEC (Contact)	2.16 hrs \$90.00		\$194.40
👤 JOE NEMEC (Contact)	0.66 hrs \$90.00		\$59.40
👤 Roper Gorgichuk (Contact)	8.14 hrs \$34.00		\$276.76
👤 Roper Gorgichuk (Contact)	9.1 hrs \$34.00		\$309.40
👤 Roper Gorgichuk (Contact)	2.57 hrs \$34.00		\$87.38
👤 Roper Gorgichuk (Contact)	4.58 hrs \$34.00		\$155.72
👤 JOE NEMEC (Contact)	1.31 hrs \$90.00		\$117.90
👤 Roper Gorgichuk (Contact)	4.45 hrs \$34.00		\$151.30
👤 Roper Gorgichuk (Contact)	4.84 hrs \$34.00		\$164.56
👤 Roper Gorgichuk (Contact)	4.5 hrs \$34.00		\$153.00
👤 Roper Gorgichuk (Contact)	4.52 hrs \$34.00		\$153.68
👤 JOE NEMEC (Contact)	4.4 hrs \$90.00		\$396.00
👤 Roper Gorgichuk (Contact) 📅 May 10, 2022. Cleaned out head bolt threads in block ran a tap to remove rust and debris. Brake cleaned threads and vacuumed out threads. Cleaned front structure to inspect it. Found front structure needs to be replaced do to it being worn out. Cleaned front of the engine and top.	1.11 hrs \$34.00		\$37.74
👤 JOE NEMEC (Contact)	0 hrs \$90.00		\$0.00
👤 Roper Gorgichuk (Contact)	4.58 hrs \$34.00		\$155.72
👤 JOE NEMEC (Contact)	1.4 hrs \$90.00		\$126.00


Item	Labor	Parts	Subtotal
👤 Roper Gorgichuk (Contact)	2.23 hrs \$34.00		\$75.82
👤 JOE NEMEC (Contact)	1.5 hrs \$90.00		\$135.00
👤 Roper Gorgichuk (Contact)	2.99 hrs \$34.00		\$101.66
👤 Roper Gorgichuk (Contact)	4.86 hrs \$34.00		\$165.24
🔧 GWK4318947CUM (Part) · Main THERMOSTAT WATER 180	1 ea \$84.05		\$84.05
🔧 GWK3685556 (Part) FRONT COVER GASKET-AD	1 ea \$12.96		\$12.96
🔧 GWK3682673CUM (Part) · Main THERMOSTAT HOUSING GA	1 ea \$27.05		\$27.05
🔧 GWK3688113 (Part) · Main ENGINE COVER PLUG S/AS X-12-1207	1 ea \$14.39		\$14.39
🔧 GWK3104392 (Part) · Main VALVE COVER GASKET IS	1 ea \$67.36		\$67.36
🔧 GWK3963991CUM (Part) · Main RUBBER LINED WASHER	2 ea \$6.29		\$12.58
🔧 GWK4928594CUM (Part) · Main EXHAUST MANIFOLD PRES	1 ea \$129.38		\$129.38
🔧 GWK4298975CUM (Part) · Main TURBO STUD NUT	1 ea \$9.84		\$9.84
🔧 GWK2874656 (Part) ACCESSORY BRACKET W/	1 ea \$200.00		\$200.00
🔧 5575513CUM (Part) · Main SCREW, HEX FLANGE HEAD CAP S/AS GWK3678882	1 ea \$9.03		\$9.03
🔧 GWK4374074 (Part) · Main FUEL PUMP IDLER SCREW	3 ea \$3.51		\$10.53
🔧 GWK5484100 (Part) · Main FUEL PUMP IDLER SHAFT	1 ea \$101.77		\$101.77
🔧 GWK3685173CUM (Part) · Main CRANK SEAL FRONT CUMM	1 ea \$71.68		\$71.68
🔧 GWK4393089 (Part) · Main GEAR HOUSING GASKET F	1 ea \$78.93		\$78.93
🔧 GWK5414049 (Part) · Main FUEL PUMP GASKET	1 ea \$27.14		\$27.14

Item		Labor	Parts	Subtotal
 GWK5440813 (Part) · Main	1 ea			\$16.07
AIR COMPRESSOR GASKET	\$16.07			
 GWK3678724 (Part) · Main	1 ea			\$3.93
WATER PUMP-BLOCK O-RI	\$3.93			
 GWK4059172 (Part) · Main	1 ea			\$7.99
WATER PUMP INLET O-RI	\$7.99			
 GWK3685173CUM (Part) · Main	1 ea			\$71.68
CRANK SEAL FRONT CUMM	\$71.68			
 GWK3336204 (Part) · Main	1 ea			\$13.14
OIL THERMOSTAT O-RING	\$13.14			
 GWKS16255 (Part) · Main	1 ea			\$6.83
SNAP RING OIL THREMOS	\$6.83			
 GWK4386527 (Part) · Main	1 ea			\$110.25
THERMOSTAT OIL X15 21	\$110.25			
 4376178 (Part)	1 ea			\$5,241.60
ISX15 150mm Rebuild Kit. Non-APR Liners, Fracture Split Rods.	\$5,241.60			
 GWK3691253RX (Part) · Main (Archived)	1 ea			\$3,421.78
CYLINDER HEAD ISX & X	\$3,421.78			
 GWK5406110 (Part) · Main	1 ea			\$314.70
KIT-MAIN BEARING	\$314.70			
 GWK5298564 (Part) · Main	6 ea			\$369.42
SHIM	\$61.57			
 GWK2894829CUM (Part) · Main	6 ea			\$623.40
INJECTOR CONNECTOR, CROSS TUBE	\$103.90			

LABOR (not linked to a Service Task)

Technician	Hours	Hourly rate	Subtotal
 Roper Gorgichuk (Contact)	6.5 hrs	\$34.00	\$221.00

PARTS (not linked to a Service Task)

Part	Quantity	Unit cost	Subtotal
 313 (Part) · Main (Archived)	1 ea	\$3.15	\$3.15
Brake Clean			

DESCRIPTION

SUMMARY

Subtotal	\$17,555.30
Labor	\$5,052.83
Parts	\$12,502.47
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$17,555.30



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245










Work Order Number: #3834
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Fri, Apr 12, 2024 11:59 AM	#39 2017 Kenworth W900	
Scheduled Start Date:	Fri, Apr 12, 2024 11:59 AM	VIN/SN: License Plate:	1XKWD40X9HJ988599
Actual Start Date:	Fri, Apr 12, 2024 11:59 AM	Operator:	Robert Hansen
Expected Completion Date:		Type: Group:	Tandem
Actual Completion Date:	Fri, Apr 12, 2024 11:59 AM	Odometer: Secondary Meter:	1,005,632km 23,953hr
Duration:			
Repair Priority Class:	Scheduled		
Status:	Completed		
Issued By:	MICHAEL ABLOG		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS



Item	Labor	Parts	Subtotal
 Hydraulic Oil Top Up	\$2.75	\$4.79	\$7.54
 Chad Caouette (Contact)	0.1 hrs \$27.50		\$2.75
 MXFMV32 (Part) · Main (Archived) HYDRAULIC OIL	1 L \$4.79		\$4.79
 #7588 · [Inspection] Hydraulic Oil Level Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Apr 12, 2024 at 2:24 PM MDT			
 Truck Preventative Maintenance Inspection	\$19.38	\$0.00	\$19.38
 MICHAEL ABLOG (Contact)	0.51 hrs \$38.00		\$19.38
 Rh Hood Pin Loose	\$7.20	\$0.00	\$7.20
 Kurt Kerekanich (Contact)  Tightened	0.2 hrs \$36.00		\$7.20

Item	Labor	Parts	Subtotal
------	-------	-------	----------

#7590 · [Inspection] Rh Hood pin

Generated by the failed inspection item "Hood Operation" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Apr 12, 2024 at 2:24 PM MDT



 A1Rh Hub Oil Low	\$6.88	\$0.00	\$6.88
---	--------	--------	--------


 Chad Caouette (Contact)	0.25 hrs		\$6.88
 checked hub oil full pulled dustshield wheel seal dry	\$27.50		


#7589 · [Inspection] A1Rh hub oil low

Generated by the failed inspection item "Front Hub Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Apr 12, 2024 at 2:24 PM MDT


 Fuel Filter Replacement	\$6.88	\$102.69	\$109.57
--	--------	----------	----------


 Chad Caouette (Contact)	0.25 hrs		\$6.88
 .	\$27.50		


 BALPF46081 (Part) · Main	1 ea		\$43.96
BALDWIN FUEL FILTER	\$43.96		


 BALBF46129 (Part) · Main (Archived)	1 ea		\$58.73
FUEL FILTER SPIN ON S/AS DBF6776	\$58.73		

 Ac Compressor Hose Repair	\$55.50	\$824.89	\$880.39
---	---------	----------	----------

 Roper Gorgichuk (Contact)	1.5 hrs		\$55.50
	\$37.00		


 GWKLF4376 (Part) · Main	1 ea		\$310.13
A/C COMPRESSOR CUMMIN	\$310.13		


 GWKF50-2351-0450 (Part) · Main	1 ea		\$85.97
HOSE ASSEMBLY S/AS F50-1792-0345	\$85.97		

 GWKF50-6242-1475 (Part) · Main	1 ea		\$428.79
A/C HOSE ASSEMBLY W90	\$428.79		

#7575 · Ac
Needs recharge

 Engine Oil & Filter Replacement	\$6.88	\$355.17	\$362.05
--	--------	----------	----------

 Chad Caouette (Contact)	0.25 hrs		\$6.88
	\$27.50		

 NXTDBL7900 (Part) · Main	1 ea		\$58.65
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$58.65		

 MXF5W40 (Part) · Main	42 L		\$296.52
ENGINE OIL 5W40 BULK	\$7.06		

Item		Labor	Parts	Subtotal
↳ Air System Leaks		\$6.88	\$0.00	\$6.88
	Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
👤 Chad Caouette (Contact)		0.25 hrs		\$6.88
📅		\$27.50		
↳ Check Diff and Trans Oil		\$6.88	\$0.00	\$6.88
👤 Chad Caouette (Contact)		0.25 hrs		\$6.88
📅		\$27.50		
↳ Inspect and Service Trailer Hitch		\$6.00	\$0.00	\$6.00
	Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.			
👤 Rickylynn Peters (Contact)		0.25 hrs		\$6.00
		\$24.00		
↳ Tire Condition and Pressure Inspection		\$6.75	\$0.00	\$6.75
	Check all tires			
👤 Allan Bates (Contact)		0.25 hrs		\$6.75
		\$27.00		
↳ Torque Wheels		\$7.77	\$0.00	\$7.77
	Verify wheels are properly torqued			
👤 Roper Gorgichuk (Contact)		0.21 hrs		\$7.77
		\$37.00		
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact)		0.25 hrs		\$22.50
		\$90.00		
↳ Grease Unit		\$6.88	\$0.00	\$6.88
	Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.			
👤 Chad Caouette (Contact)		0.25 hrs		\$6.88
📅		\$27.50		

DESCRIPTION

SUMMARY

Subtotal	\$1,456.67
Labor	\$169.13
Parts	\$1,287.54
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,456.67



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245









Work Order Number: #3903
Invoice Number:
PO Number:






















WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Apr 30, 2024 7:26 AM	#39 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X9HJ988599
Actual Start Date:	Tue, Apr 30, 2024 7:27 AM	License Plate:	
Expected Completion Date:		Operator:	Robert Hansen
Actual Completion Date:	Wed, May 1, 2024	Type:	Tandem
Duration:	1 day	Group:	
Repair Priority Class:	Non-Scheduled	Odometer:	1,011,404km
Status:	Completed	Secondary Meter:	24,056hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Drivers windsheild	\$9.50	\$53.30	\$62.80
 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00		\$9.50
 GWKDW1164-30 (Part) · Main WINDSHIELD, DS	1 ea \$53.30		\$53.30
 #7773 · [Inspection] Lh Windshield Generated by the failed inspection item "Windshields" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on May 1, 2024 at 11:31 AM MDT			
 Truck Preventative Maintenance Inspection	\$19.00	\$0.00	\$19.00
 MICHAEL ABLOG (Contact)	0.5 hrs \$38.00		\$19.00
 Oil Pan Replacement	\$76.00	\$1,066.87	\$1,142.87
 MICHAEL ABLOG (Contact)	2 hrs \$38.00		\$76.00

Item		Labor	Parts	Subtotal
 GWK102720002 (Part) · Main	1 ea			\$44.30
CUMMINS OIL QUICK DRA	\$44.30			
 GWK351-0415 (Part) · Main	1 ea			\$63.82
OIL PAN HEATER	\$63.82			
 GWK4026684 (Part) · Main	1 ea			\$308.75
OIL PAN GASKET CUMM	\$308.75			
 TTD4952540 (Part) · Main	1 ea			\$650.00
OIL PAN ISX HAWKINS	\$650.00			
 #7771 · [Inspection] Oil pan cracked Generated by the failed inspection item "Oil Pan and Engine Heater" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on May 1, 2024 at 11:31 AM MDT				
 Hood Stainless Bolts		\$7.98	\$0.00	\$7.98
 MICHAEL ABLOG (Contact)	0.21 hrs			\$7.98
 tightened all bolts	\$38.00			
 Diff Leaking At Banjo		\$237.50	\$398.38	\$635.88
 MICHAEL ABLOG (Contact)	6.25 hrs			\$237.50
 re-sealed diff. filled with new oil	\$38.00			
 FGR3303111 (Part) · Main	2 ea			\$5.60
DRIVE AXLE HUBCAP GASKET	\$2.80			
 MNACHV223030953 (Part) · Main	20 L			\$193.40
DELO S-G XDM 75W90 SYNTHETIC GEAR OIL 7590	\$9.67			
 BALB233 (Part) · Main	1 ea			\$5.98
FILTER BALDWIN SPIN O	\$5.98			
 MNACHV223030953 (Part) · Main	20 L			\$193.40
DELO S-G XDM 75W90 SYNTHETIC GEAR OIL 7590	\$9.67			
 #7774 · [Inspection] A2 Dif leaking Generated by the failed inspection item "Diff and Trans Breathers" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on May 1, 2024 at 11:31 AM MDT				
 Windshield Wiper Blade (Rh)		\$7.98	\$16.55	\$24.53
 MICHAEL ABLOG (Contact)	0.21 hrs			\$7.98
	\$38.00			
 FGR63-151 (Part) · Main	1 ea			\$16.55
TRICO SUMMER WIPER BLADES	\$16.55			
 #7772 · [Inspection] Rh wiper Generated by the failed inspection item "Windshield Wiper and Spray" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on May 1, 2024 at 11:31 AM MDT				
 Engine Oil & Filter Replacement		\$9.50	\$245.87	\$255.37

Item		Labor	Parts	Subtotal
👤 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00			\$9.50
🔧 NXTDBL7900 (Part) - Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$58.65			\$58.65
🔧 MXF15W40 (Part) - Main ENGINE OIL, 15W40 BUL	46 L \$4.07			\$187.22
↳ Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$9.50	\$0.00	\$9.50
👤 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00			\$9.50
↳ Check Diff and Trans Oil		\$9.50	\$0.00	\$9.50
👤 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00			\$9.50
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$7.98	\$0.00	\$7.98
👤 MICHAEL ABLOG (Contact)	0.21 hrs \$38.00			\$7.98
↳ Tire Condition and Pressure Inspection Check all tires		\$7.98	\$0.00	\$7.98
👤 MICHAEL ABLOG (Contact)	0.21 hrs \$38.00			\$7.98
↳ Torque Wheels Verify wheels are properly torqued		\$7.98	\$0.00	\$7.98
👤 MICHAEL ABLOG (Contact)	0.21 hrs \$38.00			\$7.98
↳ Walk Around Inspection		\$3.80	\$0.00	\$3.80
👤 MICHAEL ABLOG (Contact)	0.1 hrs \$38.00			\$3.80
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$9.50	\$6.90	\$16.40
👤 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00			\$9.50
🔧 MXFPSC30 (Part) - Main (Archived) GREASE PRECISION TUBE	1 tube \$6.90			\$6.90

DESCRIPTION

SUMMARY

Subtotal	\$2,211.57
Labor	\$423.70
Parts	\$1,787.87
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$2,211.57



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #4064
Invoice Number:
PO Number:


























WORK ORDER

WORK ORDER DETAILS

Issue Date:	Fri, May 24, 2024 1:17 PM	#39 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X9HJ988599
Actual Start Date:	Fri, May 24, 2024 1:18 PM	License Plate:	
Expected Completion Date:		Operator:	Robert Hansen
Actual Completion Date:	Mon, May 27, 2024	Type:	Tandem
Duration:	3 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,021,368km
Status:	Completed	Secondary Meter:	24,213hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Lh Sleeper Door Latch	\$27.00	\$0.00	\$27.00
Ernesto Ablog (Contact)			\$27.00
Removed sleeper door,found door latch snap ring missing.installed snap ring and re installed.			
	0.75 hrs		
	\$36.00		
Truck Preventative Maintenance Inspection	\$19.38	\$0.00	\$19.38
MICHAEL ABLOG (Contact)			\$19.38
	0.51 hrs		
	\$38.00		
Install Dash Camera	\$45.00	\$544.40	\$589.40
JOE NEMEC (Contact)			\$45.00
Installed SN: 779004951			
	0.5 hrs		
	\$90.00		
010-02619-00 (Part) · Main			\$539.99
Garmin Dash Cam Live	1 ea		
	\$539.99		
VPSP1B3922-11 (Part) · Main			\$4.41
ADAPTER PLUG 12V FEMA	1 ea		
	\$4.41		

Item	Labor	Parts	Subtotal
 A2 Diff Temp Repair	\$9.00	\$0.00	\$9.00
<div>  Ernesto Ablog (Contact) <div>0.25 hrs</div> </div> <div>  Fixed broken wire <div>\$36.00</div> </div>			\$9.00
 Windshield Wiper Blade (Lh)	\$6.88	\$16.55	\$23.43
<div>  Chad Caouette (Contact) <div>0.25 hrs</div> </div> <div>  replaced windshield wiper <div>\$27.50</div> </div>			\$6.88
<div>  FGR63-151 (Part) · Main <div>1 ea</div> </div> <div> TRICO SUMMER WIPER BLADES <div>\$16.55</div> </div>			\$16.55
<div>  #8058 · [Inspection] Lh wiper blade <div>Generated by the failed inspection item "Windshield Wiper and Spray" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on May 24, 2024 at 1:47 PM MDT</div> </div>			
 Exhaust Clamps at Turbo	\$9.50	\$0.00	\$9.50
<div>  MICHAEL ABLOG (Contact) <div>0.25 hrs</div> </div> <div>  tightened clamps <div>\$38.00</div> </div>			\$9.50
 Rh Hood Pin Loose	\$9.50	\$0.00	\$9.50
<div>  MICHAEL ABLOG (Contact) <div>0.25 hrs</div> </div> <div>  tightened nut. <div>\$38.00</div> </div>			\$9.50
<div>  #8057 · [Inspection] Rh hood pin spins <div>Generated by the failed inspection item "Hood Operation" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on May 24, 2024 at 1:47 PM MDT</div> </div>			
 Engine Oil & Filter Replacement	\$19.00	\$225.52	\$244.52
<div>  Joseph Pitney (Contact) <div>0.5 hrs</div> </div> <div> <div>\$38.00</div> </div>			\$19.00
<div>  NXTDBL7900 (Part) · Main <div>1 ea</div> </div> <div> OIL FILTER HIGH EFFICIENCY S/AS BD50000 <div>\$58.65</div> </div>			\$58.65
<div>  MXF15W40 (Part) · Main <div>41 L</div> </div> <div> ENGINE OIL, 15W40 BUL <div>\$4.07</div> </div>			\$166.87
 Air System Leaks	\$6.88	\$0.00	\$6.88
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.			
<div>  Chad Caouette (Contact) <div>0.25 hrs</div> </div> <div>  <div>\$27.50</div> </div>			\$6.88
 Check Diff and Trans Oil	\$6.88	\$0.00	\$6.88
<div>  Chad Caouette (Contact) <div>0.25 hrs</div> </div> <div>  <div>\$27.50</div> </div>			\$6.88

Item	Labor	Parts	Subtotal
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
↳ Tire Condition and Pressure Inspection Check all tires	\$6.75	\$0.00	\$6.75
👤 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
↳ Torque Wheels Verify wheels are properly torqued	\$9.50	\$0.00	\$9.50
👤 Joseph Pitney (Contact)	0.25 hrs \$38.00		\$9.50
↳ Walk Around Inspection	\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$9.50	\$6.90	\$16.40
👤 MICHAEL ABLOG (Contact)	0.25 hrs \$38.00		\$9.50
🔧 MXFPSC30 (Part) - Main (Archived) GREASE PRECISION TUBE	1 tube \$6.90		\$6.90

DESCRIPTION

SUMMARY

Subtotal	\$1,023.14
Labor	\$229.77
Parts	\$793.37
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (Fixed)
Total	\$1,023.14

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#8043 From drive axle temp Reported May 23, 2024 by Robert Hansen Not working		
#8027 Door lock Reported May 22, 2024 Driver side door lock won't unlock.		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #4387
Invoice Number:
PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:	Wed, Jul 17, 2024 8:53 AM	#39 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X9HJ988599
Actual Start Date:	Wed, Jul 17, 2024 7:10 AM	License Plate:	
Expected Completion Date:		Operator:	Robert Hansen
Actual Completion Date:	Wed, Jul 17, 2024 7:10 AM	Type:	Tandem
Duration:		Group:	
Repair Priority Class:	Scheduled	Odometer:	1,042,781km
Status:	Completed	Secondary Meter:	24,562hr
Issued By:			
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 coolant leak repair	\$41.50	\$0.00	\$41.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
 MICHAEL ABLOG (Contact)	0.5 hrs \$38.00		\$19.00
 Slave Valve Red Line Leaking	\$22.50	\$0.00	\$22.50
 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
 Steer Tire Replacement	\$24.00	\$700.00	\$724.00
 Rickylynn Peters (Contact)	1 hr \$24.00		\$24.00
 CXEXZE2 (Part) · Main STEER TIRES 11R 24.5	2 ea \$350.00		\$700.00
 Turbo Actuator	\$128.00	\$2,076.39	\$2,204.39

Item	Labor	Parts	Subtotal
👤 JOE NEMEC (Contact)			\$90.00
	1 hr \$90.00		
👤 MICHAEL ABLOG (Contact)			\$38.00
	1 hr \$38.00		
🔧 GWK6378270RXCUM (Part) · Main (Archived) KIT, VG TURBO ACTUATOR	1 ea \$2,002.63		\$2,002.63
🔧 GWKHE8716 (Part) · Main AIR-AIR BOOT 4"	2 ea \$36.88		\$73.76

DESCRIPTION	SUMMARY
	Subtotal \$2,992.39
	Labor \$216.00
	Parts \$2,776.39
	Labor Markup + \$0.00 (0.0%)
	Parts Markup + \$0.00 (0.0%)
	Warranty Credits - \$0.00 (0.0%)
	Discount - \$0.00 (0.0%)
	Tax +\$0.00 (0.0%)
	Total \$2,992.39

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#8644 Losing coolant Reported Jul 16, 2024 Losing 1/2 gallon of coolant a day. Can't find leak		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245











Work Order Number: #4439
Invoice Number:
PO Number:













WORK ORDER

WORK ORDER DETAILS

Issue Date:	Fri, Jul 26, 2024 1:31 PM	#39 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X9HJ988599
Actual Start Date:	Fri, Jul 26, 2024 1:31 PM	License Plate:	
Expected Completion Date:		Operator:	Robert Hansen
Actual Completion Date:	Fri, Jul 26, 2024 1:31 PM	Type:	Tandem
Duration:		Group:	
Repair Priority Class:	Scheduled	Odometer:	1,048,841km
Status:	Completed	Secondary Meter:	24,681hr
Issued By:			
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Truck Preventative Maintenance Inspection	\$19.00	\$0.00	\$19.00
 MICHAEL ABLOG (Contact)	0.5 hrs \$38.00		\$19.00
 HVAC Water Valve	\$76.00	\$209.75	\$285.75
 MICHAEL ABLOG (Contact)	2 hrs \$38.00		\$76.00
 replaced water valve and 5/8 coolant hoses.			
 GWKSR2000013 (Part) - Main	1 ea \$209.75		\$209.75
 A3 Input U-Joints	\$66.50	\$272.80	\$339.30
 Joseph Pitney (Contact)	0.75 hrs \$38.00		\$28.50
 start removing shaft 1 bolt head stripped			
 Joseph Pitney (Contact)	1 hr \$38.00		\$38.00

Item		Labor	Parts	Subtotal
<div>  SPISPL1704X (Part) · Main U JOINT </div>	2 ea \$136.40			\$272.80
<div>  #8765 · [Inspection] U-Joints between A2-A3 Generated by the failed inspection item "Driveline and Steady Bearing" on the "Truck Preventative Maintenance Checklist" form submitted by MICHAEL ABLOG on Jul 29, 2024 at 7:18 AM MDT </div>				
↳ Engine Oil & Filter Replacement		\$6.00	\$241.80	\$247.80
<div>  Rickylynn Peters (Contact) </div>	0.25 hrs \$24.00			\$6.00
<div>  NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000 </div>	1 ea \$58.65			\$58.65
<div>  MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL </div>	45 L \$4.07			\$183.15
↳ Air System Leaks		\$24.00	\$14.40	\$38.40
Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.				
<div>  Rickylynn Peters (Contact) </div>	1 hr \$24.00			\$24.00
<div>  Replaced trans air fitting. </div>				
<div>  FGRPC1469532A (Part) · Main ELBOW 90 5/32 TO 1/8 </div>	3 ea \$4.80			\$14.40
↳ Check Diff and Trans Oil		\$6.00	\$0.00	\$6.00
<div>  Rickylynn Peters (Contact) </div>	0.25 hrs \$24.00			\$6.00
↳ Inspect and Service Trailer Hitch		\$6.00	\$0.00	\$6.00
Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.				
<div>  Rickylynn Peters (Contact) </div>	0.25 hrs \$24.00			\$6.00
↳ Tire Condition and Pressure Inspection		\$6.75	\$0.00	\$6.75
Check all tires				
<div>  Allan Bates (Contact) </div>	0.25 hrs \$27.00			\$6.75
↳ Torque Wheels		\$6.75	\$0.00	\$6.75
Verify wheels are properly torqued				
<div>  Allan Bates (Contact) </div>	0.25 hrs \$27.00			\$6.75
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50

Item	Labor	Parts	Subtotal
<div> <div></div> <div>JOE NEMEC (Contact)</div> </div>	0.25 hrs \$90.00		\$22.50
<div> <div></div> <div>Grease Unit</div> <div>Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.</div> </div>	\$19.00	\$0.00	\$19.00
<div> <div></div> <div>Joseph Pitney (Contact)</div> </div>	0.5 hrs \$38.00		\$19.00

DESCRIPTION	SUMMARY
	Subtotal \$997.25
	Labor \$258.50
	Parts \$738.75
	Labor Markup + \$0.00 (0.0%)
	Parts Markup + \$0.00 (0.0%)
	Warranty Credits - \$0.00 (0.0%)
	Discount - \$0.00 (0.0%)
	Tax +\$0.00 (0.0%)
	Total \$997.25



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #4595
Invoice Number:
PO Number:





















WORK ORDER

WORK ORDER DETAILS

Issue Date:	Fri, Aug 16, 2024 5:10 PM	#39 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X9HJ988599
Actual Start Date:	Fri, Aug 16, 2024 5:10 PM	License Plate:	
Expected Completion Date:		Operator:	Robert Hansen
Actual Completion Date:	Fri, Aug 16, 2024 5:10 PM	Type:	Tandem
Duration:		Group:	
Repair Priority Class:	Scheduled	Odometer:	1,060,057km
Status:	Completed	Secondary Meter:	24,858hr
Issued By:			
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Cab filter replacement	\$9.00	\$29.91	\$38.91
 Ernesto Ablog (Contact)	0.25 hrs \$36.00		\$9.00
 GWKCF19501C (Part) · Main CAB AIR FILTER C/W CR	1 ea \$29.91		\$29.91
 PTO Sensor Switch Leaking	\$9.00	\$27.00	\$36.00
 Ernesto Ablog (Contact)	0.25 hrs \$36.00		\$9.00
 FGR380515 (Part) · Main PTO SWITCH BALL, CHEL	1 ea \$27.00		\$27.00
 Replace Convex Mirror Rhs	\$3.60	\$39.67	\$43.27
 Rickylynn Peters (Contact)	0.15 hrs \$24.00		\$3.60
 Installed new mirror			

Item		Labor	Parts	Subtotal
 GWKSH8S0FH (Part) · Main	1 ea			\$39.67
CONVEX MIRROR 8" S/AS GWK7085970VEL	\$39.67			
 Top up hydraulic oil		\$2.40	\$4.84	\$7.24
 Rickylynn Peters (Contact)	0.1 hrs			\$2.40
	\$24.00			
 MXFMV32 (Part) · Main (Archived)	1 L			\$4.84
HYDRAULIC OIL	\$4.84			
 A2 Input Seal Leaking		\$36.00	\$88.37	\$124.37
 Ernesto Ablog (Contact)	1 hr			\$36.00
	\$36.00			
 FGRKIT2638 (Part) · Main	1 ea			\$32.60
ROCKWELL PINION NUT/W	\$32.60			
 GWKAS2728 (Part) · Main	1 ea			\$55.77
INPUT SEAL FWD REAR S/AS FGRA11205X2728	\$55.77			
 CVIP		\$126.00	\$0.00	\$126.00
 JOE NEMEC (Contact)	1 hr			\$90.00
	\$90.00			
 Ernesto Ablog (Contact)	1 hr			\$36.00
	\$36.00			
 Truck Preventative Maintenance Inspection		\$27.00	\$0.00	\$27.00
 Ernesto Ablog (Contact)	0.75 hrs			\$27.00
	\$36.00			
 DS windshield		\$7.20	\$53.30	\$60.50
 Rickylynn Peters (Contact)	0.3 hrs			\$7.20
	\$24.00			
 GWKDW1164-30 (Part) · Main	1 ea			\$53.30
WINDSHIELD, DS	\$53.30			
 Engine Oil & Filter Replacement		\$6.00	\$221.45	\$227.45
 Rickylynn Peters (Contact)	0.25 hrs			\$6.00
	\$24.00			
 NXTDBL7900 (Part) · Main	1 ea			\$58.65
OIL FILTER HIGH EFFICIENCY S/AS BD50000	\$58.65			
 MXF15W40 (Part) · Main	40 L			\$162.80
ENGINE OIL, 15W40 BUL	\$4.07			

Item	Labor	Parts	Subtotal
↳ Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.	\$6.00	\$0.00	\$6.00
👤 Rickylynn Peters (Contact)	0.25 hrs \$24.00		\$6.00
↳ Check Diff and Trans Oil	\$9.00	\$0.00	\$9.00
👤 Ernesto Ablog (Contact)	0.25 hrs \$36.00		\$9.00
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.	\$9.00	\$0.00	\$9.00
👤 Ernesto Ablog (Contact)	0.25 hrs \$36.00		\$9.00
↳ Tire Condition and Pressure Inspection Check all tires	\$6.75	\$0.00	\$6.75
👤 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
↳ Torque Wheels Verify wheels are properly torqued	\$3.60	\$0.00	\$3.60
👤 Rickylynn Peters (Contact)	0.15 hrs \$24.00		\$3.60
↳ Walk Around Inspection	\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$6.00	\$0.00	\$6.00
👤 Rickylynn Peters (Contact)	0.25 hrs \$24.00		\$6.00

DESCRIPTION

SUMMARY

Subtotal	\$753.59
Labor	\$289.05
Parts	\$464.54
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$753.59

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#8845 Windshield Reported Aug 2, 2024 by Robert Hansen Drivers side windshield cracks through drivers vision.		
#9048 Under bunk storage lock Reported Aug 15, 2024 by Robert Hansen Drivers side under bunk storage won't unlock.		
#9075 [Inspection] Windshields Reported 12 months ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Windshields" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Aug 19, 2024 at 8:34 AM MDT		
#9074 [Inspection] Rhs convex mirror worn out Reported 12 months ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Mirrors" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Aug 19, 2024 at 8:34 AM MDT		
#9073 [Inspection] Hydraulic Oil Level Reported 12 months ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Aug 19, 2024 at 8:34 AM MDT		
#9072 [Inspection] Cab Air Filter Reported 12 months ago by Ernesto Ablog - Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Cab Air Filter" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Aug 19, 2024 at 8:34 AM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245











Work Order Number: #4733
Invoice Number:
PO Number:























WORK ORDER

WORK ORDER DETAILS


Issue Date:	Fri, Sep 6, 2024 2:13 PM	#39 2017 Kenworth W900	
Scheduled Start Date:		VIN/SN:	1XKWD40X9HJ988599
Actual Start Date:	Fri, Sep 6, 2024 2:13 PM	License Plate:	
Expected Completion Date:		Operator:	Robert Hansen
Actual Completion Date:	Mon, Sep 9, 2024	Type:	Tandem
Duration:	3 days	Group:	
Repair Priority Class:	Scheduled	Odometer:	1,071,470km
Status:	Completed	Secondary Meter:	25,036hr
Issued By:	JOE NEMEC		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 A2Rh Abs Repair	\$36.00	\$190.70	\$226.70
 Kurt Kerekanich (Contact)	1 hr \$36.00		\$36.00
 FGR4410309102 (Part) · Main ABS SENSOR KIT, 90 DE	2 ea \$95.35		\$190.70
 Engine Air Filter Replacement	\$9.00	\$208.76	\$217.76
 Ernesto Ablog (Contact)	0.25 hrs \$36.00		\$9.00
 NTXP625128 (Part) · Main AIR FILTER W900	2 ea \$104.38		\$208.76
 Exhaust Clamps Between Stacks	\$18.00	\$44.90	\$62.90
 Ernesto Ablog (Contact)  Replaced clamps	0.5 hrs \$36.00		\$18.00
 FGRSW50A3 (Part) · Main EXHAUST CLAMP 5" SS	2 ea \$22.45		\$44.90

Item		Labor	Parts	Subtotal
 A2Rhs Wheel Seal Leaking		\$108.00	\$161.40	\$269.40
 Ernesto Ablog (Contact)	3 hrs			\$108.00
 Replaced wheel seal and bearings	\$36.00			
 FGRE2468 (Part) · Main	2 ea			\$45.34
AXLE NUT EUCLID 3 1/	\$22.67			
 FGRSET403 (Part) · Main	1 ea			\$54.99
BEARINGS SET TIMKIN	\$54.99			
 FGRSET401 (Part) · Main	1 ea			\$27.51
BEARING CUP & CONE S	\$27.51			
 FGR3303111 (Part) · Main	1 ea			\$2.80
DRIVE AXLE HUBCAP GASKET	\$2.80			
 WST 10045887.00 (Part) · Main	1 ea			\$30.76
WHEELSEAL DRIVE S/AS	\$30.76			
 fuel filters replacement		\$9.00	\$108.27	\$117.27
 Kurt Kerekanich (Contact)	0.25 hrs			\$9.00
	\$36.00			
 BALPF46081 (Part) · Main	1 ea			\$43.96
BALDWIN FUEL FILTER	\$43.96			
 NTXDBF6776 (Part) · Main	1 ea			\$64.31
FUEL FILTER SPIN ON S/AS BF46129	\$64.31			
 Hydraulic Filter Replacement		\$9.00	\$13.70	\$22.70
 Kurt Kerekanich (Contact)	0.25 hrs			\$9.00
	\$36.00			
 BALBT8443 (Part) · Main	1 ea			\$13.70
HYDRAULIC FILTER GARD S/AS P565059	\$13.70			
 Top up hydraulic oil		\$9.00	\$0.00	\$9.00
 Kurt Kerekanich (Contact)	0.25 hrs			\$9.00
	\$36.00			
 Air Dryer Cartridge Replacement		\$9.00	\$22.20	\$31.20
 Ernesto Ablog (Contact)	0.25 hrs			\$9.00
	\$36.00			
 WSTN1335130010860 S/AS AC1001 (Part) · Main	1 ea			\$22.20
AIR DRYER CARTRIDGE	\$22.20			
 Truck Preventative Maintenance Inspection		\$27.00	\$0.00	\$27.00
 Ernesto Ablog (Contact)	0.75 hrs			\$27.00
	\$36.00			

Item		Labor	Parts	Subtotal
↳ Engine Oil & Filter Replacement		\$6.00	\$233.66	\$239.66
👤 Rickylynn Peters (Contact)	0.25 hrs \$24.00			\$6.00
🔧 NXTDBL7900 (Part) - Main OIL FILTER HIGH EFFICIENCY S/AS BD50000	1 ea \$58.65			\$58.65
🔧 MXF15W40 (Part) - Main ENGINE OIL, 15W40 BUL	43 L \$4.07			\$175.01
↳ Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks.		\$9.00	\$37.55	\$46.55
👤 Ernesto Ablog (Contact)	0.25 hrs \$36.00			\$9.00
🔧 GWKK342-188-21 (Part) - Main HOSE ASSEMBLY-AIR BRAKE #8X21	1 ea \$37.55			\$37.55
↳ Check Diff and Trans Oil		\$9.00	\$0.00	\$9.00
👤 Ernesto Ablog (Contact)	0.25 hrs \$36.00			\$9.00
↳ Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style.		\$9.00	\$0.00	\$9.00
👤 Ernesto Ablog (Contact)	0.25 hrs \$36.00			\$9.00
↳ Tire Condition and Pressure Inspection Check all tires		\$108.00	\$0.00	\$108.00
👤 Allan Bates (Contact) 🔧 Replaced drive tires with used ones around 12/32	4 hrs \$27.00			\$108.00
↳ Torque Wheels Verify wheels are properly torqued		\$6.75	\$0.00	\$6.75
👤 Allan Bates (Contact)	0.25 hrs \$27.00			\$6.75
↳ Walk Around Inspection		\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact)	0.25 hrs \$90.00			\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.		\$9.00	\$0.00	\$9.00

Item	Labor	Parts	Subtotal
 Ernesto Ablog (Contact)	0.25 hrs \$36.00		\$9.00

DESCRIPTION

SUMMARY

Subtotal	\$1,434.39
Labor	\$413.25
Parts	\$1,021.14
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (0.0%)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$1,434.39

RESOLVED ISSUES(not linked to a Service Task)

Issue	Assigned	Due
#9307 [Inspection] Exhaust clamps between stacks loose Reported 11 months ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Exhaust Leaks" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Sep 6, 2024 at 3:26 PM MDT		
#9305 [Inspection] Air Dryer Condition Reported 11 months ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Air Dryer Condition" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Sep 6, 2024 at 3:26 PM MDT		
#9304 [Inspection] Hydraulic Oil Level Reported 11 months ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Hydraulic Oil Level" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Sep 6, 2024 at 3:26 PM MDT		
#9306 [Inspection] Wheel Seals Reported 11 months ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Wheel Seals" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Sep 6, 2024 at 3:26 PM MDT		



CX Energy Services
PO Box 3450, 74028 RR 174, 74028 RR 174
High Prairie, AB, T0G 1E0
CA
7805230245

Work Order Number: #4952
Invoice Number:
PO Number:



















WORK ORDER

WORK ORDER DETAILS

Issue Date:	Tue, Oct 15, 2024 3:24 PM	#39 2017 Kenworth W900	
Scheduled Start Date:	Tue, Oct 15, 2024 3:27 PM	VIN/SN:	1XKWD40X9HJ988599
		License Plate:	
Actual Start Date:	Tue, Oct 15, 2024 3:27 PM	Operator:	Robert Hansen
		Type:	Tandem
		Group:	
Expected Completion Date:			
Actual Completion Date:	Fri, Oct 18, 2024	Odometer:	1,084,533km
Duration:	3 days	Secondary Meter:	25,276hr
Repair Priority Class:	Scheduled		
Status:	Completed		
Issued By:	Ernesto Ablog		
Assigned to:			
Vendor:			
Labels:			

LINE ITEMS

Item	Labor	Parts	Subtotal
 Air Filter ID Light Rhs	\$9.00	\$7.45	\$16.45
 Ernesto Ablog (Contact)	0.25 hrs		\$9.00
 Replaced one top light Rhs	\$36.00		
 FGR3050A (Part) - Main	1 ea		\$7.45
LIGHT 2. " AMBER LED	\$7.45		
 Support battery cables	\$9.00	\$0.00	\$9.00
 Ernesto Ablog (Contact)	0.25 hrs		\$9.00
 Support rubbing at cross member	\$36.00		
 Truck Preventative Maintenance Inspection	\$27.00	\$0.00	\$27.00
 Ernesto Ablog (Contact)	0.75 hrs		\$27.00
	\$36.00		
 Lhs Mirror ID Light Out	\$9.00	\$29.15	\$38.15
 Ernesto Ablog (Contact)	0.25 hrs		\$9.00
 Replaced light to Led	\$36.00		

Item	Labor	Parts	Subtotal
<div>  FGR12766093A (Part) · Main MIRROR LIGHT LED RETR </div>			\$29.15
	1 ea \$29.15		
<div>  replace gear pump and clean hydraulic system </div>	\$72.00	\$1,791.95	\$1,863.95
<div>  Ernesto Ablog (Contact) </div>	2 hrs \$36.00		\$72.00
<div>  Replaced gear and cleaned hydraulic system </div>			
<div>  DPIPL12702BPBB (Part) · Main (Archived) MUNCIE GEAR PUMP, 27 </div>	1 ea \$1,667.00		\$1,667.00
<div>  MNACHV255675-448 (Part) · Main AW32 HYDRAULIC OIL </div>	35 L \$3.57		\$124.95
<div>  Engine Oil & Filter Replacement </div>	\$6.00	\$237.73	\$243.73
<div>  Rickylynn Peters (Contact) </div>	0.25 hrs \$24.00		\$6.00
<div>  NXTDBL7900 (Part) · Main OIL FILTER HIGH EFFICIENCY S/AS BD50000 </div>	1 ea \$58.65		\$58.65
<div>  MXF15W40 (Part) · Main ENGINE OIL, 15W40 BUL </div>	44 L \$4.07		\$179.08
<div>  Air System Leaks Check air system for leaks. Check airlines and connections for signs of wear that could become a problem even if not currently leaking. Remember to check for leaks with lines in an air up state ie. airbags inflated, button pushed in and brake applied to check service brake leaks. </div>	\$9.50	\$0.00	\$9.50
<div>  MICHAEL ABLOG (Contact) </div>	0.25 hrs \$38.00		\$9.50
<div>  Check Diff and Trans Oil </div>	\$6.00	\$0.00	\$6.00
<div>  Rickylynn Peters (Contact) </div>	0.25 hrs \$24.00		\$6.00
<div>  Inspect and Service Trailer Hitch Inspect hitch whether it is a pintle or a fifth wheel. Check for secure mounting and any signs of wear. Check pintle hitch for free movement of lock and no slack shoe operation. Check fifth wheel for proper jaw adjustment and apply either grease or graphite lube depending on fifth wheel style. </div>	\$9.00	\$0.00	\$9.00
<div>  Ernesto Ablog (Contact) </div>	0.25 hrs \$36.00		\$9.00
<div>  Tire Condition and Pressure Inspection Check all tires </div>	\$5.50	\$0.00	\$5.50
<div>  Jayden Binet (Contact) </div>	0.25 hrs \$22.00		\$5.50

Item	Labor	Parts	Subtotal
↳ Torque Wheels Verify wheels are properly torqued	\$6.75	\$0.00	\$6.75
👤 Allan Bates (Contact)	0.25 hrs \$27.00		\$6.75
↳ Walk Around Inspection	\$22.50	\$0.00	\$22.50
👤 JOE NEMEC (Contact)	0.25 hrs \$90.00		\$22.50
↳ Grease Unit Grease all grease points on unit, ie. u-joints, s-cams, steering linkage.	\$6.00	\$4.67	\$10.67
👤 Rickylynn Peters (Contact)	0.25 hrs \$24.00		\$6.00
🔧 MNACHV259118-652 (Part) - Main STARPLEX EP2 TUBE Summer Grease	1 ea \$4.67		\$4.67

DESCRIPTION

SUMMARY

Subtotal	\$2,268.20
Labor	\$197.25
Parts	\$2,070.95
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$2,268.20

Issue	Assigned	Due
#9801 [Inspection] Clearance Lights Reported 10 months ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Clearance Lights" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Oct 15, 2024 at 3:50 PM MDT		
#9800 [Inspection] Batteries and Cables Reported 10 months ago by Ernesto Ablog • Truck Preventative Maintenance Checklist by Ernesto Ablog Generated by the failed inspection item "Batteries and Cables" on the "Truck Preventative Maintenance Checklist" form submitted by Ernesto Ablog on Oct 15, 2024 at 3:50 PM MDT		
#9635 Hot hydraulics Reported Sep 30, 2024 by Robert Hansen Hydraulics running hot and spilling over. Fan doesn't seem to be running fast enough.		