

Aug 13/25

W/O: 37957

Flying J Unit #317

F32-4
(LEAD)

EXTRA PARTS
Tasks

- 2HR - Reset Axle #3 bearings
- 1HR - Diagnosed ABS Issue
- 1HR - Replaced speed sensor on Axle 3 1/5
- 5HR - Replaced dust shield on axle 3 1/5
 - Set brakes & Torqued wheels
 - greased unit
- 1.5HR - Replaced Front 4" vic clamp
- 2HR - Replaced 3" vic clamp on transfer pipe
- 2HR - Trailer Alignment
- 1HR - Tie up loose Air lines
- 3.5HR - Had to Fix Rear Tail lights Both sides

JOB SCOPE

RF Dust Cover - Missing - Install New + Hardware 0.5HR

Auto Grease - Delete - Install Grease Zeros 4HR

Belly Legs - Seizing - Oil & Work / Free Up 1HR

Emergency Shut Off Valve - Unsecured - Install New Machine Screws 0.5HR

Grease Unit

Torque Tires

4HR Front Axle Air Bags - +Time to Cut Out Top Mounts x2 - Cords visible - Remove & Replace
+Time to Cut Out/Seperate Spacers x2

2HR RR Air Bag - Cords visible - Remove & Replace

4HR ALL Position Shocks - Old/Blown - Remove & Replace

- +Time - Top Bolts seized - Cut out w/ Fire & Air Hammer x4

1HR LR Hub - Hub Cap Mounting hole Damaged - had to Tap & Clean hole multiple times to get a bolt
to thread in correctly

1.5 Alignment done on both Axles