

## Work Order Details

This report was run on: Nov 24, 2024 03:08:35 PM

with the following parameters

Opened After: Nov 24, 2022 02:38:00 PM

Opened Before: Nov 24, 2024 02:38:00 PM

Parent Asset: "Articulated Rock Truck (19-30-002)"

Asset Category: "All"

Assigned User: "All"

Maintenance Type: "All"

Priority: "All"

Status: "All"

| Work  | Work Order Description   | Status            | Type             | Date Created                | Due Date  | Date Completed              | Days Late |
|---|--|-------------------|------------------|-----------------------------|-----------|-----------------------------|-----------|
| 63900   | LF tire  | Closed, Completed | Corrective       | Dec 25, 2022<br>10:37:25 AM |           | Dec 25, 2022<br>10:37:25 AM |           |
| Task Description  | Asset  | Assigned To       | Completed By     | Date Completed              | Est Hours | Spent Hours                 |           |
| 15 December 2022 - Kal Tire - Repaired LF tire  | Articulated Rock Truck   | Kal Tire          | Kal Tire         | Dec 25, 2022 10:38:32 AM    |           | 2.00                        |           |
|   |  |                   |                  |                             |           | 2.00                        |           |
| Work  | Work Order Description   | Status            | Type             | Date Created                | Due Date  | Date Completed              | Days Late |
| 65288   | Transfer gear case cracked. Front drive shaft removed. Parts ordered for rebuild with new case. **CHECK OTG PUMP PRESSURE AFTER INSTALLING OTG** | Closed, Completed | Corrective       | Jan 24, 2023<br>12:55:25 PM |           | Apr 19, 2023<br>08:46:00 AM |           |
| Task Description  | Asset  | Assigned To       | Completed By     | Date Completed              | Est Hours | Spent Hours                 |           |
| 03.04.23 JOSHUA R.<br>- HAD TO BOOST UNIT TO GET STARTED<br>- NEEDED TO BE PUSHED INTO WASH BAY<br>- WASHED UNIT<br>- DRAGGED UNIT INTO SHOP<br>- DRAINED COOLANT<br>- REMOVED ROPS GUARD<br>- LIFTED CAB   | Articulated Rock Truck   |                   | Joshua Ravelo    | Mar 04, 2023 05:12:00 PM    |           | 4.00                        |           |
| remove all drivelines remove hyd hoses remove all elctricals and lines attached to drop box removed mounts and removed drop box drained fluids and caped lines Mar 04/23 Kristian Z /NS   | Articulated Rock Truck   | Christopher Paul  | Christopher Paul | Mar 04, 2023 05:12:00 AM    | 11.00     | 11.00                       |           |
| -Assisted Chris P in removing the drop box from the unit MARCH 06, 2023-MARVI C- ORGANIZED WORK AREA, PUT SCATTERED DIFFERENTIAL PARTS AND CLEANED TABLE TO WORK ON. DISASSEMBLED DROP BOX, REMOVED ALL BEARINGS AND SEALS. WASHED PARTS, POLISHED PRIOR TO ASSEMBLY.   | Articulated Rock Truck   | Kristian Zimmer   | Kristian Zimmer  | Mar 04, 2023 05:16:00 AM    | 7.50      | 7.50                        |           |
| 07 MARCH 2023 Austin H<br>-Assisted Dan with dropdown rebuild and cleanup   | Articulated Rock Truck   | Marvin Corpuz     | Marvin Corpuz    | Mar 06, 2023 05:18:00 AM    | 11.50     | 11.50                       |           |
| Daniel Reid March 7 /23<br>checked parts to make sure we had them all. Removed oil filter and found filings. Hayden ordered a new pump and all the parts for the transfer gear assembly. We installed two new bearings on the transfer gear assembly.<br>Daniel Reid March 08/23<br>Put all bearing races in deep freeze and started installing bearing races.  | Articulated Rock Truck   | Austin Heino      |                  |                             | 7.00      | 7.00                        |           |
| 28 MARCH 2023 Austin H<br>-Cleaned rebuild area, was a total mess<br>-Organized all parts for this unit<br>-Completely disassembled carrier assembly and cleaned all parts<br>-Assembled carrier assembly with all new bearings MARCH 29, 2023-MARVIN C-<br>-REMOVED HYDRAULIC LINES AND REMOVED TRANSFER GEAR PUMP ASSEMBLY FOR THE DROP BOX. REMOVED ALL FITTINGS, RESEALED AND INSTALLED TO 20R-7998 | Articulated Rock Truck   | Austin Heino      | Austin Heino     |                             | 8.00      | 8.00                        |           |
|   | Articulated Rock Truck   | Marvin Corpuz     |                  |                             | 3.00      | 3.00                        |           |
|   |  |                   |                  |                             | 11.50     | 11.50                       |           |
|   |  |                   |                  |                             | 8.50      | 8.50                        |           |

|   |                        |              |              |       |
|---|------------------------|--------------|--------------|-------|
| REMAN PUMP ASSEMBLY. POLISHED MOUNTING AND INSTALLED NEW SEAL O-RING TO THE PUMP AND INSTALLED IT. RESEALED AND INSTALLED ALL HYDRAULIC LINES.<br>-REMOVED MAIN DRIVE SHAFT AND REPLACED ALL U-JOINTS WITH NEW ONE.<br>-DRAINED DROP BOX OIL RESERVOIR, NEW OIL TO PUT IN AFTER DROP BOX REPAIR AND INSTALLATION.   | Articulated Rock Truck | Austin Heino | Austin Heino | 11.50 |
| 29 MARCH 2023 Austin H<br>-Finished installing carrier assembly with all new friction discs and plates<br>-Installed piston with new seals<br>-Installed 2 new bearings on carrier<br>-Installed carrier assembly into transfer case<br>-Disassembled valve assembly and cleaned all parts<br>-Installed 3 new solenoids onto valve<br>-Installed valve onto transfer case  | Articulated Rock Truck | Austin Heino | Austin Heino | 11.50 |
| 30 MARCH 2023 Austin H<br>-Continued transfer case rebuild<br>-Installed yoke retainer and tightened yoke bolt to spec.<br>-Installed all new bearing cups into transfer case<br>-Installed all new bearing cones onto gears<br>-Installed gears into case<br>-Installed shroud   | Articulated Rock Truck | Austin Heino | Austin Heino | 11.50 |
| 31 MARCH 2023 Austin H<br>-Continued transfer case rebuild<br>-Installed 4 new bearing cones onto gears<br>-Installed new bearing cups into transfer case<br>-Installed cover with flange sealant, torqued bolts to spec.<br>-Middle plate doesn't fit onto the new transfer case cover, had to drill all new holes in order for it to fit<br>-Installed new lip seal and installed plate, torqued to spec.   | Articulated Rock Truck | Austin Heino | Austin Heino | 11.50 |
| 01 APRIL 2023 Austin H<br>-Continued transfer case rebuild<br>-Installed new bearing race and lip seal on output yoke 1<br>-Installed yoke, tightened bolt to spec.<br>-Installed new lip seal on output yoke 2<br>-Installed yoke, tightened bolt to spec.<br>-Performed all bearing pre load procedures, determined appropriate amount of shims on both output shafts<br>-Installed retainers with new O ring seals<br>-Transfer case ready for install<br>-Cleaned work area | Articulated Rock Truck | Austin Heino | Austin Heino | 11.50 |
| CHRIS WISEMAN APRIL 04/2023<br>-INSTALL DROP BOX<br>-INSTALL TOP DRIVELINE<br>-REMOVE CENTRE DRIVESHAFT C/O U-JOINTS<br>-INSTALL CENTRE DRIVESHAFT<br>-REMOVE WIRING HARNESS AND REPAIR/REINSTALL<br>-INSTALL TEST LINES<br>-INSTALL BOTTOM HOSE<br>-BOTTOM FRONT YOKE SHOULD BE REPLACED ON DROP BOX   | Articulated Rock Truck |              |              | 11.50 |
| 04 APRIL 2023 Austin H<br>-Installed cooling package<br>-Installed hyd. lines under cab   | Articulated Rock Truck | Austin Heino | Austin Heino | 4.00  |
| 05 APRIL 2023 Austin H<br>-Installed cooling lines on cooling package<br>-Installed ROPS and fire suppression (missing R/H rops support)<br>-Installed exhaust pipes<br>-Ordered radiator enclosures, they are all broken   | Articulated Rock Truck | Austin Heino | Austin Heino | 6.00  |
| 06 APRIL 2023 Austin H<br>-Tightened down all exhaust clamps<br>-Filled hydraulic and dropdown oils<br>-Filled coolant, bled cooling system on thermostat housing<br>-Temporarily installed front driveshaft (front diff to dropdown) to move unit outside as we wait for parts<br>-Found a truck and boosted unit, it will need new batteries as they are not holding a charge<br>-Parked in downline with a crossover   | Articulated Rock Truck | Austin Heino |              | 6.00  |
| 18 APRIL 2023 Austin H<br>-Find a machine to boost unit, brought unit inside<br>-Unit was leaking oil from dropdown tank breather, it may have been overfull<br>-Drained dropdown oil and removed driveshaft<br>-Removed front yoke<br>-Installed new yoke with new seal  | Articulated Rock Truck | Austin Heino | Austin Heino | 11.50 |

-Installed front driveshaft  
 -Filled dropdown oil  
 -Removed old batteries  
 -Retrieved new batteries from warehouse and installed  
 -Started machine, checked for leaks, good. Waiting for rad covers

|               |  |                                 |                              |   |  |   |                |        |
|---------------|--|---------------------------------|------------------------------|---|--|---|----------------|--------|
|               |  |                                 |                              |   |  |   | 11.00          | 157.00 |
| Work<br>66037 | Work Order Description<br>Pre-work inspection<br>Perform Cat inspection on wiring to secondary steering pump. Search on SIS 367-1782 -->Service magazine for proper procedure. | Status<br>Closed, Completed     | Type<br>Inspection           | Date Created<br>Feb 08, 2023<br>09:26:19 AM | Due Date                                   | Date Completed<br>May 21, 2023<br>06:48:58 AM | Days Late      |        |
|               | Task Description   | Asset<br>Articulated Rock Truck | Assigned To                  | Completed By<br>Trevor Bullock              | Date Completed<br>May 21, 2023 06:48:58 AM | Est Hours                                     | Spent Hours    |        |
| Work<br>69863 | Work Order Description<br>730C/740B PM2 500 Service Hours  | Status<br>Closed, Completed     | Type<br>Preventive - Planned | Date Created<br>Apr 19, 2023<br>02:48:07 PM | Due Date<br>Apr 19, 2023<br>02:48:00 PM    | Date Completed<br>Apr 19, 2023<br>02:49:57 PM | Days Late<br>0 |        |
|               | Task Description   | Asset<br>Articulated Rock Truck | Assigned To                  | Completed By                                | Date Completed                             | Est Hours                                     | Spent Hours    |        |
|               | Brake Pads - Check   | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Braking System(Service) - Test   | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Braking System (Park) - Test   | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Engine Air Filter Secondary Element (Inner) -Replace   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:49:00 PM                   |   | 1.00           |        |
|               | Engine Oil and Filter - Change   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:49:00 PM                   |   | 1.00           |        |
|               | Engine Oil Filter - Inspect (Cut Filter and Record Findings)   | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Fuel System Primary Filter - Replace   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:49:00 PM                   |   | 1.00           |        |
|               | Fuel System Secondary Filter - Replace   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:49:00 PM                   |   | 1.00           |        |
|               | Fuel Tank Cap and Strainer - Clean   | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Secondary Steering - Test  | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Transmission Oil Filter - Replace  | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:49:00 PM                   |   | 1.00           |        |
|               | Transmission Oil Filter - Inspect (Cut Filter and Record Findings)   | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Differential and Final Drive Oil Sample - Obtain   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:49:00 PM                   |   | 1.00           |        |
|               | Hydraulic System Oil Sample - Obtain   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:49:00 PM                   |   | 1.00           |        |
|               | Torque Converter and Transmission Oil Sample - Obtain  | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:49:00 PM                   |   | 1.00           |        |
|               | Transfer Gear Oil Sample - Obtain  | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:49:00 PM                   |   | 1.00           |        |
|               |  |                                 |                              |   |  | 9.00  |                |        |
| Work<br>69864 | Work Order Description<br>730C/740B PM3 1000 Service Hours   | Status<br>Closed, Completed     | Type<br>Preventive - Planned | Date Created<br>Apr 19, 2023<br>02:50:21 PM | Due Date<br>Apr 19, 2023<br>02:50:00 PM    | Date Completed<br>Apr 19, 2023<br>02:51:41 PM | Days Late<br>0 |        |
|               | Task Description   | Asset<br>Articulated Rock Truck | Assigned To                  | Completed By                                | Date Completed                             | Est Hours                                     | Spent Hours    |        |
|               | Battery or Battery Cable - Inspect/Replace   | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Cab Air Filter(Recirc)(Inner) - Replace  | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:51:00 PM                   |   | 1.00           |        |
|               | Hydraulic System Oil Filter and Screen - Clean/Inspect/Replace   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:51:00 PM                   |   | 1.00           |        |
|               | Hydraulic System Oil Filter - Inspect (Cut Filter and Record Findings)   | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Hydraulic Tank Strainer - Clean/Inspect/Replace  | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:51:00 PM                   |   | 1.00           |        |
|               | Fuel Tank Cap and Strainer - Replace   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:51:00 PM                   |   | 1.00           |        |
|               | Oscillating Hitch - Adjust   | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Rollover Protective Structure (ROPS) - Inspect   | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Torque Converter Scavenge Screen - Clean   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:51:00 PM                   |   | 1.00           |        |
|               | Transfer Gear Oil - Change   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:51:00 PM                   |   | 1.00           |        |
|               | Transfer Gear Oil Filter - Replace   | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:51:00 PM                   |   | 1.00           |        |
|               | Transfer Gear Oil Filter - Inspect (Cut Filter and Record Findings)  | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               | Transmission and Transfer Gear Breather - Replace  | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:51:00 PM                   |   | 1.00           |        |
|               | Transmission Oil - Change  | Articulated Rock Truck          | PMtech                       | PMtech                                      | Apr 19, 2023 02:51:00 PM                   |   | 1.00           |        |
|               | Transmission Clutch Calibrations - Complete  | Articulated Rock Truck          | PMtech                       |   |  |   |                |        |
|               |  |                                 |                              |   |  | 9.00  |                |        |
| Work<br>69865 | Work Order Description<br>730C/740B PM4 2000 Service Hours   | Status<br>Closed, Completed     | Type<br>Preventive - Planned | Date Created<br>Apr 19, 2023<br>02:52:11 PM | Due Date<br>Apr 19, 2023<br>02:52:00 PM    | Date Completed<br>Apr 19, 2023<br>02:53:11 PM | Days Late<br>0 |        |

| Task Description  |  | Asset                  | Assigned To          | Completed By             | Date Completed           | Est Hours                | Spent Hours |
|---|--|------------------------|----------------------|--------------------------|--------------------------|--------------------------|-------------|
| Brake Accumulator (Service) - Check   |  | Articulated Rock Truck | PMtech               |                          |                          |                          |             |
| Cooling System Pressure Cap - Clean/Replace   |  | Articulated Rock Truck | PMtech               | PMtech                   | Apr 19, 2023 02:53:00 PM | 1.00                     |             |
| Cooling System Water Temperature Regulator - Replace  |  | Articulated Rock Truck | PMtech               | PMtech                   | Apr 19, 2023 02:53:00 PM | 1.00                     |             |
|   |  |                        |                      |                          |                          | 2.00                     |             |
| Work  | Work Order Description                         | Status                 | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 70077   | Wheel choke holders installed                  | Closed, Completed      | Welding              | Apr 23, 2023 08:15:12 AM | Apr 23, 2023 08:15:12 AM | Apr 23, 2023 08:15:12 AM |             |
| Task Description  |  | Asset                  | Assigned To          | Completed By             | Date Completed           | Est Hours                | Spent Hours |
| 23 April 2023 - Donald K -  | Installed wheel choke holders on machine       | Articulated Rock Truck | Donald Kearley       | Donald Kearley           | Apr 23, 2023 08:18:00 AM |                          | 1.00        |
|   |  |                        |                      |                          |                          |                          | 1.00        |
| Work  | Work Order Description                         | Status                 | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 70143   | Replace all tires                              | Closed, Completed      | Corrective           | Apr 24, 2023 11:16:02 AM |                          | Apr 20, 2023 11:16:00 AM |             |
| Task Description  |  | Asset                  | Assigned To          | Completed By             | Date Completed           | Est Hours                | Spent Hours |
| Replace all tires   |  | Articulated Rock Truck | Kai Tire             | Kai Tire                 |                          |                          |             |
|   |  |                        |                      |                          |                          |                          |             |
| Work  | Work Order Description                         | Status                 | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 71443   | truck arrived on float and had emissions codes | Closed, Completed      | Corrective           | May 13, 2023 03:50:11 PM |                          | May 13, 2023 03:55:00 PM |             |
| Task Description  |  | Asset                  | Assigned To          | Completed By             | Date Completed           | Est Hours                | Spent Hours |
| no dep prime code--change def pump filter--blead out the system--full pressure<br>high ash load code--force ash regen--reset ash load chart   |  | Articulated Rock Truck | Trevor Bullock       | Trevor Bullock           | May 13, 2023 03:55:00 PM |                          | 4.00        |
|   |  |                        |                      |                          |                          |                          | 4.00        |
| Work  | Work Order Description                         | Status                 | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 71490   | hydraulic leak on drop box                     | Closed, Completed      | Corrective           | May 14, 2023 12:38:38 PM |                          | May 14, 2023 12:43:00 PM |             |
| Task Description  |  | Asset                  | Assigned To          | Completed By             | Date Completed           | Est Hours                | Spent Hours |
| Inspect for leaks--lower yoke in drop box leaking--drop box was just rebuilt at mainsite<br>about 100 hours ago--will order new seal<br>June 2/23- Aaron C- Wajax   |  | Articulated Rock Truck | Trevor Bullock       | Trevor Bullock           |                          |                          | 1.00        |
| UNIT IS DOWN FOR A DROP BOX OIL LEAK. STILL DON'T HAVE A NEW SEAL FOR OTG<br>BUT DECIDED TO LOOK OVER UNIT WHILE IT WAS SITTING. CHECK ALL FLUIDS, CHECK<br>BELTS AND ENGINE COMPARTMENT FOR ISSUES. CHECK FOR ANY OTHER LEAKS.<br>GREASE MACHINE AND ENSURE ALL ZERKS TAKE GREASE. NO OTHER ISSUES FOUND<br>ON UNIT. SPEND SOME MORE TIME TIDYING UP AROUND SITE.<br>20 June 2023 - Aaron C -  |  | Articulated Rock Truck | Aaron Curtis - Wajax | Aaron Curtis - Wajax     | Jun 01, 2023 06:33:00 AM |                          | 3.50        |
| REMOVE YOKE AND SEAL HOUSING FROM DROPBOX. REMOVE AND REPLACE SEAL<br>AND O-RING ON THE SEAL HOUSING AND REPLACE THE SEAL ON THE DRIVELINE<br>YOKE. REINSTALL THE PLATE AND THE DRIVELINE YOKE. INSTALL RETAINING BOLT<br>AND TIGHTEN. REINSTALL THE DRIVELINE AND TIGHTEN BOLTS. DRIVE UNIT UP TO<br>THE LUBE SHACK AND TOP UP THE DROP BOX OIL LEVEL. TEST DRIVE UNIT AND<br>VERIFY NO LEAKS FROM THE SEAL.   |  | Articulated Rock Truck | Aaron Curtis - Wajax | Aaron Curtis - Wajax     | Jun 20, 2023 10:09:00 AM |                          | 4.00        |
|   |  |                        |                      |                          |                          |                          | 8.50        |
| Work  | Work Order Description                         | Status                 | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 71503   | Low Air Conditioning output                    | Closed, Completed      | Corrective           | May 14, 2023 02:40:01 PM |                          | May 15, 2023 04:47:00 PM |             |
| Task Description  |  | Asset                  | Assigned To          | Completed By             | Date Completed           | Est Hours                | Spent Hours |
| blower motor working fine--no airflow out of vents--inspect vent system etc.,noticed<br>outside vent hose missing and system sucking in outside dirt dust etc--removed<br>outside cover from heater core/ac system and condenser etc plugged solid with<br>dirt/mud preventing airflow<br>-use air gun to blow off mud dirt etc from condenser/heater core ....<br>-will finish job tomorrow--end of shift ,clean up work are<br>-finished cleaning out heater assembly and venting--put panels back on heater<br>system--run system to blow out excess dirt etc -lots of airflow now |  | Articulated Rock Truck | Trevor Bullock       | Trevor Bullock           |                          |                          | 6.00        |
|   |  |                        |                      |                          |                          |                          | 6.00        |

|  |  |                        |                             |                             |                             |                             |                    |
|--|--|------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|--------------------|
| 71699  | No Start--ECM communication issues   | Closed, Completed      | Corrective                  | May 18, 2023<br>04:36:26 PM | May 25, 2023<br>06:45:03 AM |                             |                    |
|  | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>          | <b>Completed By</b>         | <b>Date Completed</b>       | <b>Est Hours</b>            | <b>Spent Hours</b> |
| Thomas Ragan May 24  |  |                        |                             |                             |                             |                             |                    |
|  | Articulated Rock Truck   | Thomas Ragan           |                             |                             | May 24, 2023 06:45:00 AM    |                             | 3.00               |
| Went to unit. started unit. scan the unit. no ecm codes. started unit a few time with no problems and no codes. reinstalled all over and wire harness covers   |  |                        |                             |                             |                             |                             |                    |
|  |  |                        |                             |                             |                             |                             | 3.00               |
| Work   | <b>Work Order Description</b>  | <b>Status</b>          | <b>Type</b>                 | <b>Date Created</b>         | <b>Due Date</b>             | <b>Date Completed</b>       | <b>Days Late</b>   |
| 71834  | Replace Plate over box sensor please   | Closed, Completed      | Welding                     | May 21, 2023<br>06:44:36 AM |                             | May 30, 2023<br>07:09:00 AM |                    |
|  | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>          | <b>Completed By</b>         | <b>Date Completed</b>       | <b>Est Hours</b>            | <b>Spent Hours</b> |
|  | May 30 2023 - Tristan Dunn<br>assess box sensor and box is bowed down a bit but it is not affecting sensor or drivability of truck.  | Articulated Rock Truck | Tristan Dunn                | Tristan Dunn                | May 28, 2023 07:11:00 AM    |                             | 1.00               |
|  |  |                        |                             |                             |                             |                             | 1.00               |
| Work   | <b>Work Order Description</b>  | <b>Status</b>          | <b>Type</b>                 | <b>Date Created</b>         | <b>Due Date</b>             | <b>Date Completed</b>       | <b>Days Late</b>   |
| 72081  | Replace left hand radiator guard.  | Closed, Completed      |                             | May 25, 2023<br>09:11:40 AM |                             | May 25, 2023<br>01:10:18 PM |                    |
|  | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>          | <b>Completed By</b>         | <b>Date Completed</b>       | <b>Est Hours</b>            | <b>Spent Hours</b> |
|  | Thomas Ragan May 25  | Articulated Rock Truck | Thomas Ragan                | Thomas Ragan                |                             |                             | 3.00               |
| Removed the left side panel and removed the screen. found a panel on site. Took the mesh screen off the old panel. installed the mesh on the new panel and installed on the unit   |  |                        |                             |                             |                             |                             |                    |
|  |  |                        |                             |                             |                             |                             | 3.00               |
| Work   | <b>Work Order Description</b>  | <b>Status</b>          | <b>Type</b>                 | <b>Date Created</b>         | <b>Due Date</b>             | <b>Date Completed</b>       | <b>Days Late</b>   |
| 73013  | needs box plate above box sensor cut out and new plate welded on-- box is bent down hitting sensor--new plates are on site ready to install  | Closed, Completed      | Welding                     | Jun 09, 2023<br>10:28:27 AM |                             | Jul 29, 2023<br>06:17:46 AM |                    |
|  | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>          | <b>Completed By</b>         | <b>Date Completed</b>       | <b>Est Hours</b>            | <b>Spent Hours</b> |
|  | Hey Tristan can you fix this puppy up got to keep blowing the dust off it  | Articulated Rock Truck | Tristan Dunn                | Ian Knott                   | Jul 29, 2023 06:17:46 AM    |                             |                    |
|  |  |                        |                             |                             |                             |                             |                    |
| Work   | <b>Work Order Description</b>  | <b>Status</b>          | <b>Type</b>                 | <b>Date Created</b>         | <b>Due Date</b>             | <b>Date Completed</b>       | <b>Days Late</b>   |
| 73741  | ECM replacement  | Closed, Completed      | Corrective                  | Jun 22, 2023<br>06:55:07 AM |                             | Jun 28, 2023<br>03:08:56 PM |                    |
|  | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>          | <b>Completed By</b>         | <b>Date Completed</b>       | <b>Est Hours</b>            | <b>Spent Hours</b> |
|  | June 22/23 -Aaron C- Wajax   | Articulated Rock Truck | Aaron Curtis - Wajax        | Aaron Curtis - Wajax        | Jun 22, 2023 09:48:00 AM    |                             | 8.00               |
| OPERATOR HAD ISSUES WITH FUEL LEVEL GAUGE YESTERDAY, MENTIONED IT WAS NOT ACCURATE AND WOULD DROP TO ZERO THEN UP TO FULL. CLEAN ALL DEBRIS FROM THE TOP OF THE TANK AND SENDING UNIT AREA. INSPECT HARNESS AND SENDING UNIT. REMOVE PANEL TO UNPLUG SENDING UNIT AND VERIFY RESISTANCE WHILE WIGGLE TESTING WIRING. I TURNED THE KEY ON TO TRY SCANNING UNIT AND NOTICED THE ENGINE ECM WAS NOT ABLE TO COMMUNICATE AND THE ENGINE WOULD NOT START. CHECK FUSES IN THE CAB THEN CHECK THE ENGINE CIRCUIT BREAKER ON THE PANEL BY THE L/S ENGINE BAY. THEN PANEL OVER TOP AND REMOVE BRAKE PANEL ASSEMBLY TO INSPECT BACK SIDE. CHECK FOR POWER AT THE REAR OF THE BREAKER. BYPASS BREAKER AND CHECK ECM COMM. STILL NO COMM FROM ECM. CHECK POWER AT BULKHEAD INTO THE BREAKER PANEL. HAD 24 VOLTS. REMOVE SIDE PANEL AND REAR RAD ASSEMBLY PANEL TO ACCESS CAB PINS. REMOVE CAB PINS AND TILT THE CAB TO BETTER ACCESS THE WIRING HARNESS AND THE ENGINE ECM. CONTINUE TO INSPECT HARNESS ALONG THE FRAME. GO THROUGH WIRING DIAGRAM ON CAT SIS. WILL NEED TO CONTINUE TROUBLESHOOTING, HAD TO MOVE ONTO OTHER MACHINES. |  |                        |                             |                             |                             |                             |                    |
|  |  |                        |                             |                             |                             |                             |                    |
|  | 23 June 2023 - Aaron C .<br>CONTINUE TROUBLESHOOTING THE ENGINE ECM COMMUNICATION ISSUES. HOOK UP COMPUTER TO SEE IF ANYTHING CHANGED OVER NIGHT OR IF I WAS ABLE TO SCAN THE ENGINE ECM. NO CHANGE AND ECM IS STILL NOT COMMUNICATING WITH ANY OTHER ECMS. ECMS ARE SHOWING FAULT CODE FOR "ENGINE ECM ABNORMAL UPDATE RATE" READ THROUGH TROUBLESHOOTING STEPS. DROP THE FRONT BELLY PAN, REMOVE THE AIR FILTER HOUSING. REMOVE MULTIPLE BRACKETS AND HOSES FROM L/S OF ENGINE. REMOVE ENTIRE AIR FILTER HOUSING MOUNTING BRACKET. | Articulated Rock Truck | Aaron Debrun - AKD Services | Aaron Curtis - Wajax        | Jun 23, 2023 07:17:00 PM    |                             | 8.00               |

HAD TO REMOVE MULTIPLE CLAMPS AND ENGINE HARNESS MOUNTING BOLTS. REMOVE MULTIPLE TIES FROM HARNESS TO ACCESS ENGINE ECM. CLEAN UP AREA AS IS WAS FULL OF OIL, DIRT AND GREASE. ONCE I WAS FINALLY ABLE TO GET INTO THE ECM AREA, I REMOVE BOTH THE OEM AND ENGINE SIDE PLUGS FROM THE ECM TO INSPECT. PERFORM PIN DRAG TESTS ON THE CONNECTORS AND 10LB PULL TEST ON THE WIRES. INSPECT FOR ANY VISUAL ISSUES WITH CONNECTORS OR PINS. REINSTALL THE ENGINE SIDE CONNECTOR ON THE ECM AND LOOK UP THE PIN OUT FOR THE OEM SIDE. VOLTAGE AND LOAD TEST ALL POWERS AND GROUNDS INCLUDING THE CONSTANT AND KEY ON POWERS. TEST THE RESISTANCE IN THE J1939 CAN BUS WIRES AND HAD 60 OHMS. REMOVE AND CHECK ALL 4 TERMINATING RESISTORS FROM AROUND THE ECMS AND VERIFY 120 OHMS. CHECK ALL GROUND WIRES AT THE ECM, CHECK GROUND AT THE STARTER AND THE FRAME. CLEAN OUT MORE DEBRIS FROM AROUND THE ENGINE HARNESS TO INSPECT FOR ANY RUBBING OR VISUAL ISSUES WITH HARNESS PROTECTION. REMOVE MULTIPLE CANNON PLUGS TO VISUALLY INSPECT. I SUSPECT THE ENGINE ECM MIGHT HAVE FAILED. I NOTICED THAT JUST BEFORE THIS ISSUE STARTED TO ARISE, THERE WAS WELDING PERFORMED ON THE FRONT BUMPER OF THE UNIT.

|  |                        |                         |                         |                          |      |
|--|------------------------|-------------------------|-------------------------|--------------------------|------|
| 27 June 2023 - Aaron C -<br>INSTALL A COUPLE MORE PANELS AND PREP FOR FINNING TO SHOW UP AND FLASH ECM. INSTALL AIR CLEANER ASSEMBLY SO WE COULD RUN UNIT. ONCE ECM FLASH WAS COMPLETE I RAN UNIT FOR A WHILE TO ENSURE NO ISSUES. INSTALL AIR CLEANER BRACKET, TIE UP ECM WIRING, INSTALL ALL OTHER PANELS AND TIE UP HOSES. SET CAB BACK ONTO MOUNTS AND INSTALL PINS. REINSTALL THE AIR CLEANER ASSEMBLY AGAIN. REINSTALL BELLY PANS, ENSURE ALL COMPONENTS IN THE ENGINE BAY ARE COMPLETELY INSTALLED. RUN UNIT AGAIN FOR ABOUT 45 MINUTES TO ENSURE NO ISSUES | Articulated Rock Truck | Aaron Curtis - Wajax    | Aaron Curtis - Wajax    | Jun 27, 2023 03:08:00 PM | 6.00 |
| 27 June 2023 - Kris W -<br>"wajax troubleshoot failed engine ecm at west pine<br>travel to west pine<br>flash engine/aftertreatment/dcuv ecms<br>program engine ecm<br>program cooling fan solenoid<br>program f1s and fts<br>program injector trim files<br>sync hour meters<br>ensure machine operates correctly<br>travel back from west pine to prince george<br>finning and prhp time cards"  | Articulated Rock Truck | Kris Williams - Finning | Kris Williams - Finning | Jun 27, 2023 08:28:00 AM | 7.00 |

|       |   |                        |                      |                          |                          |                          |             |
|-------|---|------------------------|----------------------|--------------------------|--------------------------|--------------------------|-------------|
| Work  | Work Order Description  | Status                 | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 74097 | Replace missing RH cab spot light assembly.   | Closed, Completed      |                      | Jun 28, 2023 04:29:59 PM | Jun 30, 2023 07:21:13 AM | Jun 30, 2023 07:21:13 AM |             |
|       | Task Description  | Asset                  | Assigned To          | Completed By             | Date Completed           | Est Hours                | Spent Hours |
|       |   | Articulated Rock Truck | Aaron Curtis - Wajax | Nick Vanderkooi          | Jun 30, 2023 07:21:13 AM |                          |             |
| Work  | Work Order Description  | Status                 | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 74324 | Bad coolant leak!!  | Closed, Completed      |                      | Jul 03, 2023 03:58:23 PM | Jul 06, 2023 04:33:00 PM | Jul 06, 2023 04:33:00 PM |             |
|       | Task Description  | Asset                  | Assigned To          | Completed By             | Date Completed           | Est Hours                | Spent Hours |
|       | remove panels from side of radiator assembly--lift cab of truck--run truck to find broken coolant line--remove fire suspension lines from driveshaft that rapped around--will go to napa tomorrow to get coolant line--got coolant line from napa--installed line-filled coolant--checked for leaks--lowered cab back in place--installed all panels--ran machine to temp and cleaned work area--truck back to work | Articulated Rock Truck | Trevor Bullock       | Trevor Bullock           |                          |                          | 7.00        |
| Work  | Work Order Description  | Status                 | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 74725 | operator says truck is a safety issue because truck rides rough   | Closed, Completed      |                      | Jul 11, 2023 08:36:56 AM | Jul 11, 2023 08:45:00 AM | Jul 11, 2023 08:45:00 AM |             |
|       | Task Description  | Asset                  | Assigned To          | Completed By             | Date Completed           | Est Hours                | Spent Hours |
|       | took truck out of service<br>-check strut height-good<br>-checked rear suspension-good<br>-checked air in tires-all at 70 psi<br>-checked all bushings etc- small amount of play in rear a-frame bear for rear axle<br>-checked all brake wear<br>-checked box bushing tc   | Articulated Rock Truck | Trevor Bullock       | Trevor Bullock           | Jul 11, 2023 08:45:00 AM |                          | 4.00        |

-installed shims in box support pads so box sits better  
 -greased all fittings on truck  
 -with help of driller checked all driveline etc for play-all good  
 --could not find any serious issues with this truck

| Work  | Work Order Description   | Status   | Type                 | Date Created                | Due Date                 | Date Completed              | Days Late   |
|-------|--|--|----------------------|-----------------------------|--------------------------|-----------------------------|-------------|
| 74857 | steps broken   | Closed, Completed                                | Corrective           | Jul 13, 2023<br>08:31:53 AM |                          | Jul 27, 2023<br>02:00:00 PM | 4.00        |
|       | <b>Task Description</b>  | <b>Asset</b>                                     | <b>Assigned To</b>   | <b>Completed By</b>         | <b>Date Completed</b>    |                             |             |
|       | inspected unit found all steps to be in operational state  | Articulated Rock Truck                           | Jon Strasdin - Wajax | Jon Strasdin - Wajax        |                          |                             |             |
|       |  |  |                      |                             |                          | Est Hours                   | Spent Hours |
|       |  |  |                      |                             |                          | 1.00                        | 1.00        |
|       |  |  |                      |                             |                          | 1.00                        | 1.00        |
| Work  | Work Order Description   | Status   | Type                 | Date Created                | Due Date                 | Date Completed              | Days Late   |
| 74954 | Bolt fell out that holds the red Box Lock Pin in place.  | Closed, Completed                                |                      | Jul 15, 2023<br>06:55:43 AM |                          | Jul 15, 2023<br>08:43:00 AM |             |
|       | <b>Task Description</b>  | <b>Asset</b>                                     | <b>Assigned To</b>   | <b>Completed By</b>         | <b>Date Completed</b>    |                             |             |
|       | pin secured with strap   | Articulated Rock Truck                           | Trevor Bullock       | Trevor Bullock              |                          |                             |             |
|       |  |  |                      |                             |                          | Est Hours                   | Spent Hours |
|       |  |  |                      |                             |                          | 1.00                        | 1.00        |
| Work  | Work Order Description   | Status   | Type                 | Date Created                | Due Date                 | Date Completed              | Days Late   |
| 75229 | Air intake sensor code   | Closed, Completed                                | Corrective           | Jul 20, 2023<br>04:55:59 PM |                          | Jul 21, 2023<br>05:50:03 AM |             |
|       | <b>Task Description</b>  | <b>Asset</b>                                     | <b>Assigned To</b>   | <b>Completed By</b>         | <b>Date Completed</b>    |                             |             |
|       | July 20/23<br>Checked air filters<br>and air to air connections<br>Went on s/s to read up on issue<br>Code coming up intermittently so will dig into sensor wiring tomorrow  | Articulated Rock Truck<br>Articulated Rock Truck |                      |                             |                          |                             | 8.00        |
|       | Spent lots a time cleaning and organizing c can for parts  |  |                      |                             |                          |                             |             |
|       |  |  |                      |                             |                          |                             | 8.00        |
| Work  | Work Order Description   | Status   | Type                 | Date Created                | Due Date                 | Date Completed              | Days Late   |
| 75273 | differential breather valve  | Closed, Completed                                | Corrective           | Jul 21, 2023<br>04:28:15 PM |                          | Jul 29, 2023<br>10:21:09 AM |             |
|       | <b>Task Description</b>  | <b>Asset</b>                                     | <b>Assigned To</b>   | <b>Completed By</b>         | <b>Date Completed</b>    |                             |             |
|       | **Dropbox oil level corrected, sent relief 6U1989 down. **   | Articulated Rock Truck                           | Hayden Balsiger      | Jul 29, 2023 10:21:09 AM    |                          |                             |             |
|       |  |  |                      |                             |                          | Est Hours                   | Spent Hours |
|       |  |  |                      |                             |                          |                             |             |
| Work  | Work Order Description   | Status   | Type                 | Date Created                | Due Date                 | Date Completed              | Days Late   |
| 75424 | Cooling package loose  | Closed, Completed                                | Corrective           | Jul 25, 2023<br>07:58:00 AM |                          | Jul 24, 2023<br>08:00:00 AM |             |
|       | <b>Task Description</b>  | <b>Asset</b>                                     | <b>Assigned To</b>   | <b>Completed By</b>         | <b>Date Completed</b>    |                             |             |
|       | OPERATOR NOTICED THAT THE ENTIRE COOLING PACKAGE BEHIND THE CAB WAS MOVING AROUND QUITE A BIT AND MAKING NOISE. INSPECT COOLING PACKAGE AND FOUND THE CROSS BRACE SUPPORT WAS VERY LOOSE, MULTIPLE PANLES WERE LOOSE AND BROKEN. THE LOWER MOUNTING BOLTS WERE LOOSE AS WELL. REMOVE SIDE PANEL ON L/S AND TIGHTEN UP THE LOOSE CROSS BRACE. TIGHTEN UP THE LOWER MOUNTING BOLTS. I NOTICED THE REAR L/S CAB PIN WAS ALSO COMING OUT OF ITS BORE. HAMMER PIN BACK INTO PLACE, REINSTALL PANELS AND SECURE WITH MOUNTING BOLTS. USE ZIP TIES TO SECURE BROKEN SECTIONS OF PANEL TOGETHER. CHECK FOR ANY OTHER ISSUES WITH UNIT WHILE I HAD TIME, NO VISUAL ISSUES FOUND. CHECK OIL LEVELS AND SEND UNIT BACK TO WORK. WRITE UP A CROSSOVER NOTE FOR THE MECHANIC COMING ONTO SITE TOMORROW. CLEAN UP AND GET READY TO DRIVE BACK TO FSJ. TRAVEL FROM WEST PINE TO FSJ WAJAX SHOP. | Articulated Rock Truck                           | Aaron Curtis - Wajax | Aaron Curtis - Wajax        | Jul 24, 2023 08:00:00 AM |                             | 8.00        |
|       |  |  |                      |                             |                          |                             |             |
| Work  | Work Order Description   | Status   | Type                 | Date Created                | Due Date                 | Date Completed              | Days Late   |
| 76198 | Air intake temperature sensor  | Closed, Completed                                |                      | Aug 08, 2023<br>11:03:25 AM |                          | Aug 09, 2023<br>11:46:00 AM |             |
|       | <b>Task Description</b>  | <b>Asset</b>                                     | <b>Assigned To</b>   | <b>Completed By</b>         | <b>Date Completed</b>    |                             |             |
|       | t/s code..check sensor-sensor needs replacing--ordered from warehouse<br>-got sensor-changed sensor-code gone  | Articulated Rock Truck                           | Trevor Bullock       | Trevor Bullock              |                          |                             |             |
|       |  |  |                      |                             |                          | Est Hours                   | Spent Hours |
|       |  |  |                      |                             |                          | 2.00                        | 2.00        |

| Work  | Work Order Description                             | Status                    | Type  | Date Created                | Due Date  | Date Completed              | Days Late |
|---|--|---------------------------|---|-----------------------------|-----------|-----------------------------|-----------|
| 76202   | Fuel sensor needs to be replaced.                  | Closed, Completed         |   | Aug 08, 2023<br>11:12:04 AM |           | Aug 08, 2023<br>11:47:00 AM |           |
| Task Description  | Asset  | Assigned To               | Completed By                                | Date Completed              | Est Hours | Spent Hours                 |           |
| fuel sensor ordered<br>replace fuel sensor  | Articulated Rock Truck<br>Articulated Rock Truck   | Trevor Bullock            | Trevor Bullock<br>Dane Middlemiss - Wajax - | Aug 26, 2023 08:05:00 AM    |           | 1.00<br>1.00                |           |
|   |  |                           |   |                             |           | 2.00                        |           |
| Work  | Work Order Description                             | Status                    | Type  | Date Created                | Due Date  | Date Completed              | Days Late |
| 76613   | Def pump and hydraulic codes.                      | Closed, Completed         | Corrective                                  | Aug 17, 2023<br>07:52:13 AM |           | Aug 17, 2023<br>09:38:00 AM |           |
| Task Description  | Asset  | Assigned To               | Completed By                                | Date Completed              | Est Hours | Spent Hours                 |           |
| SCAN UNIT FOR FAULT CODES. FAULT CODES ACTIVE FOR SCR SYSTEM DEF LOSS OF PRIME. INSPECT FOR ANY DEF LEAKS AT THE PUMP OR DEF HEADER. VERIFY COOLANT LEVEL. TRIED TO RUN A DEF SYSTEM VERIFICATION TEST SEE IF THE PUMP WOULD PRIME. WASN'T ABLE TO RUN TEST SO I TRIED AN AFTERTREATMENT VERIFICATION TEST. RUN TEST AND SEND AIR PRESSURE INTO DEF TANK TO ASSIST THE DEF PUMP WITH PRIMING. PUMP SEEMED TO PRIME AND THEN DROP BACK OFF AGAIN. PUMP WOULDNT HOLD PRESSURE. PULL THE DEF FILTER FROM THE PUMP HOUSING AND INSPECT. DIDNT FIND ANYTHING CONCERNING INSIDE THE FILTER. I THEN NOTICED THE DEF CONTROL MODULE WAS NOT COMMUNICATING WITH THE OTHER ECMS IN THE SYSTEM. DO A QUICK WIRING CHECK TO MAKE SURE THERE WASNT ANY LOOSE CONNECTIONS. CHECK THE CONNECTION AT THE DEF PUMP TO ENSURE DEF HADNT MADE ITS WAY INTO THE HARNESS. DECIDED TO REMOVE AND REPLACE THE DEF PUMP AS WE HAD ONE IN STOCK. REMOVE ALL LINES, BRACKETS AND HARNESS FROM THE DEF PUMP. REMOVE PUMP CAGE AND PUMP, INSTALL NEW PUMP AND ALL LINES AND BRACKETS. TIE UP WIRING HARNESS AND PRIME THE PUMP. RUN AN AFTERTREATMENT SYSTEM VERIFICATION TO ENSURE SYSTEM IS WORKING PROPERLY. CODES WENT INACTIVE ONCE THE PUMP HAD PRIMED. | Articulated Rock Truck                             | Aaron Curtis - Wajax      | Aaron Curtis - Wajax                        |                             |           | 6.00                        |           |
|   |  |                           |   |                             |           |                             |           |
| Work  | Work Order Description                             | Status                    | Type  | Date Created                | Due Date  | Date Completed              | Days Late |
| 76788   | Trouble shoot electrical issue with back up alarm. | Closed, Completed         | Corrective                                  | Aug 20, 2023<br>04:01:35 PM |           | Aug 20, 2023<br>05:39:00 AM |           |
| Task Description  | Asset  | Assigned To               | Completed By                                | Date Completed              | Est Hours | Spent Hours                 |           |
| DRIVE CAME UP TO ME EARLIER IN THE DAY WITH THE BACK UP ALARM AND LIGHTS STUCK ON. I WAS IN THE MIDDLE OF SOME THING SO I JUST PULLED THE FUSE AND LET TRUCK BACK TO WORK. LATER ON I WAS ABLE TO LOOK INTO ISSUE. I REINSTALLED THE FUSE AND THE BACK UP ALARM SEEMED TO BE WORKING FINE. BEFORE I WAS STUCK ON IN ALL RANGES AND EVEN IN NEUTRAL WITH THE KEY OFF. I TOOK UNIT FOR A TEST DRIVE TO SEE IF I COULD REPLICATE ISSUES, WIGGLE TEST WIRING AND CHECK FOR ANY STUCK RELAYS OR OBVIOUS ISSUES WITH THE HARNESS. BOTH REVERSE LIGHTS AND THE ALARM ARE WORKING PROPERLY. WILL TROUBLESHOOT FURTHER IF THE PROBLEM RETURNS. CLEAN UP TRUCK AND SEA CAN, TIDY YARD AREAS.  | Articulated Rock Truck                             | Aaron Curtis - Wajax      | Aaron Curtis - Wajax                        |                             |           | 3.00                        |           |
|   |  |                           |   |                             |           |                             |           |
| Work  | Work Order Description                             | Status                    | Type  | Date Created                | Due Date  | Date Completed              | Days Late |
| 76973   | Noise on brakes                                    | Closed, Completed         |   | Aug 24, 2023<br>04:24:25 PM |           | Aug 23, 2023<br>05:00:00 PM |           |
| Task Description  | Asset  | Assigned To               | Completed By                                | Date Completed              | Est Hours | Spent Hours                 |           |
| inspected brakes for noise when pedal was depressed, checked pressures sounds like relief going over.   | Articulated Rock Truck                             | Dane Middlemiss - Wajax - | Tristan Dunn                                | Aug 23, 2023 05:00:00 PM    |           | 2.00                        |           |
|   |  |                           |   |                             |           | 2.00                        |           |
| Work  | Work Order Description                             | Status                    | Type  | Date Created                | Due Date  | Date Completed              | Days Late |
| 77443   | BACK UP ALARM ISSUES                               | Closed, Completed         | Corrective                                  | Sep 04, 2023<br>05:42:08 PM |           | Sep 06, 2023<br>06:21:00 AM |           |
| Task Description  | Asset  | Assigned To               | Completed By                                | Date Completed              | Est Hours | Spent Hours                 |           |
| t/s back up alarm staying on<br>-go threw wiring diagram and check wiring to make sure not getting power from chaffed wire etc--issue with gear shifter in cab leaving signal on for power to back up alarm and back up lights --shifter will need to be replaced   | Articulated Rock Truck                             | Trevor Bullock            | Trevor Bullock                              |                             |           | 3.00                        |           |

-will request new part threw justin and hayden

| Work  | Work Order Description   | Status                 | Type                      | Date Created                | Due Date                 | Date Completed              | Days Late |
|-------|--|------------------------|---------------------------|-----------------------------|--------------------------|-----------------------------|-----------|
| 77529 | Tighten LH convex mirror.  | Closed, Completed      |                           | Sep 06, 2023<br>01:58:00 PM |                          | Sep 06, 2023<br>04:44:00 PM |           |
|       | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>        | <b>Completed By</b>         | <b>Date Completed</b>    |                             |           |
|       | tight mirror   | Articulated Rock Truck | Trevor Bullock            | Trevor Bullock              |                          |                             |           |
|       |  |                        |                           |                             |                          |                             | 1.00      |
|       |  |                        |                           |                             |                          |                             | 1.00      |
| Work  | Work Order Description   | Status                 | Type                      | Date Created                | Due Date                 | Date Completed              | Days Late |
| 77645 | Hydraulic leak   | Closed, Completed      |                           | Sep 08, 2023<br>02:03:00 PM |                          | Sep 10, 2023<br>06:29:28 AM |           |
|       | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>        | <b>Completed By</b>         | <b>Date Completed</b>    |                             |           |
|       |  | Articulated Rock Truck | Trevor Bullock            | Trevor Bullock              | Sep 10, 2023 06:29:28 AM |                             |           |
|       |  |                        |                           |                             |                          |                             |           |
| Work  | Work Order Description   | Status                 | Type                      | Date Created                | Due Date                 | Date Completed              | Days Late |
| 77688 | Air intake Temp Sensor Code E764(1)  | Closed, Completed      |                           | Sep 09, 2023<br>01:58:37 PM |                          | Sep 10, 2023<br>03:38:00 PM |           |
|       | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>        | <b>Completed By</b>         | <b>Date Completed</b>    |                             |           |
|       | went to machine and code was gone--checked wiring and do wiggle test on wires but code did not come back | Articulated Rock Truck | Trevor Bullock            | Trevor Bullock              |                          |                             |           |
|       |  |                        |                           |                             |                          |                             | 1.00      |
|       |  |                        |                           |                             |                          |                             | 1.00      |
| Work  | Work Order Description   | Status                 | Type                      | Date Created                | Due Date                 | Date Completed              | Days Late |
| 77749 | requires service   | Closed, Completed      |                           | Sep 10, 2023<br>03:31:49 PM |                          | Sep 10, 2023<br>03:40:00 PM |           |
|       | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>        | <b>Completed By</b>         | <b>Date Completed</b>    |                             |           |
|       | changed oil filters,engine oil,fuel filters,air filters,cab filters                                      | Articulated Rock Truck | Trevor Bullock            | Trevor Bullock              |                          |                             |           |
|       |  |                        |                           |                             |                          |                             | 2.00      |
|       |  |                        |                           |                             |                          |                             | 2.00      |
| Work  | Work Order Description   | Status                 | Type                      | Date Created                | Due Date                 | Date Completed              | Days Late |
| 78686 | box cracked around headache rack-needs welding** Duplicate.  | Closed, Completed      | Welding                   | Oct 01, 2023<br>08:17:02 AM |                          | Oct 15, 2023<br>05:43:04 PM |           |
|       | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>        | <b>Completed By</b>         | <b>Date Completed</b>    |                             |           |
|       |  | Articulated Rock Truck | Nick Vanderkooi           | Nick Vanderkooi             | Oct 15, 2023 05:43:04 PM |                             |           |
|       |  |                        |                           |                             |                          |                             |           |
| Work  | Work Order Description   | Status                 | Type                      | Date Created                | Due Date                 | Date Completed              | Days Late |
| 78905 | hydraulic leak   | Closed, Completed      |                           | Oct 06, 2023<br>10:04:34 AM |                          | Oct 06, 2023<br>10:11:00 AM |           |
|       | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>        | <b>Completed By</b>         | <b>Date Completed</b>    |                             |           |
|       | brake and transmission filter leaking--change filter   | Articulated Rock Truck | Trevor Bullock            | Trevor Bullock              |                          |                             |           |
|       |  |                        |                           |                             |                          |                             | 1.00      |
|       |  |                        |                           |                             |                          |                             | 1.00      |
| Work  | Work Order Description   | Status                 | Type                      | Date Created                | Due Date                 | Date Completed              | Days Late |
| 79251 | "HEADACHE RACK" CRACKED. NEEDS REWELD.   | Closed, Completed      |                           | Oct 15, 2023<br>06:56:18 AM |                          | Oct 18, 2023<br>12:18:00 PM |           |
|       | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>        | <b>Completed By</b>         | <b>Date Completed</b>    |                             |           |
|       | grind out and weld up crack  | Articulated Rock Truck | Tristan Dunn              | Tristan Dunn                | Oct 18, 2023 12:18:00 PM |                             |           |
|       |  |                        |                           |                             |                          |                             |           |
| Work  | Work Order Description   | Status                 | Type                      | Date Created                | Due Date                 | Date Completed              | Days Late |
| 79253 | RH TOP SPOT LIGHT MISSING  | Closed, Completed      | Corrective                | Oct 15, 2023<br>06:59:10 AM |                          | Oct 23, 2023<br>06:27:23 AM |           |
|       | <b>Task Description</b>  | <b>Asset</b>           | <b>Assigned To</b>        | <b>Completed By</b>         | <b>Date Completed</b>    |                             |           |
|       | replaced light for one in seacan   | Articulated Rock Truck | Dane Middlemiss - Wajax - | Dane Middlemiss - Wajax -   |                          |                             |           |
|       |  |                        |                           |                             |                          |                             | 2.00      |
|       |  |                        |                           |                             |                          |                             | 2.00      |
| Work  | Work Order Description   | Status                 | Type                      | Date Created                | Due Date                 | Date Completed              | Days Late |
| 79537 | Drop box leaking oil from breather   | Closed, Completed      | Corrective                | Oct 21, 2023<br>03:36:28 PM |                          | Oct 20, 2023<br>03:37:00 PM |           |

| Task Description             |  | Asset                  | Assigned To               | Completed By              | Date Completed           | Est Hours      | Spent Hours |
|------------------------------|--|------------------------|---------------------------|---------------------------|--------------------------|----------------|-------------|
| Drained oil to correct level |  | Articulated Rock Truck | Dane Middlemiss - Wajax - | Dane Middlemiss - Wajax - | Oct 20, 2023 03:37:00 PM |                | 1.50        |
|                              |  |                        |                           |                           |                          |                | 1.50        |
| Work 79777                   | Work Order Description<br>interior light burnt out   | Status                 | Type                      | Date Created              | Due Date                 | Date Completed | Days Late   |
|                              |  | Closed, Incomplete     |                           | Oct 26, 2023              | 04:52:04 PM              | Oct 28, 2023   |             |
|                              |  |                        |                           |                           |                          | 08:36:25 AM    |             |
| Task Description             |  | Asset                  | Assigned To               | Completed By              | Date Completed           | Est Hours      | Spent Hours |
|                              |  | Articulated Rock Truck | Trevor Bullock            |                           | Oct 28, 2023 08:36:25 AM |                |             |
| Work 80327                   | Work Order Description<br>Top spot lights not working. Left hand berm light not working. Tail light out. Grease line rubbing on yoke dust cover, leaking grease. | Status                 | Type                      | Date Created              | Due Date                 | Date Completed | Days Late   |
|                              |  | Closed, Completed      | Corrective                | Nov 12, 2023              | 04:03:20 AM              | Nov 25, 2023   |             |
|                              |  |                        |                           |                           |                          | 03:44:00 PM    |             |
| Task Description             |  | Asset                  | Assigned To               | Completed By              | Date Completed           | Est Hours      | Spent Hours |
|                              | berm lights fixed,rear tail lights replaced  | Articulated Rock Truck | Trevor Bullock            | Trevor Bullock            |                          |                | 2.00        |
|                              |  |                        |                           |                           |                          |                | 2.00        |
| Work 80394                   | Work Order Description<br>Tail light out **duplicate**   | Status                 | Type                      | Date Created              | Due Date                 | Date Completed | Days Late   |
|                              |  | Closed, Completed      | Corrective                | Nov 14, 2023              | 04:01:51 AM              | Nov 22, 2023   |             |
|                              |  |                        |                           |                           |                          | 01:55:26 AM    |             |
| Task Description             |  | Asset                  | Assigned To               | Completed By              | Date Completed           | Est Hours      | Spent Hours |
|                              |  | Articulated Rock Truck | Nick Vanderkooi           |                           | Nov 22, 2023 01:55:26 AM |                |             |
| Work 80544                   | Work Order Description<br>Broken back light **triplicate***  | Status                 | Type                      | Date Created              | Due Date                 | Date Completed | Days Late   |
|                              |  | Closed, Completed      | Corrective                | Nov 18, 2023              | 04:38:42 AM              | Nov 22, 2023   |             |
|                              |  |                        |                           |                           |                          | 01:56:03 AM    |             |
| Task Description             |  | Asset                  | Assigned To               | Completed By              | Date Completed           | Est Hours      | Spent Hours |
|                              |  | Articulated Rock Truck | Nick Vanderkooi           |                           | Nov 22, 2023 01:56:03 AM |                |             |
| Work 80771                   | Work Order Description<br>Hydraulic hose weep.   | Status                 | Type                      | Date Created              | Due Date                 | Date Completed | Days Late   |
|                              |  | Closed, Completed      |                           | Nov 25, 2023              | 06:13:31 AM              | Nov 25, 2023   |             |
|                              |  |                        |                           |                           |                          | 03:37:31 PM    |             |
| Task Description             |  | Asset                  | Assigned To               | Completed By              | Date Completed           | Est Hours      | Spent Hours |
|                              | remove leaking hose-drive chetwynd get new hose made--install new hose   | Articulated Rock Truck | Trevor Bullock            | Trevor Bullock            | Nov 25, 2023 03:37:31 PM |                | 3.00        |
|                              |  |                        |                           |                           |                          |                | 3.00        |
| Work 80913                   | Work Order Description<br>hydraulic leak--waiting on hose  | Status                 | Type                      | Date Created              | Due Date                 | Date Completed | Days Late   |
|                              |  | Closed, Completed      | Corrective                | Nov 30, 2023              | 06:45:17 AM              | Dec 04, 2023   |             |
|                              |  |                        |                           |                           |                          | 06:00:00 AM    |             |
| Task Description             |  | Asset                  | Assigned To               | Completed By              | Date Completed           | Est Hours      | Spent Hours |
|                              | ordered hose   | Articulated Rock Truck | Trevor Bullock            | Trevor Bullock            |                          |                | 1.00        |
|                              |  |                        |                           |                           |                          |                | 1.00        |
|                              | -leave has slowed down to a minimal weep--hose is on site incase hose blows  |                        |                           |                           |                          |                |             |
| Work 81151                   | Work Order Description<br>Emissions code   | Status                 | Type                      | Date Created              | Due Date                 | Date Completed | Days Late   |
|                              |  | Closed, Completed      |                           | Dec 07, 2023              | 01:07:31 PM              | Dec 08, 2023   |             |
|                              |  |                        |                           |                           |                          | 05:38:00 AM    |             |
| Task Description             |  | Asset                  | Assigned To               | Completed By              | Date Completed           | Est Hours      | Spent Hours |
|                              | code for conversion efficiency--checked filters etc--all good -needs set of NOx sensors  | Articulated Rock Truck | Trevor Bullock            | Trevor Bullock            |                          |                | 3.00        |
|                              | Articulated Rock Truck   |                        |                           |                           |                          |                | 3.00        |
|                              | -installed new set of sensors and performed function test--passed and sent it back to work   |                        |                           |                           |                          |                |             |
| Work 81614                   | Work Order Description<br>antifreeze leak  | Status                 | Type                      | Date Created              | Due Date                 | Date Completed | Days Late   |
|                              |  | Closed, Completed      |                           | Jan 13, 2024              | 11:34:58 AM              | Jan 14, 2024   |             |
|                              |  |                        |                           |                           |                          | 06:00:00 AM    |             |
| Task Description             |  | Asset                  | Assigned To               | Completed By              | Date Completed           | Est Hours      | Spent Hours |
|                              | cold leak--fill truck with antifreeze and run truck  | Articulated Rock Truck | Trevor Bullock            | Trevor Bullock            |                          |                | 2.00        |
|                              |  |                        |                           |                           |                          |                | 2.00        |

| Work  | Work Order Description                              | Status                            | Type                              | Date Created                | Due Date                    | Date Completed              | Days Late |
|---|---|-----------------------------------|-----------------------------------|-----------------------------|-----------------------------|-----------------------------|-----------|
| 81741   | A frame bearing gone--waiting on word for new parts | Closed, Completed                 |                                   | Jan 24, 2024<br>04:03:51 PM |                             | Jan 23, 2024<br>06:43:00 AM |           |
| Task Description  | Asset   | Assigned To                       | Completed By                      | Date Completed              | Est Hours                   | Spent Hours                 |           |
| Tested A-frame, very loose. Removed cover to see if bolts were just loose, negative. Looked up parts and ordered as no stock at WH  | Articulated Rock Truck<br>Articulated Rock Truck    | Trevor Bullock<br>Hayden Balsiger | Trevor Bullock<br>Hayden Balsiger | Feb 01, 2024 07:41:00 AM    |                             | 1.00<br>2.00                |           |
|   |   |                                   |                                   |                             |                             | 3.00                        |           |
| Work Order Description  | Status  | Type                              | Date Created                      | Due Date                    | Date Completed              | Days Late                   |           |
| 81882   | Degreasing  | Closed, Completed                 | Preventive - Planned              | Feb 07, 2024<br>05:03:42 AM | Feb 08, 2024<br>05:03:42 AM | Feb 08, 2024<br>06:27:19 AM | 0         |
| Task Description  | Asset   | Assigned To                       | Completed By                      | Date Completed              | Est Hours                   | Spent Hours                 |           |
| Degreassing   | Articulated Rock Truck<br>Articulated Rock Truck    | PMtech                            |                                   |                             |                             |                             |           |
| Work Order Description  | Status  | Type                              | Date Created                      | Due Date                    | Date Completed              | Days Late                   |           |
| 82101   | Degreasing  | Closed, Completed                 | Preventive - Planned              | Feb 29, 2024<br>05:03:17 AM | Mar 01, 2024<br>05:03:17 AM | Feb 29, 2024<br>07:45:53 AM | 0         |
| Task Description  | Asset   | Assigned To                       | Completed By                      | Date Completed              | Est Hours                   | Spent Hours                 |           |
| Degreassing   | Articulated Rock Truck<br>Articulated Rock Truck    | PMtech                            |                                   |                             |                             |                             |           |
| Work Order Description  | Status  | Type                              | Date Created                      | Due Date                    | Date Completed              | Days Late                   |           |
| 82487   | Coolant leak  | Closed, Completed                 | Corrective                        | Apr 09, 2024<br>11:03:34 AM |                             | Apr 09, 2024<br>03:35:00 PM |           |
| Task Description  | Asset   | Assigned To                       | Completed By                      | Date Completed              | Est Hours                   | Spent Hours                 |           |
| blown hose from water pump to cooler<br>-repairs complete-truck in service  | Articulated Rock Truck                              | Trevor Bullock                    | Trevor Bullock                    |                             | 4.00                        |                             |           |
|   |   |                                   |                                   |                             | 4.00                        |                             |           |
| Work Order Description  | Status  | Type                              | Date Created                      | Due Date                    | Date Completed              | Days Late                   |           |
| 82635   | AC needs inspection/ recharge                       | Closed, Completed                 | Corrective                        | Apr 23, 2024<br>06:15:40 PM |                             | May 14, 2024<br>12:21:00 PM |           |
| Task Description  | Asset   | Assigned To                       | Completed By                      | Date Completed              | Est Hours                   | Spent Hours                 |           |
| ran truck-turned off heater core valves and checked AC temp with meter<br>-AC as low as 0 degrees C<br>-no issues with ac operators just need to give the AC system time to cool down             | Articulated Rock Truck                              | Trevor Bullock                    | Trevor Bullock                    |                             | 3.00                        |                             |           |
|   |   |                                   |                                   |                             | 3.00                        |                             |           |
| Work Order Description  | Status  | Type                              | Date Created                      | Due Date                    | Date Completed              | Days Late                   |           |
| 82672   | torque arm bushings worn                            | Closed, Completed                 |                                   | Apr 28, 2024<br>02:11:39 PM |                             | May 11, 2024<br>07:52:00 AM |           |
| Task Description  | Asset   | Assigned To                       | Completed By                      | Date Completed              | Est Hours                   | Spent Hours                 |           |
| not worn out  | Articulated Rock Truck                              | Trevor Bullock                    | Trevor Bullock                    |                             | 1.00                        |                             |           |
|   |   |                                   |                                   |                             | 1.00                        |                             |           |
| Work Order Description  | Status  | Type                              | Date Created                      | Due Date                    | Date Completed              | Days Late                   |           |
| 82699   | Degreasing  | Closed, Completed                 | Preventive - Planned              | May 02, 2024<br>05:03:54 AM | May 03, 2024<br>05:03:54 AM | May 02, 2024<br>06:13:41 AM | 0         |
| Task Description  | Asset   | Assigned To                       | Completed By                      | Date Completed              | Est Hours                   | Spent Hours                 |           |
| Degreassing   | Articulated Rock Truck<br>Articulated Rock Truck    | PMtech                            |                                   |                             |                             |                             |           |
| Work Order Description  | Status  | Type                              | Date Created                      | Due Date                    | Date Completed              | Days Late                   |           |
| 82742   | Pin missing rear cab mount left side                | Closed, Completed                 |                                   | May 05, 2024<br>03:59:37 PM |                             | May 05, 2024<br>05:51:00 AM |           |
| Task Description  | Asset   | Assigned To                       | Completed By                      | Date Completed              | Est Hours                   | Spent Hours                 |           |
| Driver complained of bucking, checked a-frames etc, went for road test. Feels like cab Articulated Rock Truck is rocking forward. FOund missing cab pin. Removed pin from down unit and installed | Articulated Rock Truck                              | Hayden Balsiger                   |                                   |                             | 1.50                        |                             |           |

in bore, resecured guards

1.50

| Work   | Work Order Description                                  | Status            | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
|--|---|-------------------|----------------------|--------------------------|--------------------------|--------------------------|-------------|
| 82887  | Degreasing  | Closed, Completed | Preventive - Planned | May 23, 2024 05:04:32 AM | May 24, 2024 05:04:32 AM | May 23, 2024 06:25:48 AM | 0           |
| Task Description   | Asset   | Assigned To       | Completed By         | Date Completed           |                          | Est Hours                | Spent Hours |
| Degreasing   | Articulated Rock Truck<br>Articulated Rock Truck        | PMtech            |                      |                          |                          |                          |             |
| Work   | Work Order Description                                  | Status            | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 83048  | Tail light assembly bent                                | Closed, Completed | Corrective           | Jun 09, 2024 08:26:24 AM |                          | Jun 13, 2024 02:50:00 PM |             |
| Task Description   | Asset   | Assigned To       | Completed By         | Date Completed           |                          | Est Hours                | Spent Hours |
| use torch to heat and bend brackets back in place  | Articulated Rock Truck                                  | Trevor Bullock    | Trevor Bullock       |                          |                          |                          | 2.00        |
|  |   |                   |                      |                          |                          |                          | 2.00        |
| Work   | Work Order Description                                  | Status            | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 83233  | Headlight out passenger side                            | Closed, Completed |                      | Jun 24, 2024 07:06:39 AM |                          | Jun 26, 2024 05:54:09 AM |             |
| Task Description   | Asset   | Assigned To       | Completed By         | Date Completed           |                          | Est Hours                | Spent Hours |
|  | Articulated Rock Truck                                  |                   | Hayden Baisiger      | Jun 26, 2024 05:54:09 AM |                          |                          |             |
| Work   | Work Order Description                                  | Status            | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 83438  | Leaking brakes--JOB COMPLETED-TRUCK ON HOLD FOR AUCTION | On Hold           | Corrective           | Jul 11, 2024 12:58:33 PM |                          | Aug 05, 2024 02:50:00 PM |             |
| Task Description   | Asset   | Assigned To       | Completed By         | Date Completed           |                          | Est Hours                | Spent Hours |
| truck has worn brake pads down so far that brake metal disk has fallen out of brake caliper and the brake caliper plungers have blew out of the caliper causing brake failure!!  | Articulated Rock Truck                                  | Trevor Bullock    | Trevor Bullock       |                          |                          |                          | 36.00       |
| trucks are being pushed over their limits when hauling off the mountain<br>-will have to cap brake supply line to that tire to get truck off the mountain<br>-brake inspection done and parts list completed and forwarded to justin |   |                   |                      |                          |                          |                          |             |
| --set of brake pads out on pallet beside green sea can--2 calipers in green sea can-one rebuilt and second needs rebuild when seals show up  |   |                   |                      |                          |                          |                          |             |
| --remove all tires-remove all calipers-rebuild 2 calipers--disassemble all hub assemblies and install new brake rotors/disk--reinstall hubs and calipers--install tires  |   |                   |                      |                          |                          |                          |             |
| --one hub needs bearings replaced if truck is going to be used again for operation<br>--will talk to justin to see what he wants to do   |   |                   |                      |                          |                          |                          |             |
| -put final drive back together the way it is--install on truck--put tire back on<br>-turned truck over to dallas to fill all axles and final drives on machine!!!  |   |                   |                      |                          |                          |                          |             |
| --truck is being held on hold and not to be used because of bad bearing in left side center axle drive hub and is being held to go to auction.....   |   |                   |                      |                          |                          |                          |             |
|  |   |                   |                      |                          |                          |                          | 36.00       |
| Work   | Work Order Description                                  | Status            | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 83559  | Degreasing  | Closed, Completed | Preventive - Planned | Jul 25, 2024 05:05:04 AM | Jul 26, 2024 05:05:04 AM | Jul 28, 2024 06:18:56 AM | 2           |
| Task Description   | Asset   | Assigned To       | Completed By         | Date Completed           |                          | Est Hours                | Spent Hours |
| Degreasing   | Articulated Rock Truck<br>Articulated Rock Truck        | PMtech            |                      |                          |                          |                          |             |
| Work   | Work Order Description                                  | Status            | Type                 | Date Created             | Due Date                 | Date Completed           | Days Late   |
| 83760  | Degreasing  | Closed, Completed | Preventive - Planned | Aug 18, 2024 05:02:15 AM | Aug 19, 2024 05:02:15 AM | Aug 21, 2024 12:19:31 PM | 2           |
| Task Description   | Asset   | Assigned To       | Completed By         | Date Completed           |                          | Est Hours                | Spent Hours |

