

TRIM(WOHH.WOWH_MODEL)	WOWH_DESC	WOWH_ORDER_N	WOWH_INVOICE_DATE	WOWH_METER	Comments	Full Rep Code
P44-B-697	HILUX WORKMATE DUAL TUB 4X4	252917	23/10/2025 0:00	83039	DISPOSAL/PREP FOR AUCTION, GONE TO AUCTION	PD - PRE-DELIVERY INSPECTION
P44-B-697	HILUX WORKMATE DUAL TUB 4X4	252881	22/09/2025 0:00	83039	RR, RAISE AND SUPPORT VEHICLE, REFIT BATTERY, ELECTRICAL LOOMS TO BATTERY, D/A FUSE BOX, REAR BUMPER, L/H QTR SPLASH LINER, L/H TAILAMP ASSY, R/H TAILAMP ASSY, R/H QTR SPLASH LINER, FUEL LID RELEASE CABLE AND SECURE, FUEL NECK AND BREATHER LINES - RELEASE AND MAKE SAFE, REAR TRAY INC ALL UNDER BRKTS AND WIRING, R/H REAR DOOR PART D/A INC REFIT NEW GLASS R/H, FRONT DOOR NEC H/WARE INC INNER HANDLE L/H/F, DOOR HINGE UPPER, L/H/F DOOR HINGE LOWER, L/H/F DOOR WIRING, L/H FRONT KICK TRIM, L/H FRONT CHECK STRAP, ASSEMBLE AND FIT COMPLETE L/H FRONT DOOR L/H, DOOR APERTURE H/WARE ( STRIKERS , SENSORS ETC), L/H/R DOOR AND NEC/HARDWARE FOR ITS REMOVAL, L/H FRONT DOOR SEAL AND SCUFF PLATE, L/H REAR DOOR SEAL AND SCUFF PLATE, , Repair, R /H/F DOOR, L/H CANT RAIL, L/H FRONT DOOR HINGE PILLAR, , Paint, L /H F+R DOOR APERTURE COMPLETE, L/H CANT RAIL INC F/SCREEN PILLAR, L/H SILL PANEL, L/H SLAM PILLAR, L/H/F DOOR OUT & IN, L/H/F DOOR HINGE UPPER, L/H/F DOOR HINGE LOWER, SEAM SEAL NEW DOOR SHELL, R/H FRONT DOOR, MASK ANY NON REMOVABLE DECALS TO APERTURE, MIX & MATCH, RELEASE AND TREMCO MASK REAR CAB WINDOW, RELEASE AND TREMCO MASK F/SCREEN B/TOUCH, BOLT HEADS, , , QUOTE #5405	CD - CUSTOMER DAMAGE
P44-B-697	HILUX WORKMATE DUAL TUB 4X4	251497	15/08/2025 0:00	83039	COMPLETED PLANT INSPECTION DUE TO STOLEN BATTERY., COMPLAINT: REQUIRES BATTERY, CAUSE: STOLEN, CORRECTION: COULD NOT REPLACE BATTERY DUE TO DAMAGED WIRING, SEE PHOTOS., Completed by:Nazeer.Wilson@porterplant.com.auon:Aug 15, 2025	PI - PLANT INSPECTION
P44-B-697	HILUX WORKMATE DUAL TUB 4X4	250975	13/08/2025 0:00	83039	CARRIED OUT 80KM SERVICE & REPAIRS, COMPLAINT: DUE FOR PLANNED SERVICE, CAUSE: DUE BY TIME NOT KMS, CORRECTION: TRAVELLED TO SOMERTON, ARRIVED ON SITE & LOCATED SUPERVISOR, GOT SHOWN A DESIGNATED WORK AREA, THEN HANDED THE KEYS FOR THE VEHICLE, DRIVE VEHICLE TO WORK AREA THEN WALKED BACK TO COLLECT MY FS UTE., PLACED ON CHASSIS STANDS & CARRIED OUT COMPLETE CHECK OVER, CHECKED & TOPPED UP ALL FLUID LEVELS, REPLACED, CABIN FILTER & ENGINE AIR FILTER, REPLACED FUEL FILTER, SET TYRE PRESSURES 40 PSI, ADJUSTED REAR BRAKES, GREASED, VEHICLE, REPLACED ENGINE OIL & OIL FILTER, REPLACED SERVICE STICKER & STAMPED SERVICE BOOK., UHF RADIO NOT PICKING UP CHANNELS, CHECKED UNIT TO FIND AERIAL HAS FALLEN OUT OF THE BACK OF THE UNIT, COULD NOT, FIND THE ADAPTOR ANYWHERE TO PLUG AERIAL BACK IN, HAD A SPARE ONE FOR NO CHARGE, FITTED THEN REFITTED AERIAL &, TESTED OPERATION, ALL OK., INSPECTION PLATE MISSING FROM FIRE EXT AS WELL AS PIN LOCK, S & F NEW PLATE & STAMPED, FITTED LOCK TAG TO PIN LOCK., BEFORE STARTING SERVICE I COULD HEAR A BANG TYPE OF NOISE UNDER THE VEHICLE WHILE MOVING TO THE WORK AREA, PULLED OVER & CHECKED TO FIND THE BASH PLATE BOLTS LOOSE, WENT TO TIGHTEN BUT FOUND THE THREADS WERE CROSS-, THREADED, REPAIRED ONCE SERVICE WAS COMPLETED AS I NEEDED TO REMOVE THE PLATES ANYWAY, USED A TAP & CLEANED, UP THREADS, USED A DIE ON BOLTS, REFITTED PLATES & ALL BOLTS TIGHTENED UP NO PROBLEM., TIME ADDED FOR MOVING VEHICLE TO DESIGNATED AREA & INDUCTION., PO 217504 - HODGES MECHANICAL SERVICES	PS - PLANNED SERVICE
P44-B-697	HILUX WORKMATE DUAL TUB 4X4	248104	01/07/2025 0:00	82227	REPAIRED PUNCTURED TYRE. POS LH REAR., PO 214923 - GAC CAMPBELLFIELD	TP - PUNCTURE REPAIR
P44-B-697	HILUX WORKMATE DUAL TUB 4X4	247506	21/05/2025 0:00	81794	REPLACED FAILED BATTERY., Completed by:david.gurkin@porterplant.com.auon:May 21, 2025	ER - ELECTRICAL REPAIR
P44-B-697	HILUX WORKMATE DUAL TUB 4X4	245148	01/05/2025 0:00	81794	REPLACED BLOWN LH HEADLIGHT GLOBE, TRAVELLED TO LOCATION, CALLED CUSTOMER TWICE, GOT NO RESPONSE, WAS UNABLE TO REPAIR., REPLACED BLOWN LH HEADLIGHT GLOBE., Completed by:david.gurkin@porterplant.com.auon:Apr 02, 2025	ER - ELECTRICAL REPAIR
P44-B-697	HILUX WORKMATE DUAL TUB 4X4	242382	06/02/2025 0:00	81023	COMPLETED 80,000km SERVICE. REPLACED ENGINE OIL & FILTER., REPLACED FUEL, AIR & CABIN FILTERS. ADJUSTED REAR BRAKES/HAND BRAKE., Completed by:david.gurkin@porterplant.com.auon:Jan 31, 2025	PS - PLANNED SERVICE
P44-B-697	2021 TOYOTA HILUX WORKMATE	226951	15/01/2024 0:00	70983	COMPLETED PREDELIVERY INSPECTION., COMPLETED PREHIRE FOR SWAP WITH P44-B-807., Completed by:dai.pham@porterplant.com.auon:Jan 15, 2024	PD - PRE-DELIVERY INSPECTION
P44-B-697	2021 TOYOTA HILUX WORKMATE	226511	21/12/2023 0:00	70983	COMPLETED OFF HIRE INSPECTION. REPLACED FIRST AID KIT., Completed by:dai.pham@porterplant.com.auon:Dec 21, 2023	GR - GENERAL REPAIRS
P44-B-697	2021 TOYOTA HILUX WORKMATE	225068	21/12/2023 0:00	70983	COMPLETED 70,000km SERVICE. REPLACED ENGINE OIL & FILTER., REPLACED AIR, FUEL & CABIN FILTERS. REPLACED FIRST AID KIT., Completed by:dai.pham@porterplant.com.auon:Dec 21, 2023	PS - PLANNED SERVICE

P44-B-697	2021 TOYOTA HILUX WORKMATE	223295	05/10/2023 0:00	62626	COMPLETED PREDELIVERY INSPECTION. GREEN TAGGED., REPLACED FRONT & REAR SEAT COVERS., Completed by: rick.havlicek@porterplant.com.au on: Oct 09, 2023	PD - PRE-DELIVERY INSPECTION
P44-B-697	2021 TOYOTA HILUX WORKMATE	222436	01/10/2023 0:00	62626	REPAIRED PUNCTURED TYRE - LHR, PO 190052 - BRIDGESTONE BENALLA	TP - PUNCTURE REPAIR
P44-B-697	2021 TOYOTA HILUX WORKMATE	221926	20/09/2023 0:00	60482	REPLACED 4 TYRES & 4WD THRUST ALIGNMENT, ALL TYRES DOWN TO WEAR MARKERS, 4 X 265/65R17 112H WRL AT SILENTRAC OWL SS, PO 189453 - GAC BENALLA	TC - TYRE CHANGE/REPLACEMENT
P44-B-697	2021 TOYOTA HILUX WORKMATE	221703	22/08/2023 0:00	58375	CARRIED OUT 60KM SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED AIR FILTER ELEMENT, CLEANED AIR FLOW METER., REPLACED A/C FRESH AIR FILTER, REPLACED WIPER INSERTS, ROAD TESTED., PO 189189 - BENALLA TOYOTA	PS - PLANNED SERVICE
P44-B-697	2021 TOYOTA HILUX WORKMATE	219248	28/06/2023 0:00	46397	CARRIED OUT 50KM SERVICE, REPLACED ENGINE OIL & OIL FILTER, CLEANED AIR FLOW METER, ROAD TESTED., CHECKED BRAKES & TYRES & TESTED BATTERY., PO 186581 - BENALLA TOYOTA	PS - PLANNED SERVICE
P44-B-697	2021 TOYOTA HILUX WORKMATE	215838	01/05/2023 0:00	10893	WORK ORDER CANCELLED. NO LONGER REQUIRED.	GR - GENERAL REPAIRS
P44-B-697	2021 TOYOTA HILUX WORKMATE	216210	17/04/2023 0:00	10893	CARRIED OUT WHEEL ALIGNMENT, ALSO ROTATE 4 TYRES & BALANCE, PO 183032 - BRIDGESTONE MANSFIELD	WA - AXLE CORRECTION/ALIGNMENT
P44-B-697	2021 TOYOTA HILUX WORKMATE	206022	25/07/2022 0:00	10893	SUPPLIED FIRST AID KIT.	GR - GENERAL REPAIRS
P44-B-697	2021 TOYOTA HILUX WORKMATE	205579	15/07/2022 0:00	10893	COMPLETED PRE-DELIVERY INSPECTION. GREEN TAGGED., COMPLETED PRE-DELIVERY INSPECTION., DETAILED INTERIOR.	PD - PRE-DELIVERY INSPECTION
P44-B-697	2021 TOYOTA HILUX WORKMATE	205326	07/07/2022 0:00	10120	CARRIED OUT MULTIPLE REPAIRS, R&R FRONT BUMPER, GRILLE, RH C PILLAR FITTINGS, REAR BUMPER - STRIF & REFIT, RH TUB SIDE FITTINGS INCL LINER., RH SIDE STEPS, LHF DOOR & LHF GUARD., REPAIR FRONT BUMPER, RH C PILLAR, RHR BUMPER END, RH TUB SIDE, LHF DOOR, REAR BAR REINFORCEMENT., PAINT FRONT BUMPER, RH C PILLAR, RHR BUMPER END, RH TUB SIDE, LHF DOOR, LHF GUARD OUT & IN INCL PROOFCOAT., RE-TAPE BADGES, CUT & POLISH & BRUSH TOUCH, POLISH HEADLIGHT & TAIL LIGHT., PO 172328 - ADROIT PANELS	IR - INSURANCE REPAIRED INTERNALLY
P44-B-697	2021 TOYOTA HILUX WORKMATE	204615	22/06/2022 0:00	10120	REPAIR BODY DAMAGES, REMOVE / REFIT, FRONT BUMPER & DISS / ASS, GRILLE, RHF DOOR & DIS/ASS, RHC PILLAR FITTINGS, REAR BUMPER & DIS / ASS, REAR BUMPER STRIP AND REFIT, RH TUB SIDE FITTINGS INC LINER, LHR DOOR & DIS / ASS, LHF DOOR & DIS /ASS, LHF GUARD & DIS /ASS, LH / RH SIDE STEPS, REPAIR & PAINT, FRONT BUMPER, RHF DOOR, RHC PILLAR, RHR BUMPER END, EH TUB SIDE, RH TUB SIDE, LH TUB SIDE, LHR DOOR, LHF DOOR, LHF GUARD OUT AND IN INC PROOFCOAT, PARTS, REAR BAR REINFORCEMENT, RH TOP STEP, LHF GUARD, LH HEADLAMP ASSY,LH TAILAMP ASSY, AS PER SMASH REPAIRER QUOTE # 3083, \$7047.10+, REPLACE MISSING FIRE EXT, \$29.95+, REPLACE MISSING FIRST AID KIT, \$32.95+	CD - CUSTOMER DAMAGE
P44-B-697	2021 TOYOTA HILUX WORKMATE	204484	20/06/2022 0:00	10120	COMPLETED PRE-DELIVERY INSPECTION., GREEN TAGGED TOP HALF. REPLACED UHF, FIRST AID KIT, 1kg FIRE EXTINGUISHER & NUMBER PLATE GLOBE., NB: VEHICLE STILL WIP, TAKEN TO SMASH REPAIRS.	PD - PRE-DELIVERY INSPECTION
P44-B-697	2021 TOYOTA HILUX WORKMATE	204063	06/06/2022 0:00	10120	CARRIED OUT 10KM SERVICE, REPLACED ENGINE OIL & OIL FILTER, CLEANED AIR FLOW METER, ROTATED WHEELS & BALANCED FRONT WHEELS, ROAD TESTED., PO#171232 - NORTHPOINT TOYOTA	PS - PLANNED SERVICE
P44-B-697	2021 TOYOTA HILUX WORKMATE	204321	06/06/2022 0:00	10120	REPLACED DAMAGED LH SIDE MIRROR, MIRROR BROKEN & HELD ON BY STICKY TAPE, PO 171232 - NORTHPOINT TOYOTA	CD - CUSTOMER DAMAGE
P44-B-697	2021 TOYOTA HILUX WORKMATE	198332	11/05/2022 0:00	0	INSTALLED OVER RAIL TUB LINER, PO 165115 - NORTHPOINT TOYOTA	AR - ADDITIONAL WORK
P44-B-697	2021 TOYOTA HILUX WORKMATE	202084	14/04/2022 0:00	0	***INFORMATION ONLY***, VEHICLE INVOLVED IN ACCIDENT, COMPANY SELF-INSURED AND LOOKING AFTER REPAIRS., INCIDENT REPORT ATTACHED.	CD - CUSTOMER DAMAGE
P44-B-697	2021 TOYOTA HILUX WORKMATE	198082	04/01/2022 0:00	0	COMPLETED PRE-DELIVERY INSPECTION. GREEN TAGGED., FITTED 1kg FIRE EXTINGUISHER & STICKERS. SUPPLIED FIRST AID KIT.	PD - PRE-DELIVERY INSPECTION