

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage	Fault	Repairer / Notes	Cost / Invoice
S-7704	A	03/24/2026	26/03/2026	37	681,812	18,541	0	Internal Workshop - Night Shift REPLACED BOTH TARP CABLES. REPLACED QR1 VALVE ON FOOTBRAKE. REPAIRED PUNCTURE ON 3RD AXLE RHS INNER. REPLACD RHS STEER WHEEL NUT VCV ENGINE WAS MIS-FIRING WHEN COLD. REPLACED 4 ROCKER ARMS.	\$0.00
R-9224	MISSFIRE	04/23/2026	02/17/2026		673,374	18,317	0		\$0.00
R-9128	AC filter	03/13/2026	02/17/2026		674,825		0	Internal Workshop - Night Shift REPLACED AC FILTER.	\$0.00
S-7618	B - 15k	02/16/2026	17/02/2026	29	675,000	15,000	0	Internal Workshop - Night Shift	\$0.00
R-9131	PTO	03/13/2026	02/04/2026				0	Internal Workshop - Night Shift REPLACED WHOLE PTO.	\$0.00
S-7561	A	01/19/2026	19/01/2026	40	672,773		0	Internal Workshop - Night Shift Internal Workshop - Night Shift REAPLACED TRANS MOUNTS. REPLACED LEAKING TRANS AIR SUPPLY FITTING.	\$0.00
R-9065	Gearbox mounts	01/22/2026	01/18/2026		670,419		0		\$0.00
S-7491	A	12/01/2025	10/12/2025	30	670,135		0		\$0.00
S-7444	A	11/07/2025	10/11/2025	21	665,213		0	Internal Workshop - Night Shift REPLACED REAR MUDFLAPS. Internal Workshop - Night Shift RE-SEALED FILL AND DIPSTICK TUBE.	\$0.00
S-7391	C - 30k	10/20/2025	10/20/2025	660,000	30,000		0	ACTUALLY DONE AT 660721 KM Internal Workshop - Night Shift REPLACED BOTH TARP CABLES.	\$0.00
S-7303	A	09/18/2025	18/09/2025	23	653,206		0	SECURED TOOLBOX HANDLE	\$0.00
R-8642	Seatbelt	06/20/2025	08/26/2025		647,331		0	Internal Workshop - Night Shift REPLACED D/S SEATBELT.	\$0.00
R-8565	Exhaust manifold	05/22/2025	08/26/2025		647,331		0	REPLACED EXHAUST MANIFOLD GASKETS AND SLIPJOINTS.	\$0.00
S-7229	B - 15k	08/22/2025	08/26/2025	645,000	15,000		0	Internal Workshop - Night Shift ACTUALLY DONE AT 647331 KM Internal Workshop - Night Shift REPLACED WIPER BLADES. REPAIRED WIPER WASHERS. RE-FITTED BATTERY HOLD DOWNS. REPLACED RHS RAER PLASTIC GUARD. REPLACED PLACTIC CLIPS ON COOLANT LINES AT HEADER TANK.	\$0.00
S-7184	A	08/07/2025	07/08/2025	24	643,156		0		\$0.00
R-8641	Cab shocks	06/20/2025	07/14/2025		638,046		0	Internal Workshop - Night Shift REPLACED REAR CAB SHOCKS. Internal Workshop - Night Shift REPAIRED HINGES ON TOOL BOX LID. TIGHTENED INPUT NUT ON 2ND DIFF.	\$0.00
S-7109	A	07/10/2025	14/07/2025	26	638,046		0	REPAIRED AIR FITTING ON TRANS.	\$0.00
R-8566	Coolant hose	05/22/2025	06/18/2025		631,496		0	REPLACED BOTTOM RADIATER LINE AND CLAMPS,	\$0.00
R-8564	CAB BUMP STOPS	05/22/2025	06/18/2025		631,496		0	REPLACED FRONT CAB BUMP STOPS.	\$0.00
R-8510	Battery	04/30/2025	06/18/2025		631,496		0	CLEANED AND REPAIRED BATTERY HOLD DOWNS	\$0.00
S-7018	D - 90k	06/09/2025	06/18/2025	630,000	88,274		0	Internal Workshop - Night Shift ACTUALLY COMPLETED AT 631496 KM.	\$0.00
R-8523	Headlights	05/03/2025	05/21/2025		624,550		0	10252 REPLACED RHS HEADLIGHT.	\$0.00
S-6953	A	05/21/2025	21/05/2025	36	624,550		0		\$0.00
S-6912	B - 15k	04/14/2025	04/15/2025	615,000	15,000		0	SERVICE COMPLETED BY TYSON E. ACTUALLY DONE AT 617031 KM. Internal Workshop - Night Shift SERVICE COMPLETED BY TYSON/RITCHIE/IZAAK. R/RS-CAM BUSHES 2ND AND 3RD AXLES. R/R SLACK ADJUSTERS 2ND AND 3RD AXLE. R/RALL DIFF OILS AND DIFF FILTER. R/R ALL DRIVE BRAKE SHOES AND DRUMS. R/R ALL WHEEL BEARINGS AND SEALS 2ND AND 3RD AXLES. R/R 2ND AXLE LHS MUDGUARD AND FLAP. FIT ALL NEW WHEEL NUT INDICATORS.	\$0.00
S-6876	A	03/25/2025	25/03/2025	49	612,238		0	FIT NEW RINGFEDER WEAR PAD.	\$0.00
R-8269	BLIND SPOT MIRROR	01/21/2025	02/06/2025		602,102		0	Internal Workshop - Night Shift REPLACED BLIND SPOT MIRROR ON BONNET.	\$0.00
R-8317	Mudflap	02/05/2025	02/05/2025				0	Internal Workshop - Night Shift FITTED NEW MUDFLAP TO REAR.	\$0.00
S-6770	C - 30k	01/23/2025	02/04/2025	600,000	30,000		0	Internal Workshop - Night Shift SERVICE COMPLETED BY IZAAK H. ACTUALLY DONE AT 602429 KM.	\$0.00

R-8210	Cab mounts	12/11/2024	12/10/2024	595,105		0		Internal Workshop - Night Shift	REAR CAB SHOCKS LEAKING. FRONT CAB SHOCKS AND BUMP STOPS WORN.	\$0.00
S-6705	A	12/10/2024	10/12/2024	21	595,105	0	0	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
R-8158	Tarp	11/27/2024	11/20/2024	589,828		0		Internal Workshop - Night Shift	REPALACED ALL TARP BOW ENDS. REPLACED BOTH TARP CABLES.	\$0.00
R-8096	Slack adjusters	10/29/2024	11/19/2024	589,492		0		Internal Workshop - Night Shift	REPLACED ALL 4 DRIVE SLACK ADJUSTERS	\$0.00
S-6654	A	11/14/2024	19/11/2024	22	589,492	0	0	Internal Workshop - Night Shift	SERVICE COMPLETED BY IZAAK H.	\$0.00
R-7777	Cab shocks	08/19/2024	10/28/2024	584,257		0		Internal Workshop - Night Shift	REPLACED CAB SHOCKS AND LEAKING RHS AIR FITTING ON CAB AIRBAG.	\$0.00
R-7775	Number plate lights	08/19/2024	10/28/2024	584,257		0		Internal Workshop - Night Shift	REPLACED RHS NUMBER PLATE LIGHT.	\$0.00
								Internal Workshop - Night Shift	SERVICE COMPLETED BY TYSON E.	
								Internal Workshop - Night Shift	REPLACED LEAKING AIR FITTING ON COMPRESSOR.	
S-6619	B - 15k	10/28/2024	10/28/2024	585,000	15,000	0	0		ACTUALLY DONE AT 584 257 KM.	\$0.00
R-8093	Hydraulic coupler	10/28/2024	10/14/2024	538,990		0		Internal Workshop - Night Shift	RE-KITTED HYDRO COUPLER	\$0.00
S-6571	A	10/03/2024	03/10/2024	28	578,947	0	0	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
R-8004	Toolbox	10/08/2024	09/30/2024	577,869		0		Internal Workshop - Night Shift	REPAIR TOOLBOX LID. CUT OFF ALL MUDFLAP BOLTS AND RAPLACE BOTH REAR MUDFLAPS.	\$0.00
R-7916	CAB AIR BAGS	09/11/2024	09/11/2024	572,681		0		Internal Workshop - Night Shift	REPLACED BOTH CAB AIRBAGS.	\$0.00
R-7906	steer	09/10/2024	09/10/2024	572,561		0	9055	Internal Workshop - Night Shift	ONLY FLIPPED RHS ON THE RIM AS LHS DIDNT NEED DOING.	\$0.00
R-7825	Wiper blades	08/30/2024	09/05/2024	571,228	15,398	0	8952	Internal Workshop - Night Shift	REPLACED BOTH WIPER BLADES.	\$0.00
R-7654	Header tank	07/08/2024	09/05/2024	571,228		0		Internal Workshop - Night Shift	REPLACED THE SMALL PLASTIC LINE ON HEADER TANK WITH THE CLAMPS.	\$0.00
S-6508	C - 30k	09/05/2024	09/05/2024	570,000	28,274	0	0	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	\$0.00
									ACTUALLY DONE AT 571228KM	
R-7776	Belt tensioner	08/19/2024	08/22/2024	567,929		0		Internal Workshop - Night Shift	REPLACED ALL BELT IDLERS AND TENSIONERS AND BELTS.	\$0.00
S-6464	A	08/13/2024	15/08/2024	44	565,518	0	0	Internal Workshop - Night Shift	SERVICE COMPLETED BY TYSON E.	\$0.00
R-7765	UHF	08/05/2024	08/05/2024	562,720		0		Internal Workshop - Night Shift	Fitted new UHF supplied by truckline. Odour reported in truck.	\$0.00
R-7695	Electrical	07/10/2024	07/10/2024	556,983		0		Internal Workshop - Night Shift	Fit new starter motor. Remove and replace faulty starter motor.	\$0.00
R-7656	STEER SLACK ADJUSTER	07/08/2024	07/09/2024	556,772		0		Internal Workshop - Night Shift	REPLACED FAULTY SLACK ADJUSTER.	\$0.00
								Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	
									HEADER TANK LEAKING AT THE BOTTOM.	
									TIMING CASE AT REAR LEAKING OIL.	
									FRONT DRIVE DIIF FLANGE LEAKING.	
									LHS STEER SLACK ADJUSTER FAULTY.	
S-6351	B - 15k	07/02/2024	07/02/2024	555,000	13,274	0	0		SERVICE ACTUALLY DONE AT 554733KM	\$0.00
R-7568	Booster Controller	06/19/2024	06/19/2024	552,664		0		Internal Workshop - Night Shift	Replaced boost spool valve supplied by VCV.	\$0.00
									Service completed by Jarrod H.	
									Replaced boost spool valve.	
S-6316	A	06/19/2024	19/06/2024	41	552,664	0	0		RHS steer tyres scrubbing outside edge.	\$0.00
R-7534	Tarp cable	06/12/2024	06/10/2024	549,138		0		Internal Workshop - Night Shift	Tensioned RHS tarp cable.	\$0.00
R-7508	Valve set	05/27/2024	05/28/2024	546,005		0		Internal Workshop - Night Shift	Valve set completed by Jarrod H	\$0.00
									R&R tarp cables	
S-6203	E - 270k	04/22/2024	05/09/2024	541,726	296,904	0	0		Still to do valve set - JC done.	\$0.00
S-6173	A	04/04/2024	04/04/2024	21	534,088	0	0		Replace all heater hoses on RHS off engine.	\$0.00
S-6127	A	03/14/2024	14/03/2024	27	530,668	0	0			\$0.00
R-7365	Air con	03/10/2024	03/12/2024	530,356		0		A Grade Auto Repair	Found leaking compressor and condenser replaced both and gee-gassed by A Grade. Full details attached	\$0.00
R-7229	Air Conditioner	02/28/2024	02/28/2024	528,024		0		Internal Workshop - Night Shift	Replaced cabin air filter.	\$0.00
R-7183	Batteries	02/21/2024	02/21/2024	526,314		0	7716	Internal Workshop - Night Shift	Replaced all 4 batteries.	\$0.00

R-7101	Window Tinting	02/01/2024	02/16/2024	0	0	0	Southside Window Tinting Completed 16/2/24. Invoice to be attached.	\$0.00	
							R&R 2nd axle airbags R&R 2nd axle penhard rod R&R both short and long exhaust flex Pick up parts from Mack R&R oil line from engine cooler to filter housing R&R leaking air fitting on firewall Rotate dump pipe around off chassis		
S-6059	A	02/16/2024	16/02/2024	30	525,462	0	0	R&R 3rd axle LH guard and poles	\$0.00
							Internal Workshop - Night Shift Replaced broken penard rod on 3rd axle this is what caused the axle beam to brake also replace 2nd axel as well. Replaced all trailing arm bushes and D bushes due to 3rd axle/axle beam braking and damaging them. Replaced rhs air bag due to it being damaged when axle beam broke. Wheel alignment yet to be done will attach invoice	\$0.00	
R-6954	Trailing arm bushes	01/12/2024	02/12/2024		523,795	0	0		\$0.00
R-7125	Tarp cable	02/02/2024	02/06/2024				7576	Internal Workshop - Night Shift R&R cable on truck.	\$0.00
R-7044	Window switch	01/16/2024	01/17/2024		518,949	0	0	Internal Workshop - Night Shift Replaced switch and regulator.	\$0.00
								R&R Hydraulic Coupling Seals	
S-6010	A	01/17/2024	17/01/2024	51	518,949	0	0	R&R RH Tarp cable	\$0.00
								Internal Workshop - Night Shift Remove clean purge valve Remove and replace blown pressure protection valve Remove broken pressure signal fitting from compressor Travel to Mack for new fitting install and test OK.	\$0.00
R-7041	Purge valve	01/12/2024	01/12/2024		518,320	0	0		\$0.00
R-6832	Airbag	11/29/2023	12/06/2023		514,538	0	0	Internal Workshop - Night Shift Replaced 3rd axle LH airbag.	\$0.00
								Internal Workshop - Night Shift Tighten up LHS tarp cable. Could not fault hole in air or airbags leaking.	\$0.00
R-6831	Air Bag	11/29/2023	11/29/2023		512,024	0	0	Driver to check tyres every morning before work. Found 2 x unroadworthy tyres which have been like that for long period of time.	\$0.00
								R&R both rear mudguards.	\$0.00
S-5940	B - 30K	11/27/2023	11/27/2023	511,735	33,756	0	0		\$0.00
R-6748	Mudflap	11/04/2023	11/07/2023		505,590	0	0	7237 Internal Workshop - Night Shift Mudflap replaced	\$0.00
								LH rear mudflap and guard adjust and tighten	
								Replace LH tarp cable	
S-5906	A	11/07/2023	07/11/2023	29	505,590	0	0	Body up alarm switch damaged - still works	\$0.00
R-6760	Tarp	10/31/2023	10/31/2023					Internal Workshop - Night Shift Adjusted RH truck tarp cable.	\$0.00
R-6676	Wiper blades	10/17/2023	10/17/2023		499,713	0	7130	R&R wipers Tightened tarp cables	\$0.00
I-17	Machinery Inspection	10/13/2023	10/13/2023						\$0.00
								RH tarp cable replaced	
								LH tarp cable replaced	
S-5843	A	10/09/2023	09/10/2023	27	497,845	0	0	Rotate drive tyres	\$0.00
								Internal Workshop - Night Shift Air leak on firewall 3/8 air fitting - 90deg - 3/8 BSP -JC	\$0.00
R-6594	Air Leak	09/12/2023	09/12/2023		492,261	0	0	Air leak on firewall 3/8 air fitting - 90deg - 3/8 BSP -JC	\$0.00
								RH windscreen cracked	\$0.00
S-5798	A	09/08/2023	12/09/2023	18	492,261	0	0		\$0.00
S-5762	A	08/25/2023	25/08/2023	31	487,592	0	0	Replaced cab shocks and mounts.	\$0.00
R-6609	Guard	08/10/2023	08/10/2023		0	0	0	Internal Workshop - Night Shift	\$0.00
R-6112	Air Bag	04/03/2023	07/25/2023		477,979		0	Internal Workshop - Night Shift 3rd axle LHS air bag leaking. Replaced air bag.	\$0.00
R-4783	Cab shocks	07/26/2022	07/25/2023		477,979		0	Rear cab shockies leaking. Checked at service, not leaking.	\$0.00
S-5690	B - 30K	07/25/2023	07/25/2023	477,979	28,012	0	0		\$0.00
R-6432	Air Conditioning	07/03/2023	07/03/2023		471,976		0	A Grade Auto Repair Replaced A/c Compressor. Invoice attached.	\$0.00
								Internal Workshop - Night Shift LHS steer tyre replaced with run out and drive rotation done.	\$0.00
T-118	Steer Tyre	07/02/2023	07/02/2023		471,370	0	0		\$0.00
R-5915	Bin chock	03/01/2023	06/29/2023		471,370		6115	Fitted chock.	\$0.00
S-5624	A	06/29/2023	29/06/2023	22	471,370	0	0	Remove diff lock on rear diff found diff pin wont remove from centre.	\$0.00
R-4429	Fire Extinguisher Bracket	06/04/2022	06/28/2023				4694	Fixed by Night shift.	\$0.00
R-6331	Guard	06/16/2023	06/20/2023		468,603		6538	Internal Workshop - Night Shift Fixed	\$0.00

R-6111	Drag link	04/03/2023	06/09/2023	465,554	0	0	Internal Workshop - Night Shift	Replaced draglink supplied by VCV - Jarrod.	\$0.00	
R-6168	Diff oil	04/26/2023	06/07/2023	465,394	0	0	Internal Workshop - Night Shift	Diff oil leaking from 2nd drive pinion seal; needs to be done soon. Done - Tyson (checked service 5554 attached) RH side windscreen cracked LH side chipped R&R wiper blades	\$0.00	
S-5554	A	06/08/2023	07/06/2023	21	465,394	0	0	Repair wiring to LH daytime light	\$0.00	
S-5506	A	05/17/2023	17/05/2023	21	458,833	0	0	Repai punctured LH Steer Tyre	\$0.00	
R-6661	Diff Centre	05/09/2023	05/09/2023	456,741	0	0	Internal Workshop - Night Shift	Fit new wheel bearings and hub seals on 3rd axle. R&R uni joint on rear of jack shaft R&R pinion seal on rear diff - input Fit new yoke to 3rd axle R&R output seal on 2nd axle Make and find tools to fit the 2 piece seal to diff and yoke Tension all uni bolts and wheel nuts Fill both diffs with 85-140 Adjust brakes Degrease truck Test drive	\$0.00	
R-6167	Turbo	04/26/2023	05/02/2023	455,624	0	0	Internal Workshop - Night Shift	Exhaust leak from turbo - manifold flange gasket needs to be done soon. Jay - replace all gaskets and slip joints on manifold and turbo Tyson - R&R manifold gaskets, slip joint seals and all turbo seals & gaskets. Remove broken bolts from turbo & fit new bolts.	\$0.00	
S-5465	A	04/26/2023	26/04/2023	23	455,096	0	0	Internal Workshop - Night Shift	Completed by Tyson. Exhaust leak from turbo - manifold flange gasket needs to be done soon (R-6167). Air leak from fitting on foot valve. Diff oil leaking from 2nd drive pinion seal; needs to be done soon (R-6168). Refit LH mud flap.	\$0.00
R-6156	Tyre	04/14/2023	04/14/2023	452,183	0	0	Internal Workshop - Night Shift	Tyson - Repaired punctured RH steer tyre.	\$0.00	
R-6134	Seat Height Control Valve	04/11/2023	04/12/2023	450,965	12,235	0	6291	Internal Workshop Drivers seat continuously going up and down. ISSERI SEATS RAPLACED RIDE HEIGHT VALVE AT THERE W/S	\$0.00	
R-6132	Flasher unit	04/06/2023	04/07/2023	450,636	12,226	0	6281	Internal Workshop Indicator not working properly REPLACED INDERCATOR STALK AND FLASHER CAM Tyson - done prior to April A service.	\$0.00	
R-6127	Indicator stalk	04/06/2023	04/06/2023	450,965	0	0	Internal Workshop - Night Shift	Garth - remove broken indicator stalk and replaced with new.	\$0.00	
R-6076	Aerial	04/03/2023	04/03/2023	449,967	0	0	6265	Internal Workshop - Night Shift Aerial left hand side damaged. Garth - replaced aerial with new; tested okay.	\$0.00	
R-5985	Exhaust Brake	03/08/2023	04/03/2023	449,967	0	0	6141	Internal Workshop - Night Shift Exhaust break leaking. Garth - Tightened clamp; all okay. Internal Workshop - Night Shift Completed by Garth. Fire extinguisher out of date. Drag link U/S (R-6111). 3rd axle LHS air bag leaking (R-6112). LH & RH steer tyres turned around on rims and refit. Replaced RH front indicator globes.	\$0.00	
S-5399	C - 90K	04/03/2023	04/03/2023	449,967	90,711	0	0	Fit new bolt to body mount.	\$0.00	
R-6039	Tarp cable	03/23/2023	03/23/2023	447,433	0	0	Internal Workshop - Night Shift	Garry - Replaced LHS tarp cable. Internal Workshop - Night Shift Completed by Garth.	\$0.00	
S-5360	A	03/20/2023	17/03/2023	23	445,735	0	0	3rd drive shockies U/S. Replaced with new; tested okay. Broken mounting bolt RHS. Minor oil leak at sump from dipstick tube. First extinguisher out of date.	\$0.00	
R-6092	Tyre	03/16/2023	03/16/2023	445,373	0	0	Bridgestone Wacol	Replaced 8 x drive tyres.	\$0.00	
S-5300	A	02/22/2023	22/02/2023	29	438,994	0	0	Internal Workshop - Night Shift	Completed by Garth.	\$0.00
R-5938	Bull bar	02/09/2023	02/09/2023	435,120	0	0	Internal Workshop - Night Shift	Tyson & Ryan - Straightened bull bar and fit new bolt to drivers side quarter guard.	\$0.00	
R-5742	Bulb	01/19/2023	01/24/2023	340,920	0	0	5940	Internal Workshop - Night Shift Rhf bulb blown headlight. Tyson replaced bulb.	\$0.00	

S-5225	A	01/24/2023	24/01/2023	47	340,920	0	0	Internal Workshop - Night Shift Completed by Tyson. R&R headlight bulb. R&R faulty drive tyre - been driving on two flats therefore both tyres are stuffed. Driver no checking tyres!	\$0.00
R-5608	Turbo	12/06/2022	12/09/2022		423,378		0	Internal Workshop - Night Shift Izaak replaced turbo as other one blew. 06/12/22 - Removed turbo. Removed intercooler and pipes cleaned. Removed exhaust manifold. Remove intake manifold. 07/12/22 - Cleaned intake and manifold, refit to engine. Removed broken turbo mount bolt, cleaned and fit manifold with new gaskets. Replaced oil pressure switch and ran wiring. Fit turbo and full plumb up. Fit intercooler and pipes. Fit drive shaft. Fit exhaust. Replaced engine oil and filters. Test drove. A Grade replaced all wiring due to catching fire. VCV and A Grade invoice attached.	\$0.00
S-5144	A	12/06/2022	08/12/2022	21	423,797	0	0	Internal Workshop - Night Shift Completed by Izaak.	\$0.00
R-5478	Reverse Beeper, Wheel nut	11/28/2022	11/28/2022		421,023	0	0	Internal Workshop - Night Shift Replace missing wheel nut indicator RH steer. Reverse beeper not working. Izaak - removed and replaced trailer plug base on truck due to broken and fixed wiring. Replaced fuse for indicator under dash 15 amp.	\$0.00
R-5389	Wheel nuts	11/07/2022	11/17/2022		418,540	0	0	Internal Workshop Wheel stud missing on front right hand steer wheel Tyson - replaced stud 5583 and nut.	\$0.00
R-5335	Tarp cable	10/15/2022	11/17/2022		0	0	0	Other. Inspect Tarp & tarp cable condition and operation. Tarp cables loose. Tyson - R&R both 5476 tarp cables.	\$0.00
S-5095	B - 30K	11/17/2022	11/17/2022	418,540	27,533	0	0	Internal Workshop - Night Shift Completed by Tyson. R&R broken wheel stud & tension wheel nuts. R&R both tarp cables.	\$0.00
R-5534	Brakes	11/11/2022	11/11/2022		416,610		0	Internal Workshop - Night Shift Machinery defect: low brake efficiency. Tyson: adjusted brakes on first axle; found them a bit out.	\$0.00
R-5401	Mud Flap	11/02/2022	11/10/2022		416,171		0	Internal Workshop - Night Shift Damaged. Inspect Mud Flaps and Guards are all attached. LHR 5561 mudflap on truck Tyson - refit mud flap.	\$0.00
R-5539	Pre-machinery inspection	11/04/2022	11/04/2022		416,171		0	Internal Workshop - Night Shift Pre-machinery inspection. Izaak - fixed all rear mud flaps. Brakes adjusted. Replace engine breather canister mount o'ring. Full check over.	\$0.00
R-5590	Pre-machinery inspection	10/24/2022	10/24/2022		415,223		0	Internal Workshop - Night Shift Garth: Fit 2 x amber reflectors. Turn seat belt around correct way. Replaced blown RH parker lights globe with new. Internal Workshop - Night Shift Completed by Garth. Both drive axle brake re-line due - replaced all 4x drums and shoes. Fit 1 x red reflector. Unseized tail gate pivot pin and re-grease.	\$0.00
S-5011	A	10/21/2022	20/10/2022	24	410,677	0	0	Adjust tarp cables.	\$0.00
R-5355	Mud Guard	10/18/2022	10/18/2022		409,501		0	Internal Workshop - Fabrication Garry. LH and RH rear guard loose - tightened.	\$0.00
R-4971	Exhaust	08/18/2022	09/27/2022		403,429	0	0	NEED TO ORDER Y PIECE AND CLAMPS AND FLEX TO SUIT. ORDER 1ST SEP 06/09/22 - Tyson - needs the whole piece replaced as well. Garth - fit new exhaust.	\$0.00
R-4782	Door seal	07/26/2022	09/27/2022		403,429		0	Passenger door seal U/S. Garth - fit new door seal.	\$0.00
S-4946	A	09/27/2022	27/09/2022	21	403,429	0	0	Garth - fit new exhaust. Tyson - replaced LLH exhaust elbow into stack. Will need new flexi installed next service and clamps.	\$0.00
S-4867	A	09/06/2022	06/09/2022	21	397,625	0	0	Carroll's Tyres Fit 4 x new drive tyres to 3rd axle.	\$0.00
T-68	Drive Tyre	08/23/2022	08/23/2022		393,356	0	0	REPLACE CAB RIDE HEIGHT VALVE Tyson - replaced cab ride height valve.	\$0.00
R-4974	Cab Ride Height Valve	08/18/2022	08/19/2022		319,427	0	0	REPLACE LH HEADLIGHT BULB Tyson - replaced headlight.	\$0.00
R-4973	Head Light	08/18/2022	08/18/2022		391,972	0	0	Tyson: Exhaust leaking on inside of chassis. Needs LH headlight globe. Cabin ride height valve leaking from body. (Jay created job cards for all three of the above)	\$0.00
S-4791	B - 30K	08/16/2022	08/16/2022	391,007	31,751	0	0	REPLACE BROKE DIPSTICK USE NEW TUBE TO Garth - replaced dipstick with new. Top up engine oil.	\$0.00
R-4921	Dipstick	08/11/2022	08/11/2022		389,548	0	0		\$0.00

R-4891	Valves	08/02/2022	08/02/2022	386,895	0	0	Garth - removed and replaced valve for turbo.	\$0.00
R-4786	Mud Flaps	07/28/2022	08/02/2022	386,895	0	0	Other. Inspect Mud Flaps and Guards are all attached. Both rear mud flaps on truck missing. 5086 Garth - replaced rear LHS and RHS guards and mud flaps.	\$0.00
R-4480	Mud Flaps	06/14/2022	08/02/2022	386,895	0	0	Other. Inspect Mud Flaps and Guards are all attached. LH rear mud flap missing On truck LH rear 4729, 4963 mud flap on trailer loose. Garth - replaced rear LHS and RHS guards and mud flaps.	\$0.00
R-4690	Air Conditioner	07/09/2022	07/26/2022	384,379	0	0	4970 Not Working. Other : Major Concerns (Take pics). Aircon running hot. No cold air. Garth - check a/c and added more gas.	\$0.00
S-4724	A	07/19/2022	26/07/2022	384,379	0	0	Garth - passenger door seal U/S (R-4782). Rear cab shockies leaking (R-4783).	\$0.00
R-4862	Air con	07/14/2022	07/14/2022	280,962	0	0	A Grade Auto Repair A Grade Auto Elecs to inspect operation of A/c - not cold.. Found faulty compressor. Replaced compressor and various other parts as per attached invoice. Tested okay.	\$0.00
R-4637	Guard posts	06/21/2022	06/21/2022	374,416	0	0	Garth - Straightened and tightened rear guard poles.	\$0.00
R-4437	Exhaust Brake	06/07/2022	06/20/2022	373,966	0	0	4699 Other. Other : Major Concerns (Take pics). Exhaust brake still leaking. Jay - this has been replaced.	\$0.00
R-4349	Ride height valve	05/09/2022	06/20/2022	373,966	0	0	Cabin ride height valve leaking from body. Jay - stopped leaking. No repair required.	\$0.00
R-4332	Wiper blades	05/20/2022	06/20/2022	373,966	0	0	4599 Other. Inspect Wipers and blades operate smoothly. Need new wiper blades next service. Jay - have been replaced.	\$0.00
R-3780	Shocks	01/26/2022	06/20/2022	373,966	0	0	3rd axle LH drive shock leaking. Jay inspected and they are not leaking. No repair required.	\$0.00
R-3728	Ring Feeder	01/13/2022	06/20/2022	373,966	0	0	Internal Workshop Need to re-kit ring feeder. Garth - fit re-kitted ring feeder. Garth - straightened both rear mud guards. Fit missing reflectors.	\$0.00
S-4648	A	06/15/2022	20/06/2022	373,966	0	0	Tightened body mount bolts.	\$0.00
R-4430	Mud Flaps	06/04/2022	06/04/2022	368,898	0	0	4693 RH rear mud flap on truck missing. Tyson: done Friday night.	\$0.00
R-4458	Exhaust, Gaskets, Mud Fla	06/03/2022	06/03/2022	369,692	0	0	Tyson: Exhaust manifold gaskets leaking; replaced all manifold gaskets. RH rear mud flap; replaced. Patched hole in Y piece of exhaust.	\$0.00
R-4311	Exhaust Brake	05/17/2022	05/26/2022	365,878	0	0	4569, 4607 Other. Check for air leaks. Exhaust brake coupling leaking. Replaced hose clamp at DPF near ad blue dose pipe. Replaced RHS elbow under exhaust stack.	\$0.00
S-4566	A	05/26/2022	26/05/2022	365,878	0	0	Ring feeder need re-kit. Rotate drive tyres next service.	\$0.00
R-3779	Tyres	01/26/2022	05/24/2022	364,893	0	0	Cab height control valve.	\$0.00
R-4000	Hinges	03/13/2022	05/18/2022	363,388	0	0	Mark (as the new driver of this truck) inspected and tyres are okay.	\$0.00
R-3852	Lights	02/07/2022	05/09/2022	361,900	0	0	4139 Toolbox door hinges popped off: Tyson replaced hinges.	\$0.00
R-3781	Exhaust	01/26/2022	05/09/2022	361,900	0	0	Not Working. All lights, reflectors & lenses. Clearance light on roof not working: Tyson checked and all working okay.	\$0.00
S-4504	A	05/04/2022	09/05/2022	361,900	0	0	Exhaust split at seem from muffle to stacks: Replaced exhaust Y piece.	\$0.00
R-4036	Coolant	03/16/2022	04/07/2022	359,256	0	0	R&R tarp motor controller. Remove two old motor controllers.	\$0.00
R-4014	Engine light	03/09/2022	04/07/2022	359,256	0	0	4334, 4346 Cabin ride height valve leaking from body.	\$0.00
S-4409	C - 90K	03/31/2022	04/07/2022	359,256	0	0	Coolant topped up during service. All good.	\$0.00
R-4112	Suspension	03/31/2022	04/04/2022	0	0	0	Other. Seat and Seat belts. Engine light on dashboard: This has been hooked up to laptop and 4315 fixed.	\$0.00
S-4334	A	03/09/2022	10/03/2022	353,270	0	0	Needs ring feeder wear pad / re-kit.	\$0.00
R-4910	Compressor	03/02/2022	03/02/2022	351,459	0	0	4398 Night shift inspected and could not fault.	\$0.00
R-3977	Air leaks, Clamp	02/21/2022	02/21/2022	351,277	0	0	Internal Workshop Steer wheel nuts cracked - replaced x 3.	\$0.00
R-3668	Mudflaps	12/06/2021	01/26/2022	345,311	0	0	Toolbox door hinges popped off. Oil pressure gauges faulty - checked wipers etc.	\$0.00
							VCV Replaced compressor and air dryer as per Mack campaign.	\$0.00
							Replaced clamp supplied by Mack. Fixed air leak with 1/4 joiner.	\$0.00
							3973, 4001 Replaced mudflap.	\$0.00

								Ring feeder needs re-kit.	
								Drive tyres need rotation.	
								3rd axle LH drive shock leaking.	
S-4210	A	01/26/2022	26/01/2022	42	345,311	0	0	Exhaust split at seem from muffle to stacks.	\$0.00
R-3714	Toolbox	01/11/2022	01/17/2022		342,832	0	0	Replaced and tightened bolts.	\$0.00
R-3690	Tailgate	12/14/2021	01/11/2022		0	0	0	4007 Danny repaired.	\$0.00
R-3682	Windscreen	12/16/2021	12/16/2021		0	0	0	4017 Jay has inspected and it is not in the drivers vision. No repair required at this stage.	\$0.00
								Replaced exhaust flex under cab.	
								Need to re-kit ring feeder.	
S-4145	A	12/15/2021	15/12/2021	21	340,475	0	0	Replaced RH tarp cable.	\$0.00
S-4077	A	11/24/2021	24/11/2021	31	337,042	0	0	Internal Workshop	\$0.00
R-3577	Sensor	11/10/2021	11/22/2021		336,530	0	0	Internal Workshop Replaced horizontal oil pressure sensor.	\$0.00
R-3524	Hydraulic hose	09/09/2021	11/15/2021		335,371	0	0	3552, 3574 Internal Workshop Jarrod. Replaced o rings. Re-kit hydraulic coupling.	
R-3598	Cab mounts	10/31/2021	10/31/2021		331,685	0	0	Internal Workshop Removed LH and RHS front cab mounts and replace with new - tested okay.	
R-3489	Water pump	10/26/2021	10/26/2021		330,698	0	0	Internal Workshop Replaced water pump, re-used old coolant. Water pump supplied by VCV.	
								Internal Workshop Jarrod.	
								Oil weep at engine breather.	
								Replaced tarp cable.	
S-3993	B - 30000	10/24/2021	10/24/2021	329,986	28,959	0	0	Water pump leaking.	
R-3545	Air con filter	10/17/2021	10/17/2021		328,403	0	0	Internal Workshop Jarrod. Air con filter replaced.	
R-3330	Brakes	10/05/2021	10/11/2021		32,658	0	0	Internal Workshop Jack. Checked all abs plugs and found one loose. All good now.	
								Internal Workshop Jarrod. Checked and adjusted all brakes. All trailer brakes were out of adjustment. EBS valve leaking out exhaust between 3rd and 4th axle. Truck drives out of adjustment by 1/4 turn.	
R-3328	Brakes	10/04/2021	10/04/2021		325,928	0	0	Internal Workshop Rear mudflaps are slightly damaged from jackknifing. Please check.	
R-3241	Mudflaps	09/06/2021	09/27/2021		324,271	0	0	3551 Removed flaps and replaced.	
R-3230	Gearbox mounts	08/18/2021	09/27/2021		324,271	0	0	Internal Workshop Replaced both mounts.	
R-3067	Windscreen	07/14/2021	09/27/2021		324,271	0	0	3193 Windscreen replaced.	
								Internal Workshop Done by Jarrod.	
S-3878	A	09/27/2021	27/09/2021	40	324,271	0	0	Secured rear mud flaps and guards.	
								Internal Workshop Done by Garth. Fitted runout to 2nd axle outside driver side. Fitted 2 x runouts to 3rd axle LHS. Straightened rear guards. Fitted mud flaps to rear LHS. Remove and fit LH and RH gearbox mounts - tested all okay.	
R-3276	Transmission	09/20/2021	09/20/2021		322,409	0	0	Internal Workshop Done by Garth. Replaced top radiator hose with new hose clamps - tested	
R-3014	Clamps	07/02/2021	09/20/2021		322,409	0	0	3381 okay. Topped up coolant.	
R-3012	Oil sample	07/02/2021	08/18/2021			0	0	KOWA Engine sample - slip nr: 477618 Transmission sample - slip nr 346563	
								Internal Workshop Done by Garth.	
S-3792	A	08/17/2021	18/08/2021	50	313,855	0	0	Rear gearbox mounts need doing.	
								Internal Workshop Front right indicator not working Done by Garth. Replaced blown indicator	
R-3147	Indicators	08/05/2021	08/09/2021		311,239	0	0	3332 bulb.	
								Internal Workshop Top radiator hose leaking everywhere. Done by Garth. Re-fit hose clamp	
R-3142	Radiator	08/09/2021	08/09/2021		311,239	0	0	3353 correctly and top up coolant system.	
R-3096	Bonnet Mirror	07/22/2021	07/22/2021		306,179	0	0	3261 Internal Workshop Tightened bonnet mirror	
								Carroll's Tyres Allan took truck to Carroll's to get 2 x new steer tyres fitted & wheel balancing was done	
R-2793	Tyres	05/12/2021	07/14/2021		304,161	0	0	Internal Workshop Jarrod inspected - topped up coolant Stains from coolant change - needs	
R-3002	Coolant leak	06/30/2021	06/30/2021		301,028	0	0	3082 new top radiator clamp	

								Internal Workshop	D SERVICE DONE AT 29/06/2021 AT 301027 KMS. THIS WILL BE ADJUSTED BACK TO 270000KMS SO THAT ALL OF THE SERVICE INTERVALS REALIGN. BRAD TURNER 02/02/2022	
S-3655	D - 90k	06/29/2021	06/29/2021	270,000	25,178	0	0	Internal Workshop	Service done by Jarrod	\$0.00
								Internal Workshop	Service done by Jarrod	
									Replaced LH tarp cable	
									ABS light on	
									Wiper blades need replacing - Replaced by Jarrod	
									Front cab mounts need doing - Replaced by Jarrod	
									Fan shroud cracked	
									Oil weep - oil switch on - filter blocked	
									Oil weep at oil spinner RH Block	
									Oil weep at cam cover	
									Need clamp for top pad hose	
S-3654	B - 15k	06/29/2021	06/29/2021	301,027	0	0	0	Internal Workshop	Williams Valve leaking - replaced by Jarrod	
R-2941	Hose	06/17/2021	06/17/2021				0	Internal Workshop	Replaced radiator hose clamp - job done by Jarrod	
								Internal Workshop	Inspected by Jarrod on 18/5 - damaged & worn threads on lock nuts - to	
R-2825	Mirror	05/18/2021	06/09/2021		296,413	0	0	2727	order parts Parts in stock 9/6 - removed worn mirror and fitted new one - job done by Garth	
								Internal Workshop	Service done by Jarrod	
									Inside cab stinks - BAD smell	
									Top radiator hose leaking at clamp	
									Weeping rear cylinder head cam cover	
									Rear engine mounts need doing	
									Exhaust hitting chassis	
									RHR guard damaged	
									Steer tyres feathered heavily on edges - need new tyres ASAP	
									Cab mounts worn	
									Exhaust split from muffler to stacks	
S-3584	A	06/02/2021	02/06/2021	47	294,152		0		Ad blue leak at injectors	
R-2877	Oil sample	05/31/2021	05/31/2021				0		KOWA Engine back at CAUTION Front diff back at NORMAL Rear diff back at NORMAL	
R-2839	Mudflap	05/19/2021	05/21/2021		291,103		0	2752	Internal Workshop Mudflap fitted back on rear of truck - job done by Garth	
R-2838	Coolant leak	05/20/2021	05/21/2021		291,103	0	0	2769	Internal Workshop Replaced hose & thermostat housing - job done by Jarrod	
R-6924	Clutch	05/14/2021	05/14/2021		288,917	7,863	0		VCV Replaced clutch cylinder. Clutch actuator replaced under warranty. Invoice attached.	\$0.00
R-2790	Coolant leak	05/10/2021	05/10/2021		288,337	0	0	2637	Internal Workshop Tightened 2 x loose hose clamps - job done by Jarrod	
								Internal Workshop	Service done by Garth	
									Tightened hoist bolts	
									DEFECTS: Play in drag link	
S-3462	A	04/16/2021	16/04/2021	23	283,824	7,715	0		Needs new switch for power window	
R-2551	Gearbox	03/03/2021	04/08/2021		281,440		0	1891	Mack Brisbane Mack fitted new transmission actuator	
								Internal Workshop	ABS light on dash No engine light present No codes in computer - all ok	
R-2630	ABS Light, Engine light	03/23/2021	03/29/2021		280,115		0		Inspected by Jarrod	
R-2612	Body up alarm	03/17/2021	03/29/2021		280,115	0	0	2075	Internal Workshop Jarrod inspected - can not lower the buzzer noise - it is not that noisy	
R-2640	Brakes	03/26/2021	03/26/2021		279,475		0		Internal Workshop Re-lined drive axle brakes	
								Internal Workshop	Jarrod inspected - no obvious signs of boost leaks - found loose clamp on	
R-2557	Boost leak	03/03/2021	03/24/2021		279,136	0	0	1903	turbo side - tightened all clamps	
								Internal Workshop	Service done by Jarrod	
									Defects: Steer tyres wearing uneven	
									Exhaust splitting between mufflers & stack	
S-3403	A	03/24/2021	24/03/2021	29	279,136	0	0		Drive axle brakes need doing soon	

R-2583	Tyres	03/15/2021	03/15/2021	277,836	0	0	2049	Internal Workshop	Truck booked in at D&L Laser Alignment on 22/03/2021
R-2552	Windows	03/03/2021	03/03/2021	276,325	7,486	0	1892	Internal Workshop	Inspected by Jarrod on 24/03 - Jay to order a switch
R-2535	Windscreen	02/24/2021	03/03/2021			0			Jay confirmed that this will need to be done before next inspection - reminder set
R-2547	Air dryer	02/25/2021	02/25/2021	275,543		0			Cleaned purge valve Replaced pressure protection valve Job done by Jarrod
R-2536	Valve set	02/24/2021	02/25/2021	275,543		0			Internal Workshop Valve set done Replaced coolant housing top RHS of engine - travel to & from Mack for parts
R-2497	Header tank	02/19/2021	02/23/2021	274,970	0	0			Internal Workshop Replaced header tank - job done by Jarrod
									Internal Workshop Service done by Jarrod
									Defect: Exhaust pushing oil from muffler - pics sent to Brad
									Monitor drive axle brakes - next service
									Front cab mounts worn
									Gearbox mounts sagged
									Needs drive rotation done & valve set was not yet done
S-3338	C - 30k	02/18/2021	02/23/2021	274,970	30,148	7,447	0		Oil samples done: Engine 381592, R Diff 383174, F Diff 380992
R-2514	Windscreen	02/22/2021	02/22/2021	274,621	7,437	0	1750	Internal Workshop	Laine inspected windscreen - will need to be replaced
									Internal Workshop Coolant level ok - suspect early stages of header tank leak Checked by
R-2493	Coolant	02/18/2021	02/18/2021	274,497	7,432	0	1718	Jarrod	
R-2472	Window switch	02/12/2021	02/12/2021	0	0	0		Internal Workshop	Swapped wiring over
								Internal Workshop	Service done by Laine
									Re-sealed 1st drive output splines
S-3272	A	02/02/2021	02/02/2021	46	269,735	7,301	0		Replaced RH tarp cable
								internal workshop	Cab mounts and cab shocks worn
									Replaced ring feeder wear pad
									Top rad hose weeping tightened clamps
									Tipper pivot not taking grease (repaired)
									Tension trailing arm bolts
S-3189	A	12/18/2020	18/12/2020	29	261,080	7,077	0		Small stone chips left and right windscreen
								Internal workshop	Service done
									Leak front input diff - ok
S-1970	A	11/19/2020	19/11/2020	28	254,410	6,887	0		Clearance light on roof not working - replaced bulb
								Internal Workshop	Repaired parker lights, Checked over front end / steering - clunking noise possibly springs sliding side to side on shackle pins, fitted wheel indicators - replaced missing ones & put zig zags on steer
R-593	Lights, Steering	10/23/2020	10/23/2020		191,117		0		Internal Workshop A service done
									Replaced bulb in roof marker light
S-679	A	10/22/2020	22/10/2020	22	250,020	6,768	0		DEFECTS: Slight leak at front diff input shaft flange - minor - monitor
R-402	Coolant Sensor	10/09/2020	10/09/2020		247,012	0	0	Internal Workshop	Replaced coolant level sensor
								Internal Workshop	E service done
									Replaced purge valve
									Valve set was not done as it was done previous service
									Replaced LH tarp cable
									Tested Glycol level - 40%
S-549	E - 270k	09/29/2020	09/30/2020	244,822	244,822	6,616	0		DEFECT: Coolant level sensor fault - SPN111 FM1S
R-375		09/25/2020	09/25/2020		243,575	0	0	Internal Workshop	Replaced air/con filter
R-322	Tyres	09/08/2020	09/21/2020		241,811	0	0	Millards	Took truck to Millards and got 8 x new drive tyres
									Drive guard mudflap pulled off & dragged guard post down - re-positioned & tightened post and replaced mudflap
R-334	Mudguards	09/14/2020	09/14/2020		240,030	0	0		A service done
S-493	A	08/31/2020	03/09/2020	27	237,253	0	0		Drive tyres to be rotated
									Replaced 2 x damaged guard posts - grind holes out on chassis to fit bigger bolts - fit new RHR mudguard & 4 x mudguard mounts fitted new loop kit - refit old mudflap Repaired damaged /
R-299	Mudguards	09/01/2020	09/01/2020		236,531	0	0		torn wiring to RHR tail light & reverse light

R-264	Speed control	08/25/2020	08/25/2020	234,522	0	0	Road tested - checked cruise control - ok Checked cruise while stationary - ok FOUND: Driver pushed the incorrect button	
R-262	Engine codes	08/20/2020	08/20/2020	232,995	6,312	0	Could not get fault to come up - checked plug & pins - checked harness down side of radiator - ran engine for 0.5hrs - still would not come up	
R-249	Battery	08/17/2020	08/13/2020	231,394	0	0	Checked batteries - original batteries still fitted - all batteries swollen & out of shape - suggest replacing batteries - still charging mid to high 13V range 17/8/2020 - Replaced 4 x batteries supplied by MaxiParts	
S-422	D - 90k	08/07/2020	08/07/2020	230,602	230,602	6,240	0	A service done Did valve set Replaced fuse for cigarette lighter
R-208	Mudflaps, Mudguards	07/31/2020	08/05/2020	229,586	6,229	0	Internal Workshop Replaced 2 x rear guards Straightened mudflap brackets & guard posts & replaced 2 mudflaps	
R-204	Plugs	07/29/2020	07/29/2020	227,834	0	0	Repaired all 12V plugs in cab now working	
S-352	A	07/15/2020	07/15/2020	224,739	6,099	0	A service done	
R-147	Driveline	07/08/2020	07/08/2020	222,062	0	0	Replaced input seal front diff Replaced ad blue fitting going into diffuser at muffler	
R-119	Driveline	06/24/2020	06/25/2020	219,265	0	0	Re-sealed splines 1st diff input Internal Workshop A service done	
S-281	A	06/23/2020	06/24/2020	218,863	5,939	0	Ran out of time to do oil weep 1st drive input & output seals - needs doing ASAP	
R-83	Radiator	06/05/2020	06/08/2020	214,879	0	0	Replaced 2 x Heater hoses & refilled coolant Service done Replaced wiper blades Removed drive axle lower backing plate - refit fallen out brake spring DEFECTS: Air dryer muffler missing	
S-213	B - 15k	06/02/2020	06/02/2020	213,702	0	0	Oil weep 1st drive input & output seals getting worse	
R-39	Radiator	05/18/2020	05/18/2020	209,141	0	0	Internal Workshop Replaced / fitted new radiator Replaced broken hydro fitting on ringfeder	
R-887	Hydraulic fitting, Radiator	05/14/2020	05/14/2020	209,141	0	0	Internal workshop Fitted new radiator Replaced broken hydro fitting on ringfeder Service done Replaced RH tarp cable	
S-133	A	05/11/2020	05/13/2020	208,911	0	0	Tightened terminal on starter helper solenoid - was loose Internal workshop FOUND: could not fault operation - wear pad well worn - could have been possible cause - replaced wear pads	
R-886	Ringfeder	04/08/2020	04/08/2020	200,779	0	0	Internal workshop Inspected hoist pins truck & trailer - all good	
R-885	Hoist pin	04/03/2020	04/03/2020	198,373	0	0	Internal workshop Replaced LHS tarp cable	
R-884	Tarp cable	03/31/2020	03/31/2020	198,373	0	0	Internal Workshop A service done DEFECTS: 1. Minor oil weep 1st drive input & output seals 2. Air dryer muffler missing 3. Coolant sensor faulty	
S-101	A	03/26/2020	03/26/2020	197,235	0	0	Internal workshop Repaired parker lights DONE: Checked over front end / steering - clunking noise possibly springs sliding side to side on shackle pins, fitted wheel indicators - replaced missing ones & put zig zags on steer	
R-883	Check over, Lights	03/05/2020	03/05/2020	191,117	0	0	Internal Workshop No active codes - ran engine & drove around yard to try and get it to activate but it wouldn't	
R-592	Active Codes	02/27/2020	02/27/2020	189,475	0	0	Internal Workshop A service done	
S-777	A	02/21/2020	21/02/2020	187,940	0	0	Internal workshop Replaced 2 x air filters	
R-882	Air filter	02/03/2020	02/03/2020	184,444	0	0	Internal Workshop B service done Air filters not done - no stock	
S-776	D - 90k	01/30/2020	01/30/2020	183,740	29,815	0	0	Air filters were done on Internal Workshop Cleaned air/con evaporator - washed out with detergent & rinsed clean with water & blew out - deodorised with Wurth Spray
R-591	Air Con Evaporator	01/23/2020	01/23/2020	181,975	0	0	Internal Workshop Replaced aircon filter	
R-590	Air con filter	01/21/2020	01/21/2020	181,314	0	0		

R-589	Electrical, Wiper blades	01/16/2020	01/16/2020	180,346	0	0	Internal Workshop Repaired loose wiring Replaced window wiper blades A service done, Inspected & found LH cab mount is fine - no wear in bush - has not dropped Checked plastic guards and check if any needs replacing - all ok, Check Williams valve pressures - done - all ok Straightened LHR guard post	
S-775	A	12/19/2019	19/12/2019	21	176,644	0	0	Top up engine oil 2Ltr
R-588	Mudguards	12/06/2019	12/06/2019	172,322	0	0	Internal Workshop Adjusted rear guard LHS	
S-774	A	11/28/2019	28/11/2019	22	170,035	0	0	Internal Workshop A service done Checked Williams valve pressures - trailer maxed out at 50-65PSI with key on & test line connected to rear booster - trailer lead by 5 - 7PSI with test line connected to duo-matic Internal Workshop Pre machinery check over Removed ALL BWC stickers & replaced mudflaps with Holcim ones
R-587	Pre-machinery check	11/22/2019	11/22/2019	168,445	0	0	Internal Workshop Replaced rear mudguard bracket bolt	
R-586	Mudguards	11/14/2019	11/14/2019	166,285	0	0	Internal Workshop Checked hydraulic oil - topped up approx 25Ltrs & replaced tarp cable	
R-585	Hydraulic oil	11/12/2019	11/12/2019	165,940	0	0	Millards Replaced 8 x drive tyres Aeolus ADC53 done by Millards	
R-584	Tyres	11/08/2019	11/08/2019	165,313	0	0	A service done	
S-773	A	11/06/2019	06/11/2019	20	164,904	0	0	DEFECTS: All drive tyres need replacing Checked for codes - no codes coming up - road tested truck - fault not coming up Adjusted all brakes
R-583	Brakes, Electrical	10/31/2019	10/31/2019	163,440	0	0	Millards Replaced steer tyres x2 @ Millards Tyres	
R-582	Tyres	10/21/2019	10/21/2019	160,943	0	0	Internal Workshop A service done	
S-772	A	10/17/2019	17/10/2019	24	160,791	0	0	Drive tyres rotated
R-581	Williams valve	10/15/2019	10/15/2019	160,396	0	0	Internal Workshop Replaced Williams valve	
R-580	Tyres	10/10/2019	10/10/2019	159,780	0	0	Internal Workshop Replaced tyre with runout	
R-579	Tyres	10/03/2019	10/03/2019	157,639	0	0	Internal Workshop Replaced blown drive tyre RHR - Used one of RH tyres	
R-578	Exhaust clamp	10/02/2019	10/02/2019	157,635	0	0	Internal Workshop Removed damaged V-band clamp at exhaust brake - loosened flex clamps & at front of exhaust brake - re-aligned pipes to prevent hitting cab & chassis - tightened all clamps - removed exhaust brake actuator cylinder & operate manually to locate noise- could not locate - No. 2 cylinder definitely leaking from exhaust manifold - road tested - ok	
R-577	Brakes	10/01/2019	10/01/2019	157,580	0	0	Checked brakes & adjustment - could not fault - road tested to check brakes & exhaust brake - brakes ok - exhaust brake has loud squeaking noise on high - sounds like it's coming from DPF area, Exhaust leaking from exhaust manifold at No 2 - tightened bolts (top bolt was loose) V- band clamp behind exhaust brake also leaking - tightened clamp but picked up thread - made temp repair to clamp NEEDS TO BE REPLACED ASAP (clamp with allen key headed bolt)	
R-576	Hub Cap	09/26/2019	09/26/2019	155,455	0	0	Internal Workshop Fitted 2 x steer hub caps Internal Workshop B service done Replaced power steer filter Replaced 4 x bolts for fuel tank x-over DEFECTS: Excessive kingpin wear both sides Chrome hub cap missing RH steer G/box oil cooler lines starting to sweat	
S-771	D - 90k	09/23/2019	09/23/2019	153,925	31,247	0	0	LHF drive inside tyre chopping out

								Internal Workshop A service done Replaced a/c filter Tightened RHR mudguard post - was loose on chassis Replaced frayed tarp cable both sides Trailer safety chain brackets were damaged - cleaned up with grinder Tightened all trailing arm eye bolts Tightened leaking bottom radiator hose clamp Tightened loose fuel tank x-over bolts DEFECTS: 4 x x-over bolts missing G/box oil cooler lines starting to sweat LHF drive inside tyre chopping out Bolt missing from compressor x-over bracket
S-770	A	09/13/2019	13/09/2019	25	150,815	0	0	Internal Workshop Possibly need re-gas as per Phil BRAD NOTES: Possibly evaporator & filter will need to be cleaned
R-575		09/03/2019	09/03/2019		148,790		0	Internal Workshop Air compressor seems to be cycling on & off a lot but not really an issue. Compared with another truck & is cycling only slightly more than it. Air compressor cut in & out - pressures ok - air builds up very quickly. DONE: Replaced exhaust flange clamp at DPF - loosened - repositioned - retightened clamp at flex under cab, lubricated exhaust brake air solenoid, road tested - exhaust noise appears to have stopped along with exhaust brake solenoid noise
R-574	Air leaks	08/29/2019	08/29/2019		145,668		0	Internal Workshop Replaced mudflaps on drive & rear of trailer with BWC ones
R-573	Mudflaps	08/26/2019	08/26/2019		144,984		0	Internal Workshop A service done DEFECTS: excessive kingpin wear both sides
S-769	A	08/19/2019	19/08/2019	27	143,319	0	0	Chrome hub cap missing RH steer Internal Workshop Adjusted all brakes - fix air leaks at boosters, tightened up bolts on Williams valve
R-572	Brakes	08/15/2019	08/15/2019		141,250		0	Internal Workshop A service done Inspected tarp cable - ok until next service Replaced rear axle RHS inside tyre with run out Replaced all drive brakes & drums Repair hinge on toolbox LHS Tightened up all diff head bolts Strip & fit 1 x drive tyre Tightened up 90degree fitting at diverter valve DEFECTS: chrome hub cap missing RH steer
S-768	A	07/23/2019	23/07/2019	20	138,490	0	0	Excessive kingpin wear both sides
R-571	Toolbox	07/08/2019	07/08/2019		134,694		0	Internal Workshop Tightened toolbox door hinge bolts
R-570	Valve set	07/08/2019	07/08/2019		134,694		0	Internal Workshop Adjusted valves, injectors & engine brakes - road test - ok Internal Workshop A service done Straightened mudflap brackets below ringfeeder Re-attached mudflap to guard LHR Straightened checker plate & brackets either side of ringfeeder Tightened both guard posts LHR DEFECTS: drive brakes getting low
S-767	A	07/03/2019	03/07/2019	20	133,866	0	0	Has excessive king pin wear both sides Chrome hub cap missing RH steer Internal Workshop A service done Tightened up LHS quarter guard behind steer
S-766	A	06/13/2019	13/06/2019	27	129,602	0	0	Blew out air filters DEFECT: monitor drive brakes - approx 50%

R-569	Lights, Mudflaps	06/11/2019	06/11/2019	128,751	0	0	Internal Workshop Replaced both L&R park light bulb wedges Straightened and re-attached mudflaps on both L&R rear drive guards Couldn't tighten up guard poles as truck was pre-loaded - need bin up to get to bolts & nuts - Need to return to workshop	
S-765	E - 270k	05/17/2019	05/17/2019	122,678	122,678	0	0	Internal Workshop B service done Replaced ad blue filters Checked drive brakes - still 50% ok for a while NOT DONE: AIR DRYER FILTER TO BE REPLACED
S-764	A	04/23/2019	23/04/2019	27	115,634	0	0	Internal Workshop A service done Replace tarp g/box Tightened coolant hard line RHS engine retainer bolt as it was loose Tightened rocker cover - slight weep - monitor Tightened exhaust clamp at muffler Tightened up hydro hose at diverter valve
R-568	Fuse	04/11/2019	04/11/2019	113,633	0	0	0	DEFECTS: drive brakes 50% - monitor Internal Workshop Replaced blown fuse for lighter
R-567	Pinion Seal	03/29/2019	03/29/2019	110,750	0	0	0	Internal Workshop MACK REPAIRS: Replaced pinion seal Internal Workshop A service done Gearbox filter changed Engine oil changed to FULLY SYNTHETIC Gearbox oil sample done Tightened loose mudguard bracket on drive DEFECTS: Pinion seal front of front diff leaking BAD Drive brakes getting low (TO BE DONE NEXT GREASE / SERVICE) Tarp g/box has small crack (TO BE DONE NEXT GREASE/SERVICE)
S-763	A	03/27/2019	27/03/2019	23	110,724	0	0	Internal Workshop NOT DONE - truck was loaded, Inspect & replaced wear pad on ringfeder - replaced wear pad
R-566	Mudguards	03/11/2019	03/11/2019	109,221	0	0	0	Internal Workshop A service done Tightened loose body bolts and mudguard bolts
S-762	A	03/04/2019	04/03/2019	18	105,127	0	0	DEFECTS: Pinion seal front of front diff leaking BAD
S-761	A	02/14/2019	14/02/2019	24	100,684	0	0	Internal Workshop A service done Removed steering column covers & tightened indicator stalk Air leak at front of truck - plug leaking air - removed and made a bung from an airline - ziptied over Topped up hydraulic oil - 6 ltrs - still jumpy - need to be checked by Shephards Tightened all drive shocky bolts
R-565	Bolts, Tarp cable	01/23/2019	01/23/2019	95,367	0	0	0	DEFECTS: pinion seal front of diff leaking BAD Internal Workshop Replaced tarp cable on both sides On left air intake manifold bracket for intake pipe for compressor had a broken bolt - drill & oxy out broken bolt - found 2nd hand old bolt - cleaned up thread and refit & bolt to mount bracket
S-760	D - 90k	01/21/2019	01/21/2019	94,591	94,591	0	0	Internal Workshop B Service done Replaced tarp cable Pinion & through shaft seal done under Warranty & boost issue Internal Workshop A service done Exhaust mounting bolts loose at bottom of elbows both sides - removed bolts - checked nuts broken - refit bolts DEFECTS: RH tarp cable starting to unwind Steering pump starting to leak
S-759	A	12/17/2018	17/12/2018	24	89,406	0	0	Pinion & through shaft seal leaking on front diff
S-758	A	11/23/2018	23/11/2018	11	83,007	0	0	Internal Workshop A service done DEFECTS: Input shaft seal leaking, small leak output 1st diff
R-564	Reflectors	11/21/2018	11/21/2018	82,650	0	0	0	Internal Workshop Red & white reflectors fitted to truck & trailer

S-757	A	11/12/2018	12/11/2018	31	0	0	0	Internal Workshop	A service done
R-563	Tyres	11/03/2018	11/03/2018		77,115		0	Internal Workshop	Replaced 2 x steer tyres
S-756	A	10/12/2018	12/10/2018	21	71,833	0	0	Internal Workshop	A service done
R-562	Bolts	10/09/2018	10/09/2018		70,921		0		Rocker cover leaking - WARRANTY JOB LHS 2nd drive shock leaking - WARRANTY JOB Adjusted tarp cable All tightened
S-755	A	09/21/2018	21/09/2018	17	68,537	0	0	Internal Workshop	A service done Monitor hoist valve block leaking again Repaired hinge on toolbox Steer tyres getting low Rocker cover leaking LHS 2nd drive shock leaking Front pinion seal on front diff leaking (warranty) Fitted 16 x 33mm wheel nut covers
S-754	C - 30k	09/04/2018	09/04/2018	63,585	63,585	0	0	Internal Workshop	Service done Ad blue filters were replaced Tightened bolt & degreased - will check hoist valve block leak again Rocker cover leaking LHS 2nd drive shock leaking
S-753	A	08/14/2018	14/08/2018	27	62,308	0	0	Internal Workshop	Service done Tyres need replacing Hoist valve block leaking (Shephards?) LHS rear axle shock leaking
S-752	A	07/18/2018	18/07/2018	21	54,842	0	0	Internal Workshop	Service done PTO hose needed to be re-clamped Defect: Drive tyres low
S-751	A	06/27/2018	27/06/2018	21	48,925	0	0	Internal Workshop	Service done Internal Workshop Service done Engine oil level high Hoist valve block leaking
S-750	A	06/06/2018	06/06/2018	22	42,702	0	0	Internal Workshop	Service done Rear drive tyres wearing shoulders out
S-749	B - 15k	05/15/2018	05/15/2018	36,245	36,245	0	0	Internal Workshop	Service done Ad blue filters were replaced
R-561	Mudflaps	05/09/2018	05/09/2018		34,607		0	Internal Workshop	Service done Replaced LHR Mud flap
S-748	A	04/17/2018	17/04/2018	29	28,880	0	0	Internal Workshop	A service done
S-747	A	03/19/2018	19/03/2018	33	21,921	0	0	Internal Workshop	A service done Internal Workshop Service done Replaced damaged drive guard on the rear drivers side Tightened loose guard on the passenger steer
S-746	A	02/14/2018	14/02/2018	35	13,852	0	0	Internal Workshop	A service done Tightened all fitting at the base of the hoist as they were leaking
S-745	A	01/10/2018	01/10/2018		4,882		0	Internal Workshop	A service done