

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fault	Repairer / Notes	Cost / Invoice
R-9216	Head Light	04/23/2026	04/08/2026	685,727			Internal Workshop - Night Shift REPLACED BLOWN LHS HEADLIGHT GLOBE.	\$0.00
R-9087	Header tank	02/18/2026	03/12/2026	681,143			Internal Workshop - Night Shift REPLACD COOLANT HEADER TANK	\$0.00
R-9085	Solenoid	02/18/2026	03/12/2026	681,143			Internal Workshop - Night Shift REPLACED PISTON COOLING SOLENOID	\$0.00
R-8974	ABS valve	11/07/2025	03/12/2026	681,143			Internal Workshop - Night Shift REPLACED RHS STEER ABS VALVE LEAKING	\$0.00
S-7684	A	03/12/2026	12/03/2026	681,143		0	Internal Workshop - Night Shift FOUND REAR BAR BENT WITH BROKEN WELDS HAD TO STRAIGHTEN AND WELD. STRAIGHTEN LEFT AND RIGHT GUARD POLE AND REPLACE MISSING	\$0.00
R-9117	Ringfeder Mudflap	03/05/2026	03/05/2026	680,503		12122	MUDFLAP. REPLACE TRAILER LANDING LEG.	\$0.00
S-7607	B - 15k	02/11/2026	11/02/2026	675,000	15,000	0	Internal Workshop - Night Shift	\$0.00
S-7546	A	01/12/2026	12/01/2026	669,063		0	Internal Workshop - Night Shift REPLACED WIPER BLADES. SECURED HEADER TANK BOLTS. REPLACED ALL MUDFLAPS WITH BWC ONES.	\$0.00
S-7464	C - 30k	11/18/2025	11/18/2025	660,000	30,000	0	ACTUALLY DONE AT 660858 KM	\$0.00
S-7432	A	11/04/2025	04/11/2025	659,099		0	Internal Workshop - Night Shift Internal Workshop - Night Shift TIGHTNED 2ND AXLE DIFF HEAD BOLTS. REPLACED RHS STEER ABS VALVE. SUCCURED RUBBING HYDRAULIC HOSE.SECURED REAR MUDFLAPS.	\$0.00
S-7383	A	10/16/2025	15/10/2025	656,026		0	REPLACED HEADLIGHT BULBS.	\$0.00
S-7331	A	10/01/2025	22/09/2025	653,245		0	Internal Workshop - Night Shift	\$0.00
R-8639	Brakes	06/20/2025	09/11/2025	649,881			Internal Workshop - Night Shift REPLACED STEER BRAKES.	\$0.00
S-7286	A	09/10/2025	11/09/2025	649,881		0	Internal Workshop - Night Shift BOTH SIDES CHASSIES AND BODY MOUNT BOLTS TIGHTNED. REPLACED BOLTS IN FUEL TANK SPREADER BARS.	\$0.00
R-8703	Exhaust flex	07/08/2025	08/18/2025	645,624			Internal Workshop - Night Shift REPLACED BOTH EXHAUST FLEX UNDER CAB AND CLAMPS. Internal Workshop - Night Shift REPLACED D/S WINDOW WASHER JET. REPLACED WINDSCREEN WIPERS. REPLACED LEAKING FITTING ON CAB AIRBAG. REPLACED RHS REAR RED REFLECTOR. TIGHTNED PROP BOLTS. TIGHTNED TARP CABLES. FITTED NEW SEALS IN HYDRO COUPLER.	\$0.00
S-7208	B - 15k	08/18/2025	08/18/2025	645,000	15,000	0	REPLACED MUDFLAP ABOVE RINGFEDER.	\$0.00
R-8704	Cab Ride Height Val	07/08/2025	07/31/2025	642,951			Internal Workshop - Night Shift REPLAECED CAB RIDE HEIGHT VALVE AND AIR BAGS.	\$0.00
R-8702	Front diff	07/08/2025	07/31/2025	642,951			Internal Workshop - Night Shift REPLACED SEAL.	\$0.00
S-7153	A	07/28/2025	31/07/2025	642,951		0	Internal Workshop - Night Shift	\$0.00
R-8640	Seatbelt	06/20/2025	07/07/2025	637,947			Internal Workshop - Night Shift REPLACED D/S SEAT BELT.	\$0.00
S-7099	A	07/07/2025	07/07/2025	637,947		0	Internal Workshop - Night Shift	\$0.00
R-8531	Exhaust stack	05/07/2025	06/17/2025	667,671			REPLACED RHS EXHAUST STACK AND CLAMPS. Internal Workshop - Night Shift REPALCED ALL PLASTIC TARP ENDS. REPLACED PUSH PULL FITTING AT ENGINE. REPLACED LHS PARK LIGHT.	\$0.00
S-7032	D - 90k	06/16/2025	06/17/2025	630,000	90,000	0	ACTUALLY COMPLETED BY 634809 KM	\$0.00
S-7003	A	06/03/2025	04/06/2025	630,802		0	Internal Workshop - Night Shift REPLACED 2ND AXLE BRAKE SHOES AND DRUMS.	\$0.00

S-6934	A	05/07/2025	07/05/2025	624,231	0	SERVICE COMPLETED BY IZAAK H.				
R-8449	Batteries	02/24/2025	02/24/2025	614,979	0	REPLACED PREASURE SENSOR ON FRONT OFF CAB.		\$0.00		
R-7338	Exhaust manifold	03/28/2024	02/24/2025	613,789	0	Internal Workshop - Night Shift	Removed and replaced 4 x batteries.	\$0.00		
S-6837	B - 15k	02/20/2025	02/24/2025	615,000	15,000	0	Internal Workshop - Night Shift	REPLACED EXHAUST MANIFOLD GASKETS AND SLIP JOINTS.		
R-8451	Tarp	04/01/2025	02/19/2025	0	0	0	Internal Workshop - Night Shift	SERVICE COMPLETED BY IZAAK H.		
S-6772	A	01/23/2025	28/01/2025	609,551	0	0	Internal Workshop - Night Shift	ACTUALLY DONE AT 613789KM		
S-6719	A	12/13/2024	16/12/2024	603,592	0	0	Internal Workshop - Night Shift	Internal Workshop - Night Shift		
R-8198	FILLER TUBE	12/11/2024	12/04/2024	600,717	0	0	Internal Workshop - Night Shift	Cut and remove cable Remove all tarp ends both sides Fit new tarp end Cut and fit new cables x2 Adjust cables Test all good.		
R-8135	Machinery Defects	11/18/2024	11/18/2024	597,807	0	0	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.		
R-8011	air bag	10/09/2024	11/18/2024	597,807	0	0	Internal Workshop - Night Shift	SERVICE COMPLETED BY IZAAK H.		
R-7677	Dipstick	07/09/2024	11/18/2024	597,807	0	0	Internal Workshop - Night Shift	REPLACED OIL FILLER PIPE AND FITTINGS INTO SUMP.		
R-8089	Ride height valve	10/28/2024	11/13/2024	598,627	0	0	Internal Workshop - Night Shift	REOLACED SUMP GASKET DUE TO IT HAVING TO BE PULLED OFF TO FIX PROBLEM. REPLACED OIL AND FILTERS.		
R-7816	TRANS COOLER LINI	08/30/2024	11/13/2024	598,627	0	0	Internal Workshop - Night Shift	REPLACED P/S STEP. BENT RINGFEDER HANDLE IN POSITION		
S-6649	C - 30k	11/13/2024	13/11/2024	600,000	30,000	0	0	Internal Workshop - Night Shift	ALL GOOD NOW. REPLACED BOTH 2ND AXLE AIR BAGS.	
S-6602	A	10/17/2024	25/10/2024	591,729	0	0	Internal Workshop - Night Shift	REPLACED BOTH AIRBAGS ON 2ND AXLE		
R-8069	Electrical Fault	10/22/2024	09/30/2024	585,287	0	0	Internal Workshop - Night Shift	FITTED WHOLE NEW DIPSTICK INCLUDING PIPE GOING INTO SUMP.		
R-7815	Cab shocks	08/30/2024	09/27/2024	585,287	0	0	Internal Workshop - Night Shift	RIDE HEIGHT VALVE NOT LEAKING ANYMORE.		
S-6559	B - 15k	09/30/2024	09/27/2024	585,000	15,000	0	0	Internal Workshop - Night Shift	REPLACED TRANS COOLER LINES.	
R-8065	Transmission	10/22/2024	09/12/2024	588,263	0	0	0	Internal Workshop - Night Shift	SERVICE COMPLETED BY IZAAK H.	
R-7859	Drag link	09/09/2024	09/02/2024	578,845	0	0	0	Internal Workshop - Night Shift	REPLACED LHS ROOF LIGHT.,	
R-7427	Air Leak	04/11/2024	08/29/2024	578,623	0	0	0	Internal Workshop - Night Shift	ACTUALLY DONE AT 598627 KM	
S-6488	A	08/29/2024	29/08/2024	578,623	0	0	0	Internal Workshop - Night Shift	INTERNAL WORKSHOP - NIGHT SHIFT	
S-6444	C - 30k	07/30/2024	07/30/2024	570,000	30,000	0	0	0	Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.
R-7676	Water pump	07/09/2024	07/12/2024	566,516	0	0	0	0	Internal Workshop - Night Shift	REPLACED WORN DRAGLINK
									Internal Workshop - Night Shift	REPLACED FITTING.
									Internal Workshop - Night Shift	SERVICE COMPLETED BY IZAAK H.
									Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.
									Internal Workshop - Night Shift	R/R RHS BONNET INDICATOR.
									Internal Workshop - Night Shift	R/R 2 CAB ROOF LIGHTS.
									Internal Workshop - Night Shift	REPLACED BOTH EXHAUST ELBOWS.
									Internal Workshop - Night Shift	ACTUALLY DONE AT 571422 KM
									Internal Workshop - Night Shift	Replaced water pump and both tensioners. Reused coolant.

						Internal Workshop - Night Shift	SERVICE COMPLETED BY JARROD H.	
							WATER PUMP LEAKING.	
							ORING AT DIPSTICK TUBE AND OIL FILLER AT SUMP LEAKING	
							TIGHTEN LOOSE V-BAND CLAMP AT DPF.	
S-6360	A	07/08/2024	08/07/2024	365,312	0		FIT NEW BOLT TO MISSING GUARD BRACKET.	\$0.00
R-7754	Alternator	08/06/2024	06/19/2024	560,575			agrade AGRADE AUTO FOUND FAULTY ALTERNATOR REMOVED AND REPLACED.	\$0.00
R-7280	Exhaust elbow	03/13/2024	05/28/2024	554,727	0	Internal Workshop - Night Shift	Replaced both exhaust stack elbows left and right and all clamps.	\$0.00
S-6233	A	05/10/2024	28/05/2024	554,727	0		A service completed by Tyson E.	\$0.00
R-7476	Tyre	05/03/2024	05/03/2024	549,205	0	Internal Workshop	Repair flat drive tyre RHS inner	\$0.00
R-7475	Tarp cable	04/23/2024	04/23/2024	548,317	0	Internal Workshop	Repairs to RH tarp cable as required Refit old cable with new clamps Fit cable stops.	\$0.00
R-6955	Trailing arm bushes	01/12/2024	04/16/2024	546,143	0	Internal Workshop - Night Shift	Replaced all trailing arm bushes and D bushes Wheel alignment done by ST mechanical.	\$0.00
							1/2 air line inside RH chassis rail split	
							leaks under service brake - replaced section	
							Elbows at bottom of exhaust stacks rusted through and require replacement - JC done.	
							Exhaust manifold leaking at egl 3 and 4 suggest doing slip joints at same time - JC done.	
S-6187	A	04/11/2024	11/04/2024	545,845	0		Air leak on firewall - replaced fitting	
							Air leak on brake valve/relay - 1/2 BSP - 5/8 airline 45 deg need part. - JC	\$0.00
							Exhaust manifold gaskets starting to leak	
							Oil in Purge valve - The compressor must be passing oil	
S-6145	E - 270k	03/21/2024	03/21/2024	540,000	437,985	0	Actually done at 541780km.	\$0.00
S-6119	A	03/12/2024	12/03/2024	539,067	0		Elbows into both exhaust stacks starting to rust through. JC.	\$0.00
S-6084	A	02/22/2024	22/02/2024	534,562	0		Hoist leaking	\$0.00
							R&R leaking air fitting on compressor.	
S-6023	A	01/24/2024	24/01/2024	528,822	0		Air leaking from PTO solenoid on LH side of chassis.	\$0.00
R-7210	Seatbelt	01/23/2024	01/23/2024	528,467	0	Internal Workshop - Night Shift	Fit new seat belt buckle. Remove seat cushion and replace seatbelt buckle.	\$0.00
R-6592	Air Bags	09/22/2023	12/06/2023	521,793	0	Internal Workshop - Night Shift	Rear axle airbags perished - need replacing. Replaced prior as per attached.	\$0.00
S-5958	A	12/06/2023	06/12/2023	521,793	0			\$0.00
R-7032	Suspension	11/20/2023	11/20/2023	517,340	0	Internal Workshop - Night Shift	Replaced broken penard rod 3rd axle supplied by Mack.	\$0.00
S-5908	A	11/07/2023	07/11/2023	514,212	0			\$0.00
							Internal Workshop - Night Shift	Fit new: drive brake boosters - s-cam bushes - Slack adjusters - Wheel bearings - Hub seals - brake shoes - brake drums Adjust brakes, refit wheels. Torque wheel nuts, refit wheel nut indicators. Fit 4x new w/ speed sensors. Replace both diff oils.
R-7046	Brakes	10/26/2023	10/26/2023	513,396			Replaced grade gripper service brake valve, due to this being the cause of all that damage.	\$0.00
I-15	Machinery Inspectio	10/05/2023	10/13/2023	510,446				\$0.00

R-6593	Oil Spinner	09/14/2023	10/12/2023	510,446	0	Internal Workshop - Night Shift	Need o-ring kit for oil spinner on LH side of engine. This has been done,	\$0.00
S-5854	B - 30K	10/12/2023	10/12/2023	510,446	28,683	0		\$0.00
R-6679	Machinery Defects	10/05/2023	10/06/2023	508,727	0	Internal Workshop - Night Shift	replaced both boosters and slack adjusters all ok done buy jarrod	\$0.00
R-6654	Wipers	10/06/2023	10/04/2023	507,998	0		Fit new wiper blades.	\$0.00
R-6652	Pre Machinery Inspe	10/03/2023	10/03/2023	507,998	0	Internal Workshop - Night Shift		\$0.00
R-6580	Air Bag	09/19/2023	09/19/2023	505,059	0	Internal Workshop	R&R 3rd axle left side air bag. Rear axle airbags perished, suggest replace - JC	\$0.00
S-5792	A	09/08/2023	14/09/2023	503,291	0		Need o-ring kit for oil spinner on LH side of engine - JC Chips in LH windscreen.	\$0.00
R-6412	Oil Spinner	07/06/2023	09/08/2023	0	0	Internal Workshop - Night Shift	Oil spinner Left side of motor needs replacing. Leaking from hose from engine breather connection. Replaced O Rings as per Jay Audit 8/9/23	\$0.00
R-6533	Exhaust Brake	08/16/2023	08/17/2023	495,293	0	Internal Workshop - Night Shift	Fitted new exhaust brake solenoid.	\$0.00
R-6414	Bump stop	07/06/2023	08/17/2023	495,293	0	Internal Workshop - Night Shift	Replaced both shocks and mounts.	\$0.00
R-6365	Air Fitting	06/15/2023	08/17/2023	495,293	0		Air fitting at foot valve leaking 1/2 to 1/2 fitting. 1/2 BSP to 1/2 airline elbow 90degrees. Replaced elbow.	\$0.00
R-6367	Exhaust flex	06/15/2023	08/15/2023	494,883	0	Internal Workshop - Night Shift	Short exhaust flex leaking - fixed.	\$0.00
S-5728	A	08/04/2023	15/08/2023	494,883	0			\$0.00
R-6410	Ringfeder	07/05/2023	07/24/2023	489,362	0		Re-kited ringfeder	\$0.00
S-5688	A	07/24/2023	24/07/2023	489,362	0			\$0.00
T-129	Drive Rotation	07/20/2023	07/20/2023	488,562	0	Internal Workshop - Night Shift	2 drive tyres LH drive rotated	\$0.00
R-6223	Radiator	05/24/2023	07/07/2023	484,808	6440		R&R Radiator & top & bottom hoses and clamps. R&R short flex exhaust.	\$0.00
R-6411	Brake Shoes, Hub se	07/06/2023	07/06/2023	484,439	0	Internal Workshop - Night Shift	Remove hub and brakes on 3rd axle RH side Degrease hub and axle R&R wheel bearings and hub seal R&R brake shoes and drum Fit wheels and tension Adjust brakes.	\$0.00
R-6366	Williams valve	06/15/2023	07/05/2023	484,091	0	Internal Workshop - Night Shift	Williams valve no longer leaking.	\$0.00
S-5629	A	07/05/2023	05/07/2023	484,091	0		Radiator Leaking Tightened both front body mount bolts Re-tension diff mount bolts. No Grease and Check - B service only.	\$0.00
S-5607	B - 30K	06/22/2023	06/22/2023	481,763	30,850	0	Replaced ringfeder wear pad. Hoist leaking.	\$0.00
S-5578	A	06/15/2023	15/06/2023	480,273	0		R&R 3rd axle RH side air bag.	\$0.00
S-5527	A	05/24/2023	24/05/2023	472,809	0			\$0.00
S-5482	A	05/04/2023	04/05/2023	467,743	0	Internal Workshop - Night Shift	Completed by Tyson. Remove window tint glue. R&R air fitting on LHS gearbox.	\$0.00
R-6110	Window regulator	04/12/2023	04/17/2023	463,430	0	Internal Workshop - Night Shift	REPLACE RHS WINDOW REGULATOR Tyson replaced.	\$0.00
R-5912	Cab shocks	02/28/2023	04/17/2023	463,430	0	Internal Workshop - Night Shift	Rear cab shockies U/S; need replacing. Tyson - replaced both sides.	\$0.00
R-5910	Drag link	02/28/2023	04/17/2023	463,430	0	Internal Workshop - Night Shift	Drag link U/S; needs replacing. Tyson replaced.	\$0.00
R-5909	air bag	02/28/2023	04/17/2023	463,430	0	Internal Workshop - Night Shift	RH cab air bag U/S; needs replacing. Tyson - replaced both sides.	\$0.00

R-5907	Williams valve	02/28/2023	04/17/2023	463,430			Adjusted William's valve and now has a slight air leak; will need to be replaced. Jay - this has stopped leaking.	\$0.00
R-5755	Exhaust flex	01/31/2023	04/17/2023	463,430			Internal Workshop - Night Shift Long exhaust flex from behind turbo starting to leak. Tyson - replaced.	\$0.00
S-5435	A	04/17/2023	17/04/2023	463,430			Internal Workshop - Night Shift Completed by Tyson.	\$0.00
R-6121	Drawbar	04/06/2023	04/06/2023	461,447			Internal Workshop - Night Shift Tyson - R&R drawbar leg.	\$0.00
R-5906	Valve set	02/28/2023	04/03/2023	460,218			Internal Workshop - Night Shift Valve set not done during Feb C service. Tyson - carry out valve clearances.	\$0.00
T-114	Steer Tyre	03/27/2023	03/27/2023	0	0		Bridgestone Wacol Replaced position 1 left hand side steer tyre on site.	\$0.00
S-5367	A	03/22/2023	22/03/2023	456,790	0		Internal Workshop - Night Shift Completed by Tyson.	\$0.00
R-6087	Tyre	03/08/2023	03/08/2023	451,644			Bridgestone Wacol Replaced DS steer tyre due to damage. Called out to site. Invoice attached.	\$0.00
R-5947	Air con	03/02/2023	03/02/2023	451,684			Internal Workshop - Night Shift No A/C. Garth - Checked A/C and found A/C button not turned on. Tested all and working okay.	\$0.00
R-5756	Cab shocks	01/31/2023	02/28/2023	450,913			Internal Workshop - Night Shift Front cab shockies U/S. Garth - Replaced front cab shockies with new.	\$0.00
							Internal Workshop - Night Shift Completed by Garth. 1st drive shockies U/S. Removed and replaced with new. Side tool box loose and door hinges U/S. Tightened up tool box and replaced door hinges with new; tested okay. Tightened and adjusted door lock. RH front guard missing bolt and loose; replaced missing bolt and re-secured. Tightened up body mounts.	
S-5322	C - 90K	02/28/2023	02/28/2023	450,913	92,230	0	Adjusted William's valve and now has a slight air leak; will need to be replaced (R-5907). RH cab air bag U/S; needs replacing (R-5909). Drag link U/S; needs replacing (R5910). Rear cab shockies U/S; need replacing (R-5912). Hoist ram leaking.	\$0.00
R-5815	Aircon	02/03/2023	02/06/2023	444,429		0	Internal Workshop - Night Shift REPLACE AC COMPRESSOR DUE TO OLD ONE LETTING GO. Garth - fit new a/c compressor. Fit new TX valve. Fit new receiver dryer. Re-gased system. VCV invoice attached.	\$0.00
R-5864	Stickers	02/02/2023	02/02/2023	444,320			Internal Workshop - Night Shift Tyson - Replaced Holcim stickers on front bumper.	\$0.00
							Internal Workshop - Night Shift Completed by Garth. Fit new mud flap and straighten pole on LH rear. Fit new number plate to front bar. Tighten up loose over head compartment bolts. Long exhaust flex from behind turbo starting to leak (R-5755). Front cab shockies U/S (R-5756). Leaking oil from clip stick (minor)	
S-5239	A	01/31/2023	31/01/2023	443,544		0	Hoist leaking oil.	\$0.00
R-5754	Belts	01/25/2023	01/25/2023	443,543		0	Internal Workshop - Night Shift REPLACE ALL ENGINE BELTS AS AC BELT BROKE. garth - fit new belts.	\$0.00
R-5787	Rims	01/19/2023	01/19/2023	442,372			Internal Workshop - Night Shift Tyson - Fit new rims to truck steer. Flip tyres on rims.	\$0.00
R-5415	Brake Reline	11/07/2022	12/19/2022	438,077			Internal Workshop - Night Shift Brake reline on both drives next service. Izaak - completed full brake re-line on drives.	\$0.00

S-5188	A	12/19/2022	19/12/2022	438,077	0	Internal Workshop - Night Shift Completed by Izaak. Full brake re-line on drives done (recorded on R-5415). Replaced coupling seals.	\$0.00	
R-5586	A/C fan, Batteries	12/06/2022	12/07/2022	434,884		Internal Workshop - Night Shift Garth: removed broken a/c blower fan and replaced with new. Fit 4 x new batteries supplied by Maxi Parts. Replaced 2 x tie down bolts. Maxi Parts invoice attached.	\$0.00	
R-5588	Window switch	12/01/2022	12/01/2022	433,175		Internal Workshop - Night Shift DS window switch faulty; swap with PS. Garry swapped over. Internal Workshop - Night Shift Completed by Tyson. Coolant leaking from top radiator hose - tightened it up. Monitor. R&R both rear mud flaps.	\$0.00	
S-5119	A	11/28/2022	28/11/2022	432,049	0	R&R broken grease nipple at LH king pin.	\$0.00	
R-5579	Air Leak	11/11/2022	11/11/2022	427,556		Internal Workshop - Night Shift Air leak from elbow into compressor for governor valve; please investigate. Tyson - repaired pin hole leak in air line inside chassis.	\$0.00	
R-5464	Fuel tank	11/08/2022	11/08/2022	426,482		Internal Workshop - Night Shift Garth Refit fuel tank on RHS with new rubber on tank straps and new fuel line.	\$0.00	
R-5381	Coolant hose	11/04/2022	11/07/2022	426,482	0	Internal Workshop - Night Shift Replace radiator hose and top up coolant Garth - cut split end of hose and refit. This didn't work. Ian replaced hose on roadside and added 10L of coolant.	\$0.00	
R-5140	Cab Ride Height Val	09/09/2022	11/07/2022	426,482		Internal Workshop - Night Shift cabin ride height valve leaking. Garth - replaced QF with new.	\$0.00	
R-5005	Shock Absorber	08/18/2022	11/07/2022	426,482		Internal Workshop - Night Shift 2nd axle LHS shock absorber leaking. Garth - replaced 2nd axle LHS & RHS shocks over with new. Completed by Garth. Pressure test cooling system; found top radiator tank leaking. Replaced LHS tarp cable with new/	\$0.00	
S-5066	A	11/07/2022	07/11/2022	426,482	0	Brake reline on both drives next service (R-5415). Internal Workshop - Night Shift Machinery defect: fitting into compressor. Jay: replaced 90	\$0.00	
R-5537	Compressor	11/05/2022	11/05/2022	425,928		degree fitting going into compressor.	\$0.00	
S-4987	B - 30K	10/12/2022	10/11/2022	419,640	29,579	0	Izaak.	\$0.00
S-4952	A	09/28/2022	28/09/2022	415,701	0	Internal Workshop - Night Shift Izaak - replaced missing RH rear mud flap.	\$0.00	
R-5007	Radiator	08/18/2022	09/09/2022	410,428		Radiator top tank leaking RHS. Tyson - tank is fine or has been done previously.	\$0.00	
R-5006	Engine Oil	08/18/2022	09/09/2022	410,428		Engine oil leak from oil cannister. Tyson - replaced o'ring.	\$0.00	
R-4726	air bag	07/19/2022	09/09/2022	410,428		RHS cab air bag leaking. Tyson - air bag been done previously. Tyson - cabin ride height valve leaking (R-5140). Drained some coolant and removed top radiator hose and inspected. Hose was all good and re-installed. Topped up coolant.	\$0.00	
S-4875	A	09/08/2022	09/09/2022	410,428	0	Removed oil cannister and replaced o'ring.	\$0.00	
R-4634	Exhaust elbow	07/06/2022	08/18/2022	405,139		RHS exhaust elbows just before stack U/S. Izaak - replaced. Izaak - 2nd axle LHS shock absorber leaking (R-5005). Engine oil leak from oil cannister (R-5006). Radiator top tank leaking RHS (R-5007). Chip in windscreen drivers side. Replaced windscreen squirter #85116361 x 2 of.	\$0.00	
S-4798	A	08/18/2022	18/08/2022	405,139	0	Exhaust elbow replace RHS #21827201	\$0.00	

R-4965	Seatbelt	08/17/2022	08/17/2022	404,760	0	FIT NEW D/S SEABELT AS OLD ONE KEEPS JAMMING garth - Removed and fit new seat belt.	\$0.00	
T-70	Tyre	07/29/2022	07/27/2022	397,453	0	Bridgestone Wacol Fit 8 x drive tyres to 2nd and 3rd axle.	\$0.00	
R-4725	Steer Reline	07/19/2022	07/20/2022	397,218		Front steer reline due this week. Izaak - replaced brakes, shoes and drums.	\$0.00	
R-4677	Body up alarm	07/07/2022	07/19/2022	396,882	4943	Not Working. Check Body up alarm and light - truck and trailer. Trailer alarm not working. Garth - repaired wiring and tested oaky.	\$0.00	
R-4313	Rubber	05/16/2022	07/19/2022	396,882	4567	Other. . Fuel tank rubber hanging off under truck, driver's side. Garth - cut away loose rubber. Garth - front steer reline due this week (R-4725). Top radiator tank leaking. All drive tyres U/S. Hoist ram leaking oil. Replaced tarp cables with new.	\$0.00	
S-4717	A	07/19/2022	19/07/2022	396,882	0	RHS cab air bag leaking.	\$0.00	
S-4716	B - 30K	06/29/2022	06/29/2022	390,061	31,378	0	Jay - the grease and check was not due during this B service, so those items were crossed out on this service sheet with the A service sheet completed.	\$0.00
R-4641	Turbo	06/27/2022	06/27/2022	391,239	0	Fit new turbo, clean oil from exhaust and fit exhaust. Topped up engine oil (9 litres). Replaced exhaust elbow from PDF. RHS elbow before exhaust stack U/S. Repair air leak with a Q/F fitting.	\$0.00	
R-3944	Shocky	02/22/2022	06/16/2022			Fit new tail shaft. Degrease oil from engine and chassis. 2nd axle LH shocky leaking. Garth - removed shocky found all okay.	\$0.00	
S-4642	A	06/15/2022	16/06/2022	388,986	0	Garth: RHS exhaust elbows just before stack U/S - R4634. Replaced LHS 1st drive outer and inner tyres. Replaced LHS and RHS 2nd drive tyres. Repair air line at rear of truck.	\$0.00	
S-4554	A	05/23/2022	23/05/2022	381,395	0	Oil leak at gearbox oil filter housing; tightened oil cooler hoses and degreased area. Monitor.	\$0.00	
R-4294	Tyres	05/09/2022	05/10/2022	378,092	0	4541 Replaced illegal tyre with run out.	\$0.00	
R-4293	Tyre	05/09/2022	05/10/2022	378,092	0	4540 Replaced with run out.	\$0.00	
R-6928	Air compressor, DPF	04/28/2022	05/05/2022	279,947	6,769	VCV Replace air compressor, cooling coil and airdrier as per invoice attached. Replaced DPF.	\$0.00	
R-4248	Body up alarm	05/04/2022	05/04/2022	376,864	0	Found loose wire on truck alarm - all fixed. Trailer led light slightly working - suspect light is stuffed.	\$0.00	
R-3890	Engine	02/13/2022	04/27/2022	375,550	0	4194 Replaced DPF which fixed this problem.	\$0.00	
S-4475	A	04/21/2022	27/04/2022	375,550	0	Warning light for front body up not working. No audible alarms when either body is up. Jay created job cards for these already.	\$0.00	
R-4214	Tyres	04/26/2022	04/26/2022	374,440	0	4482 No suitable tyres in stock. Superficial damage has not penetrated sideways belts.	\$0.00	
R-3966	Indicators	03/02/2022	03/28/2022	370,586	0	4298 This was done wen indicator stalk replaced.	\$0.00	
S-4398	A	03/29/2022	28/03/2022	370,586	0	Oil leak engine breather LHS. Oil leak oil pressure switch. 2nd axle LH inner tyre U/S - replaced with run outs. Air leak at bulk head in fire wall - pics sent to Jay. Hoist leaking.	\$0.00	
R-4164	Tyres	03/27/2022	03/27/2022	370,028	0	Replaced 3rd axle LHS tyres with runouts.	\$0.00	
R-4017	Tyre	03/09/2022	03/15/2022	369,384	0	4317 Checked - tyre not flat; full pressure and no damage.	\$0.00	
R-3933	Indicators	02/20/2022	02/22/2022	365,979	0	4262 Jay removed mechanism that turns blinker off. R&R indicator stalk.	\$0.00	
R-3610	Mudflap	11/14/2021	02/22/2022	365,979	0	3921 Internal Workshop Repaired rear LH mud flap.	\$0.00	

							R&R indicator stalk.		
							Repair LH rear mud flap.		
							Repaired LH number plate light.		
							Repaired air line om Suzi.		
							Repaired 7 pin wires at Suzi.		
							Air leaks from firewall fittings (has a screw in it).		
							2nd axle LH shocky leaking.		
S-4299	A	02/21/2022	22/02/2022	365,979	0		Gear box oil leak from filter housing.		\$0.00
							Mack Brisbane Clutch replaced by Mack and clutch actuator. Resealed timing cover. New		
R-3700	Clutch, Clutch Actu	12/08/2021	01/18/2022	358,683	0	3989	exhaust manifold gaskets - all.		\$0.00
R-3688	Header tank	12/14/2021	01/18/2022	358,683	0	4009	Fixed by Mack.		\$0.00
							1st drive LH shocky monitor weeping.		
							Fitted 2 x runouts read axle LHS.		
							06/04/2022		
							2nd axle shock leaking LHS.		
							Air leak from firewall fitting (blank one).		
							Front drive rear pinion seal leaking.		
							This was originally a B service and completed 19/01/2022, but it should have been a C service.		
							Was changed over to a C service on 31/03/2022 with the C components completed 06/04/2022.		
S-4167	C - 90K	01/10/2022	01/18/2022	358,683	88,683	0	This will realign the services.		\$0.00
R-3720	Header tank	12/14/2021	12/14/2021	354,754	0		Internal Workshop Replaced header tank and hoses Work done by Jack		\$0.00
R-3623	Indicators	11/27/2021	12/08/2021	353,266	0	3954	Internal Workshop Done by Garth.		\$0.00
							Replaced indicator stalk due to them not working.		
							RH taillight needs replacing.		
S-4117	A	12/06/2021	06/12/2021	352,570	0		Resealed 1st drive input spline.		\$0.00
R-3578	Gearbox	11/09/2021	11/24/2021	350,292	0	3912, 39	Internal Workshop Replaced gear shift panel supplied by Mack.		\$0.00
R-3583	Triangles	11/18/2021	11/21/2021	349,491	0	3941	Internal Workshop Replaced triangles supplied by Maxi parts.		\$0.00
R-3634	Mud Flaps	11/14/2021	11/14/2021	0	0		Internal Workshop Fit and straightened 2 x missing rear flaps.		
R-3579	Lights	11/10/2021	11/14/2021	347,617	0	3916, 39	Internal Workshop Repaired wiring, all okay.		
R-3478	ABS Light	10/26/2021	11/11/2021	347,616	0	3853	Internal Workshop Jack. Cleaned and fitted ABS wheel sensor and cleared codes.		
							Internal Workshop Jack.		
							Refit ring feeder.		
S-4045	A	11/10/2021	11/11/2021	347,616	0		Fitted draglink.		
R-3470	Brakes	10/19/2021	10/25/2021	344,193			Internal Workshop Jack. Replaced all drive drums and shoes. Replaced 3rd axle LHS hub seal.		
S-3978	A	10/19/2021	19/10/2021	343,551	0		Internal Workshop Jack.		
R-3544	Height control valve,	10/17/2021	10/17/2021	343,301	0		Internal Workshop Fit new flasher unit. Fit seat height control valve.		
							Internal Workshop Done by Jack.		
							Drive brakes need doing - reminder next service.		
							Input 1st diff loose and leaking bolts were also loose holding tail shaft to yoke. Fitted new input seal and yoke sleeve.		
							Hoist leaking.		
							Ring feeder will need kit soon.		
							Tightened rear guard LHS.		
S-3882	A	09/28/2021	28/09/2021	343,198	0		Fitting leaking on footwell of fire wall - repalce.		

						Work done by Jarrod. Replaced power steering pump.	
						Ring feed wear pad - done	
						LH rear guard post loose - done	
						LH rear mud flap - done	
						Both tarp cables and rollers - done	
S-3809	A	09/01/2021	01/09/2021	340,454	0	Front lab shocks and mounts - done	
R-3071	Water pump	07/15/2021	07/15/2021	332,756	0	Internal Workshop Replaced water pump	
						Internal Workshop Service done by Jarrod	
S-3698	B - 15k	07/09/2021	07/15/2021	329,343	26,410	Replaced EBS valve	
R-2959	Coolant leak, Tyres	06/23/2021	06/23/2021	324,740		Internal Workshop Replaced both heater hoses Had to put 15L in header tank this morning	
						Internal Workshop Replaced 2 x mudflaps Secured & straightened guard post Job done by Jarrod	
R-2960	Mudflaps, Mudguarc	06/17/2021	06/17/2021	326,787			
R-2871	Steering	05/31/2021	06/17/2021	326,787		Internal Workshop Repaired steering - job done by Garth	
R-2847	Tyres	05/24/2021	06/17/2021	326,787		Internal Workshop Drive rotation done by Garth	
						Internal Workshop Service done by Garth	
						Adjusted bonnet	
						Re-seal 1st drive spline	
S-3622	A	06/17/2021	17/06/2021	326,787		Defect: Coolant sensor broken	
						Internal Workshop Tightened LHR guard post Replaced LHR guard mudflap Replaced ringfeder mudflap Straightened bent bracket LHR next to ringfeder Replaced LH tarp cable	
R-2971	Mudflaps, Mudguarc	06/15/2021	06/15/2021			Internal Workshop Remove x 2 gearbox mounts & replace with new - test - ok Removed exhaust flex and replaced with new - test - ok Job done by Garth	
R-2906	Gearbox mounts	06/04/2021	06/04/2021	323,170		Internal Workshop Replaced 1 x missing reflector - job done by Garth	
R-2692	Reflectors	04/13/2021	05/13/2021	316,152		Internal Workshop Service done by Garth	
						Fumes still getting into cab	
S-3500	A	04/29/2021	29/04/2021	313,085		Cab mounts u/s	
						Internal Workshop Service done by Garth	
						Refit diff lock switch on dash	
						Replaced 2 x wiper blades	
						Tightened tipper ram bolts to spec - test - ok	
						Tightened chassis bolts	
S-3432	A	04/08/2021	08/04/2021	307,710	7,869	Defect: missing red reflector LHS	
R-2624	Wheel alignment	03/19/2021	03/19/2021	304,975		D & L Laser Alignment Robbie took truck & trailer for wheel alignment	
						Internal Workshop Jarrod travelled to Mack for parts Removed tie rod - replaced tie rod Tap measure wheel alignment Fit runout to LH steer Refit tailshaft Refit pressure protect to air dryer	
R-2589	Tie rods	03/11/2021	03/11/2021	303,466		Replaced 4 x wheel nuts Still need 1 x more for LH steer - no stock left	
						Internal Workshop Service done by Jarrod	
						1st drive output splines leaking - resealed	
						DEFECTS: Exhaust flex leaking back of turbo	
						Movement in ringfeder pin	
						Nut missing RH cab mount	
						Chip LH windscreen	
						Suspect sagged engine mounts	
S-3339	B - 15k	02/26/2021	03/09/2021	302,933	29,847	7,726	RHF hubcap missing

S-3340	D - 90k	02/25/2021	03/08/2021	270,000	12,742	7,726	Internal Workshop SERVICE COMPLETE ON THE 9/03/2021 AT 302933KS. ADJUSTED BACK IN GEARBOX TO 270000 TO MAKE THE SERVICE INTERVAL REALIGN. Service done by Jarrod Internal Workshop Service done by Laine
S-3328	A	02/18/2021	18/02/2021		298,217	7,589	Chip in RH windscreen
S-3257	A	01/27/2021	27/01/2021		292,860	7,431	Internal Workshop Service done by Laine Internal Workshop Service done Drive tyres worn low Small chip LH lower windscreen Fault code - SPN131 FMI2 - engine module Clamps at dump pipe & 1st flex after dump slight soot marks Cab mounts & cab shocks worn Oil weep at engine breather canister
S-3210	A	01/04/2021	06/01/2021		289,072	7,326	
R-2229	Chassis	12/11/2020	12/11/2020		286,890	7,260	
R-2222	Hoist Valve	12/07/2020	12/07/2020		285,455	7,218	Replaced valve, topped up hydraulic oil and degreased and washed.
R-1953	Hose	11/25/2020	11/25/2020		281,878	0	Internal Workshop Replaced hose & topped up oil with 68 Internal workshop A service done Fixer Windows repaired chips in front windscreen Replaced DS seatbelt Replaced ringfeder wear pad Replaced 2 x drive tyres Replaced LHR guard Checked brake strokes
S-1565	A	11/12/2020	12/11/2020		278,162	0	
R-1205	Grab handles	11/05/2020	11/05/2020		277,025	0	Internal Workshop Refit grab handles & replaced bolts Internal Workshop A service done Drive tyres need replacing - fitted 2 x runout to 3rd axle LH outer & 3rd axle RH inner
S-652	B - 15k	10/20/2020	10/20/2020	273,086	15,828	6,882	Replaced LH tarp cable Swapped wiring over on switch - definitely switch problem 9/10/2020- replaced DS window switch
R-406	Window Switch	10/06/2020	10/09/2020		270,965	0	
R-405	Air Horn	10/09/2020	10/09/2020		270,965	0	Inspected and replaced horn assy - all good now Internal Workshop Service done Repaired puncture 2nd axle RHS inner Replaced mudflap chain on ringfeder flap
S-556	A	10/01/2020	01/10/2020		269,144	6,764	Horn burnt out - need a new one
R-316	Air Fitting, Cab shocl	09/08/2020	09/08/2020		263,889	6,621	Internal Workshop Replaced rear axle with 4 x Hankook runouts Replaced air fitting on top of the gearbox Replaced both rear cab shockies Replaced fire extinguisher with new one & bracket Inspect body up alarm - still faulting - replaced indicator switch Replaced controller on tarp Inspected park brakes - brakes release find - could not fault

S-496	A	08/31/2020	04/09/2020	263,888	0	Service done Replaced frayed RH & LH tarp cables Driver complaint: indicator fault & ABS light on dash - Dash light not present at service & could not fault indicators Found body up light for trailer on all the time - body up buzzer for trailer on all time - suggest replacing body up switch on trailer DEFECTS: Air leak from fitting on top of g/box - none in stock Rear cab shockies leaking 12 horn dull / worn out 3rd axle LH tyres worn low Wrong size fire extinguisher for bracket		
S-426	D - 90k	08/10/2020	08/10/2020	257,258	11,528	6,435	A service done Done valve set	
S-344	A	07/14/2020	07/14/2020	250,357	6,257	Service done Internal Workshop Service done Replaced purge valve Repaired air leak at firewall		
S-283	D - 90k	06/23/2020	06/24/2020	245,730	6,137	Topped up gearbox oil A service done		
S-224	A	06/04/2020	06/05/2020	241,279	0	Replaced Williams Valve		
R-58	Brakes	05/26/2020	05/27/2020	238,876	0	Replaced leaking Williams valve & checked the brake pressure - all ok Relined drive axles Checked Williams Valve pressures - needs new Williams valve - started leaking after adjustment		
R-59	Brakes	05/25/2020	05/25/2020	238,508	0	Internal Workshop A service done		
S-848	A	05/18/2020	18/05/2020	237,094	0	Replaced LHS 2nd axle slack adjuster - was wound down last G/C Internal Workshop Road tested engine brake - both stages working - difference in sound between the 2 but no change in performance - noticed what sounded like a boost leak - checked hoses - replaced 1 x clamp & tightened clamp at DPF & at turbo - re-road tested - noise still there very loud - needs further investigation		
R-642	Engine brake	05/13/2020	05/13/2020	236,200		Internal Workshop A service done LHF drive brake over-stroking - adjusted but needs new slack adjuster		
S-847	A	04/21/2020	21/04/2020	230,845	0	DEFECT: very minor movement both steer axle wheel bearings		
R-641	Indicators	04/16/2020	04/16/2020	229,656		Internal Workshop Could not fault indicators - they self-cancel just like a car Internal Workshop Replaced indicator switch Broken horn button when removing steering wheel to access indicator switch - got replacement at Mack & fitted		
R-640	Lights	04/03/2020	04/03/2020	227,214		Internal Workshop Inspected hoist pins truck & trailer - all good		
R-639	Hoist pin	04/03/2020	04/03/2020	227,214				
R-638	Tyres	03/31/2020	03/31/2020	226,382		Internal Workshop Tyre rotation - moved back drive tyres to front drive & replaced 4 x drives with new ones and put them on the front - tensioned rims (tyres out of back shed)		
R-637	Battery	03/27/2020	03/27/2020	226,079		Internal Workshop Fitted 4 x new batteries supplied by Maxiparts Repaired damaged wiring at EBS and Anderson plug Internal Workshop Service done Replaced RHR mudguard Replaced starter motor Replaced both tarp cables Engine oil sample done		
S-846	C - 90K	03/10/2020	03/10/2020	220,771	30,289	0	DEFECTS: 2nd axle tyre poor condition	\$0.00

R-636	Gaskets	02/13/2020	02/13/2020	213,447		Internal Workshop Replaced 6 x gaskets on turbo manifold to head - tightened 2 x exhaust clamps under cab - replaced o'ring in intake coupling at turbo - jump start - road tested ok Internal Workshop A service done Could NOT do diff samples - no sample bottles DEFECTS: monitor minor play both steer axle wheel bearings Exhaust manifold gasket leaking MAJOR BAD!!, LHR guard damaged	
S-845	A	02/03/2020	03/02/2020	212,249	0	LHR guard damaged	
R-635	Tyres	01/10/2020	01/10/2020	205,804		Internal Workshop Fitted 4 x runouts to 2nd axle Internal Workshop A service done Replaced diff oils & sampled DEFECTS: exhaust manifold is leaking multiple cylinders - heavy soot at manifold gaskets - needs doing asap Through shaft leaking - minor 2nd axle tyres low - will need replacement Large piece of debris found on front diff drain magnet Minor play both steer axle wheel bearings	
S-844	A	01/09/2020	09/01/2020	205,365	0	Monitor minor oil weep 2nd axle through shaft Internal Workshop A service done Reposition LHR guard post Tightened loose body mounts	
S-843	A	12/03/2019	03/12/2019	198,186	0	Replaced missing reflectors	
R-634	Machinery Defects	11/19/2019	11/19/2019	192,168		Internal Workshop Replaced bulb Body sub-frame bolts loose at front - could only tightened driver side as truck was loaded and could not raise bin to get to the other side - done on 20/11 Internal Workshop B service done DEFECTS: minor play both steer axle wheel bearings Air leak around LHS steer axle ABS valve BAD LEAK - could not see numbers on valve	
S-842	D - 90k	11/12/2019	11/12/2019	190,482	88,467	0	Monitor minor through shaft oil weep 2nd axle
R-633	Exhaust leak	11/11/2019	11/11/2019	190,350		Internal Workshop FOUND: exhaust manifold leaking in several places - flex under cab leaking & clamp at DPF leaking	
R-632	Tyres	11/05/2019	11/05/2019	188,016		Internal Workshop Flip steer tyres on rims with balancing beads & fit new radiator header tank Internal Workshop A service done Replaced missing tank brace bolts Re-secured 3rd axle guard pole DEFECTS: steer tyres scalloping Minor play both steer axle wheel bearings Air leak around LHS steer axle ABS valve BAD LEAK	
S-841	A	10/22/2019	22/10/2019	183,486		0	Monitor minor through shaft oil weep 2nd axle Internal Workshop A service done Replaced 2 x roof clearance light bulbs Exhaust flex under cab starting to leak - replaced with new clamp DEFECTS: front intercooler hose clamp loose RHS - Jay to order new clamps
S-840	A	09/26/2019	26/09/2019	177,051		0	Steer tyres scalloping

R-631	Tyres	08/28/2019	08/28/2019	167,100		DONE - rotated tyres Internal Workshop A service done Replaced both tarp cables Replaced ringfeder wear pad Drive tyres not rotated - will get done on 28/8	
S-839	A	08/27/2019	27/08/2019	166,872	0	DEFECTS: ringfeder needs re-kit, Needs 4 x exhaust clamps for DPF Internal Workshop B service done Drive tyres rotated Changed power steer filter DEFECTS: needs 4 x exhaust clamps from DPF Air leak at LHS valve at chassis rail Ringfeder needs re-kit	
S-838	B - 15k	08/05/2019	08/05/2019	161,248	59,233	0	Monitor steering bearings play Internal Workshop Safety chain pins have a burn on it - makes it hard for pin to pat in & out - removed burn
R-630	Safety chain	07/23/2019	07/23/2019	157,689		Internal Workshop A service done Batteries were flat - had to jump start - batteries extremely dry DEFECTS: monitor steer bearings play - need a tool to remove hub cap socket for steer axle so that the steer bearings can be adjusted	
S-837	A	07/15/2019	15/07/2019	155,459		0	Ringfeder needs re-kit Internal Workshop Adjusted valves, injectors & engine brakes - road test - ok FOUND: exhaust / boost leak noise on road test - checked boost hoses & clamps - ok - found exhaust leak at DPF & at flex under cab & also exhaust riding on chassis under cab - loosened & repositioned leaking clamps - loosened clamp on turbo & adjusted exhaust so as not to hit chassis - retightened clamp - road test - ok
R-629	Valve set	07/08/2019	07/08/2019	154,180		Internal Workshop Travelled to breakdown - checked Williams Valve - replaced Williams Valve Check exhaust leak - still leaking from head to muffler Tightened up mirror on bonnet Replaced wiper blades	
R-628	Breakdown	06/24/2019	06/24/2019	151,250		Internal Workshop A service done Tightened exhaust clamp at DPF Straightened out ringfeder Fit valve stem caps - none all round DEFECTS: Steer bearings have play - could not remove hub cap without Mach tool Nail in LHS steer tyre but not leaking	
S-836	A	06/24/2019	24/06/2019	151,278		0	Air filters need replacing next B service Internal Workshop Carry out A service Air filters need replacing - NO STOCK Coolant leak at top radiator hose - LHS clamp loose - tightened all clamps & top up Diff filter has come loose - removed filter - had unscrewed with filter - refit with new filter DEFECTS: rear diff centre leaking slightly Output seal rear of front diff leaking slightly
S-835	A	06/06/2019	06/06/2019	146,499		0	Possible oil dilution - engine oil appears to be slack & over full mark Steer bearings have play - can't remove hub cap without Mach tool

						Internal Workshop A service done Replaced bulb in LH park light Found dust in oil cap - added 4 litres of oil DEFECTS: rear diff centre leaking
S-834	A	05/03/2019	03/05/2019	136,450	0	Output seal rear of front diff leaking
R-627	Tyre repairs	04/29/2019	04/29/2019			Internal Workshop Puncture repair 4th RHS outside tyre
R-881	Flasher unit	04/15/2019	04/15/2019	132,721		Internal workshop Replaced flasher unit
R-626	Indicators	04/12/2019	04/12/2019	132,720		Internal Workshop Checked & found flasher unit was u/s - replaced flasher unit
						Internal Workshop A service done - NOT B as per jobcard - only replaced air dryer filter Removed & replaced tarp cables both sides Removed & replaced ringfeder wear pad & changed air dryer filter Refit LHS rear mudflap Tightened up coolant line retaining bolt DEFECTS: rear diff centre leaking
S-833	A	04/09/2019	09/04/2019	132,026	0	Output seal rear of front diff leaking
R-880	Gearbox oil & filter	03/27/2019	03/27/2019	128,438		Internal workshop Gearbox service only - changed gearbox filter & gearbox oil to Castrol SYNTHETIC & sampled gearbox oil
R-625	Gearbox oil & filter	03/27/2019	03/27/2019	128,438		Internal Workshop Gearbox service only - changed gearbox filter & gearbox oil to Castrol SYNTHETIC & sampled gearbox oil
						Internal Workshop Stripped tyres & old shoes & drums - removed brake shoes bush & install new ones - fitted new shoes & drums, rotated tyres & tensioned wheel nuts - fitted chrome & wheel nut indicators, adjusted brakes Tightened loose chassis bolts
R-624	Brake drums, Brake	03/20/2019	03/20/2019	126,967		Internal Workshop A service done Drive rotation - NOT DONE DEFECTS: drive brakes low Tarp cables fayed
						Rear diff centre leaking
S-832	A	03/19/2019	19/03/2019	126,669	0	Output seal rear of front diff leaking Internal Workshop A service done, Pumped tyres up to correct pressures Windscreen washers not working - filled up with water still not working - check fuses - ok - found wires to washer motor broken - repaired & checked - ok DEFECTS: Output seal rear of front diff leaking Pinion seal front of front diff leaking
						Both exhaust flex at back of cab leaking
S-831	A	02/18/2019	18/02/2019	119,087	0	Rear diff leaking
R-623	Steering	01/30/2019	01/30/2019	113,766		Internal Workshop Removed steering column cover & dash panels - replaced cable and gas strut assembly - adjusted & refit all panels Internal Workshop A service done Tyre rotation requested but not done DEFECTS: monitor engine oil level Both exhaust flexes at back of cab leaking
						Rear diff centre starting to leak
S-830	A	01/25/2019	25/01/2019	113,690	0	Tarp g/box housing cracked
R-622	Tarp	01/15/2019	01/15/2019	108,474		Internal Workshop Inspected truck - tarp g/box housing cracked

R-621	Hydraulic oil	01/14/2019	01/14/2019		108,154		Internal Workshop Topped up hydraulic oil - added 1L Internal Workshop Service done DEFECTS: both flexes at back of cab starting to leak Rear diff centre starting to leak WARRANTY JOB
S-828	A	12/17/2018	17/12/2018		106,615	0	Monitor engine oil over full
R-619	Hydraulic fitting, Toc	12/05/2018	12/05/2018		103,540		Internal Workshop Cut off rivets from hinges - couldn't find small bolts to fit had to drill out all holes - fit bolts & washers & nylock - nut hinges were bent - removed again & straightened - refit then cut new bolts down to size, Hydraulic coupling leaking - undo coupling remove o'rings - clean oil & dust & dirt off couplings - hose find new o-rings - fit o'rings - reconnect hose lift bin up & down a few times - check for leaks - ok, Found rear checker plate bent - removed & straightened & refit, LHR mudguard pipe was loose - adjusted pole to guard & re-secure - loaded so couldn't lift bin Internal Workshop Carry out B service Topped up coolant & washer bottle Ad blue filters were replaced Both diff oils have been changed DEFECTS: Needs drive rotation, needs brake re-line ASAP
S-827	E - 270k	11/30/2018	11/30/2018	102,015	102,015	0	Need to repair chain on ringfeder flap
R-618	Reflectors	11/21/2018	11/21/2018				Fitted red & white reflectors to truck & trailer Internal Workshop Carry out service Tightened rear guards DEFECTS: drive brakes getting low Engine oil level still over full According to Mack the movement on output shaft on g/box is fine - they allow 5mm of movement
S-826	A	11/20/2018	20/11/2018		98,448	0	
R-617	Tyres	11/13/2018	11/13/2018		96,066		Millards New drive tyres fitted - Hankook by Millards Tyre Centre (old tyres fitted to #462) Internal Workshop A service done Replaced RH tarp cable DEFECTS: engine oil level over full - driver to check & take photo in morning to see if level is the same Movement output shaft on gearbox
S-825	A	10/31/2018	31/10/2018		92,577	0	Radiator shroud cracked same as the other Holcim's
R-616	Air leaks	10/26/2018	10/26/2018		90,786		Internal Workshop Replaced split filter on air dryer
R-615	Air line	10/24/2018	10/24/2018		90,169		Internal Workshop Removed & replaced 2 x airlines RH side
R-614	Tarp cable	10/18/2018	10/18/2018		88,422		Internal Workshop Removed & replaced LH tarp cable Internal Workshop, Mack Brisbane A service done Go through & tighten all intercooler clamps RHR tappet gasket or timing plate FIXED BY MACK - WARRANTY
S-822	A	10/16/2018	16/10/2018		87,952	0	Go Pedal to be fixed - FIXED BY MACK
R-613	Bolts	10/09/2018	10/09/2018		85,947		Internal Workshop Ensured that all bolts are tightened up

S-821	A	09/27/2018	27/09/2018	83,248	0	Internal Workshop A service done
R-612	Brakes	09/26/2018	09/26/2018	82,843		DEFECTS: RHR tappet gasket or timing plate leaking - WARRANTY, Topped up coolant 2Ltrs, Airline supply for height control valve leaking air - found hole rubbed through hose - cut hose fit 3/8 tube joiner - build up with air - check for leaks - ok, Tightened both rear drive shockies top and bottom
R-611	Tyres	09/08/2018	09/08/2018	77,274		Internal Workshop Adjusted brakes Millards New steer tyres fitted by Millards Tyre Centre
S-820	A	09/06/2018	06/09/2018	76,459	0	Internal Workshop A service done DEFECT: Need to replace 1st RHS drive shock (leaking), Need steer tyres asap Tappet cover leaking Fan shroud cracked Monitor steer DS wheel bearing - slight movement
S-819	C - 30k	08/09/2018	08/09/2018	68,065	68,065	0 Internal Workshop B service done Ad-Blue filters replaced Replaced 1st axle drive tyres on 10/08/18 @ Millards (Goodyear G6675) - new on the rear and will rotate the rear to the 1st drive axle DEFECT: 1st drive RHS shock leaking
S-818	A	07/23/2018	23/07/2018	62,171	0	Internal Workshop Service done DEFECTS: 1st drive tyres low & steer tyres Rear of rocker cover starting to weep
S-817	A	07/04/2018	04/07/2018	56,447	0	Internal Workshop Service done
S-816	A	06/06/2018	06/06/2018	46,105	0	Internal Workshop A service done Checked air leak under or near the rear of truck - engine oil has a strong smell to it
S-815	B - 15k	05/04/2018	05/04/2018	34,902	34,902	0 Internal Workshop B service done Ad blue filters were replaced
R-610	Tyres	04/20/2018	04/20/2018	30,074		Internal Workshop Replaced 4 x drive tyres back axle
S-814	A	04/12/2018	12/04/2018	27,154	0	Internal Workshop A service done
R-609	Tyres	03/16/2018	03/16/2018	19,108		Internal Workshop Rotated drive tyres
S-813	A	03/13/2018	13/03/2018	17,838	0	Internal Workshop A service done Tightened fan bolts as they were loose
S-812	A	01/05/2018	01/05/2018	8,064	0	Internal Workshop A service done