

XV30QG Mack

22/6/2026

Terms 30 days

Order No Rocky

Job No 249033

Speedo

1125222

Description-Text	Qty	Unit Price	GST	Amount
Complaint & Correction :				
Failed Turbo				
Washed Down Engine Bay				
Removed RHF Wheel				
Removed Air Intake Pipes & Hoses				
Removed Exhaust				
Removed Failed Turbo & Cleaned Surfaces				
Installed New Turbo With New Seals/Gaskets				
Refit Exhaust & All Removed Components				
Removed & Replaced Muffler				
Topped Up Engine Oil				
Removed Turbo Intake Pipe & Clamps				
Fit New Sealing O Ring				
Refit Intake Pipe & Clamps				
Road Test Vehicle				
Parts:				
VT21397620 Exc Turbo MP8-Mack Late	1.00	2,829.00	282.90	2,829.00
VT20784537 Gasket Turbo Base Square Metal	1.00	23.67	2.87	28.67
VT20573472 Sleeve Spacer Turbo Base Mounting 13&16LTR Engine	4.00	15.68	6.27	62.73
VT993811 Bolt Flanged 10mm x 50mm Long 8.8 Grade	4.00	20.31	8.32	83.24
VT22206133 Gasket Turbo Feed & Filter Housing D12-13A-C	1.00	7.84	0.78	7.84
VT420643 Gasket Turbo Return Mack-Volvo	1.00	4.94	0.49	4.94
VT469601 O Ring Turbo Return Line Mack-Volvo	1.00	26.24	2.62	26.24
VT21940615 Sealing Ring Turbo Return Pipe D12A-C-D13-MP8	1.00	21.71	2.17	21.71
24783537 Muffler	1.00	7,465.20	746.52	7,465.20
Washer Flat 5/16	2.00	0.18 Each	0.04	0.36

XV30QG Mack

Terms 30 days

Order No Rocky

Job No 249033

Speedio

1125222

Description-Text	Qty	Unit Price	GST	Amount
Nut-HX-NYL-INS-NE-GRC-(ZN)-5/16_24	1.00	0.34 Each	0.03	0.34
SCR-HCS-GR8-(PL)-5/16_24 X 2	1.00	2.53 Each	0.25	2.53
Bolt M10 X 60	1.00	1.43 EACH	0.14	1.43
Hex Nut Self Locking M10	1.00	0.36 EACH	0.04	0.36
Engine Oil VDS 15w40 Bulk Per Litre	9.00	10.22 EACH	9.20	91.96
21096684 O Ring	1.00	3.20	0.32	3.20
Labour:				
Labour 10/6	1.00	85.00	8.50	85.00
Labour 19/6	3.00	85.00	25.50	255.00
Labour 22/6	9.00	85.00	76.50	765.00
Labour 26/6	0.50	85.00	4.25	42.50
VT85009796 Core Exc Turbo	1.00	477.38	47.74	477.38
85009796 Core Exc Turbo	-1.00	477.38	-47.74	-477.38

Subtotal	11,777.25
Rounding Amount	-.01
Add GST	1,177.71
Total	12,954.95



134339

XV30QG Mack

23/1/26

Terms 30 days

Order No R1074

Job No 247452

Speedo

1085850

Description-Text	Qty	Unit Price	GST	Amount
------------------	-----	------------	-----	--------

Repairs:

14/1 LH Exhaust Elbow Under Cab Cracked (30 Days) - COMPLETED

14/1 Exhaust Out Of Muffler Cracked (30 Days) - COMPLETED

14/1 Front Bonnet Bushes Worn (30 Days) - COMPLETED

14/1 Air Lines Under Cab On RH Side Need Heat Wrap Applied (30 Days) - COMPLETED

R & R LH Exhaust Elbow

R & R Muffler Outlet Pipe

R & R Front Bonnet Bushes

Replaced All Damaged & Brittle Air Lines Under Cab

R & R Exhaust Y Exhaust Section Under Cab

Parts:

1/4 Nylon Black Per Metre	13.00	1.44 Each	1.87	18.67
3/8 Nylon Black Per Metre	7.00	2.65 Each	1.86	18.58
Exhaust 5 Inch Flex Stainless Tube Per M	1.00	92.27 EACH	9.23	92.27
5 Exhaust Clamp Band Type	6.00	14.85 Each	8.91	89.13
Elbow Swivel 1/4 T - 1/8 NPT	1.00	8.11 Each	0.81	8.11
5 Exhaust Clamp Band Type	2.00	14.85 Each	2.97	29.71
5 Exhaust Clamp U Bolt Type Zinc	2.00	14.00 Each	2.80	28.00
21746976 Exhaust Pipe Elbow	1.00	600.78	60.08	600.78
25171655 Socket Sleeve	4.00	40.88	16.35	163.53
25161050 Insulator	2.00	11.49	2.30	22.98
25158280 Insulator Cab	2.00	30.29	6.06	60.53
21827215 Exhaust Elbow	1.00	856.84	85.68	853.84
20542349 Insulator Radiator Bar	2.00	73.23	14.65	146.45
21747806 Exhaust Pipe Y Piece	1.00	535.86	53.59	535.86

XV30QG Mack

Terms 30 days

Order No R1074

Job No 247452

Speedo

1085850

Description-Text	Qty	Unit Price	GST	Amount
Consumables	1.00	10.00	1.00	10.00
Labour:				
Labour 21/1	2.00	85.00	17.00	170.01
Labour 21/1	2.00	85.00	17.00	170.01
Labour 21/1	1.50	85.00	12.75	127.50
Labour 21/1	1.50	85.00	12.75	127.50
Labour 22/1	6.50	85.00	55.25	552.51
Labour 22/1	4.00	85.00	34.00	340.01

- 14/1 Front Drive Inner Tyres Worn (14 Days)

Subtotal	4,169.03
Rounding Amount	.01
Add GST	416.91
Total	4,585.95