

Cr29-4

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 2026
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	17,579 hr & 869,210 km

Type	Scheduled	Due	Started	Closed
	Jul 29, 2025		Jul 29, 2025 2:37 PM	Jul 29, 2025 2:37 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop
880 - 2019 Kenworth t800
Parent: T367 - 2015 Peerless

Work Order 2141
Trent Court
CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	17,684 hr & 875,410 km

Type	Scheduled	Due	Started	Closed
	Sep 22, 2025		Sep 22, 2025 1:09 PM	Sep 22, 2025 1:09 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1974
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	17,463 hr & 862,206 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 14, 2025	Jul 14, 2025		Jul 14, 2025 7:55 AM	Jul 14, 2025 7:55 AM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ A/C not working	\$0.00	\$0.00	\$0.00		

Notes

blower motor loose in box, replaced rivet nuts and bolted back in

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1881
Everett Twin, Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	17,322 hr & 853,954 km

Type	Created	Scheduled	Due	Started	Closed
	May 29, 2025	May 29, 2025		May 29, 2025 11:13 AM	Jul 3, 2025 8:10 AM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ Mirror cracked, replace	\$0.00	\$0.00	\$0.00		
Notes						
Needs LH mirror and RH convex, no convex in stock						
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ change windshield	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Windshield LH	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Grille bolts missing	\$0.00	\$0.00	\$0.00		
5	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
6	✓ Replace Belt	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	ac belt	Kropp Shop		1.0	\$0.00	\$0.00
	fan belt	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ replace air filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	AF4195 - air filters T800	Kropp Shop		1.0	\$0.00	\$0.00
8	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00		
9	✓ Work light mia	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1881
Everett Twin, Cam Nadeau

CLOSED

	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Work light	Kropp Shop		1.0	\$0.00	\$0.00
10	✓ Replace missing/tore mudflaps			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	24" plastic mudflap	Kropp Shop		1.0	\$0.00	\$0.00
11	✓ Rubber air lines			\$0.00	\$0.00	\$0.00

Notes

RF steer line NFG

	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	HAB 8 28 FS - Rubber air brake service 28" long	Kropp Shop		1.0	\$0.00	\$0.00
12	✓ spring pins			\$0.00	\$0.00	\$0.00

Notes

Have 4 pins and only 2 bushings. To be done on another date/when parts are in stock

13	✓ CVIP inspection (wheels off)			\$0.00	\$0.00	\$0.00
----	--------------------------------	--	--	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1926

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	17,322 hr & 853,954 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jun 23, 2025	Jun 23, 2025		Jun 23, 2025 8:06 AM	Jun 23, 2025 8:06 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1926

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	17,322 hr & 853,954 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jun 23, 2025	Jun 23, 2025		Jun 23, 2025 8:06 AM	Jun 23, 2025 8:06 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1916

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	17,272 hr & 850,959 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jun 17, 2025	Jun 17, 2025		Jun 17, 2025 7:32 AM	Jun 17, 2025 7:32 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Notes

Completed by Joe

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1791
Everett Twin

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	17,039 hr & 839,186 km

Type	Scheduled	Due	Started	Closed
	Mar 19, 2025		Mar 19, 2025 4:07 AM	Mar 19, 2025 4:07 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1757

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,875 hr & 833,058 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 7, 2025	Mar 7, 2025		Mar 11, 2025 2:26 PM	Mar 11, 2025 2:26 PM

Line	Task			Parts	Labor	Total
1	✓ Middle rh inside flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1750

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,875 hr & 833,058 km

Type	Scheduled	Due	Started	Closed
	Mar 6, 2025		Mar 6, 2025 5:34 PM	Mar 6, 2025 5:34 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1749

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,875 hr & 833,058 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 6, 2025	Mar 6, 2025		Mar 6, 2025 5:33 PM	Mar 6, 2025 5:33 PM

Line	Task			Parts	Labor	Total
1	✓ Steer Tires			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	steer tires	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ radiator leaking			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	t800 radiator	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1740

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,706 hr & 824,833 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 5, 2025	Mar 5, 2025		Mar 5, 2025 8:14 PM	Mar 5, 2025 8:14 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines <u>Notes</u> RH steer axle line leak	\$0.00	\$0.00	\$0.00
2	✓ Brake Accessories <u>Notes</u> LH middle drive brake pot nfg	\$0.00	\$0.00	\$0.00
3	✓ Exhaust <u>Notes</u> Bellows pipe broke, turbo down pipe broke	\$0.00	\$0.00	\$0.00
4	✓ Rh steer shock nfg	\$0.00	\$0.00	\$0.00
5	✓ hanger bearing nfg	\$0.00	\$0.00	\$0.00
6	✓ air leak off supply lint to tranny	\$0.00	\$0.00	\$0.00
7	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1691

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,706 hr & 824,833 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 17, 2025	Feb 17, 2025		Feb 17, 2025 2:48 PM	Feb 17, 2025 2:48 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Flat tire	\$0.00	\$0.00	\$0.00
3	✓ Scale line hose broke	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1671

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,656 hr & 818,046 km

Type	Scheduled	Due	Started	Closed
	Feb 11, 2025		Feb 11, 2025 10:10 PM	Feb 11, 2025 10:10 PM

Line	Task	Parts	Labor	Total		
1	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
2	✓ top RH mickey mouse light weather pack tore	\$0.00	\$0.00	\$0.00		
3	✓ rear drive outside low fill to 100	\$0.00	\$0.00	\$0.00		
		Part Cost		\$0.00		
		Labor		\$0.00		
		Tax 1 (0.0%)		\$0.00		
		Tax 2 (0.0%)		\$0.00		
		Credit		(\$0.00)		
		Total Cost		\$0.00		

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1653

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,554 hr & 818,046 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 3, 2025	Feb 3, 2025		Feb 3, 2025 3:02 PM	Feb 3, 2025 3:02 PM

Line	Task	Parts	Labor	Total		
1	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		12.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1640

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,554 hr & 818,046 km

Type	Scheduled	Due	Started	Closed
	Feb 2, 2025		Feb 2, 2025 6:24 PM	Feb 2, 2025 6:24 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Accessories	\$0.00	\$0.00	\$0.00

Notes

#3 s cam u bolt rh

2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
---	----------------------------	--------	--------	--------

3	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

high beam bulbs cracked

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
2 prong bulb	Kropp Shop		2.0	\$0.00	\$0.00

4	✓ Mirrors	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

mirror heat not working

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1602

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,404 hr & 811,625 km

Type	Scheduled	Due	Started	Closed
	Jan 19, 2025		Jan 19, 2025 6:40 PM	Jan 19, 2025 6:40 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Accessories	\$0.00	\$0.00	\$0.00
	Notes			
	#3 s cam u bolt			
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1561
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,263 hr & 804,918 km

Type	Scheduled	Due	Started	Closed
	Jan 7, 2025		Jan 7, 2025 6:02 PM	Jan 7, 2025 6:02 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1553
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,263 hr & 804,918 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 6, 2025	Jan 6, 2025		Jan 7, 2025 6:02 PM	Jan 7, 2025 6:02 PM

Line	Task	Parts	Labor	Total
1	✓ Alternator failed	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1527
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	16,120 hr & 797,831 km

Type	Scheduled	Due	Started	Closed
	Dec 15, 2024		Dec 15, 2024 2:33 PM	Dec 15, 2024 2:33 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines	\$0.00	\$0.00	\$0.00
	<u>Notes</u> Red glad hand line broke and leaking			
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
3	✓ Lights - All	\$0.00	\$0.00	\$0.00
	<u>Notes</u> no marker lights on whole truck			
4	✓ Mirrors	\$0.00	\$0.00	\$0.00
	<u>Notes</u> both top west coast mirrors no heat			
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1489
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,959.4 hr & 789,945 km

Type	Scheduled	Due	Started	Closed
	Dec 1, 2024		Dec 1, 2024 6:00 PM	Dec 1, 2024 6:00 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ loose yoke on diff	\$0.00	\$0.00	\$0.00
Notes				
Front input loose-tightned				
3	✓ Air fitting leaking	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1428

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,784 hr & 781,046 km

Type	Scheduled	Due	Started	Closed
	Nov 13, 2024		Nov 13, 2024 3:45 PM	Nov 13, 2024 3:45 PM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1427

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,720 hr & 776,511 km

Type	Scheduled	Due	Started	Closed
	Nov 11, 2024		Nov 11, 2024 4:25 PM	Nov 11, 2024 4:25 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1409
Everett Twin, Sam Hawksley
CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,698 hr & 776,511 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 2, 2024	Nov 2, 2024		Nov 2, 2024 10:58 PM	Nov 2, 2024 10:58 PM

Line	Task	Parts	Labor	Total		
1	✓ Mirrors	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	mirror lights out					
2	✓ Rear End	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	first diff output yoke loose					
3	✓ LH windshield nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Windshield LH	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ LH steer tire	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	steer tires	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1378

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,649 hr & 773,980 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 25, 2024	Oct 25, 2024		Oct 25, 2024 5:53 PM	Oct 25, 2024 5:53 PM

Line	Task			Parts	Labor	Total
1	✓ Batteries no good			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Group 31S battery	Kropp Shop		4.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1366

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,602 hr & 771,501 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 22, 2024	Oct 22, 2024		Oct 22, 2024 4:32 AM	Oct 22, 2024 4:32 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1109

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	14,941 hr & 738,319 km

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	May 14, 2024	May 14, 2024		May 14, 2024 9:19 AM	Jun 13, 2024 7:43 AM

Line	Task	Parts	Labor	Total
1	✓ DEF codes	\$0.00	\$0.00	\$0.00
	Notes			
	Change DEF pressure line			
2	✓ change diff filters	\$0.00	\$0.00	\$0.00
3	✓ Change air filters	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1344
Everett Twin, Trent Court
CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,602 hr & 771,501 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 19, 2024	Oct 19, 2024		Oct 20, 2024 9:28 AM	Oct 20, 2024 9:28 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00

Notes

backed off pushed in and tied up
SA right

2	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00
---	--------------------------	--------	--------	--------

Notes

tightened hose clamp and ran
coolant leak on back of head

3	✓ Driveline	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

Front diff Input yoke cracked

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
SPL 250 input yoke	Kropp Shop		1.0	\$0.00	\$0.00

4	✓ Engine	\$0.00	\$0.00	\$0.00
---	----------	--------	--------	--------

Notes

fan belt idler no good

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Fan belt tensioner	Kropp Shop		1.0	\$0.00	\$0.00

5	✓ Exhaust	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

y pipe flex pipe broken

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
------	-----------	------------	-----	-----------	------

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1344
Everett Twin, Trent Court
CLOSED

	5" flex pipe	Kropp Shop	1.0	\$0.00	\$0.00
	5" step clamp	Kropp Shop	2.0	\$0.00	\$0.00
6	✓ Fifth Wheel		\$0.00	\$0.00	\$0.00

Notes

adjust 5th wheel sloppy

7	✓ Lights - All		\$0.00	\$0.00	\$0.00
---	----------------	--	--------	--------	--------

Notes

skirt light marker out

8	✓ Mirrors		\$0.00	\$0.00	\$0.00
---	-----------	--	--------	--------	--------

Notes

RH convex broken

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Convex mirror t800	Kropp Shop		1.0	\$0.00	\$0.00

9	✓ Service Brakes		\$0.00	\$0.00	\$0.00
---	------------------	--	--------	--------	--------

Notes

front RH drive adjust

10	✓ Tires		\$0.00	\$0.00	\$0.00
----	---------	--	--------	--------	--------

Notes

RH rear drive inside flat

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Truck - Drive tire	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1315

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,488 hr & 764,792 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 8, 2024	Oct 8, 2024		Oct 12, 2024 10:36 AM	Oct 12, 2024 10:36 AM

Line	Task	Parts	Labor	Total
1	✓ LH lift axle bag blown	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1301
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,488 hr & 764,792 km

Type	Scheduled	Due	Started	Closed
	Sep 25, 2024		Sep 25, 2024 5:43 PM	Sep 25, 2024 5:43 PM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1297
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,488 hr & 764,792 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 23, 2024	Sep 23, 2024		Sep 25, 2024 5:43 PM	Sep 25, 2024 5:43 PM

Line	Task	Parts	Labor	Total
1	✓ Lower rad hose split	\$0.00	\$0.00	\$0.00
2	✓ RH hood signal wires broke at weather pack	\$0.00	\$0.00	\$0.00
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1292

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,242 hr & 754,139 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 18, 2024	Sep 18, 2024		Sep 18, 2024 6:21 AM	Sep 18, 2024 6:21 AM

Line	Task	Parts	Labor	Total		
1	✓ LH steer shock broken	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	85070 - Steer shock T800	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ LH steer brake line broke off	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	hab 6 28 fs - Rubber air brake supply	Kropp Shop		1.0	\$0.00	\$0.00
		Part Cost				\$0.00
		Labor				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1241

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,242 hr & 754,139 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 19, 2024	Aug 19, 2024		Aug 22, 2024 6:31 AM	Aug 22, 2024 6:31 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1246

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,242 hr & 754,139 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 21, 2024	Aug 21, 2024	Aug 21, 2024	Aug 21, 2024 5:49 AM	Aug 21, 2024 6:08 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00
	Notes			
	#7 and #8 LHS inside			
2	✓ Heater valve	\$0.00	\$0.00	\$0.00
	Notes			
	Change heater valve			
3	✓ Wash Radiator	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1228

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,193 hr & 750,981 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 14, 2024	Aug 14, 2024		Aug 14, 2024 7:42 AM	Aug 14, 2024 7:42 AM

Line	Task	Parts	Labor	Total
1	✓ Truck running hot	\$0.00	\$0.00	\$0.00

Notes

Fan will not lock on with no air clutch burned out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
79A9782 - Horton Fan hub	Kropp Shop	EKW	1.0	\$0.00	\$0.00

2	✓ Diagnose boost leak	\$0.00	\$0.00	\$0.00
---	-----------------------	--------	--------	--------

Notes

Hole in charge air cooler

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1228

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	15,193 hr & 750,981 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 14, 2024	Aug 14, 2024		Aug 14, 2024 7:42 AM	Aug 14, 2024 7:42 AM

Line	Task	Parts	Labor	Total
1	✓ Truck running hot	\$0.00	\$0.00	\$0.00

Notes

Fan will not lock on with no air clutch burned out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
79A9782 - Horton Fan hub	Kropp Shop	EKW	1.0	\$0.00	\$0.00

2	✓ Diagnose boost leak	\$0.00	\$0.00	\$0.00
---	-----------------------	--------	--------	--------

Notes

Hole in charge air cooler

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1134
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	14,971 hr & 739,856 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 13, 2024	Jun 13, 2024		Jun 29, 2024 9:00 AM	Jul 15, 2024 7:51 AM

Line	Task	Parts	Labor	Total
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00
2	✓ Rebuild grille	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	T800 grille Kropp Shop 1.0 \$0.00 \$0.00			
3	✓ change windshield	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	windshield RH Kropp Shop 1.0 \$0.00 \$0.00			
4	✓ Mirror cracked, replace	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	T800 west coast mirror Kropp Shop 1.0 \$0.00 \$0.00			
5	✓ change diff filters	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	LF3311 - Rockwell diff filter Kropp Shop 1.0 \$0.00 \$0.00			
6	✓ Air filters	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	air filters Kropp Shop 1.0 \$0.00 \$0.00			
7	✓ egr cooler	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	5693915 - EGR cooler kit Kropp Shop 1.0 \$0.00 \$0.00			
8	✓ wipers tore	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	15" wiper blade Kropp Shop 2.0 \$0.00 \$0.00			

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

CLOSED

9	✓ left hand step rebuild	\$0.00	\$0.00	\$0.00
10	✓ fan hub leaking air	\$0.00	\$0.00	\$0.00
11	✓ power steering leaking out cap	\$0.00	\$0.00	\$0.00

Notes

When greasing steering box on LH it over fills reservoir

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Capital gear steering box	Kropp Shop		1.0	\$0.00	\$0.00
12	✓ compressor line needs tied up	\$0.00	\$0.00	\$0.00	
13	✓ check A/C	\$0.00	\$0.00	\$0.00	
14	✓ rear wishbone cross member cracked	\$0.00	\$0.00	\$0.00	
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
48100581 - Neway crossmember kit	Kropp Shop		1.0	\$0.00	\$0.00
15	✓ Replace missing/tore mudflaps	\$0.00	\$0.00	\$0.00	
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
24" plastic mudflap	Kropp Shop		2.0	\$0.00	\$0.00
anti sail bracket	Kropp Shop		2.0	\$0.00	\$0.00
16	✓ Scale pad washer broke	\$0.00	\$0.00	\$0.00	
17	✓ RH. Rear drive scam ubolt bracket broke	\$0.00	\$0.00	\$0.00	
18	✓ wrap umbilical cord	\$0.00	\$0.00	\$0.00	
19	✓ Replace Stack bushings and bearing	\$0.00	\$0.00	\$0.00	
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
EM75-69000-HT - Stack bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
20	✓ Front diff pinion plate leaking	\$0.00	\$0.00	\$0.00	
21	✓ Drive axle brakes wore out	\$0.00	\$0.00	\$0.00	

Notes

New shoes new drums

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
------	-----------	------------	-----	-----------	------

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1134
Trent Court

CLOSED

	Es2 shoe kit	Kropp Shop	6.0	\$0.00	\$0.00	
	Brake Drum	Kropp Shop	6.0	\$0.00	\$0.00	
22	✓ LH steer scam tube bolt broke		\$0.00	\$0.00	\$0.00	
23	✓ replace fan belt		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	fan belt	Kropp Shop		1.0	\$0.00	\$0.00
24	✓ replace A/C belt		\$0.00	\$0.00	\$0.00	
25	✓ spring pins		\$0.00	\$0.00	\$0.00	
	Notes					
	Horton roller pin trial					
26	✓ Fuel leak on fuel rail		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	High pressure line	Kropp Shop		1.0	\$0.00	\$0.00
27	✓ Weld beaver tail		\$0.00	\$0.00	\$0.00	
28	✓ LH middle marker on headache rack half out		\$0.00	\$0.00	\$0.00	
29	✓ LH mirror light out		\$0.00	\$0.00	\$0.00	
30	✓ LH hood light over half out		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	G5543 - hood light T800	Kropp Shop		1.0	\$0.00	\$0.00
31	✓ RH hood light no side marker light		\$0.00	\$0.00	\$0.00	
32	✓ Replace scale pad bolts		\$0.00	\$0.00	\$0.00	
33	✓ RH high beam bulb cracked		\$0.00	\$0.00	\$0.00	
			Part Cost		\$0.00	
			Labor		\$0.00	
			Tax 1 (0.0%)		\$0.00	
			Tax 2 (0.0%)		\$0.00	
			Credit		(\$0.00)	
			Total Cost		\$0.00	

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1109
Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	14,941 hr & 738,319 km

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	May 14, 2024	May 14, 2024		May 14, 2024 9:19 AM	Jun 13, 2024 7:43 AM

Line	Task	Parts	Labor	Total
1	✓ DEF codes	\$0.00	\$0.00	\$0.00
	Notes			
	Change DEF pressure line			
2	✓ change diff filters	\$0.00	\$0.00	\$0.00
3	✓ Change air filters	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1077
Trent Court, Cam Nadeau
CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	14,941 hr & 738,319 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 23, 2024	Apr 23, 2024		Apr 23, 2024 8:52 PM	Apr 23, 2024 8:52 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Engine derate			\$0.00	\$0.00	\$0.00

Notes

Def light blinking, pinched off return line, def pressure line broke
return line melted

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Def pressure line	Kropp Shop		1.0	\$0.00	\$0.00
Def return line	Kropp Shop		1.0	\$0.00	\$0.00
Def jugs	Kropp Shop		2.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Notes

Notes	User	Time
Breakdown @ carwald pit km 27 wab highway	Trent Court	Apr 23, 2024 8:52 PM

Kropp Contracting
Shop

880 - 2019 Kenworth t800

Parent: T367 - 2015 Peerless

Work Order 1072

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX2KR951081	E68681	14,934 hr & 738,084 km

Type	Created	Scheduled	Due	Started	Closed
engine	Apr 22, 2024	Apr 22, 2024	Apr 22, 2024	Apr 22, 2024 7:40 AM	Apr 22, 2024 1:14 PM

Line	Task	Parts	Labor	Total		
1	✓ Change DEF pump	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5506956RX - Pump, doser	Kropp Shop	EKW	1.0	\$0.00	\$0.00
2	✓ repair DPF wiring	\$0.00	\$0.00	\$0.00		
3	✓ repair coolant level witing	\$0.00	\$0.00	\$0.00		
4	✓ ABS codes	\$0.00	\$0.00	\$0.00		
	Notes					
	Repair wire #3 RHS					
5	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
		Part Cost		\$0.00		
		Labor		\$0.00		
		Tax 1 (0.0%)		\$0.00		
		Tax 2 (0.0%)		\$0.00		
		Credit		(\$0.00)		
		Total Cost		\$0.00		

Notes

Notes	User	Time
Repair check engine light and derate	Trent Court	Apr 22, 2024 7:40 AM