

Model	Equipment	Description	Workorder Number	Status	Plan Start
155-65	WT19	gear shift column selector loose	CVW8064-1705	C	11/30/2017 10:00
155-65	WT19	DOOR HANDLE	CVW8061-1705	C	11/30/2017 12:20
155-65	WT19	air con compressor mount adjuster bracket repairs	CVW17320-1708	C	01/19/2018 7:16
155-65	WT19	AIRCON BELTS	CVW17333-1707	C	01/19/2018 7:16
155-65	WT19	BONNET STRUTS US	CVW17356-1707	C	01/19/2018 7:16
155-65	WT19	TRANSMISSION MOUNTS WORN OUT	CVW17582-1707	C	02/01/2018 9:02
155-65	WT19	AIR LEAK FROM SPRAY BAR CONTROL	CVW17909-1708	C	02/09/2018 9:42
155-65	WT19	Head Gasket leaking	CVW17887-1709	C	04/03/2018 14:39
155-65	WT19	Left Rear Shock Absorber broken	CVW17888-1709	C	02/22/2018 10:52
155-65	WT19	PTO does not stay engaged always	CVW17889-1808	C	02/22/2018 10:49
155-65	WT19	Indicators do not stay on	CVW17891-1709	C	04/03/2018 14:33
155-65	WT19	Tyres on tractor bald P 1,2,3,4	CVW17893-1712	C	05/28/2018 11:11
155-65	WT19	DRIBBLE BAR BENT	CVW31829-1709	C	03/20/2018 8:02
155-65	WT19	FIRE EXTINGUISHER	CVW13534-1706	C	03/01/2018 9:23
155-65	WT19	(ACC) LH mirror broken, wiper arm not working	CVW34859-1711	C	05/31/2018 8:57
155-65	WT19	Centre spray not working , jamming up	CVW34860-1711	C	05/23/2018 9:11
155-65	WT19	Mirror missing from drivers door	CVW35792-1801	C	08/13/2018 15:31
155-65	WT19	Bonnent strut broken	CVW35724-1801	C	07/19/2018 7:41
155-65	WT19	POSITION 6 TYRE STAKED	CVW35946-1802	C	08/02/2018 10:38
155-65	WT19	position 6 tyre flat, staked	CVW36179-1802	C	08/15/2018 10:05
155-65	WT19	FIRE EXTINGUISHER	CVW35939-1802	C	08/25/2018 11:46
155-65	WT19	500HR SERVICE	CVW13552-1803	C	09/16/2018 22:46
155-65	WT19	(ACC) Hose ripped from rear of tank	CVW37431-1804	C	10/30/2018 8:44
155-65	WT19	Chassis to Axle linkage u/s	CVW37701-1805	C	11/27/2018 8:00
155-65	WT19	New shift lever required	CVW38068-1806	C	12/20/2018 9:19
155-65	WT19	Reverse alarm not working , fit new hr meter	CVW38213-1807	C	01/17/2019 14:17
155-65	WT19	250HR SERVICE	CVW13543-1807	C	01/22/2019 1:36
155-65	WT19	PARK BRAKE NOT HOLDING	CVW17456-1707	C	01/09/2018 10:25
155-65	WT19	park brake not holding	CVW17462-1707	C	01/23/2018 7:22
155-65	WT19	FIRE EXTINGUISHER	CVW38412-1808	C	03/08/2019 9:44
155-65	WT19	Spray actuators need replacing , centre spray faulty	CVW38657-1811	C	02/27/2019 14:24
155-65	WT19	P1 TYRE	CVW32226-1710	C	05/28/2018 11:11
155-65	WT19	P2 TYRE	CVW32240-1710	C	05/28/2018 11:11
155-65	WT19	P3 TYRE	CVW32254-1710	C	05/28/2018 11:11

155-65	WT19	P4 TYRE	CVW32268-1710	C	05/28/2018 11:11
155-65	WT19	Aircon belt broken off , bracket modification required ?	CVW38756-1809	C	03/14/2019 15:49
155-65	WT19	Engine oil filler cap replace	CVW38879-1809	C	03/25/2019 12:11
155-65	WT19	Modify Fire hose tap access	CVW38948-1810	C	03/29/2019 12:48
155-65	WT19	Front axle failure	CVW39029-1811	C	04/16/2019 12:27
155-65	WT19	air leaks from brake air valves under cab	CVW39205-1811	C	05/21/2019 13:58
155-65	WT19	FIRE EXTINGUISHER	CVW39643-1901	C	07/08/2019 8:54
155-65	WT19	AIR CON COMPRESSOR Siezed	CVW13352-1808	C	02/13/2019 8:09
155-65	WT19	Clutch slave cylinder U/S 476/02700	CVW38263-1808	C	01/29/2019 8:21
155-65	WT19	(ACC) front windscreen cracked down middle	CVW41256-1907	C	11/17/2019 7:00
155-65	WT19	Door not opening from in cab	CVW41367-1905	C	11/25/2019 7:37
155-65	WT19	FIRE EXTINGUISHER 25.01.20	CVW41821-1906	C	01/25/2020 10:39
155-65	WT19	Alternator & Batteries Replace & Start wiring loose , would not start	CVW42309-1908	C	01/30/2020 14:12
155-65	WT19	1000HR SERVICE	CVW13561-2009	C	03/03/2021 8:45
155-65	WT19	OPERATORS SEAT	CVW13507-1706	C	07/08/2025 8:23
155-65	WT19	LH door will not close	CVW42680-1908	C	02/25/2020 10:42
155-65	WT19	Gear selector shaft lever broken	CVW42917-1909	C	03/10/2020 7:32
155-65	WT19	250HR SERVICE	CVW42652-1908	C	04/18/2020 3:37
155-65	WT19	artic jack Knife switches broken	CVW43660-1910	C	04/30/2020 6:40
155-65	WT19	Broken compressor mount bolts	CVW43813-2002	C	05/06/2020 13:46
155-65	WT19	Machine hour meter not working	CVW44833-2001	C	07/14/2020 9:34
155-65	WT19	500HR SERVICE	CVW42851-1909	C	07/17/2020 19:22
155-65	WT19	FIRE EXTINGUISHER	CVW44622-1912	C	07/23/2020 15:20
155-65	WT19	window wiper, LH Door strut U/S	CVW45268-2002	C	07/31/2020 8:22
155-65	WT19	Dash fault lights coming on 4WD switch	CVW45440-2005	C	08/06/2020 15:47
155-65	WT19	Centre spray stays on when switched off	CVW45562-2002	C	08/14/2020 7:12
155-65	WT19	Replace clutch slave cylinder Cant push clutch in	CVW45572-2002	C	08/14/2020 9:16
155-65	WT19	Hyd hose connection leaking	CVW45902-2002	C	08/28/2020 10:03
155-65	WT19	spray switches required	CVW45929-2003	C	08/31/2020 11:42
155-65	WT19	Flashing light not working	CVW46075-2003	C	09/08/2020 7:58
155-65	WT19	hyd tank cap u/s, hyd return line leak,	CVW46225-2004	C	09/11/2020 15:37
155-65	WT19	Fuel leaking line	CVW46226-2004	C	09/11/2020 15:46
155-65	WT19	engine oil cooler hoses leaking	CVW46227-2111	C	09/11/2020 15:48
155-65	WT19	Fan hub failed , damaged shroud, fan , belts, tank, hoses	CVW46228-2004	C	09/11/2020 15:51
155-65	WT19	Front springs collapsed	CVW46882-2004	C	10/13/2020 7:31

155-65	WT19	Park brake seized , no trailer brakes , low air not working	CVW47265-2005	C	11/03/2020 7:37
155-65	WT19	Rear main seal leaking	CVW47273-2005	C	10/22/2020 8:17
155-65	WT19	Steering box leaking should be WT17 *****	CVW47274-2005	C	10/22/2020 8:18
155-65	WT19	Rollbar, suspension control arms, steer damper all need overhaul WT17 Job	CVW47275-2005	C	10/22/2020 8:17
155-65	WT19	Aircon not working blowing hot air , broken vee belt also	CVW47560-2009	C	11/05/2020 12:20
155-65	WT19	Centre sprays not working	CVW47661-2005	C	11/11/2020 10:36
155-65	WT19	Alternator failed	CVW47758-2005	C	11/18/2020 6:25
155-65	WT19	coolant tank leak, stop solenoid wiring also	CVW48140-2007	C	12/07/2020 7:39
155-65	WT19	left spray wont turn off	CVW48617-2007	C	01/08/2021 13:52
155-65	WT19	air leaks from behind air tanks	CVW48729-2008	C	01/13/2021 12:05
155-65	WT19	Trailer hook up making noise even after greasing	CVW48929-2008	C	01/22/2021 8:48
155-65	WT19	viscous fan not drawing air correctly	CVW49026-2008	C	01/31/2021 8:51
155-65	WT19	air con mounting bracket repairs	CVW49031-2008	C	01/31/2021 9:24
155-65	WT19	2 way has short range ,tried different 2 ways	CVW49137-2008	C	02/03/2021 10:29
155-65	WT19	BATTERY	CVW13331-1706	C	01/30/2020 14:12
155-65	WT19	P5TYRE flat tyre	CVW32282-1907	C	01/06/2020 15:50
155-65	WT19	Flashing light not working	CVW49341-2008	C	02/12/2021 13:35
155-65	WT19	Hood catch almost broken off	CVW49342-2008	C	02/12/2021 13:36
155-65	WT19	left door not closing properly , Left window latch broken , middle spray wrong position	CVW49344-2009	C	02/12/2021 13:37
155-65	WT19	waterpump on engine leaking coolant	CVW44191-1912	C	02/14/2021 7:05
155-65	WT19	air compressor fault	CVW49384-2008	C	02/15/2021 11:21
155-65	WT19	Water cart will not go ,Possible clutch	CVW49801-2009	C	03/08/2021 14:12
155-65	WT19	aircon not working	CVW49965-2009	C	03/15/2021 14:36
155-65	WT19	wiper not working	CVW50176-2010	C	03/25/2021 8:02
155-65	WT19	often will not engage forward or reverse gears	CVW50281-2012	C	03/30/2021 10:59
155-65	WT19	250hr service	CVW47675-2005	C	03/19/2021 4:39
155-65	WT19	dribble bar not working	CVW50519-2105	C	04/08/2021 14:50
155-65	WT19	no brake fluid , brakes not working fully	CVW51576-2111	C	05/20/2021 10:01
155-65	WT19	Front axle link broken bolts	CVW51745-2011	C	05/31/2021 15:03
155-65	WT19	RADIATOR	CVW47133-2004	C	09/11/2020 15:51
155-65	WT19	THERMOSTAT/WATER TEMP REG	CVW47134-2004	C	09/11/2020 15:51
155-65	WT19	P2 tyre flat	CVW52024-2012	C	06/22/2021 10:49
155-65	WT19	Cannot select gears forward or reverse	CVW52728-2102	C	08/03/2021 15:21
155-65	WT19	minor leaks ?? brake fluid	CVW52839-2102	C	08/12/2021 8:57
155-65	WT19	2000HR SERVICE	CVW13570-1706	C	11/23/2022 9:32

155-65	WT19	steel filler pipe on tanks rusted or cracked	CVW52987-2108	C	08/23/2021 11:06
155-65	WT19	250hr service	CVW51578-2011	C	09/07/2021 21:55
155-65	WT19	Keeps popping out of gear	CVW53874-2104	C	10/15/2021 13:29
155-65	WT19	aircon and 2 way not working aerial damaged	CVW53907-2104	C	10/18/2021 12:29
155-65	WT19	Needs new rear hose,(hose reel hose)	CVW54206-2106	C	11/02/2021 14:44
155-65	WT19	no drive will not select gears	CVW54270-2105	C	11/05/2021 14:35
155-65	WT19	Clutch slave cylinder leaking	CVW54562-2108	C	11/19/2021 12:38
155-65	WT19	Air leak low air pressure	CVW55434-2107	C	01/19/2022 9:11
155-65	WT19	Right spray won't turn off	CVW55518-2107	C	01/25/2022 8:17
155-65	WT19	coolant cap or tank leaking	CVW55552-2107	C	01/28/2022 8:26
155-65	WT19	front wheel bouncing and shaking on road	CVW55711-2111	C	02/07/2022 7:21
155-65	WT19	water tank outlet tap leaking	CVW55874-2109	C	02/16/2022 7:37
155-65	WT19	lh lower window requires sealing	CVW56263-2109	C	03/09/2022 11:18
155-65	WT19	require lhs window hinges	CVW56264-2111	C	03/09/2022 11:23
155-65	WT19	Windsreen Wipers not working	CVW56425-2110	C	03/18/2022 9:21
155-65	WT19	flashing light not working , horn not working	CVW56700-2110	C	04/04/2022 9:40
155-65	WT19	possible air leak at Air compressor	CVW56752-2111	C	04/06/2022 13:59
155-65	WT19	dribble bar not working	CVW56755-2111	C	04/06/2022 14:35
155-65	WT19	500HR service	CVW55369-2107	C	01/14/2022 6:17
155-65	WT19	250HR SERVICE	CVW56288-2109	C	03/22/2022 14:53
155-65	WT19	BATTERY	CVW57532-2307	C	12/21/2023 19:52
155-65	WT19	roof leaking	CVW58338-2204	C	07/14/2022 11:32
155-65	WT19	cannot drain air tanks, debris in water tank	CVW60906-2205	C	11/08/2022 14:27
155-65	WT19	exhaust muffler rusted out	CVW39104-1811	C	05/16/2019 21:25
155-65	WT19	bolts missing on chassis to rod end	CVW61292-2205	C	11/21/2022 15:09
155-65	WT19	aircon not working	CVW61392-2207	C	11/24/2022 8:59
155-65	WT19	needs sunvisor	CVW61930-2206	C	12/15/2022 14:28
155-65	WT19	(ACC rear left tyre leaking air (P5)	CVW61932-2208	C	12/15/2022 14:42
155-65	WT19	wiper blades need replacing , dustex on windows	CVW62375-2207	C	01/12/2023 10:00
155-65	WT19	1000HR SERVICE	CVW61599-2206	C	01/19/2024 10:07
155-65	WT19	reverse beeper not working	CVW63379-2210	C	02/21/2023 9:00
155-65	WT19	left hand brake booster leaking air	CVW63449-2208	C	02/23/2023 11:30
155-65	WT19	Rear Axe changed out P5 &P6 brake need over haul	CVW63551-2307	C	12/21/2023 19:52
155-65	WT19	rear chassis on water cart rusted through	CVW63621-2307	C	12/21/2023 19:52
155-65	WT19	hydraulic line to water pump failed	CVW63641-2209	C	03/02/2023 9:39

155-65	WT19	forward reverse lever loose	CVW64151-2209	C	03/16/2023 15:24
155-65	WT19	bolts on torsion bar loose	CVW64260-2209	C	03/21/2023 7:30
155-65	WT19	(ACC) failed hydraulic hose	CVW65040-2209	C	03/29/2023 11:43
155-65	WT19	tank sight glass needs chaning	CVW65041-2209	C	03/29/2023 11:48
155-65	WT19	250HR SERVICE	CVW62229-2207	C	03/16/2023 8:54
155-65	WT19	air pressure slow to build up (air leaks)	CVW65371-2307	C	12/21/2023 19:52
155-65	WT19	Centre spray broken off rear of machine	CVW66143-2211	C	05/12/2023 10:08
155-65	WT19	500HR SERVICE	CVW63791-2209	C	05/16/2023 8:44
155-65	WT19	2-way antenna has come loose	CVW66624-2212	C	05/29/2023 10:10
155-65	WT19	CLUTCH MASTER CYLINDER	CVW51418-2404	C	10/14/2024 11:03
155-65	WT19	ELECTRIC STARTING MOTOR	CVW51403-2011	C	05/31/2021 0:00
155-65	WT19	FIRE EXTINGUISHER	CVW66044-2211	C	02/01/2023 0:00
155-65	WT19	FIRE EXTINGUISHER	CVW58776-2202	C	06/12/2022 9:54
155-65	WT19	FIRE EXTINGUISHER	CVW54350-2105	C	11/01/2021 0:00
155-65	WT19	FIRE EXTINGUISHER 26.06.21	CVW48443-2006	C	06/26/2021 0:00
155-65	WT19	P6 TYRE	CVW32294-1710	C	11/22/2021 0:00
155-65	WT19	PARK BRAKE ACTUATOR	CVW51415-2307	C	12/21/2023 19:52
155-65	WT19	POS2 TRACTOR JOINT HUB	CVW51414-2011	C	10/07/2024 12:17
155-65	WT19	rear tailshaft failure ,Uni joints	CVW49054-2008	C	02/01/2021 10:27
155-65	WT19	water tank cap leaking	CVW61218-2206	C	11/18/2022 10:27
155-65	WT19	FIRE EXTINGUISHER	CVW67663-2301	C	04/01/2024 16:10
155-65	WT19	hydraulic motor/waterpump coupling worn out	CVW70448-2307	C	12/21/2023 19:52
155-65	WT19	rear bumper rusted out on trailer	CVW70867-2307	C	12/21/2023 19:52
155-65	WT19	watertank outlet rust area to repair	CVW71266-2304	C	10/05/2023 7:52
155-65	WT19	P4 flat tyre	CVW50232-2010	C	03/29/2021 20:39
155-65	WT19	leak form rear diff pinion	CVW72174-2305	C	11/10/2023 8:43
155-65	WT19	reverse alarm not working	CVW72287-2305	C	11/15/2023 8:08
155-65	WT19	(ACC) P6 tyre flat damage	CVW73087-2306	C	12/18/2023 7:33
155-65	WT19	noise coming from gooseneck area	CVW73149-2306	C	12/19/2023 13:49
155-65	WT19	beacon not working	CVW73453-2307	C	01/08/2024 10:14
155-65	WT19	Fan-belt squeals at times.	CVW73783-2307	C	01/30/2024 9:13
155-65	WT19	250hr service	CVW71501-2307	C	12/21/2023 19:52
155-65	WT19	blown hose in gooseneck area	CVW74066-2308	C	02/13/2024 9:49
155-65	WT19	Park brake not releasing, air leaking at rear of tanker when park brake is pressed.	CVW74096-2308	C	02/14/2024 11:38
155-65	WT19	Leaking hose inside goose neck.	CVW74102-2308	C	02/16/2024 14:49

155-65	WT19	pos 3 tyre off the rim	CVW56241-2109	C	03/08/2022 3:02
155-65	WT19	2000HR SERVICE	CVW74360-2309	C	11/28/2024 7:27
155-65	WT19	Air conditioning	CVW74917-2309	C	03/27/2024 11:26
155-65	WT19	engine comes to a stop alt symbol on dash	CVW74968-2310	C	04/02/2024 11:51
155-65	WT19	(acc) Right rear quart window smashed	CVW75046-2312	C	04/04/2024 9:48
155-65	WT19	Leaking oil off trailer connection	CVW75476-2311	C	04/30/2024 9:41
155-65	WT19	p6 tyre	CVW75517-2311	C	05/01/2024 10:08
155-65	WT19	Lost all power driving won't start now	CVW75715-2311	C	05/13/2024 10:54
155-65	WT19	250HR SERVICE	CVW74706-2309	C	05/28/2024 23:37
155-65	WT19	flat tyre (p3)	CVW62740-2207	C	01/30/2023 8:05
155-65	WT19	500HR SERVICE	CVW75890-2311	C	07/21/2024 22:32
155-65	WT19	LOST POWER TO DASHBOARD	CVW77501-2401	C	07/30/2024 7:55
155-65	WT19	engine wont start	CVW77866-2402	C	08/12/2024 14:37
155-65	WT19	Gear stick feels like it's about to snap	CVW77910-2402	C	08/14/2024 11:33
155-65	WT19	no lights	CVW79233-2403	C	11/28/2024 16:31
155-65	WT19	multiple air leaks	CVW79234-2403	C	02/20/2025 13:03
155-65	WT19	FIRE EXTINGUISHER	CVW78492-2402	C	11/01/2024 13:10
155-65	WT19	REPORTED SPLITTER BOX NOT WORKING - REA118073	CVW79390-2404	C	10/07/2024 12:17
155-65	WT19	Gear loose,	CVW79418-2404	C	10/08/2024 9:50
155-65	WT19	250HR SERVICE	CVW77202-2401	C	10/27/2024 16:13
155-65	WT19	(acc) windscreen cracked	CVW80339-2405	C	11/19/2024 11:01
155-65	WT19	work done at haggies september 2024	CVW80493-2405	C	11/28/2024 16:31
155-65	WT19	P5 tyre flat	CVW77196-2401	C	07/15/2024 12:36
155-65	WT19	Brake light comes on gears hard to get in sometime	CVW80681-2406	C	12/09/2024 13:43
155-65	WT19	3rd gear hard to get in	CVW81812-2406	C	12/13/2024 10:13
155-65	WT19	park brake Lost all air lights 123 on	CVW81857-2406	C	12/17/2024 15:43
155-65	WT19	Left hand head light broken	CVW81895-2406	C	12/19/2024 9:32
155-65	WT19	(ACC) Left hand hand light broken	CVW81973-2407	C	01/06/2025 9:11
155-65	WT19	truck making clunking noise	CVW82112-2407	C	07/08/2025 8:23
155-65	WT19	air not releasing truck wont move	CVW82213-2407	C	01/17/2025 9:01
155-65	WT19	steering box leak	CVW82298-2407	C	01/22/2025 9:37
155-65	WT19	engine oil leak	CVW82299-2407	C	07/08/2025 8:23
155-65	WT19	Air leaking somewhere park brake won't release	CVW82817-2408	C	02/20/2025 9:55
155-65	WT19	(ACC) POS 4 WHEEL HUB DAMAGE	CVW82851-2408	C	07/08/2025 8:23
155-65	WT19	engine wont start	CVW77521-2402	C	07/30/2024 13:06

155-65	WT19	500HR SERVICE	CVW82260-2407	C	03/28/2025 3:54
155-65	WT19	King Pin Checks	CVW84246-2410	C	02/27/2025 13:47
155-65	WT19	NAVMAN DEINSTALL	CVW85735-2501	C	07/08/2025 8:23
155-65	WT19	To run up machine ready for disposal	CVW87637-2503	C	09/18/2025 13:11
155-65	WT19	clutch burnt out	CVW78289-2403	C	11/28/2024 16:31
155-65	WT19	rear tail shaft failed	CVW72304-2305	C	11/15/2023 7:42
155-65	WT19	REAR DRIVE SHAFT, failed uni joints	CVW51405-2012	C	06/04/2021 14:57
155-65	WT19	P5 RIM NDT	CVW71393-2304	C	12/21/2023 19:52
155-65	WT19	P6 RIM NDT	CVW71394-2304	C	12/21/2023 19:52