

Model	Equipment	Description	Workorder Number	Status	Plan Start
155-65	WT26	Windscreen cracked	CVW7918-1705	C	11/27/2017 12:11
155-65	WT26	Wipers dont work	CVW7920-1705	C	11/27/2017 13:56
155-65	WT26	Horn does not work	CVW7922-1711	C	11/27/2017 13:57
155-65	WT26	Water sprays dont work correctly	CVW7924-1707	C	11/27/2017 13:56
155-65	WT26	position 2 brake pipe leaking	CVW16829-1706	C	12/14/2017 7:37
155-65	WT26	dribble bar leaking	CVW17303-1707	C	01/13/2018 13:39
155-65	WT26	can not engage 1st-2nd gear hose clamp missing from dribble bar	CVW17522-1707	C	05/19/2018 13:36
155-65	WT26	500HR SERVICE	CVW13554-1706	C	04/10/2018 18:38
155-65	WT26	no electrical power to dash	CVW34840-1711	C	05/19/2018 13:00
155-65	WT26	cltch pedal to easy	CVW34842-1711	C	05/19/2018 13:05
155-65	WT26	FIRE EXTINGUISHER	CVW13536-1706	C	03/01/2018 9:24
155-65	WT26	Steering Shaft (Replace) @ D.Force	CVW34978-1712	C	07/01/2018 15:55
155-65	WT26	various winter repairs at diesel force	CVW36153-1802	C	08/13/2018 14:50
155-65	WT26	pressure test transmission clutch slipping also	CVW36154-1802	C	08/13/2018 14:50
155-65	WT26	engine rear main oil seal leaking	CVW36155-1802	C	08/13/2018 14:50
155-65	WT26	water tank hydraulic motor change out	CVW36156-1802	C	08/13/2018 14:50
155-65	WT26	Clutch & Rear Main @ DIESEL FORCE	CVW13578-1804	C	08/22/2018 1:58
155-65	WT26	FIRE EXTINGUISHER	CVW35940-1802	C	09/12/2018 2:00
155-65	WT26	PARK BRAKE ACTUATOR	CVW13472-1706	C	08/13/2018 14:50
155-65	WT26	POS 1 FINAL DRIVE ASSEM	CVW36157-1802	C	08/13/2018 14:50
155-65	WT26	POS 2 FINAL DRIVE ASSEM	CVW36158-1802	C	08/13/2018 14:50
155-65	WT26	POS1 TRACTOR JOINT HUB	CVW36159-1802	C	08/13/2018 14:50
155-65	WT26	POS2 TRACTOR JOINT HUB	CVW36160-1802	C	08/13/2018 14:50
155-65	WT26	Replace fill point fitting on tank	CVW37682-1805	C	11/19/2018 14:20
155-65	WT26	Fit new hour meter	CVW38289-1808	C	02/01/2019 11:43
155-65	WT26	Trouble selecting gears early in morning	CVW38316-1808	C	02/06/2019 11:04
155-65	WT26	(ACC) WATER PUMP [TRAILER] not working	CVW13636-1706	C	11/21/2018 20:46
155-65	WT26	250HR SERVICE	CVW13545-1909	C	02/25/2020 12:00
155-65	WT26	250HR SERVICE	CVW38413-2004	C	10/15/2020 11:46
155-65	WT26	FIRE EXTINGUISHER	CVW38497-1808	C	03/16/2019 14:17
155-65	WT26	Modify Fire hose tap access	CVW38950-1810	C	03/29/2019 13:43
155-65	WT26	FIRE EXTINGUISHER	CVW39837-1901	C	07/08/2019 14:09
155-65	WT26	250HR SERVICE	CVW39303-2110	C	04/04/2022 7:10
155-65	WT26	Water sight glass required	CVW41355-1905	C	11/21/2019 12:07

155-65	WT26	FIRE EXTINGUISHER	CVW41530-1906	C	01/18/2020 7:37
155-65	WT26	trailer plug electrical damaged	CVW42686-1909	C	02/25/2020 15:22
155-65	WT26	1000HR SERVICE	CVW13563-2008	C	02/24/2021 13:14
155-65	WT26	chassis on trailer rusted out(welding repairs) Total overhaul	CVW43663-1912	C	04/30/2020 7:10
155-65	WT26	Overhaul WATER PUMP (TANK)	CVW43713-1910	C	04/30/2020 7:10
155-65	WT26	P5 TYRE	CVW32275-1710	C	05/26/2020 7:15
155-65	WT26	P6 TYRE	CVW32287-1710	C	05/26/2020 7:15
155-65	WT26	Overhaul position 5 and 6 rims rusty	CVW44069-1912	C	05/26/2020 7:15
155-65	WT26	CLUTCH MASTER CYLINDER	CVW13584-1908	C	11/21/2019 5:07
155-65	WT26	FIRE EXTINGUISHER	CVW44436-1912	C	07/31/2020 9:31
155-65	WT26	Flashing light not working	CVW45115-2001	C	07/23/2020 7:03
155-65	WT26	Dribble bar actuator and lines required	CVW45128-2001	C	07/23/2020 11:51
155-65	WT26	PTO not engaging water pump	CVW45157-2001	C	07/24/2020 10:15
155-65	WT26	(ACC) P3 TYRE staked	CVW32247-2204	C	10/05/2022 6:50
155-65	WT26	2000HR SERVICE	CVW13572-2205	C	12/06/2022 9:52
155-65	WT26	air con repair	CVW36163-1802	C	08/13/2018 14:50
155-65	WT26	BATTERY	CVW50506-2305	C	11/08/2023 10:41
155-65	WT26	BATTERY	CVW13333-2009	C	03/08/2021 15:52
155-65	WT26	operator seat	CVW81896-2406	C	12/19/2024 9:34
155-65	WT26	P4 TYRE flat	CVW32261-2403	C	07/30/2024 16:54
155-65	WT26	REAR DRIVE SHAFT	CVW13382-2401	C	06/27/2024 16:06
155-65	WT26	POS 3 FINAL DRIVE ASSEM	CVW43711-2005	C	11/02/2020 6:35
155-65	WT26	Rabbit mode not working	CVW45932-2209	C	08/31/2020 11:56
155-65	WT26	aircon belt slips at times	CVW46007-2003	C	09/03/2020 11:06
155-65	WT26	Air leak from hose next to steps	CVW46211-2003	C	09/11/2020 8:45
155-65	WT26	Clutch issues	CVW46458-2003	C	09/21/2020 16:36
155-65	WT26	Replace camlock	CVW47206-2004	C	10/29/2020 11:47
155-65	WT26	FIRE EXTINGUISHER 30.01.21	CVW48495-2006	C	01/30/2021 13:32
155-65	WT26	500HR SERVICE	CVW45791-2003	C	02/06/2021 6:47
155-65	WT26	Steering wanders on the road	CVW49444-2011	C	02/18/2021 8:17
155-65	WT26	air con keeps cutting out	CVW49426-2008	C	02/19/2021 9:01
155-65	WT26	trans shifter only able to select 3rd and 4th	CVW49457-2008	C	02/19/2021 9:19
155-65	WT26	engine mounts due for change	CVW49458-2011	C	02/19/2021 9:21
155-65	WT26	Radiator ,mounts , Fan and shroud due for change	CVW49459-2011	C	02/19/2021 9:40
155-65	WT26	Throttle is getting stuck open/full now broken	CVW49510-2108	C	02/03/2022 11:46

155-65	WT26	cannot grease gooseneck	CVW49560-2008	C	02/24/2021 8:42
155-65	WT26	loss of tourqe moving at 2 kmph	CVW50194-2009	C	03/26/2021 8:51
155-65	WT26	trailer lights not working	CVW50488-2010	C	04/07/2021 11:48
155-65	WT26	FIRE EXTINGUISHER	CVW52232-2101	C	07/03/2021 14:14
155-65	WT26	FIRE EXTINGUISHER	CVW54872-2106	C	06/12/2022 9:59
155-65	WT26	aircon not working	CVW55670-2109	C	02/03/2022 14:19
155-65	WT26	No reverse	CVW55939-2108	C	02/18/2022 10:18
155-65	WT26	(ACC) RH Front lower windscreen cracked	CVW55943-2109	C	02/18/2022 11:33
155-65	WT26	Left side batter spray solenoid not opening	CVW56470-2109	C	03/21/2022 12:42
155-65	WT26	RH batter spray broke while trying to adjust	CVW56732-2110	C	03/08/2023 14:56
155-65	WT26	chain on dribble bar broken	CVW56878-2203	C	04/14/2022 10:14
155-65	WT26	left spray not working	CVW57316-2209	C	05/17/2022 13:36
155-65	WT26	Goes into gear but won't move	CVW57337-2111	C	05/18/2022 10:55
155-65	WT26	fan belts due for change out	CVW57490-2211	C	05/26/2022 14:09
155-65	WT26	Steering and Hyd pump failed P2 Shock leaking rear on bump stops	CVW57492-2207	C	05/26/2022 14:00
155-65	WT26	acc pedal not releasing off floor	CVW57675-2112	C	06/07/2022 14:01
155-65	WT26	Steer boc overhauled & steering stop mount loose	CVW38545-1809	C	02/16/2019 7:02
155-65	WT26	right side spray not turning off	CVW58387-2211	C	07/18/2022 10:54
155-65	WT26	gear shift lever has a lot of play	CVW58417-2211	C	07/20/2022 7:28
155-65	WT26	Accelerator issue stuck and not working	CVW58841-2202	C	08/15/2022 10:54
155-65	WT26	air pressure wont build up , air leak	CVW58864-2202	C	08/17/2022 9:09
155-65	WT26	jack knife alarm not working, indicators not working	CVW59079-2303	C	08/30/2022 11:27
155-65	WT26	reverse alarm not working	CVW59080-2202	C	08/30/2022 11:30
155-65	WT26	heater not working	CVW59255-2203	C	09/08/2022 14:12
155-65	WT26	needs 10 metres of 30mm hose for water tank	CVW60273-2204	C	10/17/2022 8:17
155-65	WT26	indicators not working	CVW60617-2211	C	10/31/2022 7:00
155-65	WT26	500HR SERVICE	CVW57838-2112	C	12/03/2022 12:50
155-65	WT26	FIRE EXTINGUISHER	CVW61035-2205	C	02/01/2023 13:11
155-65	WT26	steering and gearbox having issues at times	CVW62798-2211	C	03/08/2023 14:56
155-65	WT26	slow leak in rear tyres , no position given	CVW63087-2211	C	02/10/2023 13:43
155-65	WT26	aircon not cooling only fan working	CVW63383-2211	C	02/21/2023 11:19
155-65	WT26	(ACC) 2 way connection broken	CVW63411-2211	C	02/22/2023 7:59
155-65	WT26	clutch burnt out	CVW63862-2211	C	03/10/2023 7:50
155-65	WT26	air system leaks (boosters)	CVW65246-2211	C	04/05/2023 8:37
155-65	WT26	injector fuel pump leaking	CVW65281-2211	C	03/08/2023 14:56

155-65	WT26	air leaking from brake valves	CVW65282-2211	C	04/06/2023 8:50
155-65	WT26	brakes locked on	CVW65442-2210	C	04/14/2023 15:17
155-65	WT26	250HR SERVICE	CVW41861-1906	C	05/08/2023 7:55
155-65	WT26	dribble bar chain is broken	CVW66199-2211	C	05/15/2023 14:24
155-65	WT26	engine stalled and had trouble starting	CVW66300-2211	C	05/18/2023 13:53
155-65	WT26	minor works by H.I plant	CVW66561-2211	C	03/08/2023 14:56
155-65	WT26	water cart will not go into gear	CVW66663-2211	C	05/30/2023 9:14
155-65	WT26	engine oil leak	CVW66664-2301	C	05/30/2023 9:17
155-65	WT26	repair crack in gooseneck	CVW66709-2211	C	04/01/2023 14:15
155-65	WT26	rear left shockie mount cracked	CVW66710-2211	C	05/01/2023 15:18
155-65	WT26	FIRE EXTINGUISHER	CVW67664-2301	C	08/01/2023 15:36
155-65	WT26	engine wont start	CVW71539-2304	C	10/17/2023 10:57
155-65	WT26	reverse alarm not working	CVW71574-2304	C	10/18/2023 10:58
155-65	WT26	(ACC) missing rego plate	CVW72341-2305	C	11/16/2023 10:42
155-65	WT26	Hard to select gears. Losing air.	CVW72564-2305	C	11/23/2023 16:51
155-65	WT26	blown globe beacon	CVW73127-2307	C	12/19/2023 8:49
155-65	WT26	(ACC) smashed window rear	CVW73141-2307	C	12/19/2023 11:57
155-65	WT26	refit 1 kg fire to cab	CVW73761-2307	C	01/29/2024 13:41
155-65	WT26	FIRE EXTINGUISHER	CVW73374-2306	C	04/01/2024 10:34
155-65	WT26	Transmission shift lever broken	CVW74043-2308	C	02/12/2024 11:01
155-65	WT26	No air ride/suspension on seat/no cushioning over rough terrain	CVW74289-2309	C	02/27/2024 9:32
155-65	WT26	left hand rear tractor shock failed	CVW74315-2309	C	02/28/2024 8:46
155-65	WT26	possible air leak	CVW74573-2309	C	03/12/2024 9:30
155-65	WT26	air leak	CVW74930-2310	C	03/28/2024 9:47
155-65	WT26	wont go into gear	CVW74944-2310	C	03/28/2024 16:15
155-65	WT26	Right hand door windows latch	CVW74998-2310	C	04/03/2024 10:01
155-65	WT26	Water cart has got an air leak	CVW75228-2311	C	04/15/2024 10:20
155-65	WT26	The hose has holes in it (hose reel)	CVW75229-2401	C	04/15/2024 10:22
155-65	WT26	aircond belt is loose	CVW75251-2310	C	04/16/2024 10:00
155-65	WT26	Front shock absorbers are worn out and old thanks	CVW75300-2311	C	04/18/2024 10:14
155-65	WT26	(acc) p5 tyre	CVW75937-2311	C	05/22/2024 15:07
155-65	WT26	Horn not working.	CVW76343-2312	C	06/25/2024 9:49
155-65	WT26	Bonnet needs repair	CVW76344-2312	C	06/06/2024 9:53
155-65	WT26	Rain enters cab through roof	CVW76423-2312	C	06/11/2024 10:03
155-65	WT26	LHS BATTER SPRAY REQUIRES REPAIR	CVW76705-2401	C	06/20/2024 8:45

155-65	WT26	water pump on tank leaking (change out)	CVW77025-2401	C	07/03/2024 16:40
155-65	WT26	500HR SERVICE	CVW66339-2308	C	05/19/2023 8:28
155-65	WT26	Center and right spray dont work	CVW78832-2403	C	09/11/2024 16:09
155-65	WT26	FIRE EXTINGUISHER	CVW78385-2402	C	11/01/2024 11:21
155-65	WT26	(ACC) P6 tyre deflated	CVW80034-2405	C	11/11/2024 7:42
155-65	WT26	Won't start,	CVW80369-2405	C	11/20/2024 15:24
155-65	WT26	250HR SERVICE	CVW44900-2311	C	01/18/2025 9:32
155-65	WT26	Cabin air filter replacement	CVW82279-2407	C	01/21/2025 11:21
155-65	WT26	HORN NOT WORKING	CVW82560-2408	C	02/04/2025 9:33
155-65	WT26	OIL LEAK	CVW82657-2408	C	02/10/2025 9:26
155-65	WT26	BRAKES ARE LOCKING ON	CVW82787-2408	C	02/18/2025 15:07
155-65	WT26	Air leaks from solenoid	CVW82788-2408	C	02/18/2025 15:08
155-65	WT26	1000HR SERVICE	CVW57151-2312	C	06/20/2024 3:09
155-65	WT26	Water leaks dribble bar stuck open	CVW83312-2409	C	03/18/2025 10:13
155-65	WT26	250HR SERVICE	CVW80659-2406	C	03/21/2025 8:46
155-65	WT26	King Pin Checks	CVW84248-2410	C	04/04/2025 14:03
155-65	WT26	FIRE EXTINGUISHER	CVW83671-2410	C	05/01/2025 16:27
155-65	WT26	(acc)Requires new key barrel key broken off	CVW84625-2411	C	05/14/2025 9:09
155-65	WT26	Reverse Alarm	CVW84634-2411	C	05/14/2025 10:31
155-65	WT26	500HR SERVICE	CVW80660-2406	C	05/18/2025 5:22
155-65	WT26	Navman Deinstall	CVW85736-2501	C	07/08/2025 8:27
155-65	WT26	BATTERY	CVW80638-2406	C	08/18/2025 18:55
155-65	WT26	Requires 2 new batteries please, Run up machine ready for disposal, Remove RJV decals	CVW87644-2503	C	09/18/2025 13:50
155-65	WT26	Trailer brake system repairs	CVW45104-2001	C	07/22/2020 13:17
155-65	WT26	P1 coil spring broken	CVW49456-2011	C	02/19/2021 9:07
155-65	WT26	(ACC) impellerseized on pump by debris	CVW55669-2108	C	02/03/2022 14:11
155-65	WT26	water pump not working properly	CVW80259-2405	C	01/10/2024 6:00