

JBS Mechanical Inc
Box 353
Whitecourt, AB T7S 1N5

jbsmechanical.service@gmail.com

GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
1-780-779-6759

20-10

Invoice #	Date
30430	5/21/2023

P.O. No.	Terms
	Net 30

Invoice To

NEWGEN ENERGY SERVICES

Location	Work Order #	Make/Model	Unit Number
ST-13	6714		204B

Item	Description of Item	Bin	Qty	Rate	Area	Amount
CVIP Trailer ...	CVIP - 2 Axle		1	190.00		190.00
Regular Time	Inspection and repair axle 1,2 l/h brake not releasing properly, clevis is seized, remove and replaced, all shocks leaking, removed and replaced, all wheel seals leaking, removed and replaced, axle 2 r/h slack adjuster pin missing nut, replaced		8	150.00		1,200.00
65419	SHOCK ABSORBER B23566, M85000	Shock Bin	4	86.65		346.60
46300	TRAILER WHEEL SEAL	S 10 D	4	52.95		211.80
330-3009	OIL HUB CAP GASKET 3009	End 1	4	2.85		11.40
75W901LJ	75W90 SYNTHETIC OIL 1L JUG	PR 6 FL...	4	19.80		79.20
FS-5082A	CLEVIS ASSY 5/8-1/2 PIN	S 12 A	2	3.60		7.20
Shop Supplies	8% of Base Labour		9	12.00		108.00

If we have had your wheels off re-torque within 100 km's.

Flat rate charges may be subjected to a 75% increase for siezed or aftermarket parts.
A 25% increase in flat rate labor charge may occur due to excessive mud or snow on
units.

Parts warranty subject to manufactures approval.

If customer does not request old parts back they will be disposed of by JBS
Mechanical.

No return on electrical components or special order parts.

UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT
QUALIFY FOR WARRANTY

Subtotal \$2,154.20

GST/HST \$107.71

Total \$2,261.91

Payment \$0.00

Balance Due \$2,261.91