

205-39
BLUE-MAR

UNIT# 76

MAJOR WORK SUMMARY

CURRENT KMS: 1446366		CURRENT HRS: 12345			
NO.	DESCRIPTION	DATE	KM	HRS	INVOICE NO.
1	CAC KENWORTH T800 14-19	Oct-25	1427634	11964.6	238151
2	PERFORM VALVE SET	Apr-24	1242052	8663	289802
3	TRANSMISSION,CLUTCH,BEARING	Dec-23	1232597	8417	57903
4	ECM PROGRAMMING	May-22	1048561	5189	5208
5	DPF REPAIR	Apr-22	1031483	4938	5117
6	COMPLETE ENGINE REBUILT	May-19	632829	13535	LAST
*PLEASE SEE ATTACHED INVOICES FOR DETAILED REPAIR WORK DONE					

UNIT = 76

ABS TRUCK & TRAILER PARTS LTD.

6030 125 AVENUE NW
EDMONTON, ALBERTA, T5W 1Z6
CANADA
TEL: +1 (780) 479-4700
FAX: +1 (780) 479-7995

Sales Representative: SONA BHULLAR

PAYMENTS CAN BE MADE VIA.

Interac e-Transfer: ABSTRUCKPARTS@GMAIL.COM

Sold to:

ABS TRUCKING LTD
6030 125 AVENUE NW
, EDMONTON, AB, T5W 1Z6

SALES INVOICE

Sales Invoice #: 238151
Date: 28 OCT, 2025
PO: 76
Unit #: 76
VIN #:
Purchased By:
Account Number:
Page #: 1 of 1

CHECKS PAYABLE TO:

ABS TRUCK & TRAILER PARTS LTD.
6030 125 AVE NW, EDMONTON, ALBERTA, T5W 1Z6

Ship to:

ABS TRUCKING LTD
6030 125 AVENUE NW
, EDMONTON, AB, T5W 1Z6

***** ABS TRUCK & TRAILER PARTS LTD. NOW OPEN 7 DAYS A WEEK *****

Business Number: 727752099RT001

ITEM IDENTIFIER	UNIT	QTY	DESCRIPTION	TAX%	BASE PRICE	DISC%	UNIT PRICE	AMOUNT
2310279AL	Each	1	CAC 08-19 KENWORTH T800 14-19, TR 880 2310279AL 5192N 2401-005	5.00	660.00	0.00	660.00	660.00

ON ACCOUNT

2025-10-28 02:27:24 PM MDT

2025-10-28 02:27:24 PM MDT

***** No Return or Warranty on Electrical Products and Accessories. *****

Please note all Returns may be subjected upto 20% re-stocking fee.

Subtotal:	\$ 660.00
Total Discount:	\$ 0.00
Total GST/HST Tax:	\$ 33.00
Total Amount:	\$ 693.00
Amount Paid:	\$ 0.00
Amount Owing:	\$ 693.00

Terms and Conditions

Repair Acknowledgement: I, the undersigned owner or representative, acknowledge the indebtedness related to the repair and service work listed above, along with the purchase and installation of any necessary parts and materials. I confirm I have Payment Terms: Payment for repairs are due upon the receipt of unit unless charged to customer's account. Payment of account is due in full by the 15th day of the month following the statement date. Unpaid balances will be charged interest of 2% per month compounded monthly (26.82% per annum).

Garage Keepers Lien: By signing below you acknowledge and agree that the vehicle described above is subject to a Garage Keepers' Lien in favour of ABS Truck and Trailer Parts Ltd. and ABS Truck Wash and Lube Ltd. as permitted under the Garage Keepers' Lien Act (Alberta/Canada), as amended from time to time.

Warranty Considerations: ABS Truck and Trailer Parts Ltd. and ABS Truck Wash and Lube Ltd. will submit warranty claim to the manufacturer for any portion of this repair that is designated for warranty considerations. If the manufacturer rejects the or portion of the claim, the owner shall pay that portion which is rejected in accordance with the Payment Terms set out above.

Warranty Limitation: Subject to the requirement below, all services carry a 30-day warranty from the date ABS Truck and Trailer Parts Ltd. and ABS Truck Wash and Lube Ltd. completed the work. The owner must advise ABS Truck and Trailer Parts Ltd. and ABS Truck Wash and Lube Ltd. of any warranty, claim within 5 days of the failure date. Certain Parts, products, accessories, materials, and other items used in completing the repair and servicework may be manufactured and supplied by third parties. The quality and workmanship of such items are entirely outside the control of ABS Truck and Trailer Parts Ltd. & ABS Truck Wash and Lube Ltd. makes no warranties, whether expressed, implied, statutory, or otherwise, including any warranty of merchantability or of fitness for a particular purpose with respect to such such items. Responsibility for Vehicle and Contents: ABS Truck and Trailer Parts Ltd. and ABS Truck Wash and Lube Ltd. is not responsible for loss or damage to the vehicle, or to articles, left in vehicles, in case of fire, theft, vandalism, or accident.

Signature: _____

ABS TRUCK & TRAILER PARTS LTD.

6030 125 AVENUE NW
 EDMONTON, ALBERTA, T5W 1Z6
 CANADA
 TEL: +1 (780) 479-4700
 FAX: +1 (780) 479-7995

SALES INVOICE

Sales Invoice #: 57903
 Date: 28 DEC, 2023
 PO: 76
 Unit #: 76
 VIN #:
 Purchased By:
 Account Number:
 Page #: 1 of 1

PAYMENTS CAN BE MADE VIA.

Interac e-Transfer: AHSTRUCKPARTS@GMAIL.COM

CHECKS PAYABLE TO:

ABS TRUCK & TRAILER PARTS LTD.
 6030 125 AVE NW, EDMONTON, ALBERTA, T5W 1Z6

Sold to:

ABS TRUCKING LTD
 6030 125 AVENUE NW
 EDMONTON, AB, T5W 1Z6
 CANADA

Shp to:

ABS TRUCKING LTD
 6030 125 AVENUE NW
 EDMONTON, AB, T5W 1Z6
 CANADA

***** ABS TRUCK & TRAILER PARTS LTD. NOW OPEN 7 DAYS A WEEK *****

Business Number: 727752099RT0001

ITEM IDENTIFIER	UNIT	QTY	DESCRIPTION	TAX %	BASE PRICE	DISC%	UNIT PRICE	AMOUNT
RTL018918B	Each	1	18 SPEED MANUAL TRANSMISSION	5.00	4,407.00	0.00	4,407.00	4,407.00
CS106C1498	Each	1	SHAFT-CROSS, CLUTCH	5.00	18.99	0.00	18.99	18.99
SB200-B	Each	1	SB20C BABCOCK CLUTCH BRAKE	5.00	52.99	0.00	52.99	52.99
DAT12815	Each	4	BUSHING CLUTCH RELAY SHAFT	5.00	4.99	0.00	4.99	19.96
21-635P	Each	1	SWITCH-BACKUP LAMP	5.00	20.99	0.00	20.99	20.99
M-1996	Each	1	SHAFT,CROSS PETE (06-01093)	5.00	58.99	0.00	58.99	58.99
303005-25	Each	1	ADVANTAGE CLUTCH	5.00	1,325.00	0.00	1,325.00	1,325.00
SR528-1010	Each	2	FITTING,STEEL, SWIVEL, 5/8-5/8 (NO -10)	5.00	15.05	0.00	15.05	30.10
HR5-12-REEL	Each	10	3/4 NOM. ID 100R5 HOSE REEL NO 12	5.00	7.35	0.00	7.35	73.50
19094142	Each	1	CENTER BEARING	5.00	125.45	0.00	125.45	125.45
250-70-18X	Each	2	BEARING RETAINER KIT	5.00	27.99	0.00	27.99	55.98
STP900013	Each	2	V-BAND CLAMP	5.00	26.99	0.00	26.99	53.98
132033	Each	2	CASKET, AFM, DEV	5.00	12.99	0.00	12.99	25.98
30-2051	Each	1	STRAIGHT 7 WAY,ABS,12? CABLE, P HILIPS	5.00	141.35	0.00	141.35	141.35

2023-12-28 10:11:24 PM MST

*** No Return or Warranty on Electrical Products and Accessories. ***

Please note all Returns will be subjected to 20% re-stocking fee.

Subtotal: \$ 6,410.26
 Total Discount: \$ 0.00
 Total GST/HST Tax: \$ 320.51
 Total Amount: \$ 6,730.77
 Amount Paid: \$ 0.00
 Amount Owing: \$ 6,730.77

Terms and Conditions

Repair Acknowledgement: I, the undersigned owner or representative, acknowledge the indebtedness related to the repair and service work listed above along with the purchase and installation of any necessary parts and materials. I confirm I have
Payment Terms: Payment for repairs are due upon the receipt of work unless charged to customer's account. Payment of account is due in full by the 15th day of the month following the statement date. Unpaid balances will be charged interest of 2% per month compounded monthly (26.82% per annum).
Garage Keepers Lien: By signing below you acknowledge and agree that the vehicle described above is subject to a Garage Keepers Lien in favour of ABS Truck and Trailer Parts Ltd. and ABS Truck Wash and Lube Ltd. as permitted under the Garage Keepers Lien Act (Alberta/Canada), as amended from time to time.
Warranty Considerations: ABS Truck and Trailer Parts Ltd. and ABS Truck Wash and Lube Ltd. will submit warranty claim to the manufacturer for any portion of this repair that is designated for warranty considerations. If the manufacturer rejects the or portion of the claim, the owner shall pay that portion which is rejected in accordance with the Payment Terms set out above

Warranty Limitation: Subject to the requirement below, all services carry a 30-day warranty from the date ABS Truck and Trailer Parts Ltd. and ABS Truck Wash and Lube Ltd. completed the work. The owner must advise ABS Truck and Trailer Parts Ltd. and ABS Truck Wash and Lube Ltd. of any warranty, claim within 5 days of the failure date. Certain Parts, products, accessories, materials, and other items used in completing the repair and servicework may be manufactured and supplied by third parties. The quality and workmanship of such items are entirely outside the control of ABS Truck and Trailer Parts Ltd. & ABS Truck Wash and Lube Ltd. makes no warranties, whether expressed, implied, statutory, or otherwise, including any warranty of merchantability or of fitness for a particular purpose with respect to such such items. Responsibility for Vehicle and Contents: ABS Truck and Trailer Parts Ltd. and ABS Truck Wash and Lube Ltd. is not responsible for loss or damage to the vehicle, or to articles, left in vehicles, in case of fire, theft, vandalism, or accident

Signature: _____



ALLSPEC DIESEL SOLUTIONS INC INVOICE

12516 60 ST NW
 EDMONTON, Alberta T5W 5J6
 CANADA

Invoice No.: 5208
 Date: 02/05/2022
 Ship Date:
 Page: 1
 Re: Order No.

Sold to:

ABS TRUCKING LTD
 AMRIT GREWAL
 6030 125 AVE NW
 EDMONTON, AB T5W 1Z6

Ship to:

ABS TRUCKING LTD

Business No.: 784382087RT0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
		1	ECM PROGRAM	G	1,000.00	1,000.00
			Subtotal:			1,000.00
			G - GST 5% GST/HST			50.00
Shipped By: _____ Tracking Number: _____					Total Amount	1,050.00
Comment: UNIT#76					Amount Paid	0.00
Sold By: _____					Amount Owing	1,050.00



ALLSPEC DIESEL SOLUTIONS INC INVOICE

12516 60 ST NW
 EDMONTON, Alberta T5W 5J6
 CANADA

Invoice No.: 5117
 Date: 10/04/2022
 Ship Date:
 Page: 1
 Re: Order No.

Sold to:

ABS TRUCKING LTD
 AMRIT GREWAL
 6030 125 AVE NW
 EDMONTON, AB T5W 1Z6

Ship to:

ABS TRUCKING LTD

Business No.: 784382087RT0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
		1	DPF REPAIR	G	3,500.00	3,500.00
		1	SHOP SUPPLY	G	85.00	85.00
			Subtotal:			3,585.00
			G - GST 5% GST/HST			179.25
Shipped By: Tracking Number:					Total Amount	3,764.25
Comment: UNIT#76 VIN#283804					Amount Paid	0.00
Sold By:					Amount Owing	3,764.25

Stahl Peterbilt

PETERBILT
VMXXR036-1
UNIT TYPE 1

CHASSIS FINAL BILL
FOR VIN 1XPTD40X0FD283795
OF FLEET 283795 THRU 283804 *283804*

PAGE 001
AS OF 09/04/14

DEALER CODE - 1627
NAME AND ADDRESS
P.L. STAHL PETERBILT

CUSTOMER NO - 3ZQG
416/RENTAL 10-367/E015

DATES
REQ DELV 07/25/14

P.O. BOX 1518
BELLEVUE WA 98009

C20513-03

DELIVERY 09/04/14
PRIC EFF 09/04/14

Pacas Lease Back. work completed.

PREVIOUS CHASSIS NO.

THE FOLLOWING LIST DESCRIBES ALL COMPONENTS USED FOR THIS CHASSIS
DIMENSIONS AND WEIGHTS FOR THE ENTIRE ORDER ARE STATED IN CUSTOMARY.

APPLICATION
COMMODITY HAULED 0091120 CHEMICAL PRODUCTS
INTENDED SERVICE 0093020 TANKER, LIQUID BULK
BODY LENGTH .00 IN BODY HEIGHT .00 IN
MAX LADEN WEIGHT .00 LBS

TRAILER
TRAILER TYPE 0096080 TANK
TRAILER LENGTH 48.00 FT TRAILER HEIGHT 13.00 FT
KINGPIN 36.00 IN CTR LINE AXLE GRP .00 IN
CORNER RADIUS 5.00 IN NO TRAILER AXLES 03

OPERATING AREA RESTRICTIONS
LENGTH 40.00 FT WIDTH 102.00 IN HEIGHT 13.50 FT
**** DEALER ASSIGNED:

CHASSIS
FRONT AXLE LOAD 13200.00 LBS REAR AXLE LOAD 44000.00 LBS GCW 135000.00 LBS
WHEELBASE 230.00 IN FAX/BOC 76.80 IN CAB/AXLE 153.20 IN
CAB/EOF 209.20 IN MAXIMUM GRADE 09 PERCENT HIGHWAY 090
% CLASS B 005
% CLASS C 005
% CLASS D 000

PETERBILT
VMXXR036-1

CHASSIS FINAL BILL
FOR VIN 1XPTD40X0FD283795
UNIT TYPE 1 OF FLEET 283795 THRU 283804

PAGE 002
AS OF 09/04/14

SPECIAL REQUIREMENTS
SPECIAL RESTRICTIONS 0098020 CANADIAN REGISTRY

SPECIAL RESTRICTIONS 0098060 SEVERE SERVICE CATEGORY NUMBER TWO

ENGINEERING ASSIGNED RATINGS

GAWR FRONT: 13,200.00 LBS
GAWR FIRST INTER 23,000.00 LBS SECOND INTER 23,000.00 LBS
GAWR REAR: 0.00 LBS
GVWR: 59,200.00 LBS

CODE	DESCRIPTION	PUB CD	PRICE	WEIGHT
BASE MODEL				
3003671	MODEL 367 CONVENTIONAL	P		15,201
0200009	OMIT DUAL COMPLIANCE(CANADIAN REGISTRY)	P	0	0
FRAME AND EQUIPMENT				
0514000	10-3/4" STEEL RAILS TO 354" 3/8" RAIL THICKNESS	P	383	205
0611250	HD IRON FRONT SPRING BRKTS FORWARD & REAR	P	256	35
3644000	EOF TRACTOR TAPERED WITH XMBR INCL KINGPIN CUTOFF, CUTOFF NA W AL EOF	P	0	0
0651800	PB REAR MUDFLAPS, PREMIUM HANGERS STAINLESS STEEL	P	464	0
0835860	HOLLAND FW35 FIFTH WHEEL TOP PLATE	P	2,008	240
0870060	REAR OR FIXD SETTING BHD C/L BOGIE 006.			
0890090	LH FIFTH WHEEL RELEASE	P	0	0
0890550	7.6"-8" FIFTH WHEEL HEIGHT	P	0	95
0890590	20", 24", OR 24.5" AIR SLIDE FOR FIFTH WHEEL	P	60	216
0890642	SINGLE PLATE SLIDER ONLY AVAIL W/ 60" & 72" SLIDERS	P	0	0
0960000	FRAME MTD DECK PLATE & ACCESS PKG, LH SIDE	P	450	42
FRONT AXLE AND EQUIPMENT				
1011340	DANA SPICER E1322I 13,200 LB 3.5" DROP	P	275	44
1111200	TAPER LEAF SPRINGS, SHOCKS 13,200 LB	P	162	44
1233030	POWER STEERING TRW TASES	P	10-	0
1250180	POWER STEERING RESERVOIR, FRAME MOUNTED	P	0	0
1353550	PHP10 ALUMINUM PRESET+ HUBS - AIR DISC USE WITH FRONT AXLE	P	0	0
1380070	GREASABLE FRONT SPRING PINS	P	23	0
1380240	DANA SPICER WIDE TRACK 1PO STD FRONT AXLE(S)	P	100	4
1380290	AIR DISC FRONT BRAKES	P	0	0
1390540	DUST SHIELDS, CAM AND AIR DISC BRAKES FRONT AXLE	P	27	4
1390630	80 MM FRONT SPRING SPACER BLOCKS	U	0	0

CODE	DESCRIPTION	PUB CD	PRICE	WEIGHT
REAR AXLE AND EQUIPMENT				
1523340	DANA SPICER D46-170 46,000 LB	P	2,883	434
1616290	PHP10 ALUMINUM PRESET+ HUBS	P	0	0
1632640	HALDEX LIFESEAL PARKING BRAKES DRIVE AXLE(S)	P	102	18
1632650	LONG STROKE PARKING BRAKES DRIVE AXLE(S)	P	0	0
1660000	DUST SHIELDS FOR CAM BRAKES DRIVE AXLE(S)	P	82	0
1672630	DIFF LOCK BOTH AXLES	P	1,879	60
1673090	SEPARATE DASH CTRL CONT TRAC FULL LOCK TANDEM, TRI-DRIVE AXLES	P	100	2
1680420	X30 BRAKE DRUMS IPO STANDARD DRIVE AXLE(S)	P	188	79
1680450	REAR BRAKE CAMSHAFT REINFORCEMENT	P	94	9
1680470	LUBE PUMP, DRIVE AXLE(S)	P	279	35
1680490	GUSSETED CAM BRACKETS, DRIVE AXLE(S)	P	65	2
1680950	STABILITY SYSTEM NOT SELECTED OR NOT AVAILABLE	P	489	0
1682420	ISO 3731 CONNECTOR TRAILER ABS POWER MTD ADJACENT TO TRAILER SOCKET(S)	P	189	9
1682710	ANTI-LOCK BRAKING SYSTEM (ABS) 6S6M	P	0	0
1682830	15FT STRAIGHT ABS CABLE (2) ISO 3731 PLUGS	P	67	13
1684200	SYNTHETIC AXLE LUBRICANT ALL AXLES	P	0	0
1687010	BENDIX AIR CAM REAR DRUM BRAKES 16.5X7	P	0	0
1703910	RATIO 3.91 REAR AXLE	P	0	0
1821640	PETERBILT AIR TRAC 46,000 LB, 54" AS	P	1,685	291
1911010	STEEL SUSP INSERT UP TO 77" OVERHANG	P	581	185
1922260	DASH MTD DUMP SWITCH WITH INDICATOR LIGHT FOR SUSPENSTION	P	36	2
ENGINE AND ENGINE EQUIPMENT				
2059952	ISX15 550@2000 GOV@2000 1850@1200 FAMILY 3 (2013 EMISSIONS)	P	3,935	340
2091300	ENABLE PREFERRED EIST SETTINGS	P	0	0
2091305	ENGINE IDLE SHUTDOWN TIMER ENABLED	P	0	0
2091315	ENABLE EIST AMBIENT TEMP OVERRULE	P	0	0
2091384	EFF EIST 500000 EXPIRATION MILES (CAN)	P	0	0
2091760	EFFECTIVE VSL SETTING 65.0 MPH OR GREATER (CAN)	P	0	0
2140150	REMOTE PTO & THROTTLE PROVISION 12-PIN CONNECTOR ON ENGINE HARNESS	P	31	0
2140220	CARB ENGINE IDLING COMPLIANCE DECLINED BY DEALER/CUSTOMER	P	0	0
2141000	STEEL FRONT ENGINE SUPPORT IPO STD ALUM . P	P	333	20
N2132	N205 120...STANDARD MAXIMUM SPEED LIMIT			
N2133	N207 0....EXPIRATION DISTANCE (N207)			
N2134	P112 120...HARD MAXIMUM SPEED LIMIT (P1			
N2135	P001 75...MAXIMUM ACCELERATOR PRDAI, VE			
N2136	P110 0....ACCELERATOR LOWER DROOP (P11			
N2137	P059 75...MAXIMUM CRUISE SPEED (P059)			

CODE	DESCRIPTION	PUB CD	PRICE	WEIGHT
N2138	P111 0... CRUISE CONTROL LOWER DROOP (
N2140	N203 474... RESERVE SPEED FUNCTION RESET			
N2141	N202 0... MAXIMUM CYCLE DISTANCE (N202			
N2142	N206 10... MAXIMUM ACTIVE DISTANCE (N20			
N2143	N201 0... RESERVE SPEED LIMIT OFFSET (
N2144	P015 NO... ENGINE PROTECTION SHUTDOWN (
N2145	P026 NO... GEAR DOWN PROTECTION (P026)			
N2146	P046 1400... MAX PTO SPEED (P046)			
N2147	P062 NO... CRUISE CONTROL AUTO RESUME (
N2148	P068 NO... AUTO ENGINE BRAKE IN CRUISE			
N2150	N209 500... EXPIRATION DISTANCE (N209)			
N2151	P520 YES... ENABLE IDLR SHUTDOWN PARK BR			
N2152	P030 5... TIMER SETTING (P030)			
N2153	P233 YES... ENABLE IMPENDING SHUTDOWN WA			
N2154	P234 60... TIMER FOR IMPENDING SHUTDOWN			
N2155	P516 35... ENGINE LOAD THRESHOLD (P516)			
N2157	P031 NO... IDLE SHUTDOWN MANUAL OVERRUL			
N2159	P230 YES... ENABLE HOT AMBIENT AUTOMATIC			
N2161	P172 40... LOW AMBIENT TEMPERATURE THRE			
N2162	P173 60... INTERMEDIATE AMBIENT TEMPERA			
N2163	P171 80... HIGH AMBIENT TEMPERATURE THR			
2513060	PACCAR 160 AMP ALTERNATOR, BRUSHED	P	0	0
2521090	IMMERSSION TYPE PRE-HEATER 110-120V	P	105	2
2521110	OIL PAN HEATER 120V/300W	P	116	2
2522050	PACCAR STARTER 12V	P	0	0
2538050	4 PACCAR PREMIUM 12V DUAL PURPOSE BATTERIES, 2800 CCA	P	252	62
2539090	BIG SWITCH BATTERY DISCONNECT MOUNTED ON BATTERY BOX	P	459	4
2539640	IVD (LOW VOLTAGE DISCONNECT) CAB & SLEEPER	P	249	4
2621000	2-SPEED FAN CLUTCH FOR FREQUENT START/STOPS	P	263	0
2723210	18.7 CFM AIR COMPRESSOR	P	0	0
2812170	INTEBRAKE	P	0	0
2922040	ISX/ISX15 (FURNISHED ON ENGINE) PACCAR FUEL FILTER, UNHEATED	P	0	0
3010170	IGNITION IDLE TIMER	P	28	0
3114270	HIGH EFFICIENCY COOLING SYSTEM	P	0	0
3212010	(2) 13" SS AIR CLEANERS, COWL MTD, SS CAP	P	1,044	53
3365090	EXHAUST DUAL SIDE OF CAB DPF/SCR RH UNDER CAB	P	1,167	130
3381790	CHROME FINISH OVER ELBOWS FOR DUAL EXHAUST	P	262	13
3381830	MUFFLER GUARD / PAIRING STAINLESS STEEL	P	64	7
3387500	48" HT, 5" DIA STANDPIPE(S) CHROME WITH CLEAR COAT	P	104	9
4022200	TRANSMISSION AND CLUTCH FULLER RT10189188 18 SPEED WATER-TO-OIL COOLER, INTERNAL PUMP	P	3,175	119

CODE	DESCRIPTION	PUB CD	PRICE	WEIGHT
4210960	SPL250HD-XL DRIVELINE, 1 MIDSHIP BKG	P	1,050	161
4216330	SPL170-XL DRIVELINE INTERAXLE	P	195	44
4233030	(1) DASH MTD SINGLE ACTING AIR PTO CTRL	P	69	0
4250790	ALUMINUM BELL HOUSING IBO IRON	P	62	53-
4256100	FULLER TRANS 1400/1500/1600/1800/2000	P	0	0
4256250	HD INPUT BEARING FOR PTO OPERATION	P	41	0
4256440	HIGH PRESSURE RANGE SHIFT KIT	P	170	0
4390270	REMOVE LUBE HOSES FOR CLUTCH LINKAGE,	P	234	7
4380360	UPGRADE CLUTCH TORQUE CAPACITY	P	308	0
4540420	BERG PULL CORDS - ALL AIR TANKS	P	6	0
4540220	WIRE BRAID BRAKE HOSE, REAR	P	172	25
4540420	NYLON CHASSIS HOSE	P	0	0
4543320	STEEL PAINTED AIR TANKS	P	0	0
4543330	POLISH ALUM AIR TANKS OUTSIDE FRM RAILS	P	393	0
4544020	COALESCING FILTER FOR USE WITH AD-IS	P	53	0
4622800	TRAILER HAND VALVE	P	0	0
4614810	A&E CONNECTIONS BOC/BOS W/ HOSE TENNA	P	0	0
4614850	12' A&E LINES STRAIGHT W/TWO 7-WAY PLUGS	P	106	9
4614870	LOCATE A&E CONNECTIONS 41"-54" BOC/BOS	P	0	0
5069170	FF: MN 14PLY 11R24.5 K2A3+	P	314	31
5169560	RR: BR 16PLY 11R24.5 M799	P	1,488	204
5190008	CODE-REAR TIRE QTY 08.	P	397	33-
5220430	RR: ALCOA 983637 LVL1 24.5XR.25 ALM WHL	P	1,588	132-
5220430	RR: ALCOA 983637 LVL1 24.5XR.25 ALM WHL	P	1,588	132-
5390008	CODE-RRR RIM QTY 08.	P	0	0
5552340	FUEL TANKS	P	152	26
5556220	26" ALUM 110 GAL FUEL TANK LH BOC	P	119	11
5603135	LOCATION RH BEHIND CAB 135 GAL.	P	0	0
5604110	LOCATION LH BEHIND CAB 110 GAL.	P	12	0
5650140	FUEL TANK FILL REAR	P	0	0
5650710	LOCATE BOC FUEL TANK(S) FORWARD AS FAR	P	0	0
5652570	AS POSSIBLE	P	27	0
5652800	DUAL DRAW / RETURN	P	202	2
5652830	ADDITIONAL SENDING UNIT IN SECONDARY	P	62	0
5652890	FUEL TANK, GAUGE SELECTOR SWITCH	P	0	0
5652890	POLISH ALL FUEL / HYDRAULIC TANK STRAPS	P	0	0
5652890	DEF TANK MOUNTED LH BOC	P	0	0

CODE	DESCRIPTION	PUB CD	PRICE	WEIGHT
5653000	POLISHED SS COVER FOR DEF TANK	P	204	0
5655029	DEF TANK MEDIUM	P	34	22
BATTERY BOX AND BUMPER				
6010030	ALUMINUM BATTERY BOX NON-SLIP STEP LH U/C	P	0	0
6030150	RUBBER BATTERY PAD IN BOTTOM (1) BATTERY BOX	P	14	4
6034620	HD BATT BOX STEP REINFORCEMENT	P	66	2
6040550	DPF CAB ENTRY ALUMINUM NON-SLIP STEP RH U/C	P	0	0
6121120	STEEL BUMPER CHROMED SWEEP BACK 2 TOW PINS	P	641	9-
6132450	HEAVY DUTY EXTERNAL TOW EYE 1PO STD (N/A W/FEPTO)	P	809	42
CAB AND EQUIPMENT				
6515570	ALUM CAB 123" BBC FBGLS HOOD SBFA W/POLISHED CROWN & SPRING TILT ASSIST	P	0	75
6540120	SEVERE SERVICE CAB PACKAGE #1 INCLUDES ALUM SIDE SKINS, ALUM REAR	P	32	49
6540600	REMOTE KEYLESS ENTRY SYSTEM W/PLATINUM INTERIOR	P	175	0
6540660	SMARTSOUND CAB INSULATION PKG	P	327	64
6701820	58" ULTRACAB SLPR W/PLATINUM INTERIOR	P	15,192	809
5810290	SLEEPER DOOR DIAPHRAGM 44"/58"/72"/78"/80" ULTRACAB SLEEPER	P	86	2
6810730	RH BAGGAGE DOOR 44"/58"/72"/80" SLPR	P	242	11
6812590	POLISHED STAINLESS STEEL SLEEPER VENTS	P	32	0
6814260	THERMAL INSULATION PACKAGE 58" HIGH ROOF AND 72"/80" LOW ROOF	P	100	4
6911700	PETERBILT ULTRARIDE DRIVER SEAT	P	0	0
6921700	PETERBILT ULTRARIDE PASSENGER SEAT	P	0	0
6930060	DRIVER SEAT HEATED AVAIL W/EVOLUTION, ULTRARIDE, AND SEARS	P	110	4
6930230	SEAT SKIRT - ALL ELIGIBLE AIR SEATS	P	32	2
6930800	BLACK SEAT COLOR IPO STD COLOR	P	0	0
6939360	RH FOLD-AWAY, IH STD ARM REST - DRVR	P	159	4
6939370	FOLD-AWAY ARM REST LH ONLY PASS SEAT	P	112	2
6939400	AIR RIDE DRIVER	P	0	0
6939420	HIGH BACK DRIVER	P	0	0
6939450	LEATHER DRIVER	P	315	0
6939510	NON-AIR RIDE PASSENGER	P	0	0
6939520	HIGH BACK PASSENGER	P	0	0
6939550	LEATHER PASSENGER	P	317	0
7001610	LEATHER STEERING WHEEL	P	98	0
7039220	PLATINUM INTERIOR - ARCTIC GRAY	P	3,440	33
7040150	RUBBER FLOOR IPO CARPET - PLAT/PREMIER INTERIOR FOR CAB OR 587 PLATINUM ONLY	P	49-	7-
7210180	FIXED REAR WINDOW BOS STD TINT	P	110	31

CODE	DESCRIPTION	PUB CD	PRICE	WEIGHT
7230350	TWO-PIECE FLAT WINDSHIELD	P	0	0
7322010	COMBO FRESH AIR HEATER/AIR CONDITIONER	P	0	0
7330160	ARTIC WRAP ON SLPR HEATER WATER SUPPLY LINES	P	5	0
7330700	PB COMFORT CONTROL - CAB	P	32	7
7330770	AIR CONDITIONING EXCISE TAX-CANADA	P	195	0
7410040	OUTSIDE SUNVISOR - STAINLESS STEEL	P	144	4
7560100	SSTL MIRRORS EACH SIDE HTD & MTRZD (N/A W/6501020)	P	350	2
7560950	(2) CONVEX 8" SS MIRROR, CNTR MTD UNDER MIRROR BRKT; INCLUDES DUAL DOOR STOPS	P	0	0
7565180	POLISHED LOWER MIRROR BRACKET COVERS	P	12	0
7620630	(2) AIR HORNS 30" CHROME - ROUND INCLUDES POLISHED HORN SHIELDS	P	429	11
7725740	MIDLEVEL SPEAKER PACKAGE FOR CAB (4) SPEAKERS	P	117	7
7725780	MIDLEVEL SPEAKER PACKAGE FOR SLEEPER (2) SPEAKERS W/SUBWOOFER	P	370	33
7740100	COBRA 40 CHNL CB RADIO W/INTEGRAL SPKR	P	258	11
7748680	CB ANTENNA MOUNTING, RH & LH MIRROR N/A W/RAMI	P	48	0
7749500	STRUIS SATELLITE RADIO SERVICE PROVIDER	P	0	0
7788980	BRKT FOR F/O COMMUNICATION SYSTEM SINGLE ANTENNA MTD CENTER BOC/BOS	P	223	2
7789240	WIRING PROVISIONS FOR PEOPLENET MTD CENTER BOS/RH BOC ON DAYCAB CONFIG	P	1,824	0
7850030	PB WINTERFRONT WHITE W/ LOGO	P	92	2
7850210	PLUG-IN AUTO RESET CIRCUIT BRKR IPO FUSES IN JUNCTION BOX	P	57	0
7851040	REMOVABLE BUGSCREEN BEHIND GRILLE	P	69	2
7851480	PB ELEC WINDSHIELD WIPERS W/INTERMITTENT FEATURE	P	0	0
7856100	FRNCH NAMEPLATES, SHIPPED LOOSE CANADIAN REGISTRY	P	40	0
7870180	SLEEPER EXTENDERS, ULTRACAB	P	501	35
7870440	SLPR EXTENDERS BOLTED IPO HUCK FASTENED	P	58	0
7900070	5 LB 3A:40BC FIRE EXTINGUISHER MTD IN SLEEPER BAGGAGE COMPARTMENT	P	87	9
7900090	TRIANGLE REFLECTOR 11" SHIP LOOSE	P	18	13
7901130	BACKUP ALARM (107DB)	P	58	2
8011140	ENGINE OIL TEMPERATURE LOCATED IN SMARTNAV DISPLAY	P	0	0
8011150	MAIN TRANSMISSION OIL TEMPERATURE LOCATED IN SMARTNAV DISPLAY	P	19	0
8011220	AXLE TEMPERATURE GAUGES, TANDEM DRIVE	P	158	2
8011390	ENGINE OIL TEMPERATURE GAUGE	P	39	0
8012240	GUARD(S) FOR REAR AXLE HEAT GAUGE	P	79	2
8021380	AIR RESTRICTION INDICATOR MTD ON AIR CLEANER OR INTAKE PIPING	P	0	0
8032420	BUZZER ON AIR SUSPENSION DUMP VALVE	P	10	0

CODE	DESCRIPTION	PUB CD	PRICE	WEIGHT
8041170	SPEEDOMETER TO BE KPH IFO MPH REQ'D FOR CANADA, MEXICO & LATIN AMERICA VEHICLES	P	30	0
8070120	MANIFOLD PRESSURE, BOOST LOCATED IN SMARTNAV DISPLAY	P	0	0
8070170	DPF STATUS LOCATED IN SMARTNAV DISPLAY	P	0	0
8070180	FUEL ECONOMY LOCATED IN SMARTNAV DISPLAY	P	0	0
8070190	PERCENT TORQUE LOCATED IN SMARTNAV DISPLAY	P	0	0
8071280	SUSPENSION PRESSURE GAUGE	P	50	2
8071750	(2) DUMP SWITCHES, BOTTOM DUMP TRAILER WIRED TO BERG 4-WAY SOCKET AT BOC/BOS	P	154	9
8071870	MAIN INSTRUMENTATION PANEL W/ GRAPHICS DISPLAY	P	0	0
8072560	(1) ADDITIONAL DASH SWITCH WITH WIRING EXTRA WIRE INCLUDED AT THE SWITCH	P	52	0
8072910	UP TO 6 ADDITIONAL ROCKER SWITCHES IN D PANEL	P	159	0
8111140	PROJECTOR MODULE POD HEADLIGHTS INTEGRAL TURN SIGNALS	P	257	0
8120980	(5) MARKER LIGHTS, AERO LED	P	0	0
8131130	SWITCH & WIRING FOR F/O FOG/ROADLIGHT W/O BUMPER CUTOUTS	P	13	0
8132860	(2) STROBE LIGHTS, ROOF MOUNTED EACH SIDE CAB ROOF BRACKET	P	803	11
8133120	SWITCH & WIRING F/O AUX LIGHT ON DUAL AIR CLEANERS	P	79	2
8133500	SWITCH ON DASH FOR LIGHT IN SLEEPER (IN ADDITION TO STD SWITCH)	P	59	2
8133950	COURTESY LIGHTS MOUNTED UNDER CAB TO ILLUMINATE STEPS, DRIVER & PASSENGER	P	96	2
8133960	DAYTIME RUNNING LIGHTS REQUIRED ON ALL CANADIAN VEHICLES	P	76	0
8140700	TRUCKLITE 40242R STOP/TURN/TAIL 40244 BACKUP, SUPER 40 BULBS	P	109	20
8151150	(2) LOAD LIGHTS, FLUSH MOUNTED MID LOCATION C, SLEEPER ONLY	P	103	4
8152560	(2) LOAD LIGHTS, BRACKET MTD OUTBOARD LOCATION J, CANADIAN STYLE	P	177	7
8153100	(1) F/O LOADLIGHT, SWITCH & 10 FT WIRE COIL UNDER/IN CAB/SLEEPER	P	34	2
PAINT				
8500710	STANDARD PAINT COLOR SELECTION	P	200-	0
8530780	(1) COLOR AXALTA TWO STAGE CAB/HOOD/SLEEPER	P	626	0
N8502	A - L0006EB WHITE - STAND			
N8520	FRAME N0001EA BLACK			
N8530	FENDER L0006EB WHITE - STAND			
N8540	HOOD TOP L0006EB WHITE - STAND			
N8550	CAB ROOF L0006EB WHITE - STAND			
N8560	SLEEPER ROOF L0006EB WHITE - STAND			

Trina Drake

From: Sergio Munoz
Sent: Thursday, November 01, 2018 11:13 AM
To: Konrad Augustson; Trina Drake
Subject: PacLease Units for Sale
Attachments: 416190 -416199.pdf

Konrad/Trina

I have the following trucks in my yard they will be slated for getting UVMA done next week and then off to clean up. Let me know if you have any questions.

2015 Peterbilt 367 58" Sleeper

Unit: 416198

VIN#:283803

534,171 Kms

11202 Hrs

Inservice date: January 14 2015

Extended Warranty: 5year 800K Engine and aftertreatment

2015 Peterbilt 367 58" Sleeper

Unit: 416199

VIN#:283804

613,012 Kms

13163 Hrs

Inservice date: January 14 2015

Extended Warranty: 5year 800K Engine and aftertreatment

Add Ons:

- Moose Bumper
- Headache Rack
- Positive Air Shutdown
- Chain hangers
- ½ Checker plate fenders
- Bunk and engine heater
- Step Tool Box



Sergio Munoz | PacLease General Manager
smunoz@stahlpeterbilt.com
| Office 780.483.6666 | Cell 780.297.7773
18020 118 Ave Edmonton, AB T5S 2G2
www.stahlpeterbilt.com/Paclease
Facebook | Twitter | LinkedIn



Chassis

VIN	1XPTD40X8FD283804	Months in Service	46
Model	367	In-Service Date	1/14/2015
Intended Service	TANKER, LIQUID BULK	Build Date	9/22/2014

Customer

Name	PACCAR LEASING COMPANY
City	HOUSTON
State/Province	TX

Selling Dealer

Name	I627 - PACCAR LEASING- STAHL PETERBILT PACLEASE
City	BELLEVUE
State/Province	---

Servicing Dealer

Name	I627 - PACCAR LEASING- STAHL PETERBILT PACLEASE
City	BELLEVUE
State/Province	---

∨ **Components**

Engine Make	Transmission Make	DPF Make	Steer Axle Make	Forward Rear Axle Make	Rear Rear Axle Make
---	---	---	---	---	---
Engine Model	Transmission Model	DPF Model	Steer Axle Model	Forward Rear Axle Model	Rear Rear Axle Model
ISX15	RTLO18918B	N/A	E1322I	D46-170	D46-170
Engine Serial	Transmission Serial	DPF Serial	Steer Axle Serial	Forward Rear Axle Serial	Rear Rear Axle Serial
79774286	S1100249	56250145104	MY01367673	HN04575441	HN04575442

∨ **Campaigns**

Campaign Code	Description	Campaign Status	Expiration Date	Repair Type	Type
PDI	NO CAMPAIGN DETAIL AVAILABLE	Completed	NONE		Vehicle
1214L	HALDEX BRAKE DIAPHRAGM MISLOCATED	Completed	NONE	PROACTIVE	Vehicle
1638	CUMMINS CAMPAIGN: VERIFY ELIGIBILITY THROUGH CUMMINS QUICKSERVE	Completed	NONE	PROACTIVE	PACCAR
1651	CUMMINS CAMPAIGN: VERIFY ELIGIBILITY THROUGH CUMMINS QUICKSERVE	Completed	NONE		PACCAR
1763	CUMMINS CAMPAIGN: VERIFY ELIGIBILITY THROUGH CUMMINS QUICKSERVE	Completed	NONE		PACCAR
1996		Open	NONE		PACCAR

CUMMINS CAMPAIGN: VERIFY
ELIGIBILITY THROUGH CUMMINS
QUICKSERVE

▼ Truck Notes

Truck Notes	Description
Truck Note 1	2013 EPA EMISSIONS ENGINE

▼ Base Warranty

Warranty Code	Warranty Description	Max Coverage Months	Max Coverage Mileage	Max Coverage Kilometers	Max Engine Hours	Active/Expired
No items found						

▼ Extended Warranty

Warranty Code	Warranty Description	Max Coverage Months	Max Coverage Mileage	Max Coverage Kilometers	Max Engine Hours	Active/Expired
No items found						

▼ Supplier Extended Warranty

Warranty Code	Warranty Description	Max Coverage Months	Max Coverage Mileage	Max Coverage Kilometers	Max Engine Hours	Active/Expired
Warranty Code 1	5 yrs / 500,000 mi, Plan 1, 476 HP and over	60	500000	804672		Active
Warranty Code 2	5 yrs / 500,000 mi, Aftertreatment, 476 HP and over	60	500000	804672		Active

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 1
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
DR11545	OPEN	11-01-18	613012
HOUR METERS: ENGINE	13162.6	METER2	0.0 METER3 0.0

DR11341 CLOSED 10-17-18 607133

HOUR METERS: ENGINE 13043.0 METER2 0.0 METER3 0.0

CONDITION:-1: PACLEASE CLASS 8 CUMMINS B SERVICE

* REMEDY CODES - PLBCUMM

COMMENTS-1: Performed b service and inspection.

DR10821 CLOSED 08-29-18 584846

HOUR METERS: ENGINE 12546.0 METER2 0.0 METER3 0.0

CONDITION:-1: PACLEASE CLASS 8 CUMMINS B SERVICE

COMMENTS-1: Performed B Service, reported all faults

CONDITION:-2: PACLEASE DPF CLEANING 4500 HOURS

COMMENTS-2: Performed preburn Removed the DPF assembly and separated. Cleaned off old gaskets and took to main shop to clean. Trap test went from 1.7 WG to 1.5WG. Reassembled the DPF assembly with new gaskets, mounted in truck, performed final burn.

RO NUMBER	STATUS	DATE	MILEAGE
CONDITION:-3: EXHAUST LEAK ON CLAMP ON dpf			
CONDITION:-4: CB ANTENNA FAULT			
COMMENTS-4: Replaced CB antennas			
CONDITION:-5: BUMPER CRACKED AT HINGE			
CONDITION:-6: NOTE FENDERS DAMAGED			
CONDITION:-7: ADJUST 5TH WHEEL			
COMMENTS-7: Adjusted 5th wheel using tool			
CONDITION:-8: D/S MARKER LIGHT ON BUMPER NOT WORKING			
COMMENTS-8: Found that there was no power found bad connection at the connectors, repaired the connections and found the lights still NW. Changed light. Done			
CONDITION:-9: ADJUST CLUTCH			
COMMENTS-9: Adjusted clutch brake and set free play to 1 1/2"done			
CONDITION:-10: WIPER BLADES			
CONDITION:-11: TOP UP COOLANT			
CONDITION:-12: P/S BUNK SHOCK LEAKING OIL			
COMMENTS-12: Replaced bunk shock			
CONDITION:-13: SLEERING WHEEL LEATHER RIPPED			

RO NUMBER	STATUS	DATE	MILEAGE
COMMENTS-13: not changed			
CONDITION:-14: COOLANT LEAK AT LOWER RAD HOSE			
CONDITION:-15: ENGINE OIL PAN GASKET LEAKING OIL			
COMMENTS-15: leave			

SR146802 CLOSED 07-27-18 568915

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: INJECTOR CUPS LEAKING

COMMENTS-1: Hooked up to unit with INSITE. Started EDS DSBRF2235. Verified customer complaint of valve covers leaking. Pressure tested cooling system. Disassembled and cleaned all parts as required. Cleaned injector bores and sucked fuel from top of piston heads. Installed retaining rings. Performed leak test- no bubbles. Found large amounts of coolant in fuel. Drained, cleaned and refilled fuel tanks. Replaced both fuel filters as they were contaminated. Pressure tested cooling system- no leaks. Ran unit to temp to check for leaks- repair complete. 13778275 C36478

CONDITION:-2: B SERVICE

COMMENTS-2: Topped up oil using 2L

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 2
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
DR10079	CLOSED	06-15-18	556459

HOUR METERS: ENGINE 11914.1 METER2 0.0 METER3 0.0
 CONDITION:-3: BROKEN BOLT IN MANIFOLD
 COMMENTS-3: Drained coolant. Removed intake piping. Removed all lines and electrical to turbo. Removed turbo. Removed exhaust manifold. Drilled out broken bolt on # 2 upper hole. Cleaned all parts for re-assembly. Installed and torqued manifold with new gaskets and one new bolt. Re installed turbo with new gaskets. Installed all piping removed. Filled coolant and pressure tested - good. Topped up fluids.

RO NUMBER	STATUS	DATE	MILEAGE
DR10079	CLOSED	06-15-18	556459

HOUR METERS: ENGINE 11914.1 METER2 0.0 METER3 0.0
 CONDITION:-1: COOLANT IN FUEL/ DRAIN ALL TANKS
 COMMENTS-1: Drained fuel from primary filter and both tanks, ran truck and drained again, checked for codes and non showing on dash. found truck had broken exhaust manifold bolt will repair at next service as customer needs truck back. Parked truck in yard
 CONDITION:-2: 2 BOLTS ON EXHAUST MANIFOLD BROKEN

RO NUMBER	STATUS	DATE	MILEAGE
DR9788	CLOSED	05-28-18	543995

HOUR METERS: ENGINE 11680.0 METER2 0.0 METER3 0.0
 CONDITION:-1: FRONT CRANK SEAL STARTING TO LEAK ****HOLD UNTIL NEXT SERVICE

 CONDITION:-2: PACLEASE CLASS 8 CUMMINS B SERVICE
 COMMENTS-2: CORRECTION: Performed B-SERVICE and reported all faults
 CONDITION:-3: BUNK HEATER NOT WORKING
 COMMENTS-3: CORRECTION: Heater would not start, just smoked. Blew out intake and forced air out exhaust, with not much flow. Connected to computer, view faults, get hours. Foreman instructed to remove heater and inspect. Found soot and debris in combustion chamber. Cleaned parts and mating surfaces. Installed new gaskets, cleaned atomizer. Reinstalled. Unit not running quite right, seems to be over fueling. Used desk top to run heater, started to run better with time. Fired bunk heater next day, and let run, everything seems to be in working order. Installed cage and put customers belongings back in bunk.
 CONDITION:-4: CHECK CODES - 1 HAD COME ON
 COMMENTS-4: Hooked up to insite printed off codes, trouble shoot the water in fuel code 1845 followed trouble shooting steps and found small amount of moisture and dirt in the connector, cleaned and sprayed with electrical cleaner, reinstalled performed ecm update, checked for codes none present, ran truck and made sure no codes came back
 CONDITION:-5: D/S REAR MARKER LIGHT
 COMMENTS-5: Found that the connections on light and pig tail were corroded. Replaced both, as well as pig tail.
 CONDITION:-6: DAMAGE ON FRONT BUMPER (TAKE PICS)
 CONDITION:-7: P/S WINDSHIELD CRACKED. REPLACE?
 COMMENTS-7: Removed and replaced p/s windshield, replaced wiper blades removed stickers
 CONDITION:-8: AIR LEAK UNDER HOOD BY HORN
 COMMENTS-8: Found airline on firewall had rubbed through another off of tee. Cut out damaged airline and installed quick connectors, extended line to avoid tightness, aired up and found another airleak on top of transmission, removed and replaced, 1/4" airline fitting, installed air line and aired up, checked for air leaks, no air leaks at time of inspection, reinstalled floor plate for shifter, secured in place.
 CONDITION:-9: D/S BOOT LIGHT CUT

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 3
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
COMMENTS-9:			
Removed boot light and shrink tubed remaining wire and tied up, interior lights were not working, found 6 burnt out bulbs and blown fuses replaced all and everything is in workling order			
CONDITION:-10:			
REAR FENDERS DAMAGED			
CONDITION:-11:			
5TH WHEEL CYLINDER LEAKING			
COMMENTS-11:			
Removed 5th wheel compressed springs, removed pins and removed cylinder, replaced cylinder, reused air fitting, function tested and every thing is in working order			
CONDITION:-12:			
P/S REAR DRIVE BRAKE PUSH RODTRAVEL EXSESSIVE			
COMMENTS-12:			
Found slack adjuster, auto adjusting guide was broken off at m ounting bolt for brake pot, ordered parts installed new slack adjuster guid e bracket, torqued bolts, installed drum and wheels, set brakes, torqued wh eels, measure push rod travel, and scam rotation, everytghing in working or der, installed torque tag on keys.			
CONDITION:-13:			
FIRST DRIVE TRANSVERSE ROD POUNDED OUT			
COMMENTS-13:			
Removed deck plate, removed and replaced transverse rod, ensur ed washers went in proper placement, torqued, reinstalled deck plate.			
CONDITION:-14:			
OIL LEAK AT THE REAR OF ENGINE LOOKS LIKE OIL PAN LEAKING			
RO NUMBER	STATUS	DATE	MILEAGE
COMMENTS-14:			
Removed power steering reserivor and bracket, drained coolant, removed and inspected compressor. Looks like possible leak at compressor g asket but still a chance the front structure is leaking a well. Will have t o keep an eye on it to see if leak continues. Replaced gasket with new, ins talled compressor, torqued to specs, found radiator tie rod bushing was wor n, removed and replaced, filled coolant and topped up power steering ran an d tested everything in working order			
CONDITION:-15:			
ADJUST 5TH WHEEL			
COMMENTS-15:			
Adjusted 5th wheel; last adjustment			
CONDITION:-16:			
DECK PLATE MISSING THE SIDE STRIP			

DR9159	CLOSED	03-23-18	519592
HOUR METERS: ENGINE	0.0	METER2	0.0 METER3 0.0
CONDITION:-1:			
PACLEASE CLASS 8 CUMMINS B SERVICE 11097 HRS			
* REMEDY CODES - PLBCUMM			
COMMENTS-1:			
Started inspection part of B service. Completed b service			
CONDITION:-2:			
OILPAN GASKET LEAKING			
COMMENTS-2:			
Inspected unit and found oil pan gasket leaking. Removed oil pa			
RO NUMBER	STATUS	DATE	MILEAGE
n,			
cleaned all surfaces, applied sealant to all 4 corners of pan and re-ass embled with new gasket. Re-installed oil pan 13665836 C6860			
CONDITION:-3:			
ABS LIGHT ON			
COMMENTS-3:			
Hooked up computer and printed/attached codes. Found 1 count fo r addition axle right wheel end and 57 counts for low voltage at take off. Ohmed out sensor and was with in spec. Checked voltage of harness and also was with in spec. Grabbed bore scope camera and inspected tone ring looked ok. Discussed with foreman and decided to push sensor in as far as possible clear codes and take for a road test. Cleared codes waiting on road test. Took truck for a road tests and light stayed off. Installed new air line fi tting on back of trans to stop air leak. Brought unit back into shop to ins pect new oil pan gasket for leaks			
CONDITION:-4:			
REPLACE WIPER BLADES			
COMMENTS-4:			
Installed new wiper blades.			
CONDITION:-5:			
AIR LEAK ON TOP OF TRANSMISSION			
COMMENTS-5:			
Found air leak at back of transmission and on top of transmissi on. Order parts.			
CONDITION:-6:			
ADJUST 5TH WHEEL, MIGHT NEED REBUILD			

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 4
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER STATUS DATE MILEAGE

COMMENTS-6: Adjusted 5th with using tester tool it is now on its last adjustment done

CONDITION:-7: RIVETS MISSING FROM BATTERY BOX LID

COMMENTS-7: Installed new rivets

CONDITION:-8: BUMPER PIN MISSING

CONDITION:-9: PASSENGER SIDE 1/4 MUDFLAP RIPPED OFF

COMMENTS-9: Measure, cut, punched holes and mounted mud flap done

CONDITION:-10: REAR DRIVE AXLE TORQUE ARM BUSHINGS POUNDED OUT, REPLACE

COMMENTS-10: Removed worn torque arm and installed new torque arm 'tagged parts for warranty

CONDITION:-11: DRIVER SIDE CONVEX MIRROR HEAT NOT WORKING

COMMENTS-11: Replaced d/side mirror and wired in. Test ok.

DR8943 CLOSED 02-27-18 510655

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: REPLACE PASSENGER SIDE MUDFLAP AND HANGER (MUDFLAP IS THE LONG WHITE PETERBILT ONES)

COMMENTS-1: CHANGED MUDFLAP AND HANGERS

RO NUMBER STATUS DATE MILEAGE

CONDITION:-2: TOP UP OIL

COMMENTS-2: TOPPED UP OIL

CONDITION:-3: CHECK BEACON LIGHT, WE REPAIRED RECENTLY AND ONLY WORKED FOR FEW HOURS. OTHER ONE WORKS GREAT

COMMENTS-3: CAUSE: . CORRECTION: REPLACED BEACON LIGHT

DR8826 CLOSED 02-13-18 503708

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: PACLEASE CLASS 8 CUMMINS B SERVICE 10754 hrs

* REMEDY CODES - PLBCUMM

COMMENTS-1: BRING THIS UNIT IN. DID B SERVICE .REPAIR FOUND LISTED ON COMPUTER SHEET.

CONDITION:-2: OILPAN GASKET ***HOLD TILL NEXT SERVICE***

CONDITION:-3: BEACON LAMPS NOT WORKING

COMMENTS-3: CAUSE: BEACON LAMP NOT WORKING CORRECTION: STARTED O TROUBLE SHOOT ,HAS TO REMOVE BEACON.FOUND BULB ITSELF NOT WORKING.TALKED TO PARTS AND ORDERED THE BULB. got bulb still controler is not responding flashing.Cont rolle itself is bad.Got new beacon and installed .Checked operation working

RO NUMBER STATUS DATE MILEAGE

good now.

CONDITION:-4: P/S ,MARKER LAMP BURNT OUT

COMMENTS-4: CAUSE: p/s side marker lamp n/w CORRECTION: has to replace the bulb.

DR8354 CLOSED 01-12-18 485291

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: PACLEASE SAFETY

* REMEDY CODES - PLCVIP

COMMENTS-1: CAUSE: . . CORRECTION: perfomed saftey inspection and handed in list of repairs .

CONDITION:-2: PACLEASE CLASS 8 CUMMINS B SERVICE 10827hrs

* REMEDY CODES - PLBCUMM

COMMENTS-2: CAUSE: . CORRECTION: STARTED performed b service and reported all faultsdone

CONDITION:-3: PASSENGER SIDE FRONT 1/4 FENDER MARKER LIGHT FLICKERING

COMMENTS-3: CAUSE: . CORRECTION: removed 1/4 fender light and found corroded wiring. installed new light in fender and wired in tests ok

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 5
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
-----------	--------	------	---------

CONDITION:-4: PASSENGER SIDE REAR MARKER LIGHT NOT WORKING
COMMENTS-4: CAUSE: . CORRECTION: found light to be no good and wiring corroded. replaced light and wired in new pigtail tests ok

CONDITION:-5: BOTH LOADING LIGHTS NOT WORKING
COMMENTS-5: CAUSE: . CORRECTION: found burnt out fuse replaced and tests ok

CONDITION:-6: REPLACE GLAD HAND RUBBERS
COMMENTS-6: CAUSE: . CORRECTION: installed new glad hand rubbers done

CONDITION:-7: PAC PLEASE WINDSHIELD REPLACEMENT-BOTH
COMMENTS-7: CAUSE: . . CORRECTION: started on windshields installed windshields, cleaned and removed stickers. installed new b service sticker on driver side windshield. replaced wiper blades

CONDITION:-8: RIDE HEIGHT VALVE LEAKING
COMMENTS-8: CAUSE: . CORRECTION: removed leaky ride height valve and swapped fittings over to new valve. installed on truck and set ride height to factory tests ok

CONDITION:-9: GPS ANTENNA BROKEN
CONDITION:-10: CB ANTENNA BROKEN

RO NUMBER	STATUS	DATE	MILEAGE
-----------	--------	------	---------

COMMENTS-10: REPLACED CB ANTENNA

CONDITION:-11: SERVICE AND LOAD TEST BATTERIES
COMMENTS-11: CAUSE: . CORRECTION: serviced battery cables and load tested batteries. batteries all failed test with 8 volts. got new one from parts and installed. had to disconnect batteries and ecm connections on fire wall for (jason) to weld up fender

CONDITION:-12: TRAILER CORD END DAMAGE
COMMENTS-12: CAUSE: . . CORRECTION: . found corrosion on other end of trailer cord as well, played it safe and replaced cord. had to unwind trailer cord rapping and installed new cord. re wrapped cord/air lines with protector.

CONDITION:-13: SYNCHRO BRACKET BROKEN
COMMENTS-13: CAUSE: . CORRECTION: removed floor access panel and removed broken synchro valve bracket and installed new reinstalled floor tests ok

CONDITION:-14: ADJUST CLUTCH
COMMENTS-14: CAUSE: . CORRECTION: found clutch to be out of adjustment had over 2" free play. adjusted clutch under truck and brought free play back in to spec

CONDITION:-15: FUEL LEAK ON PASSENGER SIDE FUEL TANK

RO NUMBER	STATUS	DATE	MILEAGE
-----------	--------	------	---------

COMMENTS-15: CAUSE: . . CORRECTION: found both the fuel sending unit and webasto fuel pickups to be leaking. removed fuel sending unit to replace core gasket but found that the sending unit itself was all bent up. got new sending unit on order from main shop. removed webasto fuel pickup and cleaned threads installed pipe sealer and reinstalled nut tests ok installed fuel sending unit as old one was bent at top and would not seal

CONDITION:-16: PASSENGER SIDE REFLECTIVE STRIP MISSING ON REAR MUD FLAP
COMMENTS-16: CAUSE: . CORRECTION: removed mud flap and installed reflective strip, reinstalled mud flap tests ok

CONDITION:-17: BED SHOCK MISSING
CONDITION:-18: BOTH REAR FENDERS DAMAGED- *****HOLD***** TAKE PICTURES

CONDITION:-19: ADJUST 5TH WHEEL
COMMENTS-19: CAUSE: . CORRECTION: ADJUSTED FIFTH WHEEL, DONE adjusted 5th wheel back into spec and lubricated

CONDITION:-20: ROO BAR HANDLE BROKEN
COMMENTS-20: CAUSE: . CORRECTION: removed broken pieces of handle. installed new handle/latch and tests ok

CONDITION:-21: BEACON BACKUP LIGHT NOT WORKING

INQUIRY

CUST # YEAR MAKE MODEL SERIAL 6
 51250 2015 PETERBILT 367 1XPTD40X8FD283804

RO NUMBER STATUS DATE MILEAGE
 COMMENTS-21: CAUSE: . CORRECTION: removed dash to gain acces and removed s
 witch installed new and tests ok resinstalled dash
 CONDITION:-22: ADJUST TIRE PRESSURE
 CONDITION:-23: FIRE EXT MISSING?
 COMMENTS-23: CAUSE: . CORRECTION: got fire extinguisher from parts and insta
 lled
 CONDITION:-24: OIL LEAK AROUND OIL PAN GASKET
 CONDITION:-25: PASSENGER SIDE REAR FENDER CRACKED, WELD
 CONDITION:-26: TIRES GETTING LOW THREAD
 CONDITION:-27: DRIVER SIDE 1ST DRIVE AXLE BRAKE CLEVIS SEIZED
 COMMENTS-27: FREED UP CLEVIS PIN TESTS OK
 CONDITION:-28: ENGINE WEBASTO NOT WORKING
 COMMENTS-28: CAUSE: . CORRECTION: .

 OUT578 CLOSED 11-06-17
 HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: MUDFLAP AND BRACKET

RO NUMBER STATUS DATE MILEAGE
 DR7840 CLOSED 11-07-17 458487
 HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: PACLEASE CLASS 8 CUMMINS B SERVICE CUSTOMER WAITING OIL CHANG
 E ONLY AND QUICK CHECK OVER, TRUCK WILL BE BACK WITHIN A MONTH FOR CVIP 958
 5 hrs

* REMEDY CODES - PLBCUMM

COMMENTS-1: CAUSE: replaced tail lamp CORRECTION:CAUSE: . CORRECTION: repla
 ced tail lamp performed fluid and filter change and greased unit done
 CONDITION:-2: REPLACE TAIL LIGHT
 COMMENTS-2: replaced tail light

OUT568 CLOSED 10-25-17 450885
 HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: CAM CLIP RELEASED FROM SLACK ADJUSTER ON P/S REAR AXLE 9382 H
 RS

DR7515 CLOSED 10-03-17 438255
 HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

RO NUMBER STATUS DATE MILEAGE
 CONDITION:-1: PACLEASE CLASS 8 CUMMINS B SERVICE 9170 HRS

* REMEDY CODES - PLBCUMM

COMMENTS-1: CAUSE: CORRECTION: completed b service
 CONDITION:-2: ADJUST CLUTCH
 COMMENTS-2: CAUSE: . CORRECTION: adjusted clutch back into spec tests ok,
 CONDITION:-3: POWER STEERING HOSE FROM RESIVIOR TO PUMP LEAKING
 COMMENTS-3: CAUSE: . CORRECTION: REPAIRED POWER STEERING HOSE FROM RESIVIOR
 TO PUMP
 CONDITION:-4: FRONT CRANK SEAL STARTING TO LEAK ****HOLD UNTIL NEXT SERVICE

DR7266 CLOSED 09-06-17 422279
 HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: TRUCK RECENTLY HAD OIL CHANGE ONLY!! CHECK AND SEE IF GREASE
 IS NEEDED AND CHECK OVER ON TRUCK
 COMMENTS-1: CAUSE: pm CORRECTION: perform checksheet and report adjusted cl
 utch passenger side marker light changed in bumper

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 7
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
OUT520	CLOSED	08-22-17	415002
HOUR METERS: ENGINE		0.0 METER2	0.0 METER3
CONDITION:-1: OIL CHANGE 8774 HRS			
* REMEDY CODES - PLBCUMM			

OUT511	CLOSED	08-18-17	395399
HOUR METERS: ENGINE		0.0 METER2	0.0 METER3
CONDITION:-1: AFTER HOURS CALL OUT TRUCK WON'T REGEN			

OUT490	CLOSED	07-03-17	
HOUR METERS: ENGINE		0.0 METER2	0.0 METER3
CONDITION:-1: REPAIR TIRE			

DR6758	CLOSED	07-03-17	394180
HOUR METERS: ENGINE		0.0 METER2	0.0 METER3
CONDITION:-1: PACLEASE CLASS 8 CUMMINS B SERVICE 8309 HRS			
* REMEDY CODES - PLBCUMM			
COMMENTS-1: performend service and reported repairs			
RO NUMBER	STATUS	DATE	MILEAGE
CONDITION:-2: GLAD HANDS LEAKING			
COMMENTS-2: CAUSE: WEAR CORRECTION: CUT AND RE-ASSEMBLED GLAD HANDS BEYOND WORN AREA OF TRAILER AIR LINES, REPLACED GLAD HAND RUBBERS			
CONDITION:-3: LEFT REAR SIGNAL			
COMMENTS-3: CAUSE: GREET CUSTOMER , REQUEST WORK ORDER BASED ON CUSTOMER CO MPLAINT, REMOVE AND CLEAN PIGTAIL OF LIGHT, REPLACE LIGHT AND RE-TEST , APP LY CORROSION PROTECT SPRAY CORRECTION: GREET CUSTOMER , REQUEST WORK ORDER BASED ON CUSTOMER COMPLAINT, REMOVE AND CLEAN PIGTAIL OF LIGHT, REPLACE LIG HT AND RE-TEST , APPLY CORROSION PROTECT SPRAY			
CONDITION:-4: OIL COMNSUMPTION			
CONDITION:-5: WINDSHIELD WASHER NOT WORKING			
CONDITION:-6: BOOT BRUSH END CAP MISSING			
CONDITION:-7: BOLTS LOOSE IN PASSENGER SIDE STEP			
CONDITION:-8: WINTER FRONT CLIPS BROKEN			
CONDITION:-9: INNER BUG SCREEN RUBBING A/C CONDENSOR			
COMMENTS-9: R+I Inner bug screen. Install three studs for hold bug screen.			
CONDITION:-10: HOOD DELAMINATION			
COMMENTS-10: TOOK PICTURES SENT AWAY			
RO NUMBER	STATUS	DATE	MILEAGE
CONDITION:-11: DRIVER SIDE HOOD CABLE STARTING TO FRAY			
CONDITION:-12: AIR TO AIR (INTERCOOLER) LOOSE			
CONDITION:-13: DRIVERS SIDE FIRST DRIVE SHOCK BUSHING CRACKED			
CONDITION:-14: 5TH WHEEL ADJUSTMENT			

DR6389	CLOSED	05-23-17	378461
HOUR METERS: ENGINE		0.0 METER2	0.0 METER3
CONDITION:-1: PACLEASE CLASS 8 CUMMINS B SERVICE 7945 HRS			
* REMEDY CODES - PLBCUMM			
COMMENTS-1: performed b-serv. done.			
CONDITION:-2: DPF CLEANING 4500 HOURS			
* REMEDY CODES - PLDPF			
COMMENTS-2: dpf preburned, removed and cleaning in progress. pin checked dp f filter, passed with average of 10.5" and W.G. 1.1 reassembled dpf filter assembly, performed final regen, no leaks. done.			
CONDITION:-3: ORINGS FUEL CAPS			
COMMENTS-3: CAUSE: LEAKY FUEL CAPS CORRECTION: REPLACED FUEL CAP O RINGS TE STS OK.			

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL #
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
CONDITION:-4:	CHECK BUNK SHOCKS		
COMMENTS-4:	replaced bunk shocks with new. done.		
CONDITION:-5:	CHECK MASTER SWITCH		
COMMENTS-5:	CAUSE: master power switch failed master power switch failed .. . CORRECTION: all positive battery cables were bolted together and hanging off frame with bungee cord. Arced out to battery box when unhooking. unit wont start, all fuses are good. computer reads ECM just fine, printed codes as well, nothing related. jumped starter relay, starter tries to start unit , but wont stay running. checked continuity of master power switch, everything works, cant find anything wrong with it. hooked it back up as suppose to be. waiting for Sid. removed master power switch from system and unit started just fine. replaced master power switch and tested. works. done. ...		
CONDITION:-6:	BIGGER SCREWS/ WASHER FRONT PLATE		
COMMENTS-6:	CAUSE: . CORRECTION: INSTALLED PROPER LICENCE PLATE HOLDING SCREWS		
CONDITION:-7:	gps update		
COMMENTS-7:	CAUSE: gps update CORRECTION: updated gps with new OBC. verified operation. done. ...		
RO NUMBER	STATUS	DATE	MILEAGE
CONDITION:-8:	BOTH BELTS CRACKED		
COMMENTS-8:	replaced cracked belts with new. done.		
CONDITION:-9:	GLAD HAND RUBBERS WORN		
COMMENTS-9:	replaced worn glad hand rubbers with new. done		
CONDITION:-10:	BOTH EXHAUST STACK BUSHINGS WORN		
COMMENTS-10:	CAUSE: worn bushings ... CORRECTION: replaced worn stack bushings with new, both sides. done. ...		
CONDITION:-11:	BATTERY BOX CRACKED (REAR), BATTERIES NEED SERVICE		
COMMENTS-11:	CAUSE: cracked box CORRECTION: ... in progress replaced cracked battery box with repaired box since out of warranty. load tested and cleaned batteries and terminals. reinstalled everything and secured cables. done.		
CONDITION:-12:	TRAILER TERMINAL & CORD CORROSION (CLEANING)		
COMMENTS-12:	CAUSE: CORROSION CORRECTION: CLEANED TRAILER CORD PLUG TRUCK AND TRAILER SIDE TESTS OK		
CONDITION:-13:	PASSENGER 1/4 FENDER CRACKED AT MUDFLAP		
COMMENTS-13:	CAUSE: BROKEN 1/4 FROM MUD AND SNOW BUILD UP CORRECTION: REMOVED MUD FLAP AND INSTALLED PRE FABBED METAL SUPPORT BRACKET. INSTALLED MUD FLAP		
RO NUMBER	STATUS	DATE	MILEAGE
LAP TEST OK			

SR138250	CLOSED	04-27-17	377000
HOUR METERS: ENGINE	0.0	METER2	0.0 METER3 0.0
CONDITION:-1:	CHECK AND ADVISE FOR FRONT OUTPUT SHAFT BEARING POUNDED OUT - TRUCK WAS TOWED IN AS DRIVELINE IS READY TO FALL OUT		
COMMENTS-1:	Brought unit into shop. Disassembled and inspected, found the end play was at 0.075" which is out of spec. Removed driveline and power divider, found the pump bearing failed and the input/output gears had metal transfer. Pacific Truck sold the original components. Contacted Dale at Pacific, Dale sent replacement parts (except seal and nut) and agreed to pay labor (9hrs @ \$115.00/hr). Installed new assembly in unit. Tested after repair.		

DR6199	CLOSED	04-25-17	369883
HOUR METERS: ENGINE	0.0	METER2	0.0 METER3 0.0
CONDITION:-1:	DRIVER SIDE WINDOW WON'T GO UP AND DOWN		
COMMENTS-1:	STARTED INSTALLED NEW REGULATOR AND STARTED PIECING DOOR BACK T		

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 9
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER STATUS DATE MILEAGE

TOGETHER, EVAN TOOK OVER REMOVED DOOR PANNEL TESTED FOR POWER BOTH WAYS ORDE
 RED NEW WINDOW REGULATOR INSTALLED WINDOW REGUALTOR INSTALLED DOOR PANNEL D
 ONE

CONDITION:-2: NEEDS MUDFLAPS
 COMMENTS-2: REPLACED MUDFLAPS

SR138012	CLOSED	04-28-17	377000
----------	--------	----------	--------

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: OPERATION MOVED TO REPAIR ORDER SR138250
 CONDITION:-2: CHECK AND ADVISE FOR FRONT POWER DIVIDER HAS EXTENSIVE PLAY B
 OTH HORIZONTAL AND VERTICAL **SEE INVOICE SR138250 FOR REPAIRS**
 COMMENTS-2: Inspected and measured play at both input and output of #1 diff
 erential, input at(.075") and output at (.020") waiting to find out warrant
 y from pacific truck, went through service history and found that the unit
 has been here 4 times in the last 6 months for #1 diff issues
 CONDITION:-3: P/S HEADLIGHT LOWER MARKER LIGHT NOT WORKING
 COMMENTS-3: Removed light cover and tested for power. ok. Found bulb burnt
 out. replaced bulb

RO NUMBER	STATUS	DATE	MILEAGE
-----------	--------	------	---------

OUT444	CLOSED	04-11-17	360748
--------	--------	----------	--------

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: AMBIENT TEMP SENSOR

OUT440	CLOSED	03-31-17	360767
--------	--------	----------	--------

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: CEL, ADJUST CLUTCH, ADJSUT RIDE HEIGHT

DR5843	CLOSED	03-22-17	350506
--------	--------	----------	--------

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL
 EETGUARD FILLTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN**** 7354 hrs
 COMMENTS-1: Completed service inspection as requested.
 CONDITION:-2: CHECK BATTERY DISCONNECT
 COMMENTS-2: Verified disconnect operation - likely frozen but small amounts
 of corrosion on positive battery terminals and disconnect.
 CONDITION:-3: CHECK PLAY AT FRONT DIFF JUST INSTALLED NEW ONE HAS PLAY AT I

RO NUMBER	STATUS	DATE	MILEAGE
-----------	--------	------	---------

NPUR

COMMENTS-3: Checked play at input with dial indicator - measures 60+thou. R
 emoved yoke, set bearing and reinstalled yoke. Verified end play. Removed y
 oke. Install seal, yoke with new hardware and rechecked final end play at 1
 2 thou. Reinstalled driveline with new strap kit 1419
 CONDITION:-4: PASSENGER SIDE ANTISAIL BRACKET LOOSE
 COMMENTS-4: Repaired anti sail as requested
 CONDITION:-5: AIRDRYER LEAKING OUT EXHAUST
 COMMENTS-5: Replaced leaking air dryer port and filter
 CONDITION:-6: WIPERS DAMAGED
 COMMENTS-6: Removed and adjusted arms, and replaced with new part
 CONDITION:-7: REAR DIFF LEVEL LOW
 COMMENTS-7: Topped up rear diff with 41 of 75w90.
 CONDITION:-8: FORWARD DIFF LEVEL LOW
 COMMENTS-8: Filled front diff with 75w90.
 CONDITION:-9: TIRE PRESSURES
 COMMENTS-9: Corrected tire pressures.
 CONDITION:-10: OIL PRESSURE AT 24PSI

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 10
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
-----------	--------	------	---------

COMMENTS-10: Cut filter element and check filtration media - showed customer

CONDITION:-11: WINTERFRONT CLIPS BROKEN

COMMENTS-11: Inspected and found screws are stripped for crown. Tried to replace broken clips with 340 clips, cut off broken clips. Repairs not completed at this time

CONDITION:-12: AIRLINE RUBBED THROUGH NEAR AIR DRYER

COMMENTS-12: Repaired air line.

CONDITION:-13: TRAILER CORD DAMAGED & TERMINAL CORRODED

COMMENTS-13: Replaced damaged trailer cord with new. Cleaned terminal and applied dielectric grease. Wrapped with hydraulic wrap and new hanger.

DR5366 CLOSED 01-14-17 321575
HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
CONDITION:-1: FAN HUB LEAKING AIR Fan hub leaking through center. Removed and replaced unit
COMMENTS-1: 1325
CONDITION:-2: LABOR TO REPLACE FAN CLUTCH ASSY - NOT COVERED UNDER WARRANTY
RO NUMBER STATUS DATE MILEAGE

DR5267 CLOSED 01-11-17 321575
HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
CONDITION:-1: PACLEASE SAFETY
* REMEDY CODES - 2
COMMENTS-1: PERFORMED SAFETY
CONDITION:-2: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FLUETGUARD FILTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN****
* REMEDY CODES - PLB
COMMENTS-2: started b-service , retrieved another unit that needs to be finished for pickup greased unit
CONDITION:-3: PERFORM BRAKE INSPECTION
COMMENTS-3: put unit on stands, remove all wheels and brakes, inspect and measure, re-install all brakes and wheels, torque wheels and bring repairable items to laura
CONDITION:-4: COOLANT LOW
COMMENTS-4: placed pressure tester on unit and held pressure, topped up coolant. went to main shop to install a safety sticker
RO NUMBER STATUS DATE MILEAGE
CONDITION:-5: PASSENGER SIDE REAR S-CAM SEAL LEAKING
COMMENTS-5: removed drum and wheel end , remove wheel seal and begin removing brakes. replaced scam seal and reinstalled. replaced brake hardware kit as one of the springs was damaged. cleaned hub and bearings, found the inner bearing to be damaged and needs replacing, got parts ordered from main shop and informed chairity/laura. punched out old race and got new race punched in. started to reassemble finished reassembling pre lubed bearings and filled hub ll adjusted breaks and torqued on axle nut as wheel as wheel nuts. went around truck and double checked to make sure they were all torqued. installed hub caps and nut covers
CONDITION:-6: PASSENGER SIDE FIRST DRIVE SHOCK BROKEN
COMMENTS-6: removed broken shock and gave to parts to tag for warranty. installed new shock with new bushings and a new nut on the top tests ok. spent first part of the morning figuring out what was going on in the shop/ where all the parts were
CONDITION:-7: PASSENGER SIDE FULE TANK GAUGE NOT WORKING- CUSTOMER COMPLAINT

INQUIRY

CUST # YEAR MAKE MODEL SERIAL 11
 51250 2015 PETERBILT 367 1XPTD40X8FD283804

RO NUMBER STATUS DATE MILEAGE
 COMMENTS-7: hooked up to esa and monitored/ simulated guage and tested ok. removed sending unit from tank and checked different position whith multie meter to make sure it was reading properly. reinstalled unit in tank but tu rned so that it will not interfere with the pick up and return lines now te sts ok

CONDITION:-8: OPERATION MOVED TO REPAIR ORDER DR5366
 CONDITION:-9: ENGINE WEBASTO RUNNING ROUGH, 2-3 ATTEMPTS TO START
 COMMENTS-9: CAUSE: OVERHEAT. CORRECTION: FOUND HEATER OPERATING BUT NO COOL ANT FLOW. FOUND DEBRIS IN MAGNETIC DRIVE IMPELLOR IN WATER PUMP. CLEANED RE -CHECKED OPERATION. OK

CONDITION:-10: FLEX PIPE LEAKING
 CONDITION:-11: 1/2 INCH UP AND DOWN MOVEMENT ON INPUT YOKE
 COMMENTS-11: found .5 inch up and down movement. removed drive shaft and me assured end play 0.46thou removed power divider and found damage on both be arings and a broken gear in the spyder cage, took pictures of everything. w ent to check if it was warranty and i had to call into dana and deal with t he whole warranty process. claim got denied as it was a spin out failure. go t parts quote made up and sent off request parts and bring units in grab un RO NUMBER STATUS DATE MILEAGE

it from main building , drain and remove diff section, assemble power divid er and store diff on pallet . remove hubs with wheels and through shaft, in spect and clean bearings and races. clear banjo housing bearings all seem f ine , report to forman STARTED INSTALLING WHEEL ENDS INSTALLED FRONT AXLE C ARRIER WITH SILICONE AND TORQUED. INSTALLED FRONT INPUT YOLK AND INSTALLED DRIVELINE NUT WITH 1'' GUN AND RED LOCKTITE. finished securing front axle c arrier and lines. installed output shaft with snapring, seal, yolk, and nut . installed interaxle driveline and main driveline, torqued. filled axle hu bs and front carrier with 75w90. installed driver step and cat walk. garret took unit for road test, no complaints.

CONDITION:-12: DRIVERS SIDE UPPER STACK BUSHING WORN OUT
 COMMENTS-12: removed old bushings and installed new tests ok
 CONDITION:-13: 5TH WHEEL SLIDE RELEASE LEAKING
 COMMENTS-13: replaced air line and both fitting tests ok
 CONDITION:-14: UPPER RAD HOSE CLAMP MISSING
 COMMENTS-14: REPLACED MISSING CLAMP TESTS OK
 CONDITION:-15: CHANGE OIL IN REAR DRIVE DIFFERENTIAL
 COMMENTS-15: DRAINED REAR DIFF OIL AND TOPPED UP WITH 75W90.

RO NUMBER STATUS DATE MILEAGE

 OUT354 CLOSED 11-25-16 304774
 HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: WARRANTY PENDING WHEEL SEAL LEAKING

OUT352 CLOSED 11-22-16 306322
 HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: 2 new steer tires and alignment

OUT323 CLOSED 11-02-16 243015
 HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: 2 STEER TIRES 8 DRIVE TIRES

DR4814 CLOSED 10-31-16 291777
 HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL EETGUARD FILLTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN**** ENGINE HOURS;
 COMMENTS-1: started b-service, brought unit from main building complted b-s

INQUIRY

RO NUMBER	CUST #	YEAR MAKE	MODEL	SERIAL 12	MILEAGE
	51250	2015 PETERBILT	367	1XPTD40X8FD283804	
416223					
service park unit at main building, programed unit					
CONDITION:-2: ITEMS OR REPAIR-NEXT TIME CUSTOMER COMES IN -ENGINE FLEX PIPE LEAKING -P/S FUEL TANK, REAR STRAP LOOSE					

OUT241		CLOSED	10-25-16		177080
HOUR METERS: ENGINE			0.0 METER2	0.0 METER3	0.0
CONDITION:-1: REPAIR AIR LEAK					

DR4647		CLOSED	10-13-16		280078
HOUR METERS: ENGINE			0.0 METER2	0.0 METER3	0.0
CONDITION:-1: PAC PACLEASE WINDSHIELD REPLACEMENT-BOTH					
COMMENTS-1: Replace both windsheilds and perform complimentary inspection					
CONDITION:-2: TAIL LIGHTS OUT (STOP LIGHTS)					
COMMENTS-2: Check wiring and request new lamps, re-test. Lights are working proper at this time					
CONDITION:-3: CIGAR LIGHTER OUT					
CONDITION:-4: COOLANT LOW (BOTTOME RAD HOSE LEAKING)					
COMMENTS-4: Replace lower rad hose clamp. Re-fill and re-check. Found Webas					
RO NUMBER		STATUS	DATE		MILEAGE
to heater hose loose, tighten hose clamps					

DR4436		CLOSED	09-16-16		263699
HOUR METERS: ENGINE			0.0 METER2	0.0 METER3	0.0
CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL					
EETGUARD FILLTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN**** ENGINE HOURS;					
* REMEDY CODES - PLB					
COMMENTS-1: Performed service					
CONDITION:-2: REPLACE DAMAGED CB ANTENNAS					
COMMENTS-2: Installed					
CONDITION:-3: P/S TAIL LAMP OUT					
CONDITION:-4: aIR TANK UNDRRE D/S DOOR LOOSE					

DR4220		CLOSED	08-12-16		243015
HOUR METERS: ENGINE			0.0 METER2	0.0 METER3	0.0
CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL					
EETGUARD FILLTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN**** 5161 HRS					
COMMENTS-1: Performed B service					
RO NUMBER		STATUS	DATE		MILEAGE
CONDITION:-2: UNIT WAS RUNNING HOT					
COMMENTS-2: Hookup computer and get codes. Check over wiring. OK. Rinse rad and torque wheels. Charge unit.					
CONDITION:-3: AIR LEAK UNDER SLEEPER					
COMMENTS-3: Inspect, found leaking swivel fitting on rear of trans. Removed and replaced, test, found leaking fitting on side of trans, removed and replaced, re-tested. OK					
CONDITION:-4: BUNK CLIMATE CONTROLS NOT WORKING					
COMMENTS-4: Check operation, could not duplicate					
CONDITION:-5: OIL LEAK INPUT FRONT DIFF					
COMMENTS-5: Remove drivehaft, yoke nut, yoke and seal. Clean components, Fo und seal had grooved yoke. Reassemble with new seal and yoke. Top up fluids . 1102					
CONDITION:-6: COOLANT LEAK AT HEATER HOSES					
COMMENTS-6: Replace heater hose union and clamps, re check for leaks OK. To pped up coolant.					
CONDITION:-7: YOKE AND END PLAY OUT OF SPEC					

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 13
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
DR3982	CLOSED	07-07-16	225047

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL
 EETGUARD FILLTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN****
 * REMEDY CODES - PLB
 COMMENTS-1: Performed B service
 CONDITION:-2: ADJUST PROTECTION BUMPER
 COMMENTS-2: adjusted
 CONDITION:-3: INPUT OF FIRST DRIVE LEAKING
 COMMENTS-3: Remove driveline, yoke nut and yoke. Remove and replace seal, c
 lean components and reassemble with new strap kit. Fill oil as it was almos
 t entirely empty due to leak. 1027
 CONDITION:-4: CLEAN COROSION FROM TRAILERCORD AND PORT
 COMMENTS-4: Cleaned and applied protectant on cord terminals
 CONDITION:-5: REPAIR P/S ANTI SAIL BRACKET
 COMMENTS-5: repaired bolts holding anti sail
 CONDITION:-6: REMOVE LISCENSE PLATE LAMP
 COMMENTS-6: removed and sealed wireing

RO NUMBER	STATUS	DATE	MILEAGE
DR3911	CLOSED	06-27-16	215000

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: BATTERY FAULT/ESA CODES
 * REMEDY CODES - BATTERIES
 COMMENTS-1: inspected batteries and cables, found mega fuse broken , replac
 ed fuse and holder , checked cab ground , dissassembled and cleaned , re-ass
 embled and requested road test , unit is fine at this time
 CONDITION:-2: INSTALL BOOT BRUSH
 * REMEDY CODES - M18
 COMMENTS-2: installed boot brush to d/s step

RO NUMBER	STATUS	DATE	MILEAGE
DR3820	CLOSED	06-13-16	212008

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: CUSTOMER COMPLAINT THAT POWER STEERING IS FAILING
 COMMENTS-1: installed power steering cooler , bleed system and test ,park u
 nit
 CONDITION:-2: PERFORM CUMMINS 1763 UPDATE, OIL RING UPDATE UNIT IS ON ESN "
 B" LIST-ONLY NEEDS 6 O-RINGS. INSPECT FOR GROOVE AND LEAKS AND REPORT TO SI
 D
 COMMENTS-2: performec campaign as required C85324 12912536

RO NUMBER	STATUS	DATE	MILEAGE
DR3729	CLOSED	05-30-16	204932

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: REPAIR RH CB ANTENNA MOUNT AND COAX CABLE
 * REMEDY CODES - ANTENNA
 COMMENTS-1: replaced r/h antenna mount and antenna. replaced end on coax ca
 ble and checked operation OK.
 CONDITION:-2: BOTH LH DOOR STOPS BROKEN
 COMMENTS-2: replaced both l/h door stops.

RO NUMBER	STATUS	DATE	MILEAGE
DR3725	CLOSED	05-30-16	204930

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 14
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
-----------	--------	------	---------

CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL
EETGUARD FILLTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN****

* REMEDY CODES - PLB

COMMENTS-1: Change oil/fuel and coolant filters. Replace ecm filter

CONDITION:-2: RE-CONDITION BATTERY DISCONNECT AND CABLES

* REMEDY CODES - ..

COMMENTS-2: Remove and clean cables at disconnect switch and cut out factor
y inline disconnect. Install a soder in one with shrink tube

CONDITION:-3: AIR LEAK WHEN BRAKES APPLIED

COMMENTS-3: Replaced 45 degree fitting

CONDITION:-4: REPLACE CB ANTENNAS

* REMEDY CODES - 21

COMMENTS-4: Found antenna on p/side was broken off. Removed bulkhead to acc
ess coaxle cable. Found wire was only holding onto casing. Bent wire over b
ent wire over and soder/melt wiring together so it would work

CONDITION:-5: ADJUST CLUTCH FOR FREE PLAY

* REMEDY CODES - CLADJ

COMMENTS-5: Adjust clutch

RO NUMBER	STATUS	DATE	MILEAGE
-----------	--------	------	---------

CONDITION:-6: ADJUST BUMPER LATCH

COMMENTS-6: Adjusted

CONDITION:-7: REPLACE GLAD HAND RUBBERS

COMMENTS-7: Replaced glad hand rubbers

CONDITION:-8: SERVICE TRAILER CORD AND REPLACE TRAILER CORD PORT

COMMENTS-8: Completed service

CONDITION:-9: REPAIR BUG SCREEN RUBBING ON A/C CONDENSOR

COMMENTS-9: Completed temp. repair

DR3313	CLOSED	04-08-16	187966
--------	--------	----------	--------

HOUR METERS: ENGINE	0.0	METER2	0.0	METER3	0.0
---------------------	-----	--------	-----	--------	-----

CONDITION:-1: BOTH D/S MARKER LAMPS BURNT OUT

* REMEDY CODES - LIGHTS

COMMENTS-1: Removed d/s back access panel, checked and replaced bulbs. Re-t
est, bulbs still not on. Troubleshoot wiring , find weather pack plug corro
ded , cut plug out and wire together. Re- test, all lights on at this time
, stopped unit when backing out , p/s marker lamp is out, troubleshoot and
find the same weather pack at the d/s is corroded , cut plug out and wired

RO NUMBER	STATUS	DATE	MILEAGE
-----------	--------	------	---------

around, re-test, all lights working at this time.

DR3229	CLOSED	03-28-16	187720
--------	--------	----------	--------

HOUR METERS: ENGINE	3895.0	METER2	0.0	METER3	0.0
---------------------	--------	--------	-----	--------	-----

CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL
EETGUARD FILLTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN**** ENGINE HOURS;
4185

* REMEDY CODES - PLB

COMMENTS-1: performed B service

DR3040	CLOSED	03-11-16	176958
--------	--------	----------	--------

HOUR METERS: ENGINE	0.0	METER2	0.0	METER3	0.0
---------------------	-----	--------	-----	--------	-----

CONDITION:-1: P/S CLEAR BUMPER LIGHT FLICKING

COMMENTS-1: Removed both bumper lights found corrosion in wire , repaired c
orrosion and re-tested , lights are fine at this time

CONDITION:-2: PERFORM PACLEASE A SERVICE AS PER INSPECTION SHEET ENGINE HOU
RS: 4029.7

* REMEDY CODES - PLA

INQUIRY

CUST # YEAR MAKE MODEL SERIAL 15
51250 2015 PETERBILT 367 1XPTD40X8FD283804

RO NUMBER STATUS DATE MILEAGE

COMMENTS-2: PERFORM SERVICE AND COMPLETE INSPECTION

CONDITION:-3: PACLEASE WINDSHIED REPLACEMENT USE TRP WINDSHIELD ONLY DRIVER
'S SIDE

* REMEDY CODES - PLWIND

COMMENTS-3: installed windshield

CONDITION:-4: DEF COVER LOOSE

COMMENTS-4: TOOK PICTURES FOR WARRENTY, REMOVED AND REPLACED RIV NUTS INSTA
LLED STAINLESS HARDWARE DELIVERED TRUCK TO MAIN BUILDING

CONDITION:-5: RECONDITION HEADLIGHT LENSES

COMMENTS-5: reconditioned headlight lenses and installed 3m film

CONDITION:-6: REPAIR WINTER FRONT CLIP

CONDITION:-7: ADJUST D/S QUARTER FENDER

COMMENTS-7: adjusted

CONDITION:-8: LOAD TEST BATTERIES, SIGNS OF A LEAK

COMMENTS-8: load tested batterys at 13.0 volts , battery voltage dropped to
6.1 volt instantly and never recovered , replaced with exide batterys

CONDITION:-9: P/S FIRST DRIVE AIR BAG LEAKING AT FITTING

COMMENTS-9: removed and replaced air bag fitting , handed part for warranty

RO NUMBER STATUS DATE MILEAGE

CONDITION:-10: BATTERY BOX IS CRACKED

COMMENTS-10: Remove components for access. Remove and replace battery box a
nd reassemble. 0686

CONDITION:-11: DRIVER SIDE TAIL LIGHT CORRODED AND BURNT OUT

COMMENTS-11: checked and applied dielectric grease to all rear lamps, cut a
nd replaced corroded lamp , requested parts for saturday shift

CONDITION:-12: NOTE: BOTH REAR FENDERS DAMAGED BY TRAILER

CONDITION:-13: UPDATE ENGINE PARAMETERS

* REMEDY CODES - M19

COMMENTS-13: UPDATE PARAMETERS

DR2922 CLOSED 02-25-16 170705

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: TRAILER AND TAILLIGHTS NOT WORKING

COMMENTS-1: REPLACED TRAILER TAIL LAMP FUSE AND CHECKED TRAILER PLUG, OK. R
EPLACED R/H TAIL LAMP AND PIG TAIL ASSY AND CHECKED OPERATION, OK.

RO NUMBER STATUS DATE MILEAGE

DR2842 CLOSED 02-17-16 166807

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL
EETGUARD FILLTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN**** ENGINE HOURS:
3819.7

COMMENTS-1: COMPLETED B- SERVICE reported deficencys and requested conditio
n

CONDITION:-2: PERFORM CUMMINS TRP _1651_____ RECORD BEFORE _____ REC
ORD AFTER _____ -SEE ATTACHED

COMMENTS-2: CALIBRATED THE ECM FROM EF10067.31 TO EF10067.32 C20487 1272191
3

CONDITION:-3: QUARTER FENDER LIGHTS, BOTH SIDES ARE CORRODED

COMMENTS-3: removed and replaced both sides 1/4 fender lamps , wired and te
sted

CONDITION:-4: SUPPLY AND INSTALL RAD GUARD

COMMENTS-4: installed

DR2566 CLOSED 01-12-16 155091

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 16
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
HOUR METERS: ENGINE		0.0 METER2	0.0 METER3 0.0

CONDITION:-1: PERFORM READY, RENT, GO
 * REMEDY CODES - PAC
 COMMENTS-1: performed checkover ,

DR2404	CLOSED	12-21-15	155090
--------	--------	----------	--------

HOUR METERS: ENGINE	0.0 METER2	0.0 METER3	0.0
---------------------	------------	------------	-----

CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL
 EETGUARD FILLTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN****
 COMMENTS-1: COMPLETED B SERVICE
 CONDITION:-2: INSTALL GUARD FOR BUNK HEATER-SEE SHAWN
 COMMENTS-2: FABRICATED SHIELD & INSTALLED
 CONDITION:-3: PERFORM CVIP
 COMMENTS-3: PERFORMED CVIP PER SHEET

DR2365	CLOSED	12-10-15	144320
--------	--------	----------	--------

HOUR METERS: ENGINE	0.0 METER2	0.0 METER3	0.0
---------------------	------------	------------	-----

CONDITION:-1: REPLACE BROKEN MUDFLAPS AND HANGERS
 RO NUMBER STATUS DATE MILEAGE
 COMMENTS-1: make up new flaps and hangers and install.

DR2166	CLOSED	11-18-15	144320
--------	--------	----------	--------

HOUR METERS: ENGINE	0.0 METER2	0.0 METER3	0.0
---------------------	------------	------------	-----

CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL
 EETGUARD FILLTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN**** (LAST B SERVIC
 E WAS OCT 13 AT 3000 HOURS) ***CHECK DATE ON SAFETY *****
 COMMENTS-1: performed B service.
 CONDITION:-2: OIL LEAK FRONT OF OIL COOLER
 COMMENTS-2: Steamed engine and found the oil cooler thermostat seal was lea
 king oil. Removed and replaced the oil cooler thermostat seal. Reassembled
 and tested after repair. C5959 12598337
 CONDITION:-3: ADD A PURGE VALVE AND CORD ONTO THE RIGHT HAND SIDE AIR TANK
 UNDER THE TRUCK SO CUSTOMER CAN PULL THE CORD TO DRAIN INSTEAD OF CRAWLING
 UNDER TRUCK
 COMMENTS-3: install air tank drain on L/H rear air tank with pull cord. chec
 k operation OK

RO NUMBER	STATUS	DATE	MILEAGE
DR1889	CLOSED	10-13-15	124890

HOUR METERS: ENGINE	0.0 METER2	0.0 METER3	0.0
---------------------	------------	------------	-----

CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL
 EETGAUED FILTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN****
 * REMEDY CODES - PLB
 COMMENTS-1: performed B service and road test.
 CONDITION:-2: REPAIR WIRING AT REAR CROSSMEMBER
 COMMENTS-2: repaired rubbed wiring at rear crossmember
 CONDITION:-3: 3 BROKEN WINTER FRONT CLIPS
 COMMENTS-3: removed grill insert, un bolted grab handle and unbolted hood c
 rown.cut rivets and handed winterfront clips in for warrenty . installed ne
 w clip assemblys and re-assembled grill.re-installed hood crown and grab ha
 ndle
 CONDITION:-4: REPLACE GLAD HAND RUBBERS
 COMMENTS-4: REPLACED GLAD HAND RUBBERS
 CONDITION:-5: TURBO-NOISY
 COMMENTS-5: found air to air clamp loose , test drove unit unable to find w
 histle .checked codes and updated engine file

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 17
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER	STATUS	DATE	MILEAGE
DR1477	CLOSED	08-31-15	106142

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-6: SERVICE AIR DRIER
 COMMENTS-6: removed cleaned and replaced cartridge and purge valve

RO NUMBER	STATUS	DATE	MILEAGE
DR1477	CLOSED	08-31-15	106142

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: PERFORM B SERVICE
 COMMENTS-1: B SERVICE. ... COMPLETED B SERVICE
 CONDITION:-2: PEDESTAL REPLACEMENT
 COMMENTS-2: REMOVED AND INSTALL NEW PEDISTAL
 CONDITION:-3: WHISTLING NOISE UNDER BOOST
 COMMENTS-3: tightened loose air to air clamps and road test OK
 CONDITION:-4: LEFT HAND TAIL LAMP NOT WORKING
 COMMENTS-4: REPLACED LEFT HAND TAIL LAMP AND PIGTAIL. CHECKED OPERATION OK
 CONDITION:-5: REPLACE LEFT HAND 1/4 FENDER SEAL
 COMMENTS-5: REPLACED LEFT HAND 1/4 FENDER SEAL
 CONDITION:-6: LEFT HAND BUNK DOOR POWER LOCK NOT WORKING
 COMMENTS-6: FIND DOOR LOCK ACTUATOR NOT RESPONDING. REMOVE AND REPLACE ACTUATOR AND TEST. GOOD 0120

RO NUMBER	STATUS	DATE	MILEAGE
DR1226	CLOSED	08-25-15	92473

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: PAINT PEELING ON WINDSHIELD MAST
 COMMENTS-1: Removed sunvisor and wiper arms. Removed windshields on both sides. Sandblast and prep surface. Paint and refinish as required. Reassy. 0101

RO NUMBER	STATUS	DATE	MILEAGE
DR1177	CLOSED	07-31-15	92473

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: PERFORM PACLEASE B SERVICE
 * REMEDY CODES - PLB
 COMMENTS-1: performed B service
 CONDITION:-2: HORN COVER MISSING CB ANTENNA MISSING, BROKEN.
 COMMENTS-2: INSTALLED TAKE OFF HORN COVER AND TAKE OFF CB ANTENNAS.
 CONDITION:-3: LEFT HAND WINDSHIELD CRACKED SUPPLY TRP WINDSHIELD ONLY -replaced both windshields due to windshield mask repair. -moved to warranty condition on work order DR1226
 * REMEDY CODES - BOTHWS
 CONDITION:-4: PASS SIDE WINDOW WON'T WORK
 COMMENTS-4: trouble shoot door locks and windows , change fuses ,re-test, p/s window motor has broken ,open door skin and replace window motor ,re-test ,clean track and re assemble
 CONDITION:-5: EGP PRESSURE TUBE NEEDS TO BE REPLACED-HOLD TURBO SPEED SENSOR-HOLD -SEE DEREK
 COMMENTS-5: REPLACED EGR PRESSURE SENSING TUBE. C35823 12434292
 CONDITION:-6: OPERATION MOVED TO REPAIR ORDER DR1226
 CONDITION:-7: LEFT HAND AIR TANK LOOSE
 CONDITION:-8: BACK UP ALARM MISSING
 COMMENTS-8: INSTALLED NEW BACK-UP ALARM AND WIRE IN CHECK OPERATION OK

RO NUMBER	STATUS	DATE	MILEAGE
MS2455	CLOSED	08-12-15	75712

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0
 CONDITION:-1: travel to tofield
 COMMENTS-1: TRAVEL TO CUSTOMER LOCATION

INQUIRY

CUST #	YEAR MAKE	MODEL	SERIAL 18
51250	2015 PETERBILT	367	1XPTD40X8FD283804

RO NUMBER STATUS DATE MILEAGE

CONDITION:-2: cel

COMMENTS-2: CAUSE: CEL ON CORRECTION: T/S ACTIVE FAULT 2973 CHECKED TURBO SPEED SENSOR RESISTANCE @ 1.032K OHMS OK.CHECKED SIGNAL AND GROUND TO ENGINE BLOCK OK OPEN . FOUND INTAKE MANIFOLD SENSOR READING 2.2 IN/HG KEY ON . REPLACED SENSOR CODE INACTIVE DERATE WOUNDNT GO INACTIVE ,HAD TO UPDATE ECM CAL. RAN REGEN OK.

S125315	CLOSED	06-23-15	65000
---------	--------	----------	-------

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: SERVICE ENGINE, GREASE UNIT, CHECK ALL LEVELS PERFORM CHECK LIST AND REPORT ANY PROBLEMS

COMMENTS-1: change oil filter and oil only greased unit and quick look over

CONDITION:-2: C1638 .ISX12/15 CM2250/CM2350 LUBRICATING OIL FILTER BYPASS VALVE CAMPAIGN

COMMENTS-2: remove and replace oil by pass valve torque to spec, painted cap C71366 12375597

RO NUMBER	STATUS	DATE	MILEAGE
S124507	CLOSED	05-28-15	54076

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FLEETGAUED FILTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN**** performed B service.

* REMEDY CODES - PLB

CONDITION:-2: PASSENGER SIDE POWER WINDOW NOT WORKING Test powers and fuses ect. Good. Remove door panel, Test regulator and find shorted. Remove and replace regulator, reassemble and test. 6617

* REMEDY CODES - WINDOWS

CONDITION:-3: DRIVERS SIDE SEAT BELT CUT AND TIED IN A KNOT noticed seat belt has extra piece tied to it, removed. ok

* REMEDY CODES - SEAT BELT

CONDITION:-4: 5TH WHEEL AIRSLIDE AIR LINE MISSING repaired issue.

* REMEDY CODES - 5TH

CONDITION:-5: POWER LOCKS NOT WORKING ON DOOR SWITCH removed 10 amp door lock & rke fuses & installed 20 amp. checked operation. all ok.

* REMEDY CODES - POWERLOCKS

RO NUMBER	STATUS	DATE	MILEAGE
S123297	CLOSED	04-13-15	33549

CONDITION:-6: DEF COVER LOOSE put new bolts in. checked, ok.

* REMEDY CODES - DEFCOVER

S123141	CLOSED	04-13-15	33545
---------	--------	----------	-------

CONDITION:-7: PERFORM FEDERAL RECALL 1214L BRAKE ACTUATOR Remove and replace brake actuators as per recall 6618

* REMEDY CODES - RECALL

CONDITION:-8: REPAIRS FROM B SERVICE -GLAD HAND RUBBERS -WIPER BLADES -TIGHTEN BUMPER -AIR DRYER LEAKING made repairs. ok.

* REMEDY CODES - PLB REPAIRS

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: PACLEASE SAFETY -perform Safety

HOUR METERS: ENGINE 0.0 METER2 0.0 METER3 0.0

CONDITION:-1: SUPPLY AND INSTALL 16" STEP TOOL BOX (SEE LANE)

CONDITION:-2: SUPPLY AND INSTALL MUD FLAPS UNDER CHAIN HANGERS ON THE HEADACHE RACK

INQUIRY

RO NUMBER	CUST #	YEAR MAKE	MODEL	SERIAL 19	MILEAGE
	51250	2015 PETERBILT	367	1XPTD40X8FD283804	

CONDITION:-3: SUPPLY AND INSTALL 1 DURA WORK LIGHT ON HEADACHE RACK (EASIES T LOCATION)
CONDITION:-4: SUPPLY AND INSTALL 2 EXTRA CHAIN HNGERS ON HEADACHE RACK
CONDITION:-5: SUPPLY AND INSTALL RED AND BLUE EXTENSION HANDLES ON GLAD HAN DS

S122955 CLOSED 04-14-15 33545
CONDITION:-1: PERFORM PACLEASE B SERVICE AS PER INSPECTION SHEET ****USE FL EETGAUED FILTERS UNLESS OTHERWISE INSTRUCTED BY FOREMAN**** PERFORM CHECK-I N
CONDITION:-2: DRIVERS SEAT BROKEN Inspected. Found bolt fell out of pivot p oint. Reinstalled the bolt and secured. 6013
CONDITION:-3: PLACLEASE WINDSHIELD REPLACEMENT USE TRP WINDSHIELD ONLY
CONDITION:-4: ABS LIGHT ON Hook up computer and troubleshot code for wheel speed sensor open. Adjusted speed sensor gap and clear codes 5997
CONDITION:-5: REPAIRS FROM B SERVICE -COOLANT LOW -GLAD HAND RUBBERS NEED R EPLACING -CAB AND SLPR AIR FILTERS NEED REPLACING -CB ANTENNAS -LUBRICATE 5 TH WHEEL -NUT COVERS -WIPER BLADES

RO NUMBER	STATUS	DATE	MILEAGE

CONDITION:-6: D/S REAR LEAF SPRING BROKEN-SAVE PARTS Removed and replaced l eaf spring assembly and torque 5998
CONDITION:-7: P/S 1/4 FENDER CRACKED AT BOTTOM Paint and refinish new fende r as required. Replaced fender, cowl seal and marker lamp. 6009
CONDITION:-8: COOLANT AT FIREWALL Removed and replaced leaking clamps and t est 5999
CONDITION:-9: AIR FITTING DAMAGED ON AIR DRYER Removed and replaced fitting 6000

S120893 CLOSED 01-21-15 3461
CONDITION:-1: GPS WON'T SET Removed and replaced ECM for people net system. Checked diagnostics parameters.Sent OBC information, and recieved confirmat ion.

S120206 CLOSED 01-14-15 3459
CONDITION:-1: PERFORM PRE DELIVERY INSPECTION KEY CODE# G-149, 3429 KM **** *****IF TRUCK IS EQUIPPED WITH AN ALLISON TRANSMISSION***** CHECK AN D RECORD DRIVELINE ANGLES AND REPORT TO DON OR ANGELO

RO NUMBER	STATUS	DATE	MILEAGE

CONDITION:-2: PERFORM SAFETY INSPECTION AND REPORT TO FOREMAN FOREMAN TO NO TIFY CUSTOMER OF REPAIRS REQUIRED
CONDITION:-3: SUPPLY AND INSTALL STAINLESS HUB CAPS AND NUT COVERS W/SIGHT HOLE IN FRONT CAPS
CONDITION:-4: SUPPLY AND INSTALL CHECKER PLATE 1/2 FENDERS W/CHAIN HANGERS
CONDITION:-5: SUPPLY AND INSTALL BUMPER -SEE JOSH OR WAYNE
CONDITION:-6: SUPPLY AND INSTALL BOOT BRUSH SUPPLY AND INSTALL BACK UP LIGH TS ON EXISTING BRACKETS SUPPLY AND INSTALL CB ANTENNAS SUPPLY AND INSTALL F LOORMATS
CONDITION:-7: SUPPLY AND INSTALL RODA, RPM SENSITIVE
CONDITION:-8: SET PARAMETERS ON ENGINE SUPPLY AND INSTALL BETZ STYLE REMOVA BLE MUDFLAP HANGERS SUPPLY AND INSTALL FIRE EXT, FLARE KIT, FIRST AID KIT-I F NOT IN TRUCK CHANGE REAR FLAPS TO STAHL PETEBILT STYLE
CONDITION:-9: SUPPLY AND INSTALL GPS
CONDITION:-10: ** WEBASTO COMBO SERVICE SPECIAL ** *****SUPPLY AND INSTALL WEBASTO COMBO HEATER***** *****ENGINE HEATER S/N 1422302567__MODEL #_THERM O TOP C *****BUNK HEATER S/N__1421687229__MODEL #AIR TOP 2000
CONDITION:-11: SUPPLY AND INSTALL STARR LED DRIVING LIGHTS ON SEPARATE SWIT

INQUIRY

RO NUMBER	CUST #	YEAR MAKE	MODEL	SERIAL 20	MILEAGE
	51250	2015 PETERBILT	367	1XPTD40X8FD283804	

CH

CONDITION:-12: FILL WITH FUEL AND DEF

CONDITION:-13: PERFORM WHEEL ALIGNMENT

CONDITION:-14: DRILL HOLES IN BUMPER FOR LICENCE PLATE SUPPLY AND INSTALL RUBBER FLAP INSIDE OF FRONT FENDERS SUPPLY AND INSTALL RUBBER STRIPS BETWEEN BUMPER AND FENDERS INSTALL WIDER MUDFLAPS ON REAR OF FRONT FENDERS

CONDITION:-15: SET PARAMETERS TO 110KM ON CRUISE, 115 ON FOOT FEED ENGINE BRAKE SET TO COME ON AS SOON AS THROTTLE IS RELEASED VERIFY LOW VOLTAGE IS SET

CONDITION:-16: SUPPLY AND INSTALL HEADACHE RACK
