



504-9

530 MacKenzie Blvd.
Fort McMurray AB T9H 4C8
(780) 743-2871

SERVICE REPAIR ORDER

CUSTOMER NAME	NORTHSTAR FORD	CONTACT NUMBER	780-713-2888 OR EMAIL QUICKLANE@NORTHSTARFORD.COM
MILEAGE	64745	LICENSE	NO PLATE
VIN:	1GAZGPF5H1126174	IN SERVICE DATE	
MODEL	2017 EXPRESS	COLOR	WHITE
UNIT #		PROMISE TIME	
RO OPENED	26-Jun-24	ADVISOR	7541299 - KELLY
TAG #	T2328		

A CONCERN Tech # 7541133

REPROGRAM NEW ABS MODULE. ABS MODULE WAS INSTALLED BY FORD.

CAUSE:

2:46 PM 06/26 PROGRAM NEW EBCM MODULE INSTALLED BY ANOTHER SHOP.. LCAIM CODE: 28YN222275712. NOTE: ABS LIGHT GONE.

LBR Type _____ LBR TIME _____

LBR
MENU LBR
PARTS
TOTAL \$0.00

B CONCERN Tech #

INFO

CAUSE:

CDK WAS DOWN DURING WRITE UP. PO FROM NORTHSTAR FORD PO# 154. PLEASE CONFIRM THAT.

LBR Type _____ LBR TIME _____

LBR
MENU LBR
PARTS
TOTAL \$0.00

C CONCERN Tech #

CAUSE:

LBR Type _____ LBR TIME _____

LBR
MENU LBR
PARTS
TOTAL \$0.00



530 MacKenzie Blvd.
Fort McMurray AB T9H 4C8
(780) 743-2871

SERVICE REPAIR ORDER

CUSTOMER NAME	NORTHSTAR FORD	CONTACT NUMBER	780-743-2871 OR EMAIL QUICKLANE@LINCOLN@NORTHSTAR
MILEAGE	64745	LICENSE	NO PLATE
VIN:	1GAZGPGF5H1126174	IN SERVICE DATE	
MODEL	2017 EXPRESS	COLOR	WHITE
UNIT #		PROMISE TIME	
RO OPENED	45469	ADVISOR	7541299 - KELLY
TAG #	T2328		

J CONCERN

Tech #

CAUSE:

LBR Type

LBR TIME

LBR

MENU LI

PARTS

TOTAL \$0.00

K CONCERN

Tech #

CAUSE:

LBR Type

LBR TIME

LBR

MENU IT

PARTS

TOTAL \$0.00

LABOUR AMOUNT	\$0.00
PARTS AMOUNT	\$0.00
SHOP SUPPLIES	\$0.00
SUBTOTAL CHARGES	\$0.00
G.S.T. #794 477 323 RT0001	\$0.00
TOTAL	\$0.00

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE \$0.00 BEING ALL OR THE
OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. AN EXPRESS MECHANIC'S LIEN IS
HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

AUTHORIZER CUSTOMER SIGNATURE

DATE