

Unit	Model	Date	Work Order Details
1682	SY215C	6/9/2023	Tried boosting. Battery blown out. Grab new ans install.
1682	SY215C	6/30/2023	Started line boring
1682	SY215C	7/6/2023	Assemble wrist bucket
1682	SY215C	8/18/2023	Look over machine to diagnose codes and no throttle
1682	SY215C	11/13/2023	Fix wiring under cab for wiper motor. Order new bottom front glass and wiper arm, wiper
1682	SY215C	12/8/2023	Remove old window, clean rubber, install new window, install new wiper arm
1682	SY215C	12/17/2023	Flip blade clean all surfaces install new hardware chip tracks.
1682	SY215C	12/17/2023	cleaned track frames and turned cutting edge
1682	SY215C	1/17/2024	Check over unit/install radio
1682	SY215C	2/1/2024	Start unit and work implement to check for leak, the. Tightened loose fitting
1682	SY215C	2/1/2024	Replace seal on boom line
1682	SY215C	2/19/2024	Drive to unit change out bucket had to chip dirt out of quick attach
1682	SY215C	2/20/2024	Drive to R1 and remove bucket. Ops to move to other unit
1682	SY215C	2/20/2024	Travel to unit. Setup work area. Remove bucket. Cleanup work area.
1682	SY215C	2/25/2024	Installed bucket onto unit and sent to work.
1682	SY215C	2/27/2024	Bucket swap
1682	SY215C	2/27/2024	Remove bucket and install another bucket
1682	SY215C	2/28/2024	Removed worn out bucket teeth and replaced with new teeth.
1682	SY215C	2/29/2024	Replaced bucket tooth pin
1682	SY215C	3/2/2024	Remove bolts acting as pins. Install new pins and keepers on 2 teeth.
1682	SY215C	3/2/2024	Keeper fell of one of the teeth, go through truck to find something to get by until crew change, put a bolt in tooth until crew change, didn't have time to come back to laydown and back out to unit
1682	SY215C	3/3/2024	Tooth fell off grab parts run out to unit grabbed right keeper but wrong tooth gave info to nights to install didn't have time to run back and change
1682	SY215C	3/3/2024	Drove out to unit, replaced missing bucket tooth, installed new pin and keeper. Got called to unit again, installed bucket tooth with new pin and keeper.
1682	SY215C	3/10/2024	Ran unit out of fuel
1682	SY215C	3/19/2024	Grab multiple sets of frost teeth from laydown and rip out to machine. Incorrect teeth - none in stock at laydown. Order parts.
1682	SY215C	3/21/2024	Check over unit, bucket teeth need to be changed, and tooth shanks need to be built up
1682	SY215C	3/21/2024	Try and inatal teeth we have but they are to big

1682	SY215C	3/22/2024	Grab pins and keepers and locate machine. Bucket is in need of repair. Welder secured tooth by welding pin and keeper.
1682	SY215C	3/22/2024	Bucket tooth come off, built up tooth tanks and made new pin, so unit could still work, new teeth on the way
1682	SY215C	3/23/2024	Removed bucket
1682	SY215C	4/11/2024	Install grease block on stick
1682	SY215C	4/22/2024	Boost unit
1682	SY215C	5/28/2024	Plug into unit, repair wiring to def header. Call unit up
1682	SY215C	5/28/2024	Scr code got to unit found obd plug hooked up computer found vgt codes and temperature sensor code. Fixed wiring cleared codes and did a regen codes stayed away
1682	SY215C	5/31/2024	Checked connections to def dosing valve. Ran dosing test. Failed test, ordered new valve. drained def tank and refilled with new. Didn't get a chance to retest for def quality
1682	SY215C	6/4/2024	Looked into the codes Diagnosed that it was the DEF sending unit is the tank NFG ordered parts
1682	SY215C	6/6/2024	Install DEF injector
1682	SY215C	6/6/2024	Installed new DEF injector
1682	SY215C	6/11/2024	Replaced def tank/unit
1682	SY215C	6/11/2024	Run up and check over
1682	SY215C	6/11/2024	Tried to get unit to do a regen but couldn't. Engine code cleared itself. Called unit up.
1682	SY215C	10/12/2024	Go over machine for demob. Needs wiper arm tightened. Bottom stump pan pushed in a bit
1682	SY215C	10/13/2024	Mobilization inspection of machine, repaired right hand mirror and front wiper, ordered parts
1682	SY215C	11/8/2024	replace serpentine belt
1682	SY215C	11/9/2024	change right rear rollers 2pcs
1682	SY215C	12/6/2024	demob and repairs
1682	SY215C	12/6/2024	change 3 rollers on rh side
1682	SY215C	12/7/2024	demob and repairs
1682	SY215C	2/6/2025	Premobe
1682	SY215C	2/23/2025	Go to machine for no start Night switch was off
1682	SY215C	3/14/2025	Machine has been parked for a while, drove out to machine boosted unit, cold start machine with trucker
1682	SY215C	3/17/2025	Drive out to machine, swap out bucket on unit
1682	SY215C	3/24/2025	Bucket swap

1682	SY215C	3/30/2025	Install clean out bucket onto machine
1682	SY215C	6/7/2025	Complete 250 hr service