

Unit	Model	Date	Work Order Details
1769	A40G	8/5/2023	Replace leaking hoses
1769	A40G	8/8/2023	Straighten step and weld in stiffener on step
1769	A40G	8/16/2023	Fill tire and repair slow leak, tighten valve stem.
1769	A40G	8/23/2023	Walk around
1769	A40G	8/25/2023	Pre shift inspections
1769	A40G	8/26/2023	Tighten mounting screws for load/back up cam monitor as needed
1769	A40G	9/19/2023	Drive to site Set up work area. Repaired seat. Hydraulic leak on tank: loose cap. Fire extinguisher bracket loose, added mounting bolt.
1769	A40G	9/19/2023	Drove to camp pad from camp pad park up Inspected seat air ride messed with air ride switch and it started working. Diagnosed and repair hydrology oil leak Found loose quick connect fitting on top of hydraulic tank. Tightened fitting and checked for leaks Cleaned up.
1769	A40G	9/25/2023	Drove out to machine diagnosed seat air ride not working. Seat switch is faulty and needs to be replaced
1769	A40G	9/25/2023	Wrap up from HCL: Drive out to site Wait for truck to come in. Checked over unit. Drive back to HCL for end of shift clean up.
1769	A40G	9/26/2023	Order parts
1769	A40G	10/3/2023	Replace seat valve and test for brakes locking up when reversing, found no issue. Could not replicate.
1769	A40G	10/13/2023	Replace dryer
1769	A40G	10/20/2023	Travel to machine and replace leaking orings for test fittings.
1769	A40G	10/26/2023	Tested seat. Checked for leaks but found none.
1769	A40G	11/30/2023	Boost unit at camp pad
1769	A40G	12/10/2023	Called for a no start, grab batteries and head to unit, found fire switch was flipped and emergent switch in cab was pushed in, reset switches and fired right up
1769	A40G	1/5/2024	Look up parts.
1769	A40G	1/5/2024	Diagnose no propel
1769	A40G	1/8/2024	Go to unit inspect broken driveshaft in center hitch area, flanges on drop box ok will need a new driveshaft and mounting hardware/ U-joints. Warranty repair as unit fairly new, remove driveshaft and bring back to office for supervisor.
1769	A40G	1/18/2024	Drove to machine. Started up. Turned machine and locked steering.
1769	A40G	1/19/2024	Start unit let warm up, pull articulation lock out. Angle to the left for strongco.

1769	A40G	2/29/2024	Started looking into low fuel pressure code, got pulled off
1769	A40G	3/2/2024	Let unit warm up, test unit and code won't pop up now, sent to work and ordered fuel filter housing due to leaking primer
1769	A40G	3/21/2024	Unit died at ped 25. Fuel filters full of ice. Thaw fuel and add melt down. Get unit primed and started.
1769	A40G	3/26/2024	Ops report unit had an active code. Check codes, nothing active- had some data link errors. Return to service.
1769	A40G	3/30/2024	Horn and wipers not working. Find blown 10 amp fuse. Replace fuse and test.
1769	A40G	4/7/2024	Drive to unit, test drive unit, remove air lines on solenoids and hit foot switch, could hear it leak air out of solenoids.
1769	A40G	5/15/2024	Repair coolant leak. Get topped up from fuel and lube.
1769	A40G	5/26/2024	250hr pm service done to unit. Changed outer engine air filter and outer cab air filter. Took samples of engine and a resample of transmission as per comments on service sheet. Checked over unit. Topped up hydraulic oil. Called unit up.
1769	A40G	5/26/2024	250 hour service, took engine and transmission sample, changed air filters, checked all guilds add hyd oil, checked all difs and greased machine
1769	A40G	6/19/2024	Plug into unit. Found no relevant codes to complaint. Check turbo for damage. Check air boots for damage, all looked ok. Ran out if time, end of day.
1769	A40G	7/2/2024	Wait for operator to bring unit. Test pressures, test ac system. Works fine.
1769	A40G	8/5/2024	Completed 500 hr service
1769	A40G	8/5/2024	500 hour service
1769	A40G	9/29/2024	Demob
1769	A40G	9/29/2024	Demobbed unit
1769	A40G	9/30/2024	Drive to unit check what seat button issues unit has. Look up part number, not in inventory. Look through seat based in glass can found seat with same switch (same as JD hitachi) installed and tested. Cleaned out back up alarm.
1769	A40G	10/8/2024	Install iecu
1769	A40G	10/15/2024	Mobilization inspection of machine, see attached paper work
1769	A40G	10/29/2024	Machine lost power and throwing codes for possible fuel leak, inspected machine, replaced fuel filters, fuel water separator full.of debris, sent unit back to work, will monitor for further faults
1769	A40G	11/4/2024	Perform 250 hour service, see attached paper work
1769	A40G	12/22/2024	Demobilization inspection of machine, see attached paper work

1769	A40G	1/8/2025	Complete demobe checks, fill out and submit paperwork
1769	A40G	1/9/2025	Mob in unit
1769	A40G	1/21/2025	Went to fire up machine prior to use next day, battery's were dead and key was left on, drove to pcy for batteries, swap out, fire up machine
1769	A40G	1/25/2025	Operator complaint that battery box door is stuck shut, inspected machine, removed lid covers, adjusted latch, sent back to work
1769	A40G	1/26/2025	Operator complaint that signal light is not working, replaced burnt out bulb, semtnunit back to work
1769	A40G	2/19/2025	Machine needs to be started to be moved, drove out to machine, boosted unit and got going, checked brake fluid level once parked at moose laydown
1769	A40G	3/8/2025	Operator complaint of low coolant alarm, checked over machine, checked coolant level sensor, pulled codes, no recorded codes for low coolant, unit is down for 2000hr service
1769	A40G	3/10/2025	Operator complaint of fresh oil on the back of the hydraulic oil tank, inspected unit, no signs of where oil is cokjng from whole tank is covered, cleaned off tank, checked for leaks, sent unit to work, came back and reinspected at coffee, filter lids are leaking, removed cleaned and reinstalled, ordered new seals
1769	A40G	3/12/2025	New seals came in for brake oil and hydraulic oil tanks, replaced all seals
1769	A40G	6/11/2025	Boosted unit
1769	A40G	6/27/2025	Complete service