

| Unit | Model | Date       | Work Order Details                                                                                                                                                                                                                                                              |
|------|-------|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1761 | A45G  | 6/23/2023  | Boost unit. Masters and 4 ways left on for days.                                                                                                                                                                                                                                |
| 1761 | A45G  | 7/7/2023   | Look at step, needed new got step brought out and installed                                                                                                                                                                                                                     |
| 1761 | A45G  | 7/7/2023   | Removed damaged step , and installed new step with new hard ware . Checked over unit before sending back to work                                                                                                                                                                |
| 1761 | A45G  | 7/16/2023  | No codes active. Checked oil levels. And took unit for a drive while monitoring pressure and temp. Stayed in the normal range the whole time. Did a shake test aswell and couldn't make unit duplicate problem. Sent back to work. Ordered new hyd test port as one was leaking |
| 1761 | A45G  | 7/17/2023  | -replace leaking remote test port orings -send unit to lube bay to top up hyd oil                                                                                                                                                                                               |
| 1761 | A45G  | 7/19/2023  | Replaced test port fittings and orings, run unit and checked for leaks                                                                                                                                                                                                          |
| 1761 | A45G  | 8/2/2023   | Tight loose guard                                                                                                                                                                                                                                                               |
| 1761 | A45G  | 8/16/2023  | Complaints of fire extinguisher, falling off Re bent bracket and re secured fire extinguisher                                                                                                                                                                                   |
| 1761 | A45G  | 9/18/2023  | Drove out to the oilers pad and cut off bent shackel                                                                                                                                                                                                                            |
| 1761 | A45G  | 9/19/2023  | Fix lines                                                                                                                                                                                                                                                                       |
| 1761 | A45G  | 10/15/2023 | Go to x-4, wait for SXS to take me to unit with booster pack, SXS got stuck, carry booster pack in peat pile and boost truck, drive unit to x-4.                                                                                                                                |
| 1761 | A45G  | 10/18/2023 | Repair radios coax cable, test to ensure it has proper range                                                                                                                                                                                                                    |
| 1761 | A45G  | 10/21/2023 | Look over SCR codes. Forced a burn and everything cleared up.                                                                                                                                                                                                                   |
| 1761 | A45G  | 10/29/2023 | Boost to start - no crank. Troubleshoot no crank - find ground level shutdown tripped. Rest switch and start machine.                                                                                                                                                           |
| 1761 | A45G  | 11/25/2023 | Check over unit                                                                                                                                                                                                                                                                 |
| 1761 | A45G  | 11/25/2023 | Try and start unit. Won't take charge ordered batteries                                                                                                                                                                                                                         |
| 1761 | A45G  | 12/8/2023  | Checked unit over as it went through fuel bay                                                                                                                                                                                                                                   |
| 1761 | A45G  | 12/9/2023  | Checked over in fuel bay                                                                                                                                                                                                                                                        |
| 1761 | A45G  | 12/11/2023 | Unit won't shift into gear. Go to unit inspect found truck parkbrake switch flipped the wrong way rest and test all good                                                                                                                                                        |
| 1761 | A45G  | 12/12/2023 | 1761 (updated) Units down Emission fault codes Needs differential pressure sensor (Cross with Kevin on parts)                                                                                                                                                                   |
| 1761 | A45G  | 12/12/2023 | Travel to unit and did DPF test and checked the perimeters there was no reading for differential pressure trouble shoot and unit needs a new differential pressure sensor                                                                                                       |
| 1761 | A45G  | 12/12/2023 | Travel around to where wiggles are working and found out the unit is working                                                                                                                                                                                                    |
| 1761 | A45G  | 12/13/2023 | Inspect unit and found dpf codes order orts                                                                                                                                                                                                                                     |

|      |      |            |                                                                                                                                                                                                                             |
|------|------|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1761 | A45G | 12/13/2023 | Installed the new DPF differential pressure sensor tested good gave unit a manual regen and called unit up                                                                                                                  |
| 1761 | A45G | 1/22/2024  | Replaced robbed egt probe                                                                                                                                                                                                   |
| 1761 | A45G | 1/25/2024  | Start units let warm up move to back of lay down                                                                                                                                                                            |
| 1761 | A45G | 1/30/2024  | Step crunched Bend back out and looked over all welds                                                                                                                                                                       |
| 1761 | A45G | 1/31/2024  | Replace def filler neck. Top up def                                                                                                                                                                                         |
| 1761 | A45G | 2/2/2024   | Install new coax connector and mic                                                                                                                                                                                          |
| 1761 | A45G | 2/3/2024   | Horn not working. Check the fuses for the horn was good. Checked other fuses for that circuit windshield wiper motor fuse was long. Replaced that fuse. Everything working                                                  |
| 1761 | A45G | 2/4/2024   | Inspect unit pull apart def filler line find old filter wedged into tube remove and clean out new screen all good                                                                                                           |
| 1761 | A45G | 3/13/2024  | Drive to machine through very muddy conditions. Repair wiring from antennae                                                                                                                                                 |
| 1761 | A45G | 4/5/2024   | Tshoot and diag codes. Egr no flow read. Clean venturi and perform service regej unit is now up                                                                                                                             |
| 1761 | A45G | 5/13/2024  | Got to unit field washed found hydraulic hose leaking. Looked up parts and ordered                                                                                                                                          |
| 1761 | A45G | 5/23/2024  | Installed new brake line                                                                                                                                                                                                    |
| 1761 | A45G | 7/20/2024  | Troubleshoot ac compressor clutch operation, found loose connected at panel in cab, troubleshoot lights not working, troubleshoot engine failure code                                                                       |
| 1761 | A45G | 8/12/2024  | Drove to unit across bridge at breaker 5, attempted to hook up Volvo computer to unit, tech tool will not open, put unit in service mode, found code for transmission lube pressure low, ran out of time to diagnose issue. |
| 1761 | A45G | 8/12/2024  | Drive across bridge to unit. Plug in with Volvo computer. Tech tool would not work. Put unit into service mode. Found low transmission lube pressure code. Ran out of time to diagnose                                      |
| 1761 | A45G | 8/22/2024  | Got to unit looked it over and ordered parts step and exhaust stack                                                                                                                                                         |
| 1761 | A45G | 8/29/2024  | Replaced broken exhaust stack, welded up cracks in heat shield/mount                                                                                                                                                        |
| 1761 | A45G | 8/29/2024  | Replaced broken step                                                                                                                                                                                                        |
| 1761 | A45G | 9/25/2024  | Got to unit and repaired coax cable to back of radio                                                                                                                                                                        |
| 1761 | A45G | 10/7/2024  | Replaced radio , range is now good                                                                                                                                                                                          |
| 1761 | A45G | 10/28/2024 | Inspection                                                                                                                                                                                                                  |
| 1761 | A45G | 10/28/2024 | Checked unit over                                                                                                                                                                                                           |
| 1761 | A45G | 11/11/2024 | Unit needed regen. Preformed regen had to regen twice                                                                                                                                                                       |

|      |      |            |                                                                                                                                                                                                                                          |
|------|------|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1761 | A45G | 11/19/2024 | Drove to unit out W4, T/S poor radio reception, checked connections and cable out to antenna, found antenna missing and replaced.                                                                                                        |
| 1761 | A45G | 11/27/2024 | Operator wrapped cable around tire. Cut cable in various spots, remove cable and asses damage.                                                                                                                                           |
| 1761 | A45G | 11/27/2024 | 500 hours service Changing engine oil and engine oil filters, Changing diesel filters and air filters, cab filters, Changing hydraulic filters, brake filter,changing transfer box oil ,taking oil samples                               |
| 1761 | A45G | 11/27/2024 | Did 500hr service.                                                                                                                                                                                                                       |
| 1761 | A45G | 12/4/2024  | Drove to unit, found missing a part to install hard pipe, found fitting broken off in final drive. Extracted broken fitting from final. Looked up part for unit and ordered.                                                             |
| 1761 | A45G | 12/4/2024  | Drive to unit to begin changing out brake lines, found another part damaged that we need to start repairs. Ordered parts.                                                                                                                |
| 1761 | A45G | 12/5/2024  | Drove to unit, assisted with replacement of broken off hydraulic brake lines.                                                                                                                                                            |
| 1761 | A45G | 12/5/2024  | Repairs completed                                                                                                                                                                                                                        |
| 1761 | A45G | 12/5/2024  | Use easy out and remove broken off fitting inside final. Install new fitting. Remove all 3 old/ broken lines. Change out fittings and orings. Install new lines. Check hydraulic oil on unit. Called for hydraulic oil to get topped up. |
| 1761 | A45G | 12/19/2024 | Unthawed park brake with my heater found hydraulic line loose under cab fixed leak unit needs steer oil topped up.                                                                                                                       |
| 1761 | A45G | 12/20/2024 | Checked diff oils transmission oil. Unit coded looked up codes found this code needs software update                                                                                                                                     |
| 1761 | A45G | 12/26/2024 | Drive to unit and fix parking brake                                                                                                                                                                                                      |
| 1761 | A45G | 12/26/2024 | Four leaking hoses. Ordered hoses and damaged wear indicator plug on rear left axle                                                                                                                                                      |
| 1761 | A45G | 12/26/2024 | Tested all the selonoids                                                                                                                                                                                                                 |
| 1761 | A45G | 1/4/2025   | Change out damaged wear indicator on unit. Tighten loose fitting, fire up unit and check hoses that were ordered. Hoses barely sweating. Place hoses in stock.                                                                           |
| 1761 | A45G | 1/6/2025   | Move heat to better location. Thaw park brake. Made no difference. Got through wiring and inspect connectors, all looked good. Tried again after that and pb worked                                                                      |
| 1761 | A45G | 1/6/2025   | Drove to unit and found heater pointed at side of box. Moved heater and thawed out park brake, inspected plugs on park brake solenoid and park brake pressure sensor, inspected brake pads, park brake working properly again.           |
| 1761 | A45G | 1/6/2025   | Diagnosed park brake the dirt in the box is so wet it's melting and running down on the park brake                                                                                                                                       |

|      |      |           |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
|------|------|-----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1761 | A45G | 1/17/2025 | Checked a few things on park brake and ran out of time                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 1761 | A45G | 1/17/2025 | Park brake won't release tested spool valve to try to get it to release                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| 1761 | A45G | 1/23/2025 | Park brake issues                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| 1761 | A45G | 1/23/2025 | Asses cable wrapped around right hand rear tire, cut damaged section of cable and remove shackles, unwrap cable from around tire. Asses damage done. Found all lines and fittings plus the wear indicator damaged. Lookup and order parts                                                                                                                                                                                                                                                                                                                                                                                                     |
| 1761 | A45G | 1/31/2025 | Remove damaged brake lines, found two fittings on hub broken off inside, extract broken fittings. Install all new fittings and orings, run new lines and install. Button up all clamps etc. Call for hydraulic oil to unit as it's out of the sight glass                                                                                                                                                                                                                                                                                                                                                                                     |
| 1761 | A45G | 2/12/2025 | Park and ran out of fuel                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 1761 | A45G | 2/12/2025 | Complaints of park brake not releasing, got unit running and let wamr up. Press park brake and it released, functioned park brake and drove multiple times with no issue. Ops used unit all night.                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| 1761 | A45G | 4/12/2025 | 2000 hr service                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 1761 | A45G | 4/12/2025 | Complete 2000 hr service                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 1761 | A45G | 4/12/2025 | Service 2000 completed                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 1761 | A45G | 5/23/2025 | Inspection of unit, check all levels, grease                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| 1761 | A45G | 5/30/2025 | Steamed Unit                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| 1761 | A45G | 6/4/2025  | Went through de-mob inspection sheet.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
| 1761 | A45G | 6/6/2025  | Setup for inspection, check over per mob checklist.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| 1761 | A45G | 6/6/2025  | Assist with checking lights                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
| 1761 | A45G | 6/7/2025  | Repair exhaust pipe. Repair exhaust heat sheild.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 1761 | A45G | 6/7/2025  | Travel to unit, PM repairs. Disassemble exhaust for welder to repair broken flange and guard. Changeout expired fire extinguisher. Remove burnt bulb for sample and search for new bulbs - none on hand. Setup crane and straighten bent steps. Connect laptop and check error code - active code for climate control, a/c not working. Connected gauges and found no charge. Charged up to 300 psi nitrogen and searched for leaks but couldn't find any, vacced system for 45 min and left discharged, ordered new schraeders and valve caps. Repaired shifter console panel. Reassembled exhaust, cleaned up. Looked up and ordered parts. |

|      |      |           |                                                                                                                                                                                                                                                                                    |
|------|------|-----------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1761 | A45G | 6/8/2025  | Troubleshoot, AC, not working. Found no refrigerant in system, vac system and held no leak found until I removed fittings and noticed trader was stuck remove trader and replaced revac system and then sure no leaking. Charged with 1.35 KG's and tested AC blowing at 8° in cab |
| 1761 | A45G | 6/10/2025 | Check over unit. Change buggy whip on truck for driving in the mine.                                                                                                                                                                                                               |
| 1761 | A45G | 6/17/2025 | Install new wiper, reverse alarm, signal light, light houseing, arm rest, ac saftey valve and staotoer valve, and emergency switch on fender                                                                                                                                       |
| 1761 | A45G | 6/19/2025 | Demob to go off site                                                                                                                                                                                                                                                               |