

Unit	Model	Date	Work Order Details
1763	A45G	8/23/2023	Walk around
1763	A45G	8/25/2023	Pre shift inspections
1763	A45G	8/26/2023	Turn on master switch and fire unit
1763	A45G	8/28/2023	Operator pulled up to line up. Had codes in Co-pilot monitor for DNSS signal not responding. Think it has something to do with GPS within that system. Plug in bTech tool to verify no engine or machine codes. Non active. Sent unit back to work.
1763	A45G	9/4/2023	Called about scr codes. None active. Torque stall and drive could not recreate
1763	A45G	9/4/2023	Go to unit for codes. No codes active while at machine
1763	A45G	9/20/2023	LM tire low. Checked and filled tire checked beads and oring for leaks. Checked tire face for damages. Operator to monitor.
1763	A45G	10/16/2023	Check air dryer for service. Dryer has recently been serviced and does not require maintenance
1763	A45G	10/17/2023	Troubleshoot gmss codes. Found gps antenna has failed
1763	A45G	11/10/2023	No start. Turn on both Master switches and start
1763	A45G	11/10/2023	Get running
1763	A45G	3/27/2024	Remove tailgate from 1527 install on unit
1763	A45G	3/27/2024	Installed tailgate
1763	A45G	5/12/2024	4000h service
1763	A45G	6/24/2024	Brake pressure codes removed codes good to go
1763	A45G	8/23/2024	Boost
1763	A45G	10/13/2024	Warm up unit. Bad def quality code active. Drained flushed and filled def tank. Test again and codes cleared.
1763	A45G	11/12/2024	Travel, check codes and has full derate for DEF quality, replace inlet filter in tank, waited for DEF to be drained and flushed out tank refilled DEF tank, started unit and code disappeared, let unit warm up to temp no codes
1763	A45G	11/15/2024	Pick parts. Travel to unit. Change out LH tailgate cable. Test and right side snapped. Wait for parts and change out right side cable.
1763	A45G	11/24/2024	250 service charge Air filter Samples check House keeping and checking over the equipment
1763	A45G	3/11/2025	Run check for cards check harness on transmission looks good only give issue when you drive over 30 km an hour pull the cords looks like spinning or have files and transmission let no supervisors come to decision to to do service transmission cut filters check

1763	A45G	3/12/2025	Warm up unit test drive ,troubleshoot problem, wait for service to drain fluid test drive unit shifting good at this time
1763	A45G	4/13/2025	Test drive unit and reduced shift function EF4206-7 comes up at 7th gear and a few seconds later transmission error EF4207-7. Check levels and visual inspection. Call strongco for troubleshooting tree as no Thompson laptop available. Strongco getting back with procedures
1763	A45G	4/14/2025	Troubleshoot shifting issues, check pressures
1763	A45G	4/14/2025	Get talked through troubleshooting tree with strongco rep and looks like lock up slippage and unit is found to still be under warranty. With travel and troubleshooting
1763	A45G	5/5/2025	Travel to units and boost to get running and check over for demob
1763	A45G	5/8/2025	Steamed
1763	A45G	5/8/2025	Steamed box / back / tires / sides
1763	A45G	6/16/2025	Moby units ordered four switches . (Seat heat, region , engineRPM , mirror, heat .)ordered wiper blade. needs fire extinguisher. Coolant was low had it topped up.
1763	A45G	6/19/2025	repairs
1763	A45G	6/20/2025	500hr pm on 1763 wiggle
1763	A45G	6/20/2025	500hr pm on 1763 wiggle
1763	A45G	6/22/2025	Look for new cables for end dump tailgate found cable but called to dozer
1763	A45G	6/23/2025	Thorough demob done check fluid levels missing bunch of switches
1763	A45G	6/23/2025	Removed old cables installed new cables with 3 clamps per loop
1763	A45G	6/25/2025	Brought unit into shop and started inspection
1763	A45G	6/25/2025	Dropped stump pans for the steam guy to steam out then went back when he was done and installed the pans
1763	A45G	6/26/2025	Went through inspection topped up all levels. Removed def head to change filter had to install new style head. Repaired 2 leaks by lh steering cylinder and removed tailgate as per guy.
1763	A45G	6/26/2025	Clean cab
1763	A45G	6/27/2025	Finish pm. Force burn and repaired coolant leak under cab
1763	A45G	6/28/2025	replaced steer tires
1763	A45G	7/20/2025	Complete mob inspection