

WO No.	Asset ID	WO Date	Brief Description	Job Status
577	HV202	12/24/2020	International 9400 250 Hour Inspection	Completed
635	HV202	12/27/2020	Replace alternator	Completed
2336	HV202	03/16/2021	PMVI Inspection	Completed
2673	HV202	05/06/2021	complete yearly CVIP	Completed
3184	HV202	06/29/2021	Replace transmission output U-Joint and steady bearing, Interaxle driveshaft & front diff output seal	Completed
3530	HV202	08/19/2021	500 HR PM	Completed
4008	HV202	10/04/2021	Starter issues and clutch issues	Completed
4650	HV202	12/01/2021	Complete commercial vehicle inspection and repairs	Completed
5118	HV202	01/04/2022	International 9400 500 Hour Inspection	Completed
6740	HV202	04/26/2022	Unit will not start	Completed
6824	HV202	05/02/2022	repair broken hood at retaining cable	Completed
7317	HV202	06/01/2022	Complete commercial vehicle inspection and repairs	Completed
7365	HV202	06/04/2022	repair air leak at outlet	Completed
8184	HV202	07/22/2022	Replace all drive tires *****Contractor site visit*****	Completed
8888	HV202	08/29/2022	repair jake brake	Completed
9247	HV202	09/14/2022	repair/install white noise & retorque wheels 350FT LBS	Completed
10380	HV202	11/03/2022	repair air leak in dash - from inspection	Completed
10381	HV202	11/03/2022	diagnose front left brakes oil soaked	Completed
10382	HV202	11/03/2022	repair marker lights - from inspection	Completed
10512	HV202	11/09/2022	replace LF wheel bearings, hub seal and brakes	Completed
13980	HV202	03/27/2023	Dump box will not raise or lower	Completed
17532	HV202	07/22/2023	replace fuel filter - hole	Completed
17566	HV202	07/23/2023	Diagnose & Repair Rear Axle Leak	Completed
20549	HV202	10/22/2023	replace batteries	Completed
29128	HV202	06/08/2024	250 Hour PM & Inspection	Completed
29412	HV202	06/16/2024	Repair safety related items	Completed
29425	HV202	06/17/2024	Replace Rear Engine Mounts *PMVI Inspection Repair(WO#29631)*	Completed
29630	HV202	06/22/2024	2000 Hour PM & Inspection	Completed
29631	HV202	06/22/2024	PMVI Inspection/Repairs-WO#28750 *Several repairs required Before Returning To Service*	Completed
30972	HV202	07/25/2024	Diagnose engine oil leaks, possibly from valve cover breather and injection pump	Completed
31044	HV202	07/26/2024	250 Hour PM & Inspection	Completed
31414	HV202	08/02/2024	Follow up Repair from Inspection 31044	Completed
34827	HV202	10/26/2024	Start truck, bring in shop, inspect for any work left on CVIP	Completed
34856	HV202	10/27/2024	Replace drag link, check unit for remaining work.	Completed
34860	HV202	10/27/2024	Install new muffler, new oil filler tube & o-ring, new valve cover breather & o-ring, R&R injection pump with new o-rings,R&R hydraulics	Completed
43221	HV202	05/27/2025	Box hoist does not lift.	Completed
49215	HV202	10/29/2025	start up	Completed

GB03-5